

Description:	Front view of Subject Property.





View of north corner of Subject Property (looking northeast).	





View of northern fence line of Subject Property (looking southeast).	





Description:	View of west corner of Subject Property (looking southwest).





Description:	View of west fence line of Subject Property (looking southeast).





	operty (looking n	





¾ view of Subject Property (looking east).





Description:	View of proposed parking lot on Subject Property (looking north).





Front view of Subject Structure.





¾ view of Subject Property (looking south).





Description:	¾ rear view of Subject Structure (looking west).





Description:	Rear view of Subject Property.	





View of rear fence line of Subject Property (looking northeast).





Description:	View of rear fence line of Subject Property (looking southwest).





r view of Subject Property.





Description:	View of fence line of Subject Property (looking northwest).





Description:	View of car wash from East Main Street (looking southeast).





Description:	View of car wash from driveway off East Main Street (looking southeast).





Description:	View of car wash (looking southeast).





Description:	View of rear and side of car wash (looking south).

