


New Jersey Department of Environmental Protection Hurricane Sandy Community Development Block Grant Form – 1 : No Historic Properties Affected (Version 1.0)



Applicant Name: Big Top Arcade In. Street Address: 1020 Boardwalk Municipality: Seaside Heights County: Ocean PAMS PIN: 1527 60 1 Longitude: UTM 18 S 579,401 m E Undertaking: Rehabilitation: Interior Exterior Both Elevation Property Reconstruction: Within Existing Footprint, plus 2 feet Outside Existing Footprint Property The project includes the clean out and gutting of a two story 80-foot oby 80-foot concrete commercial building. Everything was stripped down inside and out to the poured concrete and block superstructure. Dumpsters were purchased for debris removal and an extensive mold remediation throughout the entire building. The attached brick structure, located on the same tax parcel, had electrical service repairs and replacement on the first floor. All aspects of new construction were completed in the following areas: total new electrical system including new transformer, complete new plumming system, PVAC, six new 10 by 20 steel commercial security rollup doors with electric motors and manual doors. All concrete cracks and fissures were repaired all new tile and carpet flooring was installed, interior pair twas completed, extensive interior and exterior signage and props were installed. A new 6400 square foot roof system was installed. The final step was the acquisition of all new arcade and food equipment. There are no historic properties affected within the project's area of potential effects, pursuant to 36 CFR 800.4(d)(1) for the following reason(s):
Municipality: Seaside Heights County: Ocean PAMS PIN: 1527 60 1 Image: County: UTM 18 \$ 579,401 m E Latitude: UTM 18 \$ 4,421,996 m N Longitude: UTM 18 \$ 579,401 m E Undertaking: Rehabilitation: Interior Exterior Both Elevation Property Reconstruction: Within Existing Footprint, plus 2 feet Outside Existing Footprint Property: The project includes the clean out and gutting of a two story 80-foot concrete commercial building. Everything was stripped down inside and out to the poured concrete and block superstructure. Dumpsters were purchased for debris removal and an extensive mold remediation throughout the entire building. The attached brick structure, located on the same tax parcel, had electrical service repairs and replacement on the first floor. All aspects of new construction were completed in the following areas: total new electrical system including new transformer, complete new plumbing system, HVAC, six new 10 by 20 steel commercial security rollup doors with electric motors and manual doors. All concrete cracks and fissures were repaired all new tile and carpet flooring was installed, interior and exterior paint was completed, extensive interior and exterior signage and props were installed. A new 6400 square foot roof system was installed. The final step was the acquisition of all new arcade and food equipment. There are no historic properties affected within the project's area of potential effects, pursuant to 36 CFR 800.4(d)(1) for the following reason(s): [Check All Th
PAMS PIN: 1527 60 1 Latitude: UTM 18S 4,421,996 m N Longitude: UTM 18 \$ 579,401 m E Undertaking: Rehabilitation: Interior Exterior Both Elevation Property Reconstruction: Within Existing Footprint, plus 2 feet Outside Existing Footprint Property The project includes the clean out and gutting of a two story 80-foot by 80-foot concrete commercial building. Everything was stripped down inside and out to the poured concrete and block superstructure. Dumpsters were purchased for debris removal and an extensive mold remediation throughout the entire building. The attached brick structure, located on the same tax parcel, had electrical service repairs and replacement on the first floor. All aspects of new construction were completed in the following areas: total new electrical system including new transformer, complete new plumbing system, HVAC, six new 10 by 20 steel commercial security rollup doors with electric motors and manual doors. All concrete cracks and fissures were repaired all new tile and carpet flooring was installed, interior and exterior paint was completed, extensive interior and exterior signage and props were installed. A new 6400 square foot roof system was installed. The final step was the acquisition of all new arcade and food equipment. There are no historic properties affected within the project's area of potential effects, pursuant to 36 CFR 800.4(d)(1) for the following reason(s): [Check All That Apply] Historic Architecture: Located in "Green Zone" (Areas determined by FEMA/HPO to have low potential for
Latitude: UTM 18S 4,421,996 m N Longitude: UTM 18 S 579,401 m E Undertaking: Rehabilitation: Interior Exterior Both Elevation Property Reconstruction: Within Existing Footprint, plus 2 feet Outside Existing Footprint Description: The project includes the clean out and gutting of a two story 80-foot by 80-foot concrete commercial building. Everything was stripped down inside and out to the poured concrete and block superstructure. Dumpsters were purchased for debris removal and an extensive mold remediation throughout the entire building. The attached brick structure, located on the same tax parcel, had electrical service repairs and replacement on the first floor. All aspects of new construction were completed in the following areas: total new electrical system including new transformer, complete new plumbing system, HVAC, six new 10 by 20 steel commercial security rollup doors with electric motors and manual doors. All concrete cracks and fissures were repaired all new tile and carpet flooring was installed, interior and exterior paint was completed, extensive interior and exterior signage and props were installed. A new 6400 square foot roof system was installed. The final step was the acquisition of all new arcade and food equipment. There are no historic properties affected within the project's area of potential effects, pursuant to 36 CFR 800.4(d)(1) for the following reason(s): [Check All That Apply] Historic Architecture: Located in "Green Zone" (Areas determined by FEMA/HPO to have low potential for above-ground historic properties) Not 48 Years of
Undertaking: Rehabilitation: Interior Exterior Both Elevation Property Reconstruction: Within Existing Footprint, plus 2 feet Outside Existing Footprint Property The project includes the clean out and gutting of a two story 80-foot by 80-foot concrete commercial building. Everything was stripped down inside and out to the poured concrete and block superstructure. Dumpsters were purchased for debris removal and an extensive mold remediation throughout the entire building. The attached brick structure, located on the same tax parcel, had electrical service repairs and replacement on the first floor. All aspects of new construction were completed in the following areas: total new electrical system including new transformer, complete new plumbing system, HVAC, six new 10 by 20 steel commercial security rollup doors with electric motors and manual doors. All concrete cracks and fissures were repaired all new tile and capet flooring was installed, interior and exterior paint was completed, extensive interior and exterior signage and props were installed. A new 6400 square foot roof system was installed. The final step was the acquisition of all new arcade and food equipment. There are no historic properties affected within the project's area of potential effects, pursuant to 36 CFR 800.4(d)(1) for the following reason(s): [Check All That Apply] Historic Architecture: Located in "Green Zone" (Areas determined by FEMA/HPO to have low potential for above-ground historic properties) Not 48 Years of Age Lacks Integrity of Materials/Design Not 48 Years of Age Lacks Integrity of Mate
Reconstruction: Within Existing Footprint, plus 2 feet Outside Existing Footprint Property Description: The project includes the clean out and gutting of a two story 80-foot by 80-foot concrete commercial building. Everything was stripped down inside and out to the poured concrete and block superstructure. Dumpsters were purchased for debris removal and an extensive mold remediation throughout the entire building. The attached brick structure, located on the same tax parcel, had electrical service repairs and replacement on the first floor. All aspects of new construction were completed in the following areas: total new electrical system including new transformer, complete new plumbing system, HVAC, six new 10 by 20 steel commercial security rollup doors with electric motors and manual doors. All concrete cracks and fissures were repaired all new tile and carpet flooring was installed, interior and exterior paint was completed, extensive interior and exterior signage and props were installed. A new 6400 square foot roof system was installed. The final step was the acquisition of all new arcade and food equipment. There are no historic properties affected within the project's area of potential effects, pursuant to 36 CFR 800.4(d)(1) for the following reason(s): [Check All That Apply] Historic Architecture: Located in "Green Zone" (Areas determined by FEMA/HPO to have low potential for above-ground historic properties) Not 48 Years of Age Lacks Integrity of Materials/Design Not Within / In View of a National Register of Historic Places Listed / Eligible Historic District Not a Building (per FEMA Definition) Other – Lacks Distinctive Characteristics That Make It
Property Description: The project includes the clean out and gutting of a two story 80-foot by 80-foot concrete commercial building. Everything was stripped down inside and out to the poured concrete and block superstructure. Dumpsters were purchased for debris removal and an extensive mold remediation throughout the entire building. The attached brick structure, located on the same tax parcel, had electrical service repairs and replacement on the first floor. All aspects of new construction were completed in the following areas: total new electrical system including new transformer, complete new plumbing system, HVAC, six new 10 by 20 steel commercial security rollup doors with electric motors and manual doors. All concrete cracks and fissures were repaired all new tile and carpet flooring was installed, interior and exterior paint was completed, extensive interior and exterior signage and props were installed. A new 6400 square foot roof system was installed. The final step was the acquisition of all new arcade and food equipment. There are no historic properties affected within the project's area of potential effects, pursuant to 36 CFR 800.4(d)(1) for the following reason(s): [Check All That Apply] Historic Architecture: Located in "Green Zone" (Areas determined by FEMA/HPO to have low potential for above-ground historic properties) Not 48 Years of Age Lacks Integrity of Materials/Design Not Within / In View of a National Register of Historic Places Listed / Eligible Historic District Not a Building (per FEMA Definition) Other – Lacks Distinctive Characteristics That Make It Individually Eligible for Listing on NRHP Archaeology: Low Archaeological Potenti
Description: was stripped down inside and out to the poured concrete and block superstructure. Dumpsters were purchased for debris removal and an extensive mold remediation throughout the entire building. The attached brick structure, located on the same tax parcel, had electrical service repairs and replacement on the first floor. All aspects of new construction were completed in the following areas: total new electrical system including new transformer, complete new plumbing system, HVAC, six new 10 by 20 steel commercial security rollup doors with electric motors and manual doors. All concrete cracks and fissures were repaired all new tile and carpet flooring was installed, interior and exterior paint was completed, extensive interior and exterior signage and props were installed. A new 6400 square foot roof system was installed. The final step was the acquisition of all new arcade and food equipment. There are no historic properties affected within the project's area of potential effects, pursuant to 36 CFR 800.4(d)(1) for the following reason(s): [Check All That Apply] Historic Architecture: Located in "Green Zone" (Areas determined by FEMA/HPO to have low potential for above-ground historic properties) Not 48 Years of Age Lacks Integrity of Materials/Design Mot within / In View of a National Register of Historic Places Listed / Eligible Historic District Not a Building (per FEMA Definition) Other – Lacks Distinctive Characteristics That Make It Individually Eligible for Listing on NRHP Archaeology: Mot Archaeological Potential: Mot Archaeological Potential:
following reason(s): [Check All That Apply] Historic Architecture: Located in "Green Zone" (Areas determined by FEMA/HPO to have low potential for above-ground historic properties) Not 48 Years of Age Lacks Integrity of Materials/Design Not Within / In View of a National Register of Historic Places Listed / Eligible Historic District Not a Building (per FEMA Definition) Other – Lacks Distinctive Characteristics That Make It Individually Eligible for Listing on NRHP Archaeology: Low Archaeological Potential: Located on Barrier Island
Historic Architecture: Located in "Green Zone" (Areas determined by FEMA/HPO to have low potential for above-ground historic properties) Not 48 Years of Age Lacks Integrity of Materials/Design Not Within / In View of a National Register of Historic Places Listed / Eligible Historic District Not a Building (per FEMA Definition) Other – Lacks Distinctive Characteristics That Make It Individually Eligible for Listing on NRHP Archaeology: Low Archaeological Potential: Located on Barrier Island
Located on Barrier Island
 Substantially Conforms to the Original Footprint Located on Disturbed Soils Not Located within 500 Feet of Waterways and/or Wetlands Not Located on Well-drained Soils Not Identified Within a Historic Property / Historic District
Public Consultation Federally Recognized Tribes, Certified Local Governments, Historic Preservation Commissions, etc:
HISTORIC PRESERVATION OFFICE USE ONLY
□ I concur with this finding,
I do not concur with this finding for the following reason(s):
Daniel D. Saunders Deputy State Historic Preservation Officer
Architecture Reviewer John P. Kurth Archaeology Reviewer John W. Martin
Date Reviewed June 11, 2014
Required Documentation: ☑ Historic Properties Map ☑ Soils Map ☑ USGS Quad ☑ Property Photos V1.0 9/26/13 Page 1 of 1