FIBI514-R1r

Peach Orchard Brook

Hussa Street

Municipality: Linden

County: Union

Drainage Area (sq miles): 2.9

Sample Date: 5/23/2014

Site Type: Fixed





Metric 1 - Number of intolerant vertebrate species	0.00
Metric 2 - Proportion of vertebrate species as top carnivores	0.00
Metric 3 -Percent tolerant fish	0.00
Metric 4 -Proportion of total richness as native	71.43
Metric 5 -Percent native crayfish	0.00
Metric 6 -Brook trout density	0.00

Air Temperature (°C)	18.6
Water Temperature (°C)	16.53
Dissolved Oxygen (mg/L)	10.86
% Saturation	111.2
pН	6.74
Conductivity (uS/cm)	698

Headwaters IBI Score (0-100):	11.90
IBI Rating:	Very Poor
High Gradient Habitat Score (0-200):	87
Habitat Rating:	Marginal

Summary:

FIBI514 was rated "very poor" in 2014, and also in its previous sampling in 2013. This site contained tolerant fish and a non native crayfish. Peach Orchard Brook is located adjacent to a park and lacked suitable habitat, had poor bank stability, and had several stormwater outfalls.

FIBI514-R1r

Peach Orchard Brook

Common Name	Scientific Name	Abundance
Banded Killifish	Fundulus diaphanus	471
Green Sunfish	Lepomis cyanellus	95
Mummichog	Fundulus heteroclitus	38
Pumpkinseed	Lepomis gibbosus	24
Brown Bullhead	Ameiurus nebulosus	6
Golden Shiner	Notemigonus crysoleucas	3
Red Swamp Crayfish	Procambarus clarkii	2