

# Return & Repair Form:

## Customer Information:

Company Name: HAMILTON TWP P.D. B: \_\_\_\_\_ S: \_\_\_\_\_  
 Date Received: 3.17.09 Date Given to Service: \_\_\_\_\_  
 Carrier: FedEx - UPS - DHL - USPS Method: GRD - NDA - 2DY - 3DY - Other

## Product Information:

Product: 7410 - 7110 - 6510 - 6810 Serial #: AR WA - 0162  
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR -  
 Whole Instrument Top 1/2 Sim Ser #: \_\_\_\_\_  
 Other \_\_\_\_\_ Probe Ser # DD P -  
**ACCESSORIES:**  
 110 V A/C Adapter  Regulator  Mag Card Rdr# \_\_\_\_\_  
 Printer Paper  Printer Ribbon  Casio # \_\_\_\_\_  
 Mouthpieces  Carrying Case  Dry Gas  
 Other (Please Specify) \_\_\_\_\_ Warranty Exp. Date \_\_\_\_\_

## Repair Information:

Test #

Reason for Return: ERROR 75 HOSE HEATER?

Part Number	Description	Qty	Total Cost
<u>B100902</u>	<u>FLOW SENSOR</u>	<u>1</u>	<u>n/c w/WRK</u>
<u>MPCAL71</u>	<u>CHK</u>	<u>1</u>	<u>n/c w/WRK</u>
<u>MPLABOR</u>		<u>2.0</u>	<u>n/c w/WRK</u>

### Repair Notes:

BLOWING NOT ALLOWED ERROR - FLOW SENSOR BROKEN / REPLACED - ERROR 75 NOT DUPLICATED AFTER 6 DAYS - "BNA" ERROR ALSO CAUSED BY BLOCKED BACK VALVE ON CUVEITE - REPAIRED

CAL w/ QC & OPS CHECKS

Service Technician: [Signature]

Date: 03.24.09