RETURN & REPAIR FORM

CUSTOMER KEAN UNIV Cust. #

Date ret. 7/12 Carrier Fed Exp Method Priority RMA#

7110 Serial# ARWC-0020 Warranty exp.:

Reported Problem: ERROR 32 - NEW UNIT!

Accessories (check all that apply): ☐ Regulator ☐ P.Paper ☐ Scotty V ☐ Printer Rib. ☐ Pouch
Sim. Temp. Probe Ser.# ☐ Keyboard ☐ Organizer ☐ Key
☐ Mouthpieces ☐ Sim. To cuvette hose ☐ Pump to Sim. hose ☐ Power cord
☐Other (specify)
☐Other (specify)

	Part#	Description	$	Qty	Total
WARRANTY	6810269	MOTOR		1	N/C
WARRANTY	8314351	PCB		1	N/C
WARRANTY	MPCAL71	CAL		1	N/C
			Repair Time		Time $

TOTAL REPAIR $

REPAIR NOTES:
REPLACED MOTOR - DUE TO ERROR 032
NEW ERROR 072 = HOSE NTC

FOUND JACK SCREW UNDER PCB - "LUBECK PRODUCTION"

REPLACED PCB UNDER WARRANTY

CAL + FULL QC & OPS CHECKS

Date 07-12-2005 Technician

Every above checked item is included ☐ Shipping