

Doss, Gary

From: Rutala Associates <jmrutala@comcast.net>
Sent: Monday, November 10, 2014 7:41 AM
To: Bonny Serratelli
Cc: Jmrutala@comcast.net
Subject: RE: NCR40014 Somers Point
Attachments: Gateway Latest Set (3).pdf

Hi Bonnie,

1. The building was not substantially damaged.
2. The latest set of plans are attached.
3. There are no underground or above ground tanks on site.
4. I am not aware of a lead base paint/ asbestos screening having been conducted. The interior of the building has been gutted to bare block.

Hope this is helpful.

Jim

James M. Rutala, PP, AICP, MBA
Rutala Associates, LLC
Linwood, New Jersey 08221-1226
jmrutala@comcast.net
609.743.0354



Please consider the environment before printing this email.

This email message, including attachments, from Rutala Associates, LLC is for the sole use of the intended recipient(s), and may contain confidential and privileged information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, please contact the sender by reply email and delete the message. Thank you for your cooperation.

From: Bonny Serratelli [<mailto:bserratelli@njeda.com>]
Sent: Thursday, November 06, 2014 8:16 AM
To: Rutala Associates
Subject: FW: NCR40014 Somers Point

Jim,
Below is the request for additional information received from DEP regarding the Somers Point Theater property.

Please provide the responses.

Thank you,

From: Pettit, Chris [<mailto:Chris.Pettit@icfi.com>]
Sent: Wednesday, November 05, 2014 10:59 AM

To: Bonny Serratelli
Cc: Jerri Weigand
Subject: NCR40014 Somers Point

Bonny,

Here is some additional information requested for this application, please let me know if I should forward this request onto additional people within EDA.

Cheers

Chris

To All

Below are the preliminary questions:

1. Was the property “substantially damaged” (i.e., the cost to rehabilitate the building is greater than 50% of the market value of the structure before the storm damage?)
2. The site plans are not very high quality and difficult to read – can a higher quality scan be provided?
3. Are there any underground or aboveground storage tanks at the property?
4. Has a lead-based paint and/or asbestos screening survey been conducted?

CHRISTOPHER J. PETTIT | Senior Associate | +1.609.403.7443 Office | christopher.pettit@icfi.com | icfi.com

ICF INTERNATIONAL | 850 Bear Tavern Road, Suite 101, Ewing, NJ 08628



Please consider the environment before printing this e-mail.

--

This message has been scanned for viruses and dangerous content by [MailScanner](#), and is believed to be clean.

Notice: This e-mail message and any attachment to this e-mail message contain information that may be legally privileged and confidential from the New Jersey Economic Development Authority. If you are not the intended recipient, you must not review, transmit, convert to hard copy, copy, use or disseminate this e-mail or any attachments to it.

If you have received this e-mail in error, please immediately notify us by return e-mail or by telephone at 609-858-6700 and delete this message. Please note that if this e-mail message contains a forwarded message or is a reply to a prior message, some or all of the contents of this message or any attachments may not have been produced by the New Jersey Economic Development Authority.

This notice is automatically appended to each e-mail message leaving the New Jersey Economic Development Authority.

Please consider the environment before printing this message.
Please consider the environment before printing this message.

--

This message has been scanned for viruses and dangerous content by [MailScanner](#), and is believed to be clean.