

*New Jersey Department of Transportation*  
1035 Parkway Avenue, PO Box 600, Trenton, New Jersey 08625-0600



## *Baseline Document Change Announcement*

**ANNOUNCEMENT: BDC15D-05**

**DATE: November 30, 2015**

**SUBJECT: Butt Joint Detail for Full Depth Concrete Pavement Repair  
Revised CD-453-1 of the 2007 Standard Roadway Construction  
Details  
BDC15D-05**

---

The Standard Construction Details sheet CD-453-1 has been revised to correct the size of the hole diameter drilled for the 1½” epoxy coated smooth dowel bar in the Butt Joint Detail for the Full Depth Concrete Pavement Repair. Added a new note No. 5: “Drill 1⅝” holes for dowel bars. Epoxy grout dowel bars into drilled holes.”

Also, deleted the metric units from the retention disk detail.

### **Implementation Code R (ROUTINE)**

Changes must be implemented in all applicable Department projects scheduled for Final Design Submission at least one month after the date of the BDC announcement. This will allow designers to make necessary plan, specifications, and estimate/proposal changes without requiring the need for an addenda or postponement of advertisement or receipt of bids.

***Recommended By:***

Original Signed

---

Richard Jaffe, P.E.  
Director  
Capital Program Support

***Approved By:***

Original Signed

---

Eli D. Lambert  
Acting Assistant Commissioner  
Capital Program Management

RJ:KS:YB

Attachments:

Revised sheet CD-453-1 of the Standard Roadway Construction Details 2007.