

Return & Repair Form:

Customer Information:

Company Name: NEW Jersey state B: _____ S: _____
 Date Received: 03/09/2010 Date Given to Service: _____
 Carrier: FedEx UPS DHL USPS Method: GRD - NDA 2DY 3DY - Other _____

Product Information:

Product: 7410-~~7110~~-6510-6810-7510 Serial #: AR NK-0035
 9510- Drug Tester 5000
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR -
 Whole Instrument Top ½ Sim Ser #: _____
 Other _____ Probe Ser # DD P -
ACCESSORIES:
 110 V A/C Adapter Regulator Mag Card Rdr# _____
 Printer Paper Printer Ribbon Casio # _____
 Mouthpieces Carrying Case Dry Gas
 Other (Please Specify) _____ Warranty Exp. Date _____

Repair Information:

Test #

Reason for Return: FC + FW UPDATE

Part Number	Description	Qty	Total Cost
<u>MPMISC</u>	<u>DEMO MODEM PN 12130 (NON INV.)</u>	<u>1</u>	<u>116⁰⁰</u>
<u>6808455</u>	<u>FC</u>	<u>1</u>	
<u>MP Cal 71</u>	<u>Cal</u>	<u>1</u>	
<u>8100902</u>	<u>Flow Sensor</u>	<u>1</u>	
<u>MP Labor</u>	<u>Labor</u>	<u>.5</u>	

Repair Notes:

MODEM ERROR / REPLACE MODEM WITH DEMO PART @ 1/2 LIST #.
LOAD NJ 312 A0 / NEW FW NJ 3.12 A0

Cal w/ RL's ops check

NEW FC# ARNK-0524

Flow Sensor replace because of corrosion.

Service Technician: JS

Date: 3/11/2010
2/17/2010