

# Return & Repair Form

## Customer Information:

Company Name: Egg Harbor TWP B: \_\_\_\_\_ S: \_\_\_\_\_  
 Date Received: 6-25-08 Date Given to Service: \_\_\_\_\_  
 Carrier: (FedEx) - UPS - DHL - USPS Method: GRD - NDA - 2DY (3DY) Other \_\_\_\_\_

## Product Information:

Product: 7410 - (7110) - 6510 - 6810 Serial #: AR 3B - 0112  
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR - \_\_\_\_\_  
 Whole Instrument Top ½ Sim Ser #: \_\_\_\_\_  
 Other \_\_\_\_\_ Probe Ser # DD P - \_\_\_\_\_

**ACCESSORIES:**

110 V A/C Adapter       Regulator       Mag Card Rdr# \_\_\_\_\_  
 Printer Paper       Printer Ribbon       Casio # \_\_\_\_\_  
 Mouthpieces       Carrying Case       Dry Gas  
 Other (Please Specify) \_\_\_\_\_ Warranty Exp. Date \_\_\_\_\_

## Repair Information:

Test #

Reason for Return: "LOCKS UP"

Part Number	Description	Qty	Total Cost
<u>6808455</u>	<u>FC</u>	<u>1</u>	<u>N/C WARR</u>
<u>MPCAL 71</u>	<u>CAL</u>	<u>1</u>	<u>N/C WARR</u>
<u>B315075</u>	<u>7110 PCB</u>	<u>1</u>	<u>N/C WARR</u>
<u>MPCM 71</u>	<u>CAL</u>	<u>1</u>	<u>N/C WARR</u>
<u>MPLABOR</u>		<u>2.5</u>	<u>N/C WARR</u>

### Repair Notes:

REPLACED PCB = PROBLEM WAS DUPLICATED - REPLACE PCB  
 SET UP - CONFIG / CAL W/ QC & OPS CHECKS

Service Technician: [Signature]

Date: 07-01-08