

RETURN AND REPAIR FORM



Customer Information

B:

S:

Company Name: South Amboy P.D., NJ

Date Received: 04-03-12 Date given to service: 04-03-12

Carrier: FedEx UPS USPS Shipping Method: GRD 3DAY 2DAY
 NDA-PRI NDA-STD

Product: 6510 6810
 7110 8610
 7510 DT5000
 7410 Upper-half 9510
 7410 Whole

Serial Number: AR SC-0059
 Printer Serial#: AR
 Sim Serial#: DD
 Probe Serial#: DD

Warranty Expires: _____

Description: A B Plus Demo Screener Trade In

Accessories

110V A/C Adapter Regulator Printer Ribbon Printer Paper
 Mouthpieces 9510 Stylus 9510 Top Cover Carrying Case
 Dry Gas Other (please specify) _____

Repair Information:

Test#:

Part Number	Description	Qty	Total Cost
<u>mp Cal 71</u>	<u>Calibration</u>	<u>1</u>	<u>w/cw</u>
<u>6808455</u>	<u>Fuel Cell</u>	<u>1</u>	<u>w/cw</u>
<u>6808374</u>	<u>motor</u>	<u>1</u>	<u>w/cw</u>
<u>mp Labor</u>	<u>Labor</u>	<u>0.5</u>	<u>w/cw</u>

Repair Notes: Replaced Capacitor at Location C-156 and C-167, to restore the modem connection. While completing the QC check the Fuel cell did not pass because of leakage and the motor made a squeal sound, replaced both. Cal w/ QC Ops check. Replaced FC # AR5B-0197, with ARCM-0309.

Service Technician: JS Date: 4-4-12