

# Return & Repair Form:

## Customer Information:

Company Name: Bloomfield PD B: \_\_\_\_\_ S: \_\_\_\_\_  
 Date Received: 12-17-2010 Date Given to Service: \_\_\_\_\_  
 Carrier: FedEx - UPS - DHL - USPS Method: GRD - NDA - 2DY - 3DY - Other

## Product Information:

Product: 7410-7110-6510-6810-7510  
 9510-Drug Tester 5000  
 Description: A - B - Plus - Screener - Demo  
 Serial #: ARUM-0067  
 Printer Ser #: AR  
 Whole Instrument Top 1/2 Sim Ser #: \_\_\_\_\_  
 Other \_\_\_\_\_ Probe Ser # DD P  
**ACCESSORIES:**  
 110 V A/C Adapter  Regulator  Mag Card Rdr# \_\_\_\_\_  
 Printer Paper  Printer Ribbon  Casio # \_\_\_\_\_  
 Mouthpieces  Carrying Case  Dry Gas  
 Other (Please Specify) \_\_\_\_\_ Warranty Exp. Date \_\_\_\_\_

## Repair Information:

Test #

Reason for Return: \_\_\_\_\_

Part Number	Description	Qty	Total Cost
<u>8315075</u>	<u>PCB</u>	<u>1</u>	<u>w/cw</u>
<u>6808455</u>	<u>FC</u>	<u>1</u>	<u>w/cw</u>
<u>MP Cal 41</u>	<u>Cal</u>	<u>1</u>	<u>w/cw</u>
<u>MP Labor</u>	<u>Labor</u>	<u>.5</u>	<u>w/cw</u>

### Repair Notes:

FC# ARBL-1036 Installed FC# ARZK-0695 replace for preventive maintenance.

Install new PCB, because unit would no longer download to memory.

Cal w/DC; ops check

Service Technician: \_\_\_\_\_

Date: 1/25/2011