

~~Return~~ & Repair Form:

**Customer Information:**

Company Name: NJSP Woodbine B: \_\_\_\_\_ S: \_\_\_\_\_  
 Date Received: 4-14-10 Date Given to Service: \_\_\_\_\_  
 Carrier: ~~FedEx~~ - UPS - DHL - USPS Method: GRD - ~~NDA~~ - 2DY - 3DY - Other

**Product Information:**

Product: 7410-7110-6510-6810-7510 Serial #: AR WC-0015  
 9510- Drug Tester 5000  
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR \_\_\_\_\_  
 Whole Instrument Top 1/2 Sim Ser #: \_\_\_\_\_  
 Other \_\_\_\_\_ Probe Ser # DD P -  
**ACCESSORIES:**  
 110 V A/C Adapter  Regulator  Mag Card Rdr# \_\_\_\_\_  
 Printer Paper  Printer Ribbon  Casio # \_\_\_\_\_  
 Mouthpieces  Carrying Case  Dry Gas  
 Other (Please Specify) \_\_\_\_\_ Warranty Exp. Date \_\_\_\_\_

**Repair Information:**

Test #

Reason for Return:

Part Number	Description	Qty	Total Cost
<u>1815113</u>	<u>7110 FUSE</u>	<u>1</u>	<u>N/K/W</u>
<u>MP labor</u>	<u>Labor</u>	<u>.5</u>	<u>N/K/W</u>

Repair Notes:

Replace 100V FUSE in back of 7110.

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Service Technician: [Signature]

Date: 4/15/2010