

**Return & Repair Form:**

**Customer Information:**

Company Name: City of Plainfield P.D. B: \_\_\_\_\_ S: \_\_\_\_\_  
 Date Received: \_\_\_\_\_ Date Given to Service: \_\_\_\_\_  
 Carrier: FedEx - UPS - DHL - USPS Method: GRD - NDA - 2DY - 3DY - Other

**Product Information:**

Product: 7410-7110 6510-6810-7510 Serial #: ARWC-00109  
 9510- Drug Tester 5000  
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR -  
Whole Instrument Top ½ Sim Ser #: \_\_\_\_\_  
 Other \_\_\_\_\_ Probe Ser # DD P -  
**ACCESSORIES:**  
 110 V A/C Adapter  Regulator  Mag Card Rdr# \_\_\_\_\_  
 Printer Paper  Printer Ribbon  Casio # \_\_\_\_\_  
 Mouthpieces  Carrying Case  Dry Gas  
 Other (Please Specify) \_\_\_\_\_ Warranty Exp. Date \_\_\_\_\_

**Repair Information:**

Test #

Reason for Return: \_\_\_\_\_

Part Number	Description	Qty	Total Cost
<u>6808455</u>	<u>FC</u>	<u>1</u>	<u>w/c w</u>
<u>8100902</u>	<u>Flow sensor</u>	<u>1</u>	<u>w/c w</u>
<u>6808486</u>	<u>Plate</u>	<u>1</u>	<u>w/c w</u>
<u>mp cal 71</u>	<u>Cal</u>	<u>1</u>	<u>w/c w</u>
<u>mp labor</u>	<u>Labor</u>	<u>.5</u>	<u>w/c w</u>

Repair Notes:

FCT ARCA-0786  
Unit gave repeated blowing, not allowed error.  
Evaluation: Flow sensor for damage, replaced ES.  
Cal w/QC & Ops Check  
Cal w/QC & Ops Check

Service Technician: AS

Date: 6/15/2011