

RETURN AND REPAIR FORM

Customer Information

B:

S:

Company Name: Newfield Boro P.D., Newfield N.J.

Date Received: 09/30/11 Date given to service: _____

Carrier: FedEx UPS USPS Shipping Method: GRD 3DAY 2DAY
 NDA-PRI NDA-STD

Product: 6510 6810
 7110 8610
 7510 DT5000
 7410 Upper-half 9510
 7410 Whole

Serial Number: AR WC 0071
 Printer Serial#: AR
 Sim Serial#: DD
 Probe Serial#: DD

Warranty Expires: _____

Description: A B Plus Demo Screener Trade In

Accessories

110V A/C Adapter Regulator Printer Ribbon Printer Paper
 Mouthpieces 9510 Stylus 9510 Top Cover Carrying Case
 Dry Gas Other (please specify) _____

Repair Information:

Test#:

Part Number	Description	Qty	Total Cost
<u>6808455</u>	<u>Fuel Cell</u>	<u>1</u>	<u>N/C W</u>
<u>6808486</u>	<u>Plate</u>	<u>1</u>	<u>N/C W</u>
<u>mp cal 91</u>	<u>Calibration</u>	<u>1</u>	<u>N/C W</u>
<u>mp labor</u>	<u>labor</u>	<u>.5</u>	<u>N/C W</u>

Repair Notes: SIM TEMP OUT OF RANGE - PERFORMED AUTO-ADJUST
IN SIM TEMP/OFFSET 1831 TO 1842 ! GAIN IS 2687 -

Install a new Fuel cell # ARCH-1183, the old Fuel
cell was breaking. also install a new capacitor a location
C-167.
cal w/ QC & OPS check

Service Technician: [Signature] Date: 10-4-11