

# Return & Repair Form:

## Customer Information:

Company Name: New Jersey State Police B: 53069 S: \_\_\_\_\_  
 Date Received: 1-22-09 Date Given to Service: \_\_\_\_\_  
 Carrier: FedEx UPS - DHL - USPS Method: GRD - NDA 2DY - 3DY - Other

## Product Information:

Product: 7410 7110 - 6510 - 6810 Serial #: AR WC - 0072  
 De: EAH Printer Ser #: AR -  
 W: EMAIL KEVIN Sim Ser #: \_\_\_\_\_  
WITH QUOTE Probe Ser # DD P -  
TO GET PO #  
 Mag Card Rdr# \_\_\_\_\_  
 Casio # \_\_\_\_\_  
 Dry Gas  
 Ot: \_\_\_\_\_ Warranty Exp. Date \_\_\_\_\_

## Repair Information:

Test #

Reason for Return: ? FC? + ERROR 23's

Part Number	Description	Qty	Total Cost
<u>6808455</u>	<u>FC</u>	<u>1</u>	
<u>MPCAL 71</u>	<u>CAL</u>	<u>1</u>	
<u>6809458</u>	<u>IR DETECTOR</u>	<u>1</u>	<u>N/C WARR</u>
<del>7110715</del>			
<u>8315075</u>	<u>PCB</u>	<u>1</u>	
<u>MPLA FOR</u>		<u>1.0</u>	

### Repair Notes:

REPLACE FC / REPLACE IRD N/C / PROBLEM ON PCB - COMPONENT  
BLOWS IR SOURCE - REPLACED SOURCE W/ NON-INVENTORY PART  
REPLACED MOTHERBOARD (PCB)  
CAL W/ QC & OPS CHECKS

Service Technician: AS / RL

Date: 03-25-09