

# Return & Repair Form

## Customer Information:

Company Name: Maple Shade TWP B: \_\_\_\_\_ S: \_\_\_\_\_  
 Date Received: 5-7-08 Date Given to Service: \_\_\_\_\_  
 Carrier: FedEx - UPS - DHL - USPS Method: GRD - NDA - 2DY (3DY) - Other

## Product Information:

Product: 7410 (7110) - 6510 - 6810 Serial #: AR WF - 0404  
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR -  
 Whole Instrument Top 1/2 Sim Ser #: \_\_\_\_\_  
 Other \_\_\_\_\_ Probe Ser # DD P -

## ACCESSORIES:

110 V A/C Adapter  Regulator  Mag Card Rdr# \_\_\_\_\_  
 Printer Paper  Printer Ribbon  Casio # \_\_\_\_\_  
 Mouthpieces  Carrying Case  Dry Gas  
 Other (Please Specify) \_\_\_\_\_ Warranty Exp. Date \_\_\_\_\_

## Repair Information:

Test #

Reason for Return: IR SPIKE ON RESULTS

Part Number	Description	Qty	Total Cost
<u>MPMISC</u>	<u>IR DETECT PCB (PN 6809458 NO STOCK)</u>	<u>1</u>	<u>N/C W/ARR</u>
<u>6808455</u>	<u>FC</u>	<u>1</u>	<u>N/C W/ARR</u>
<u>MPCAL 71</u>	<u>CAL</u>	<u>1</u>	<u>N/C W/ARR</u>
<u>MP LABOR</u>	<u>LABOR</u>	<u>1.5 HR</u>	<u>N/C W/ARR</u>

## Repair Notes:

REPLACE FC: IR DETECT PCB - CAL W/ QC: OPS CHECKS

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Service Technician: [Signature]

Date: 05-08-08