

Return & Repair Form:

Customer Information:

Company Name: Absecon B. 102015 S: _____
 Date Received: 6-7-10 Date Given to Service: _____
 Carrier: FedEx - UPS - DHL - USPS Method: GRD - NDA - 2DY - 3DY - Other

Product Information:

Product: 7410-7110-6510-6810-7510 Serial #: ARXA-0045
 9510- Drug Tester 5000
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR -
 Whole Instrument Top 1/2 Sim Ser #: _____
 Other _____ Probe Ser # DD P -

ACCESSORIES:

110 V A/C Adapter Regulator Mag Card Rdr# _____
 Printer Paper Printer Ribbon Casio # _____
 Mouthpieces Carrying Case Dry Gas
 Other (Please Specify) _____ Warranty Exp. Date _____

Repair Information:

Test #

Reason for Return: PCB/FC

Part Number	Description	Qty	Total Cost
<u>8315875</u>	<u>PCB</u>	<u>1</u>	<u>N/C W</u>
<u>6808455</u>	<u>FC</u>	<u>1</u>	<u>N/C W</u>
<u>6808486</u>	<u>Plate</u>	<u>1</u>	<u>N/C W</u>
<u>MP Cal 71</u>	<u>Cal</u>	<u>1</u>	<u>N/C W</u>
<u>MP Labor</u>	<u>Labor</u>	<u>5</u>	<u>N/C W</u>

Repair Notes:

Charge button would not bring unit out of sleep mode, installed New PCB.
Inspected FC, it had began to leak, new FC # ARBD-2535.
Cal w/DC & ops check

Service Technician: jc

Date: 06/10/2010