

RETURN AND REPAIR FORM



Customer Information

B:

S:

Company Name: West Wildwood Pp., West Wildwood, NJ

Date Received: 09/12/11 Date given to service: _____

Carrier: FedEx UPS USPS Shipping Method: GRD 3DAY 2DAY
 NDA-PRI NDA-STD

Product: 6510 6810
 7110 8610
 7510 DT5000
 7410 Upper-half 9510
 7410 Whole

Serial Number: AR XA-0068
 Printer Serial#: AR
 Sim Serial#: DD
 Probe Serial#: DD

Warranty Expires: _____

Description: A B Plus Demo Screener Trade In

Accessories

110V A/C Adapter Regulator Printer Ribbon Printer Paper
 Mouthpieces 9510 Stylus 9510 Top Cover Carrying Case
 Dry Gas Other (please specify) _____

Repair Information:

Test#:

Part Number	Description	Qty	Total Cost
<u>12111</u>	<u>Thermal Fuse</u>	<u>1</u>	<u>w/c w</u>
<u>6808455</u>	<u>Fuse cell</u>	<u>1</u>	<u>w/c w</u>
<u>mp cal 71</u>	<u>Calibration</u>	<u>1</u>	<u>w/c w</u>
<u>mp Labor</u>	<u>Labor</u>	<u>.5</u>	<u>w/c w</u>

Repair Notes: Since the would not warm up replace thermal Fuse.

Fuel Cell AR2K-0669 showing signs of leaking, replaced with Fuel Cell AR4H-0424

Per-Superv. say, I ran a .1% wet test 9/16/11 and 9/19/11. Cal w/DC, ops check

Service Technician: [Signature]

Date: 9/16/2011