

# RETURN AND REPAIR FORM



## Customer Information

B:

S:

Company Name: Tinton Falls Boro. P.D., Tinton Falls, NJ

Date Received: 07/01/15

Date given to service: 07/01/15

Carrier:  FedEx  UPS  USPS Shipping Method:  GRD  3DAY  2DAY  
 NDA-PRI  NDA-STD

Product:  6510  6810  
 7110  8610  
 7510  DT5000  
 7410 Upper-half  9510  
 7410 Whole

Serial Number: AR XB-0072

Printer Serial#: AR

Sim Serial#: DD

Probe Serial#: DD

Warranty Expires: November 2016 (63703)

Description:  A  B  Plus  Demo  Screener  Trade In

## Accessories

110V A/C Adapter  Regulator  Printer Ribbon  Printer Paper  
 Mouthpieces  9510 Stylus  9510 Top Cover  Carrying Case  
 Dry Gas  Other (please specify) \_\_\_\_\_

## Repair Information:

Test#:

Part Number	Description	Qty	Total Cost
4414161	Calibration	1	NC/W
4414166	Labor	5	NC/W
6808455	Fuel Cell	1	NC/W
6808486	Spacer Plates	2	NC/W
8315075	Alcotest 7110 Motherboard	1	NC/W
6809458	IR Detector	1	NC/W

Repair Notes: Replaced defective motherboard, IR detector, fuel cell, and spacer plates.

Motherboard was changed due to unit showing wrong solutions during Linearity Tests.

IR Detector was changed due to IR being unstable.

Fuel Cell = ARHE-1523

CAL W/QC AND OPS CHECK

Service Technician: BC

Date: 08/05/15