

# RETURN AND REPAIR FORM



## Customer Information

B:

S:

Company Name: Westwood P.D., Westwood N.J.

Date Received: 12/22/11 Date given to service: 12/22/11

Carrier:  FedEx  UPS  USPS Shipping Method:  GRD  3DAY  2DAY  
 NDA-PRI  NDA-STD

Product:  6510  6810  
 7110  8610  
 7510  DT5000  
 7410 Upper-half  9510  
 7410 Whole

Serial Number: AR 2L-0133

Printer Serial#: AR

Sim Serial#: DD

Probe Serial#: DD

Warranty Expires: \_\_\_\_\_

Description:  A  B  Plus  Demo  Screener  Trade In

## Accessories

110V A/C Adapter  Regulator  Printer Ribbon  Printer Paper  
 Mouthpieces  9510 Stylus  9510 Top Cover  Carrying Case  
 Dry Gas  Other (please specify) \_\_\_\_\_

## Repair Information:

Test#:

Part Number	Description	Qty	Total Cost
8314566	Cable (key board)	1	w/c w
8100902	Flow Sensor	1	w/c w
6808455	Fuel Cell	1	w/c w
6808486	Plate	1	w/c w
mp cal 71	Calibration	1	w/c w
mp labor	labor	.5	w/c w

Repair Notes: Replaced key board cable, because I could not access the functions on the 710, replace the fuel cell, because of leakage. Unit displayed a error (41) so I installed a new Flow sensor.  
cal w/DC; ops check

Service Technician: [Signature] Date: 12-29-11