

New Jersey Department of Transportation

1035 Parkway Avenue, PO Box 600, Trenton, New Jersey 08625-0600



Baseline Document Change Announcement

CD-607-2
Resurfacing of Existing HMA Driveway

BDC02D-06

January 06, 2003

Subject: Revision to the 2001 Standard Roadway Construction Details in English and Metric units, CD-607-2 (Driveways)

Roadway Construction Details CD-607-2.1, CD-607-2.2 & CD-607-2.3 have been revised to require 1 ½" (40 mm) thick HMA layer in lieu of a thin-feathered HMA layer to ensure a better bonding and eliminate raveling problems.

The revisions to CD-607-2 are as follows:

CD-607.2.1 and CD-607-2.2 are revised to require 1 ½" (40 mm) thickness for HMA layer. CD-607-2.3- Note No. 2 is revised to include use of any surface course mix as an alternate material.

Instructions for Designers

All projects scheduled for final design submission after January 21, 2003 shall include the revised Construction Detail sheet CD-607-2 (if resurfacing of HMA driveway is required on the project).

Distribution and Announcement Access Information

This announcement is being distributed electronically to our in-house staff and various public agencies based on our Construction Details BDC distribution list maintained by the Engineering Documents Unit.

Internet access to this BDC Announcement can be downloaded and viewed from the following New Jersey Department of Transportation Web Page:

<http://www.state.nj.us/transportation/cpm/BaselineDocuments/>.

Hard copies of this document can be acquired on a limited basis by contacting:

Engineering Documents Unit
E&O Building, 1st Floor
1035 Parkway Avenue, PO Box 600
Trenton, New Jersey 08625-0600
Phone: (609) 530-5587
Fax: (609) 530-6626

Recommended By:

ORIGINAL SIGNED

Brian Strizki
Director,
Quality Management Services

BJS:KS: FA
☐ BDC02D-06.doc

Attachment: Revised CD-607-2 in Metric units
Revised CD-607-2 in English units

Approved By:

ORIGINAL SIGNED

Art Silber
Assistant Commissioner,
Capital Program Management