SECTION III-A SEVEN-YEAR CAPITAL IMPROVEMENT PLAN FISCAL 2011 – 2017

Department of Agriculture
Department of Children and Families
Department of Corrections
Department of Education

Fiscal Year 2011

7 Year Agency Summary of Capital Requests and Recommendations

General Fund

* Amounts Expressed in Thousands (000's)

DEPARTMENT	Total 7 Yr Program	Request FY 2011	Request FY 2012	Request FY 2013	Request FY 2014 - 2017	FY 2011 Commission Recommendation
Department of Agriculture	\$5,022	\$5,022	\$0	\$0	\$0	\$0
Department of Children and Families	\$2,535	\$895	\$300	\$330	\$1,010	\$0
Department of Corrections	\$1,146,786	\$301,555	\$145,697	\$501,278	\$198,256	\$5,312
Department of Education	\$11,873	\$1,350	\$2,026	\$4,322	\$4,175	\$400
Department of Environmental Protection	\$1,498,021	\$386,965	\$418,109	\$393,422	\$299,525	\$93,371
Department of Human Services	\$300,061	\$160,862	\$48,265	\$29,778	\$61,156	\$4,000
Department of Law and Public Safety	\$11,059	\$11,059	\$0	\$0	\$0	\$0
Juvenile Justice Commission	\$73,805	\$18,404	\$17,064	\$21,787	\$16,550	\$1,000
Department of Military and Veterans Affairs	\$27,911	\$8,048	\$4,660	\$5,728	\$9,475	\$0
Department of State	\$197	\$197	\$0	\$0	\$0	\$0
Rutgers, The State University	\$1,341,728	\$243,379	\$236,109	\$278,749	\$583,491	\$0
University of Medicine and Dentistry	\$1,867,803	\$659,770	\$363,340	\$237,288	\$607,405	\$0
New Jersey Institute of Technology	\$544,264	\$117,368	\$134,014	\$178,246	\$114,636	\$0
Rowan University	\$252,714	\$35,264	\$58,918	\$71,406	\$87,126	\$0
New Jersey City University	\$130,705	\$9,062	\$17,220	\$11,918	\$92,505	\$0
Kean University	\$694,444	\$353,823	\$264,907	\$57,619	\$18,095	\$0
William Paterson University	\$387,493	\$59,003	\$85,277	\$72,290	\$170,923	\$0
Montclair State University	\$282,725	\$66,725	\$64,500	\$64,475	\$87,025	\$0
The College of New Jersey	\$260,787	\$77,901	\$53,838	\$24,979	\$104,069	\$0
Ramapo College of New Jersey	\$2,030	\$1,230	\$800	\$0	\$0	\$0
Richard Stockton College of New Jersey	\$427,937	\$11,699	\$20,521	\$129,081	\$266,636	\$0
Thomas Edison State College	\$1,254	\$1,254	\$0	\$0	\$0	\$0
Department of Transportation	\$6,265,000	\$895,000	\$895,000	\$895,000	\$3,580,000	\$895,000
Interdepartmental Accounts	\$794,275	\$145,425	\$108,900	\$107,750	\$432,200	\$115,500
The Judiciary	\$3,893	\$3,893	\$0	\$0	\$0	\$0
GRAND TOTALS:	\$16,334,322	\$3,575,153	\$2,939,465	\$3,085,446	\$6,734,258	\$1,114,583

The amounts above for Interdepartmental Accounts do not include recommended funding of \$77,429 for New Jersey Building Authority.

DEPARTMENT OF AGRICULTURE

AGRICULTURE

Overview

The mission of the Department of Agriculture is to promote and provide high quality, nutritious, abundant, safe and affordable food, and other agricultural products. The Department promotes the economic viability of the agriculture industry, fosters opportunities for farm profitability, preserves and protects agricultural and natural resources, and provides leadership and specific services to New Jersey agricultural community and consumers.

The Department's major responsibilities include:

- Preservation of farmland:
- Protection and conservation of natural and agricultural resources;
- Protection for farmers and consumers by ensuring safe, high quality agricultural products and services;
- Support for and expansion of profitable and innovative agricultural development;
- Provision of fresh and nutritious food for children, the needy and other New Jersey citizens;
- Promotion of agricultural education, awareness and involvement; and
- Delivery of quality services by a well-trained and motivated workforce to the agricultural community and the food industry.

Farmland Preservation

Farmland covers over 820,000 acres or about 20% of New Jersey's land area. Virtually all of the farms are family-owned with an average size of 82 acres.

Retaining productive, taxpaying farmland is important to all New Jersey residents, and agriculture is an essential component in preserving open space. Open space is preserved through the Farmland Preservation Program, which purchases farmlands and development easements. Funding is provided through the Garden State Preservation Trust Fund. Since its inception in 1983, the Farmland Preservation Program preserved over 1,222 farms, totaling approximately 133,000 acres.

Conservation of Natural and Agricultural Resources

To improve the quality of New Jersey's waterways and ground water, the Conservation Cost Share Program provides financial and technical assistance to farmers who implement conservation practices that control non-point source pollution. This funding, combined with the federal Environmental Quality Incentive Program, maximizes assistance to farmers and promotes a cleaner environment.

Food Distribution

The Department coordinates several programs that annually provide over 41 million pounds of food from United States Department of Agriculture to schools, State, county, and municipal institutions and to charitable and welfare organizations. These tasks are performed through the Child Nutrition and the Commodity Distribution program.

Developing New Economic Opportunities

The Department is a major advocate for developing and strengthening New Jersey's agricultural industry. The major sectors of the State's agricultural industry include produce, horticulture, aquaculture, dairy, field crops, livestock, horse breeding, poultry, wine, and organic produce. The Department supports organic production to increase the diversity and value of field crops, helps to identify and promote

community farm markets, and assists growers in identifying and sponsoring local and regional fresh market processors.

The Department also encourages new agricultural markets. For example, by supporting the construction of an ethanol plant in South Jersey there will be an increased need for locally grown grain. To expand existing markets, such as the demand for milk, the Department encourages the marketing of flavored milk thereby promoting the nutritional benefits of drinking more milk at a younger age. In addition, by establishing Jersey Fresh brands and Jersey Fresh Organic labels, the Department promotes a common trademark for New Jersey's agricultural products.

Department of Agriculture FY 2011 Capital Budget Request By Project Category and Project Type: All Fund Sources

* Amounts Expressed in Thousands (000's) Number of --Department Request----FY2011 FY 2011 Total **Projects** FY 2012 FY 2013 FY 2014 - 2017 Acquisition D02 Acquisition-Equipment 2 \$1,411 \$0 \$0 \$0 \$1,411 Sub Totals: 2 \$1,411 \$0 \$0 \$0 \$1,411 Construction E02 Construction-New \$51 \$51 1 \$0 \$0 \$0 E03 Construction-Renovations and Rehabilitation \$60 \$0 \$0 \$0 \$60 Sub Totals: 2 \$0 \$0 \$0 \$111 \$111 Infrastructure F01 Infrastructure-Energy Improvements \$3,500 \$0 \$0 \$3,500 1 \$0 Sub Totals: 1 \$0 \$0 \$3,500 \$3,500 \$0

5

\$5,022

\$0

\$0

\$0

\$5,022

Grand Totals:

By Department Priortiy 10/7/2009

Department of Agriculture

Agency Capital Budget Request

(000's)

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED	REQUESTED	REQUESTED
FY - 2011	FY- 2012	FY - 2013	FY 2014 - 2017

DIVISION OF PLANT INDUSTRY

LABORATORY RENOVATIONS

Dept Priority 1

LOCATION: WEST TRENTON

Project ID: 10-036

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$3,500
 \$3,500
 \$0
 \$0
 \$0

 Sub-Total:
 \$3,500
 \$3,500
 \$0
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The Phillip Alampi Beneficial Insect Rearing Laboratory (PABIL) is a 21,000 square-foot special use facility constructed in 1985. The Insect Rearing Laboratory is more than 25 years old and needs major renovations and upgrades to continue to provide a controlled environment to mass-produce a variety of beneficial insect species for control of many different species of pest insects and weeds. HVAC control problems and inefficiencies have severely hampered insect rearing capabilities. Uncontrolled humidity in some rooms has resulted in numerous indoor "rain" events causing slippery floors, mold and hazardous work conditions. An Environmental Control Study conducted by the Miller-Remick Corporation (June 20, 2007) at the request of the Department of Treasury recommended demolition and removal of the penthouse heat exchangers, main supply and return fans, all heating and cooling coils and humidifier units; installation of new HVAC equipment, ductwork, and piping; installation of building automation system; and revision of the electrical power system to comply with current codes. The physical shell of the building is sound. These upgrades are expected to add 25 years or more to the useful life of the facility.

Designed for biological pest control, the facility allows state entomologists to develop insect rearing techniques and mass produce beneficial insects to be used to help reduce insect and weed populations. Over the years the New Jersey Department of Agriculture has introduced hundreds of beneficial insects into forests and crops of New Jersey. Many of the beneficial insects have established and are controlling pest populations, year after year, in thousands of acres. Beneficial insects help control damaging weeds and insects, and also reduce the amount of pesticides used by farmers and gardeners.

In 2007 alone, the Mexican bean beetle program eliminated more than \$1.2 million in pesticide costs in New Jersey, and also eliminated the need to apply nearly 60,800 pounds of pesticide impacting our environment. Before the introduction of the parasites to control Alfalfa Weevil, most of the 25,000 acres of alfalfa produced in New Jersey each year required chemical treatment to control this pest. Since the productions and release of the beneficial insects, chemical spraying for this pest has been reduced by more than 95%.

HVAC control problems and inefficiencies have and are severely hampering insect rearing capabilities.

Section III-A, Page 9 REQ-04: Page 1 of 6

Department of Agriculture

Agency Capital Budget Request

(000's)

7 YR PROG FY - 2011 FY - 2012 FY - 2013 FY 2014 - 2017	TOTAL COST 7 YR PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
--	-------------------------	------------------------	-----------------------	------------------------	---------------------------------

DIVISION OF ANIMAL HEALTH

AVIAN INFLUENZA MOBILE LAB - DOCKING STATION

LOCATION: WEST TRENTON

Dept Priority 2

Project ID: 10-040

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$51
 \$51
 \$0
 \$0

 Sub-Total:
 \$51
 \$51
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

MOBILE LABORATORY: request for \$50,887 to fund docking station adjacent to the new laboratory

The mobile laboratory was delivered in May 2009 and is temporarily housed at the USDA, APHIS, VS offices in Robbinsville, NJ. This capital request will provide for the costs of incorporating the unit into the new laboratory under construction in West Trenton to maximize its use. This flexibility would provide for use in " surge" conditions or on a daily basis if desired - but in both cases it is still mobile trailer vehicle, ready to be moved at a moment"s notice in response to any mission that requires response.

This unit is a "tagged" vehicle, licensed and registered with the State of New Jersey and is not considered a modular unit. The laboratory was purchased with funds from the Department of Homeland Security, through the NJ Office of Homeland Security and Preparedness for \$160,000. The lab will serve as an intermediate facility for response to animal diseases, including avian influenza, and will be deployed throughout the state as necessary. When not deployed, it will be utilized for additional lab work so that the mobile lab is maintained and utilized. The new laboratory project includes a concrete pad for the mobile laboratory, which had not been poured as of June 1, 2009, but the cost for the pad and electrical, water and plumbing hookups will be encumbered by the Department. Estimates to complete this project are \$50.887.

The projected cost to incorporate it in the new laboratory including engineering fees, design costs, any permits, utility hook-ups, etc.:

- Providing power hook-up: a 50 amp 50" length cable with a 50 amp connection box next to the building. The cable could be placed in conduit.
- ii. The water is a hose bib connection that would have to be insulated for the winter.
- iii. If the sewer connection is a problem, we could have an additional effluent bladder that would be pumped out on a periodic basis from a "Port-o-john" company.
- iv. In regards to tie-downs. For a temporary movable structure this might not be needed, however if it were needed the trailer would have tie-down loops.
- No IBC Certificate will be required for the trailer. This
 means that it does not need to be constructed to the
 building codes.

Section III-A, Page 10 REQ-04: Page 2 of 6

Department of Agriculture

Agency Capital Budget Request

(000's)

DIVISION OF MARKETING SERVICES

REPLACEMENT OF ROOF ON ADMINISTRATION BUILDING

LOCATION: IMLAYSTOWN, NJ

Dept Priority 3

Project ID: 10-034

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

General:	\$60	\$60	\$0	\$0	\$0
Sub-Total:	\$60	\$60	\$0	\$0	\$0

Operating Impact: Increase: \$0 Decrease: \$0

The Horse Park of New Jersey is a unique combination of state government and private not-for-profit organizations working together to maintain a world class facility for equine and agricultural events.

The Park was opened in 1987 when the property owner, DEP, leased the facility to the NJDA who in turn gave the responsibility of operation and maintenance to the Horse Park of New Jersey at Stone Tavern, Inc. This group, who serve without compensation, has continued to build a facility that has hosted national and international events as well as Olympic qualifiers.

The Administration Facility was the first building on site to be constructed in 1990. The roof has been a problem since the construction was completed. Numerous leaks have been repaired eight times in the past years.

A Water Infiltration Study was conducted by the architectural firm of Ronald A. Sebring Associates, LLC in July, 2007 with a report prepared in August 2007. The major findings of this report are as follows:

- The existing roof system is in premature failure. The roof needs to be replaced.
- All of the trim, fascia, spandrels and soffits should be replaced.
- The low slope roofs are in poor condition and need to be replaced.
- The awning windows are leaking around the gaskets and need to be replaced.
- The security shutters which serve no useful purpose need to be removed and the adjacent walls modified to allow for a weather tight configuration.
- All insulation should be removed from the rafters beneath the roof deck in the attic space.
- · All joint seals need to be replaced.

Recommendations are as follows:

- o Replace the existing metal roof with a fiberglass-asphalt shingle system. This system has an expected life of over 30 years.
- o Replace all the steel trim, fascia, spandrels and soffits with either wood, cellular PVC lumber or aluminum. This will also increase the expected life of the components beyond that of the steel.
- o Replace the entire low sloop roof including base and counter flashing.
- o Install new gutters and leaders.
- Re-install existing lightning rod system

Other related items would be to remove and replace a section of water damaged ceiling, replace a damaged door, minor stucco and coating repairs and legally dispose of all construction debris.

To allow these items to remain unaltered will only allow for further deterioration of the structure. This could lead to structural damage, interior finishes being compromised and indoor air quality issues which would greatly increase the future costs to refurbish this building.

Please note that this site represents our department's emergency operations center in the event our building must be shut down due to a manmade or natural disaster, and the department finds is necessary to relocate our operations.

Section III-A, Page 11 REQ-04: Page 3 of 6

Department of Agriculture

Agency Capital Budget Request

(000's)

7 YR PROG F\	Y - 2011	FY- 2012	FY - 2013	FY 2014 - 2017

DIVISION OF ANIMAL HEALTH

TISSUE DIGESTER / NECROPSY ANIMAL DIAGNOSTIC LABO

LOCATION: WEST TRENTON

Dept Priority 4
Project ID: 10-039

Project Type Code: D02 Project Type Description: Acquisition-Equipment

 General:
 \$1,350
 \$0
 \$0

Sub-Total: \$1,350 \$1,350 \$0 \$0 \$0

Section III-A, Page 12 REQ-04: Page 4 of 6

Department of Agriculture

Agency Capital Budget Request

(000's)

7 YR PROG FY - 2011 FY - 2012 FY - 2013 FY 2014 - 2017	TOTAL COST 7 YR PROG	REQUESTED FY - 2011		REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
--	-------------------------	------------------------	--	------------------------	---------------------------------

Operating Impact: Increase: \$20 Decrease: \$0

The animal disease diagnostic laboratories together with practicing veterinarians are the front-line defense that protects our domestic, wild animal populations as well as human health and economic welfare. The early identification at the animal disease diagnostic laboratory of foreign diseases and emerging and re-emerging diseases enables to mount a rapid response. Early containment and elimination are keys to restoring livestock industries and the critically important export markets.

The foreign animal disease laboratories operated by the United States Department of Agriculture (USDA) in Ames, Iowa and Plum Island, New York are responsible for testing samples for foreign animal disease. However, almost all of the day-to-day animal disease diagnostic work is performed in an animal disease laboratories operated by either state governments or state universities, of which NJ laboratory is an integral part. These laboratories, distributed throughout the country with nearly one in each state, may be the first to see a suspected foreign animal disease or a newly emerging disease. The concept of connection of these front-line laboratories into a network that can enhance our nation's animal disease surveillance system and provide surge capacity in the event of a disease outbreak gave birth to the United States' National Animal Health Laboratory Network (NAHLN). NAHLN was established by USDA's Homeland Security Office as part of a national strategy to coordinate and network the diagnostic testing capacities of the Federal veterinary diagnostic laboratory with the extensive infrastructure (facilities, professional expertise, and support) of State and university veterinary diagnostic laboratories. This network is enhancing the Nation's early detection of, response to, and recovery from animal health emergencies, including bioterrorist events, newly emerging diseases, and foreign animal disease agents that threaten the Nation's food supply and public health.

The establishment of the NAHLN provided for the standardization of testing techniques, improved the infrastructure of network laboratories including the procurement of equipment, enhanced training and increased the sample capacity. NAHLN laboratories are currently participating in USDA surveillance efforts by performing screening assays and forwarding any suspect or positive samples to the appropriate section of the NVSL (the national reference laboratory), for confirmatory testing.

Since the inception of NAHLN, APHIS established contracts with several State and university diagnostic laboratories to assist with testing and surveillance. These contracts incorporate 55 State/university laboratories of which are part, the Department of the Interior laboratory (DOI) in Madison, Wisconsin, the Food Safety and Inspection Services laboratory in Athens, Georgia, and the National Veterinary Services Laboratories (NVSL- Ames, IA and Plum Island, NY campuses) for a total of 59 labs in 46 States. The NAHLN member laboratories are trained and proficiency tested by USDA, APHIS, VS, NVSL on an annual or semi-annual basis. These laboratories are tested on standardized screening methods for the currently targeted diseases in the NAHLN [avian influenza (AI), exotic Newcastle disease (END), foot and mouth disease (FMD), classical swine fever (CSF), bovine spongiform encephalopathy (BSE), chronic wasting disease (CWD), and scrapie]. NJ laboratory is a member laboratory that currently participates in the AI, END and CSF surveillance efforts. NJ has a critical role with the AI surveillance given that the possibility of a pathogenic AI is greater in the live bird markets as different species that may harbor the virus co-mingle.

Collaboration of the animal health diagnostic networks and connection improve the ability to safeguard our important animal industries. Enhancement of real-time disease surveillance shortens the time to respond. Enhanced and interconnected laboratory networks also provide surge capacity during outbreaks of disease that overwhelm our individual resources.

Given the international relevance of this network for the nation and for international trade USDA/APHIS/VS/NVSL adopted the American Association of Veterinary Laboratory Diagnosticians Quality System. USDA is now also requiring for laboratories that are part of the NAHLN network to undergo approval.

NAHLN review and approval processes for the continuation of its members laboratories in its network is based on AAVLD processes that include:

- AAVLD accreditation
- Equivalency to OIE Standard
- ISO 17025 based Quality System

The work carried out by the Animal Diagnostic Laboratory is essential to the economic welfare of the state and the health of its domestic, wild animal and human populations. In order to continue to be a part of NAHLN and an accredited laboratory NJDA/DAH/Animal Diagnostic Laboratory needs to incorporate a full service necropsy suite that is in compliance with the set QA standards. For the handling of large animal carcasses in a safe and cost effective manner a tissue digester is necessary. We propose to ask for the funding to obtain a tissue digester with the capacity to handle carcasses up to 1,000lb and the structure to house it, (concrete pad, rails, roof and connections to water, sewer and electrical).

Section III-A, Page 13 REQ-04: Page 5 of 6

Department of Agriculture

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

DIVISION OF PLANT INDUSTRY

GREENHOUSE

LOCATION: WEST TRENTON

Dept Priority 5

Project ID: 10-038

Project Type Code: D02 Project Type Description: Acquisition-Equipment

 General:
 \$61
 \$61
 \$0
 \$0
 \$0

 Sub-Total:
 \$61
 \$61
 \$0
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The Plant Industry greenhouse is a resource that is used for a number of projects that support the nursery, pest survey, and seed certification programs. Plants are inoculated with plant pathogens for disease identification and serve as checks for bioassays of plant viruses. In addition, the greenhouse functions as a laboratory for the isolation and identification of soil-borne fungi nematodes, as well as propagation of plant material for the Philip Alampi Beneficial Insect Laboratory.

Maintenance of the greenhouse, located in Trenton, has been deferred for a number of years and there are serious needs that limit its current usefulness. The temperature controls are obsolete and are malfunctioning. Replacement parts are no longer available to repair these controls. The lighting needs to be upgraded with the installation of high intensity sodium lights. Shading needs to be installed so that the sun does not scald the plants in summer. Due to these reasons above the construction of a new greenhouse was placed on an Add-Alternate list at the PHEL facility and just recently approved. The maintenance of the current greenhouse has been presented in the past and has not received support; however the approval of the new greenhouse will enhance and greatly benefit the programs of the department.

Totals For: Department of Agriculture

General:	\$5,022	\$5,022	\$0	\$0	\$0	
Bond:	\$0	\$0	\$0	\$0	\$0	
Federal:	\$0	\$0	\$0	\$0	\$0	
Other:	\$0	\$0	\$0	\$0	\$0	
Sub-total:	\$5,022	\$5,022	\$0	\$0	\$0	

Section III-A, Page 14 REQ-04: Page 6 of 6

DEPARTMENT OF CHILDREN AND FAMILIES

CHILDREN and FAMILIES

Overview

Committed to turning around New Jersey's child welfare system with an aggressive and focused plan, Governor Corzine prioritized the creation of the State's first Cabinet agency devoted to serving and safeguarding the most vulnerable children and families in the State. In July 2006, Governor Corzine signed legislation, which received overwhelming support in the legislature, to establish the New Jersey Department of Children and Families (DCF). The Department is staffed by over 7,000 employees and provides services to more than 150,000 children every year. Within DCF, staff in the Division of Youth and Family Services' (DYFS) respond to more than 60,000 referrals annually, supervising at any given time approximately 54,000 children, including just over 11,000 children in out-of-home placement. The Department also includes the Division of Child Behavioral Health Services (DCBHS), which supports a statewide children's behavioral health system, including round-the-clock mobile response for families in crisis, care management for children with behavioral health needs and a broad continuum of residential services and in-home community supports for vulnerable children. Through the Division of Prevention and Community Partnerships (DPCP), the Department supports numerous programs focused on primary child abuse prevention for children from birth to three years old, scores of family support centers in schools and community-based organizations, and a growing home visitation program for at-risk families.

DCF has focused initially on achieving results in several fundamental, priority areas: (1) reducing child welfare caseloads; (2) improving our children's behavioral health system by expanding access to in-state treatment options; (3) growing relevant emergency, assessment and family support services; (4) recruiting and licensing foster and adoptive families; (5) improving permanency practice; and (6) enhancing training initiatives for child welfare workers and system partners throughout the State. DCF has used a data-driven approach to manage the reform process and incorporated the best thinking of New Jersey's child welfare stakeholders, child welfare workers and supervisors to identify and chart office-by-office and program-by-program the strengths and weaknesses in the State's child welfare work.

Department of Children and Families FY 2011 Capital Budget Request By Project Category and Project Type: All Fund Sources

		Number of	* Amounts Expressed in Thousands (00				
		FY2011 Projects	FY 2011	FY 2012	FY 2013	FY 2014 - 2017	Total
Preservation							
A01 Preservation-Electrical		1	\$240	\$0	\$0	\$0	\$240
	Sub Totals:	1	\$240	\$0	\$0	\$0	\$240
Environmental C02 Environmental-Asbestos		1	\$360	\$300	\$330	\$1,010	\$2,000
CO2 Environmental-Aspestos			Ψ300	Ψ300	Ψ550	Ψ1,010	Ψ2,000
	Sub Totals:	1	\$360	\$300	\$330	\$1,010	\$2,000
Construction							
E02 Construction-New		2	\$295	\$0	\$0	\$0	\$295
	Sub Totals:	2	\$295	\$0	\$0	\$0	\$295

\$895

\$300

\$330

\$1,010

\$2,535

Grand Totals:

By Department Priortiy 9/28/2009

Department of Children and Families

Agency Capital Budget Request

(000's)

- 2017

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED	REQUESTED	REQUESTED
FY - 2011	FY- 2012	FY - 2013	FY 2014 - 2017

OFFICE OF EDUCATION

ASBESTOS REMOVAL AND SITE RESTORATION

LOCATION: 12 DCF REGIONAL SCHOOLS

Dept Priority 1 Project ID:

16-074

Project Type Code: C02 Project Type Description: Environmental-Asbestos

General: \$2.000 \$360 \$300 \$330 \$1,010 Sub-Total: \$2,000 \$360 \$300 \$330 \$1,010

\$0 Decrease: \$0 Operating Impact: Increase:

Twelve of the sixteen schools have abatement needs to fully comply with our asbestos management planning and reduction in asbestos hazards as required by the Federal Asbestos Hazard Emergency Response Act (AHERA). Schools have been prioritized based upon the condition of the materials and the potential health hazard to students and staff. Ten schools continue to require full abatement.

DIVISION OF YOUTH AND FAMILY SERVICES

INSTALL NEW EMERGENCY GENERATORS

LOCATION: 3 RTC'S

Dept Priority 2 Project ID: 16-147

Project Type Code: Project Type Description: Preservation-Electrical A01

\$240 General: \$240 \$0 \$0 \$0 \$240 \$240 \$0 Sub-Total: \$0 \$0

Operating Impact: Increase: Decrease: \$0

Install new emergency generators including appropriate electrical upgrades to expand the utilization and capacity at all three DYFS residential treatment centers. The existing generators are obsolete and undersized. This request was approved through the Capital Funding process in FY09, however, funds became unavailable due to the states financial budget crisis.

DIVISION OF YOUTH AND FAMILY SERVICES

ROOF REPLACEMENT

LOCATION: VINELAND RTC

Project ID: 16-148

Dept Priority 3

Project Type Code: Project Type Description: Construction-New E02

\$225 \$225 \$0 \$0 \$0 General: \$225 Sub-Total: \$225 \$0 \$0 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Demolition, removal, replacement of existing concrete canopy roof at the Vineland Residential Treatment Center.

REQ-04: Page 1 of 2 Section III-A, Page 18

Department of Children and Families

Agency Capital Budget Request

(000's)

\$0

REQUESTED

FY 2014 - 2017

\$0

TOTAL COST REQUESTED REQUESTED 7 YR PROG FY - 2011 FY- 2012	REQUESTED FY - 2013
---	------------------------

DIVISION OF YOUTH AND FAMILY SERVICES

HVAC REPLACEMENTS

LOCATION: VINELAND RTC

Dept Priority 4

Project ID: 16-149

General:

Project Type Code: E02 Project Type Description: Construction-New

\$70 \ \$70 \ \$0

Sub-Total: \$70 \$70 \$0 \$0 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Removal and replacement of two existings rooftop HVAC units at the Vineland Residential Treatment Center.

Totals For:

Department of Children and Families

General:	\$2,535	\$895	\$300	\$330	\$1,010	
Bond:	\$0	\$0	\$0	\$0	\$0	
Federal:	\$0	\$0	\$0	\$0	\$0	
Other:	\$0	\$0	\$0	\$0	\$0	
Sub-total:	\$2,535	\$895	\$300	\$330	\$1,010	

Section III-A, Page 19 REQ-04: Page 2 of 2

DEPARTMENT OF CORRECTIONS

CORRECTIONS

Overview

The mission of the New Jersey Department of Corrections (NJDOC) is to ensure that all persons committed to State correctional institutions are confined within the level of custody necessary to protect the public and to provide the care, discipline, training, and treatment needed to prepare them for reintegration into the community.

The Department's goals are to control costs, improve productivity and operational efficiencies, expand treatment and rehabilitation services, increase community programs and reintegration services, and improve educational programs. The Department intends to accomplish these goals through several approaches including maximization of technology, expansion of inmate services, outreach programs evaluations, measurements of program effectiveness, enhancement of emergency response capabilities, and expansion of inmate work programs.

Statistical Data

Collectively, county jails, community treatment programs, and State correctional facilities house approximately 27,000 inmates of which approximately 2,000 are incarcerated in county facilities due to lack of bed space in State institutions.

Since 1979, the New Jersey courts have utilized mandatory minimum sentences, which require offenders to serve the entire minimum sentence before becoming eligible for parole. These mandatory minimum sentences cannot be reduced through earned credits, good behavior, minimum security, or work programs. Consequently, as of January 2006, 43 percent of all adult offenders with mandatory minimum terms had mandatory minimums of four years or less, 35 percent were serving five to fourteen-year minimums, and 22 percent had mandatory minimums of fifteen or more years. At present, the median term for all NJDOC inmates is five years.

As of January 2006, 40 percent of the inmates (10,708) were convicted of violent offenses such as homicide, sexual assault, robbery, death-by-auto, and negligent manslaughter. Of the violent offenders, 1,122 are serving life sentences. Drug convictions also account for a substantial number of offenders, constituting 32 percent of the inmate population. Eighty percent of all narcotics law violations are for sale and distribution of drugs.

Facilities

NJDOC operates 14 major institutions. These include eight adult male correctional facilities, one woman's correctional institution, a central reception/intake unit, a sex-offenders facility, and three youth institutions. The department also operates satellite facilities at Ancora, Marlboro Camp, and Jones Farm and provides a stabilization and reintegration unit for inmates in need of special training, education, and supervision.

The major adult correctional facilities include South Woods State, New Jersey State, East Jersey State, Bayside State, Northern State, Riverfront State, Southern State, Mid-State, and the Edna Mahan Correctional Facility for adult females.

The three youth facilities administered by the Department include Garden State, Mountainview, and Albert C. Wagner. These facilities provide for the custody, care, and rehabilitation of men aged 18 to 26 who are serving indeterminate sentences and for those who are less violent and serving determinate sentences.

Other facilities provide specialized functions in the correctional system. The Central Reception and Assignment Facility is responsible for initial custody and classification of offenders entering the prison system; the Adult Diagnostic and Treatment Center offers specialized treatment services for sex offenders; and a Special Treatment Unit, operated jointly by the Department of Corrections and Department of Human Services, provides for custodial supervision of civilly committed sex offenders.

Services

The Department offers an array of institutional services for offenders including work programs in the State Use shops, farms, bakeries, maintenance, and food services. Also provided are academic and vocational education training, recreational activities, library services, and substance abuse treatments. All inmates receive medical care, psychological counseling, and treatments to improve social behavior and skills necessary for positive social interaction. For offenders under community supervision, the Department contracts with private and non-profit organizations to provide a variety of residential treatment programs.

The State Parole Board supervises parolees through the Electronic Monitoring/Home Confinement Program, the Gang Supervision Program, Satellite Based Monitoring of Sex Offenders, and the Re-Entry Substance Abuse Program. The Day Reporting Program provides additional skill development not available through other parole tracks. The Halfway Back Program, initiated in 2002, is designed to reduce recidivism for technical parole violators, by providing a highly supervised residential environment that concentrates on areas of the offenders' highest needs such as addiction or life skills development.

Department of Corrections FY 2011 Capital Budget Request By Project Category and Project Type: All Fund Sources

* Amounts Expressed in Thousands (000's)

	Number of		^ Amc	=	ed in Thousar t Request	
	FY2011 Projects	FY 2011	FY 2012	FY 2013	FY 2014 - 2017	Total
Preservation						
A01 Preservation-Electrical	3	\$1,740	\$16,612	\$22,978	\$5,204	\$46,534
A02 Preservation-HVAC	1	\$4,212	\$210	\$496	\$0	\$4,918
A03 Preservation-Critical Repairs	2	\$10,307	\$2,656	\$0	\$7,653	\$20,616
A04 Preservation-Roofs & Moisture Protection	1	\$38,446	\$10,657	\$13,833	\$26,143	\$89,079
A05 Preservation-Security Enhancements	1	\$961	\$0	\$0	\$0	\$961
A06 Preservation-Other	6	\$19,789	\$15,471	\$15,977	\$9,199	\$60,436
Sub Totals:	14	\$75,455	\$45,606	\$53,284	\$48,199	\$222,544
Compliance						
B01 Compliance-ADA	0	\$0	\$0	\$0	\$1,673	\$1,673
B02 Compliance-Fire Safety Over \$50,000	1	\$38,980	\$17,141	\$20,099	\$20,059	\$96,279
Sub Totals:	1	\$38,980	\$17,141	\$20,099	\$21,732	\$97,952
Environmental						
C01 Environmental-Hazardous Substances	1	\$13,000	\$3,226	\$9,078	\$9,732	\$35,036
C03 Environmental-Wastewater Treatment	2	\$6,715	\$4,624	\$64	\$4,648	\$16,051
Sub Totals:	3	\$19,715	\$7,850	\$9,142	\$14,380	\$51,087
Acquisition						
D02 Acquisition-Equipment	1	\$224	\$0	\$0	\$0	\$224
Sub Totals:	1	\$224	\$0	\$0	\$0	\$224
Construction						
E01 Construction-Demolition	0	\$0	\$0	\$0	\$867	\$867
E02 Construction-New	2	\$80,881	\$18,319	\$357,569	\$59,810	\$516,579
E03 Construction-Renovations and Rehabilitation	11	\$73,664	\$51,493	\$44,403	\$40,894	\$210,454
Sub Totals:	13	\$154,545	\$69,812	\$401,972	\$101,571	\$727,900
Infrastructure						
F01 Infrastructure-Energy Improvements	5	\$11,769	\$5,173	\$15,965	\$11,109	\$44,016
F02 Infrastructure-Roads and Approaches	0	\$0	\$115	\$816	\$1,265	\$2,196
F04 Infrastructure-Other	1	\$867	\$0	\$0	\$0	\$867
Sub Totals:	6	\$12,636	\$5,288	\$16,781	\$12,374	\$47,079
Grand Totals:	38	\$301,555	\$145,697	\$501,278	\$198,256	\$1,146,786

By Department Priortiy 9/30/2009

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	,
7 YR PROG	

REQUESTED	REQUESTED	REQUESTED	REQUESTED
FY - 2011	FY- 2012	FY - 2013	FY 2014 - 2017

NEW JERSEY STATE PRISON

CHILLER SYSTEM REPLACEMENT

Dept Priority 1 LOCATION: POWER HOUSE

Project ID: 26-290

Project Type Code: A02 Project Type Description: Preservation-HVAC

 General:
 \$4,212
 \$0
 \$0
 \$0

 Sub-Total:
 \$4,212
 \$4,212
 \$0
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$300

This project is for the replacement of the existing chiller units (2) at the New Jersey State Prison with higher-efficiency equipment and control systems. The existing units are over 25 years old and, as shown by the recent breakdown, are in such a condition as being beyond repair by the facility maintenance staff. In May 2006, chiller #2 failed. In order to ensure adequate cooling to the facility, portable chillers (2) and ancillary equipment were rented and put into operation. This scenario was repeated in May 2007, May 2008 and May 2009 and will contune each cooling season (May thru November)until the failed units are replaced.

DIVISION OF MANAGEMENT AND GENERAL SUPPORT

FIRE SAFETY CODE COMPLIANCE

LOCATION: STATEWIDE

Dept Priority 2 Project ID: 26-005

Project Type Code: B02 Project Type Description: Compliance-Fire Safety Over \$50,000

 General:
 \$96,279
 \$38,980
 \$17,141
 \$20,099
 \$20,059

 Sub-Total:
 \$96,279
 \$38,980
 \$17,141
 \$20,099
 \$20,059

Operating Impact: Increase: \$0 Decrease: \$0

To provide for the necessary repairs, renovations and installations of required fire safety devices to comply with the New Jersey Uniform Fire Safety Code. Funding is requested in FY 2011 for projects at the Albert Wagner (Detection, Alarm and Suppression), East Jersey (Old School Secondary Egress), ADTC (Enclose Housing Units Secondary Egress) and Southern State (Fireblocking in Trailers) facilities. Should this request not be funded the potential for loss of life and structures, due to fire, will continue at the remaining institutions and the Department will remain non-compliant with the New Jersey Fire Safety Code.

Section III-A, Page 25 REQ-04: Page 1 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

BAYSIDE STATE PRISON

MICROSTEAM TURBINE & DEAERATION TANK REPLACEMENT

LOCATION: POWERHOUSE

Dept Priority 3 Project ID: 26-282

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$1,587
 \$1,587
 \$0
 \$0

 Sub-Total:
 \$1,587
 \$1,587
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$337

This request is for funding to support an electric co-generation/CHP initiative at Bayside State Prison/BSP; as part of the State's new Energy Master Plan/EMP. The project will involve the purchase and installation of a 275KW back Pressure/Microsteam Turbine to be connected to an existing high pressure boiler which is currently under utilized. Also included in this project will be the replacement of the system's deairation tank which is leaking and likely to fail completely resulting in a total system shutdown and a very costly emergency replacement. The electrical power generated by the proposed microsteam turbine represents approximately 15% of the facility's load and will save \$337,260.00 annually yielding a payback in just 4 years. The boiler to which the turbine will be connected is not currently being utilized to its full potential as a high pressure device and as such is an untapped energy resource. The deaeration tank replacement is necessary as total system support and integrity; has been identified in the facilities most recent state pressure vessel inspection as in need of replacement. Likewise the facility was recently advised by the State's insurance carrier that if this device was not dealt with appropriately, the facility's insurance coverage could be negatively affected. The replacement of this leaking tank will also improve energy and operational efficiencies both in raw water and treatment chemical usage.

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

200-CELL MEDIUM SECURITY UNIT

LOCATION:

Dept Priority 4

Project ID: 26-291

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$42,284
 \$0
 \$0
 \$0

 Sub-Total:
 \$42,284
 \$0
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

This project is for the design and construction of a 200-bed medium security unit on the grounds of the Edna Mahan facility. The unit is needed due to the type of inmates presently housed at the facility and the lack of sufficient single cell capacity. The Scope of Work calls for the construction of four 50-cell (single) housing units in one building similar to the housing units constructed at the Northern State Prison, with sufficient program and staff support space, surrounded by the Department's prototype perimeter security system. Due to the configuration into four separate housing units, the building could house several divergent populations such as General Population, Administrative Segregation, Protective Custody, Special Needs inmates and inmates requiring extended care or the provision of specialized medical care as identified by facility staff.

Section III-A, Page 26 REQ-04: Page 2 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

	TOTAL COST 7 YR PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
--	-------------------------	------------------------	-----------------------	------------------------	---------------------------------

SOUTHERN STATE CORRECTIONAL FACILITY

FACILITY REHABILITATION

LOCATION: PRESENT SITE

Dept Priority 5

Project ID: 26-008

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

General:	\$3,000	\$3,000	\$0	\$0	\$0
Sub-Total:	\$3,000	\$3,000	\$0	\$0	\$0

Operating Impact: Increase: \$0 Decrease: \$0

Southern State Correctional Facility which currently houses 2,054 inmates opened in 1983. The entire Southern State complex, with the exception of a few support buildings, is comprised of trailer units. These units, which are constructed of inexpensive non-durable materials, have a normal life expectancy of ten (10) years and these are over 25 years old. Since FY 1997 the DOC's Capital Budget has included requests for the design and construction of a conventionally built facility on this site. These requests have not been funded and in the current economic environment, it is unlikely that the DOC will be appropriated the funds (approximately \$300 million) necessary to reconstruct this facility utilizing traditional Capital Improvement Program delivery method.

The DOC is requesting funding to develop operational and energy efficient program design specifications, as prescribed in EO #11 and the State's recently revised Energy Master Plan (EMP). A variety of delivery methods are being considered. This initiative will enlist the services of current correctional industry technology and design professionals to help the DOC determine the most operationally efficient and fiscally prudent approach.

The development of said program specifications will focus on the production of new improved and Operational and Energy efficient NJDOC standards and Best Practices in areas such as; Perimeter Security, Building and Facility Security designations, Housing types and sizes (i.e. cells and/or dormitories), Staffing, building material component functionality and mechanical systems. These new standards, when coupled with the prescribed energy and operational efficiencies and the savings realized by a DBL, will net a result that provides for the needed improved facility without increasing the existing fiscal obligations of the current facility. Failure to fund this request exposes the DOC and the State to a potentially catastrophic event and associated liabilities. Support of this planning initiative, will allow the DOC to eliminate approximately \$20 million from its Southern State Correctional Facility FY2011 Capital Improvement Program request.

DIVISION OF MANAGEMENT AND GENERAL SUPPORT

TRAILER UNIT REPLACEMENTS

LOCATION: STATEWIDE

Dept Priority 6

Project ID: 26-071

Project Type Code: E02 Project Type Description: Construction-New

General:	\$91,710	\$38,597	\$17,705	\$8,853	\$26,555
Sub-Total:	\$91,710	\$38,597	\$17,705	\$8,853	\$26,555

Operating Impact: Increase: \$0 Decrease: \$625

In response to the prison-overcrowding crisis, the Department initiated a trailer installation program in May 1981. At the present time, the Department occupies 8 units with an operating capacity of 1,029 beds. These units, which are constructed of inexpensive non-durable materials, have exceeded the normal life expectancy of ten years, require an inordinate amount of maintenance and are not energy efficient. This project is for the phased replacement of the following units, with the Department's dormitory prototype inside the secure perimeter of the host facilities: TM 3 (148 beds) and TM 4 (149 beds), Bayside (installed in March 1985); East Cottage (120 beds, Installed in May 1988) and Hillcrest Cottage (120 beds, installed in March 1990) at Edna Mahan; Rahway Camp, East Jersey (132 beds installed in November 1985); and Housing Units G, H and I, Northern (360 beds, installed in January 1990) . Presently,H Unit at Northern is not occupied due to a fires in the unit. Phase 1 of the program, the installation of a 134 bed unit at the Bayside State Prison, was funded in Fiscal Year 2009 but the funding was subsequently pulled by Treasury to cover a statewide deficit. This request is for the refunding of Phase 1(replacement of TM #3-148 beds) and for the funding of Phase 2 (replacement of TM #4-149 beds) of this initiative. Should this request not be funded, the Department will be forced to initiate major capital repairs.

Section III-A, Page 27 REQ-04: Page 3 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

ALBERT C. WAGNER YOUTH CORRECTIONAL FACILITY

REHABILITATION OF WWTP RBC TRAIN #1

LOCATION: WASTEWATER TREATMENT PLANT

Dept Priority 7
Project ID: 26-336

Project Type Code: C03 Project Type Description: Environmental-Wastewater Treatment

 General:
 \$1,600
 \$1,600
 \$0
 \$0

 Sub-Total:
 \$1,600
 \$1,600
 \$0
 \$0

Operating Impact: Increase: \$16 Decrease: \$0

This work is necessary to restore the Wastewater Treatment Plant (WWTP) at A.C Wagner to its full operating capacity of 1.2 million gallons per day. The complete WWTP at this facility is comprised of three (3) Rotating Biological Contactors (RBCs) Trains, various holding tanks, pumps and supporting equipment.

Trains 1 and 2 are presently out of service. As a result Train #3, is functioning above capacity; processing approximately 500,000 to 600,000 gallons of sewage per day, and has recently undergone an emergency repair which averted the need to invoke a sewage hauling contract of approximately \$ 75,000.00 per day. This plant process wastewater for the inmate populations and staff of both A.C. Wagner/1,257 inmates, and Garden State Youth Correctional Facility/1,838 inmates. Also, by an Inter-Governmental Agreement- IGA, this plant processes the sewage of Chesterfield Township, whose current flows are approximately 75,000 gal/day; but has an upper limit of 400,000 gal/day. In recent months the plant has been cited and faces possible fines from the State Department of Environmental Protection-DEP for redundancy and overloading. The Department of Environmental Protection is seeking and Administrative Consent Order- ACO which will require the Department of Corrections to accomplish the upgrade and improvements to this plant by specific dates.

Design specifications and construction permits for the need rehabilitation of RBC Trains 1 and 2 are complete and the DPMC will be bidding the work for Train # 2 within the next month. Funding for the work associated with Train #1 is needed to complete the project. If these funds are not appropriated the DOC will not be able to meet it's contractual obligations of the IGA with Chesterfield Township and faces additional fines and penalties for non-compliance with the DEP-ACO.

DIVISION OF MANAGEMENT AND GENERAL SUPPORT

LOCKING SYSTEM REPLACEMENTS

LOCATION: STATEWIDE

Project ID: 26-183

Dept Priority 8

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$16,153
 \$5,421
 \$6,109
 \$3,977
 \$646

 Sub-Total:
 \$16,153
 \$5,421
 \$6,109
 \$3,977
 \$646

Operating Impact: Increase: \$0 Decrease: \$0

The locking systems at many of our facilities are outdated and parts are no longer available from the original manufacturer or other after market suppliers. Replacement parts can only be obtained through special orders as fabricated to fit. The delays experienced by obtaining these specially fabricated parts often results in the vacating the cells until the parts are received. At times, multiple doors have failed to open in the group (open) mode during a mass movement. When this occurs the mess, shop or yard movement is delayed. Extra officers are dispatched to the unit to facilitate the mass movement which compromises the security of the rest of the facility or requires additional staff so as to assure the safty and security of the facility. Funding for this work is requested over several fiscal years, which will enable the Department to initiate a phased replacement program for locking systems throughout the state. Phase 1 of the program; will include replacement of the locking systems in Wings B, D and E, the Albert C.Wagner facility (AC Wagner) and the Central Reception and Assignment Facility (CRAF).

Section III-A, Page 28 REQ-04: Page 4 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

7 YR PROG FY - 2011 FY - 2012 FY - 2013 FY 2014 - 2017	TOTAL COST 7 YR PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
--	-------------------------	------------------------	-----------------------	------------------------	---------------------------------

DIVISION OF MANAGEMENT AND GENERAL SUPPORT

PERIMETER SECURITY REPLACEMENTS

LOCATION: STATEWIDE

Dept Priority 9

Project ID: 26-070

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$59,408
 \$28,662
 \$12,585
 \$18,161
 \$0

 Sub-Total:
 \$59,408
 \$28,662
 \$12,585
 \$18,161
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The Scope of Work for this project, initiated in 1996, called for the replacement of deteriorated perimeters of ten (10) of the Department's facilities with a prototype secure perimeter. East Jersey, Mountainview and Cottage C and Hillcrest Cottages at Edna Mahan were added later. Funding previously appropriated for the program, totaling \$25.789 million, was from existing capital fund balances (\$0.186 million) supplemented by capital appropriations in FY97 (\$6.5 million), FYs 99 - 02 (\$18.704 million) and \$0.399 million from the 1987 Bond Issue. However, \$11.212 million was lapsed in FY02 to cover the State's Operating Budget deficits. To date, Bayside, CRAF, East Jersey (Perimeter Wall, Phase 1), ADTC (Rahway Camp) and Hillcrest Cottage (Edna Mahan) have been completed. The priority order for completion of the remaining facilities is Mid-State, Garden State, Albert Wagner, Mountainview, East Jersey (Perimeter Wall, Phase 2), Northern, R, Edna Mahan, ADTC (Main Fence) and Southern State. Currently, security perimeter failures result in additional custody overtime in the form of increased roving patrol posts. Failure to fund this request would increase the potential for perimeter security breaches at those facilities whose perimeter security systems were not yet upgraded.

DIVISION OF MANAGEMENT AND GENERAL SUPPORT

ROOF REPAIRS/RENOVATIONS

LOCATION: STATEWIDE

Dept Priority 10 Project ID: 26-006

Project Type Code: A04 Project Type Description: Preservation-Roofs & Moisture Protection

 General:
 \$89,079
 \$38,446
 \$10,657
 \$13,833
 \$26,143

 Sub-Total:
 \$89,079
 \$38,446
 \$10,657
 \$13,833
 \$26,143

Operating Impact: Increase: \$0 Decrease: \$0

Many facility roofs have been leaking for a number of years and are beyond repair. Without funding for roof repairs, facilities will experience continued structural damage and the potential for health and safety hazards to staff and inmates. Funding of the project would result in a cost saving from the reduction of the cost of materials, equipment and man-hours associated with maintaining the roofs and repairing any damage created by the leaks. Partial project funding, from the FY2010 Statewide Appropriation for Roof Replacements has been approved by OMB, for roof replacements for the Administrative Close Supervision Units at the Albert Wagner and East Jersey facilities. However during the design phase the SOW was expanded to include the replacement of the rooftop mounted HVAC systems; due to their age and condition, which resulted in a project funding shortage of \$4 million. This shortage has been added to the first year of this multiple year request. If this request is not funded the project will be terminated and the funds spent on the design will have been wasted.

Section III-A, Page 29 REQ-04: Page 5 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

DIVISION OF MANAGEMENT AND GENERAL SUPPORT

HEALTH & ENVIRONMENTAL HAZARDS CLEAN UP

LOCATION: STATEWIDE

Dept Priority 11

Project ID: 26-069

Project Type Code: C01 Project Type Description: Environmental-Hazardous Substances

 General:
 \$34,168
 \$13,000
 \$3,226
 \$9,078
 \$8,864

 Sub-Total:
 \$34,168
 \$13,000
 \$3,226
 \$9,078
 \$8,864

Operating Impact: Increase: \$0 Decrease: \$0

This project is required to conduct Statewide engineering studies to determine the potential hazard of suspected asbestos contaminated materials as well as health and environmental hazards, such as toxic materials spills, at DOC's facilities throughout the State. Funding is requested for the study and subsequent abatement of these materials. This program is phased over four (4) years. The Fiscal Year 2011 Capital Request is for \$13.0 million to concentrate efforts at Garden State facility. A Design Consultant has been selected for the Garden State project (DPMC C0831). The Design Phase is complete. Awaiting direction on swing space and additional funding to move forward with project.

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

UPGRADE WATER SUPPLY/DISTRIBUTION SYSTEM

LOCATION:

Dept Priority 12

Project ID: 26-292

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$4,785
 \$0
 \$0
 \$0

 Sub-Total:
 \$4,785
 \$4,785
 \$0
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The upgrade of the domestic water supply and distribution system of the Edna Mahan facility. Due to the increase in population over the last 15 years the water supply, treatment and distribution system are running at capacity. Also due to the age and condition of the existing system, ongoing maintenance is a problem. To accommodate an increase in supply and to improve the condition of the existing distribution system, the following work must be completed: 1) The construction of a new well house and treatment building or the upgrade of the existing well house and treatment facilities. 2) The upgrade of the existing water distribution system, including, but not limited to new connections, valves, fire hydrants and relays and the cleaning and lining of all water mains.

RECEPTION & ASSIGNMENT FACILITY

200 RECEPTION BED REPLACEMENT

LOCATION: ENTIRE SITE

Dept Priority 13
Project ID: 26-058

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$29,638
 \$29,638
 \$0
 \$0

 Sub-Total:
 \$29,638
 \$29,638
 \$0
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$3,000

In October 2006 the DOC discovered some deterioration in the floor systems of the bathroom/shower sections of Dormitory wing of CRAF. Preliminary structural reports resulted in the evacuation of the second floor dormitory. Since then several structural assessments have been done in an effort to determine the extent of the structural damage; resulting in the closure of the entire wing. As a result the DOC lost 196 beds in its Reception facility.

The most recent structural analysis indicated that the unit is not structurally sound and must be replaced.

This request is for the replacement funds to reconstruct these lost beds with 200 new, reception program appropriate, bedspaces.

Section III-A, Page 30 REQ-04: Page 6 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED
FY - 2011	FY- 2012

 REQUESTED
 REQUESTED

 FY - 2013
 FY 2014 - 2017

\$0

\$0

\$0

\$0

SOUTH WOODS STATE PRISON

NEW PUBLIC ADDRESS SYSTEM

LOCATION:

Dept Priority 14

Project ID: 26-298

Project Type Code: A01

Project Type Description: Preservation-Electrical

 General:
 \$273
 \$0

 Sub-Total:
 \$273
 \$273
 \$0

Operating Impact: Increase: \$0 Decrease:

The facility public address system for the South Woods facility has been struck by lightening several times in the last year. While attempting to make repairs to the system, facility maintenance staff have been advised by the original manufacturer that replacement parts for the system are no longer manufactured. Any parts that have been obtained have had to be specially fabricated to fit the system. Delays in obtaining parts leave staff in numerous areas of the institution in communication "dead zones", which jeopardizes staff safety. This project is for the phased replacement of the existing public address system with a state of the art system.

\$0

DIVISION OF MANAGEMENT AND GENERAL SUPPORT

RENEWABLE ENERGY INITIATIVES

LOCATION: STATEWIDE

Dept Priority 15

Project ID: 26-337

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$4,339
 \$4,339
 \$0
 \$0
 \$0

 Sub-Total:
 \$4,339
 \$4,339
 \$0
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$163

This request is for funding to support solar energy initiatives at East Jersey State Prison/EJSP, Agri-Industries at Jones Farm and Bayside State Prison/BSP; as part of the State's new Energy Master Plan/EMP.

The projects will replace the current operationally and energy inefficient refrigeration trailers at these facilities with specified efficient/energy star like, solar powered conventional refrigerated units.

Utilizing solar/Photovoltaic panels as the primary renewable energy source for these refrigerated boxes at these sites will reduce operational costs for the Department by \$163,086.00 and will net the DOC a minimum of \$514,800.00 in Solar Renewable Energy Credits/SREC's revenue annually. This action will also reduce the State's annual carbon footprint by 1,028 metric tons of Carbon/CO2 emissions

ALBERT C. WAGNER YOUTH CORRECTIONAL FACILITY

SECURITY CAMERA INSTALLATION

LOCATION:

Dept Priority 16

Project ID: 26-294

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$239
 \$239
 \$0
 \$0

 Sub-Total:
 \$239
 \$239
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Upgrade and expansion of the existing closed circuit TV system to include video taking capability. The video surveillance system in the gym and dining hall is outdated and does not provide clear pictures. Funding is also requested to purchase cameras, which will be installed in the Mess Hall, A-Wing and D-Shop and monitored by Center Control. These additions would enable facility staff to view and record and retrieve video data of inmate activity such as inmate gatherings, assaults on staff, fights, contraband exchange, escape attempts and misuse of equipment. Thereby increasing the safety of both staff and inmates

Section III-A, Page 31 REQ-04: Page 7 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

	TOTAL COST 7 YR PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
--	-------------------------	------------------------	-----------------------	------------------------	---------------------------------

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

CENTER RENOVATIONS (CONSTRUCTION)

LOCATION:

Dept Priority 17

Project ID: 26-172

Project Type Code: A05 Project Type Description: Preservation-Security Enhancements

 General:
 \$961
 \$961
 \$0
 \$0

 Sub-Total:
 \$961
 \$961
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

This request is for the complete renovation of the basement and first floor levels of the Center Control at the Garden State facility. The Garden State facility was built in the early 1960's and the Center Control was not constructed to accommodate the high technology control devices that exist today. With subsequent additions to the mission of the facility and physical plant, the area is a mixture of varying technologies. This includes an abundance of counters, filing cabinets and other controls of various eras. A variety of electrical equipment, emergency phone boards and the fire alarm system reside in the basement. Design of this project was funded from the FY 2000 Capital Appropriation for Security Improvements. This request is for construction funding.

MOUNTAINVIEW YOUTH CORRECTIONAL FACILITY

SECURITY SURVEILLANCE SYSTEM INSTALLATION

LOCATION: FACILITY PERIMETER

Dept Priority 18
Project ID: 26-313

Project Type Code: D02 Project Type Description: Acquisition-Equipment

 General:
 \$224
 \$224
 \$0
 \$0
 \$0

 Sub-Total:
 \$224
 \$224
 \$0
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The design and installation of a security surveillance system around the perimeter of the institution. System capabilities would include but not be limited to auto-tracking and recording. The system would be monitored from the center control area of the facility.

SOUTHERN STATE CORRECTIONAL FACILITY

COMMUNICATION TOWER INSTALLATION

LOCATION:

Dept Priority 19 Project ID: 26-297

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$188
 \$188
 \$0
 \$0

 Sub-Total:
 \$188
 \$188
 \$0
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

This project is for the installation of a 100 ft. radio communications tower, with all ancillary antenna units and a support building for electronic equipment, adjacent to the new Minimum Camp. Two areas of the Southern State complex have radio "dead zones." Also the existing tower no longer functions to the level of security required for the safety of the staff and inmate population. The new tower will provide maximum communication capability for the facility radio systems.

Section III-A, Page 32 REQ-04: Page 8 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

ALBERT C. WAGNER YOUTH CORRECTIONAL FACILITY

CONDENSATE RETURN LINE REPLACEMENT

LOCATION:

Dept Priority 20

Project ID: 26-241

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$3,237
 \$3,237
 \$0
 \$0

 Sub-Total:
 \$3,237
 \$3,237
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The replacement of the condensate return line that runs from the Garden State facility to the Wagner facility powerhouse. The existing condensate return line has numerous leaks. Facility maintenance staff have attempted repairs, however when one is complete new leaks appear. This situation has significantly reduced the amount of condensate being returned to the plant. To operate the boiler plant, facility staff must then use more make-up water and the chemicals used to treat the water. The more make-up water used the less cost efficient the boiler plant operation becomes.

NORTHERN STATE PRISON

STORM DRAINAGE/LEVELING ACSU YARDS

LOCATION: ADMIN. CLOSE SUPERVISION UNIT

Project ID: 26-109

Dept Priority 21

Project Type Code: F04 Project Type Description: Infrastructure-Other

 General:
 \$867
 \$867
 \$0
 \$0

 Sub-Total:
 \$867
 \$867
 \$0
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Initially a study will be performed to determine the cause and extent of the problems with the storm drainage system in and around the ACSU yards. Based on the recommendations made in the study the necessary remedial work will be carried out. It has been identified in various reports, and a staff grievance, that large amounts of water do not drain during heavy rains. Thereby creating large ponds of water in the ACSU yard areas. This has created an unsafe condition for both staff and inmates.

MID-STATE CORRECTIONAL FACILITY

REPLACE GUARD TOWERS

LOCATION: GUARD TOWERS

Dept Priority 22 Project ID: 26-192

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$4,883
 \$4,883
 \$0
 \$0
 \$0

 Sub-Total:
 \$4,883
 \$4,883
 \$0
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The existing guard towers (5) at the Mid-State facility were installed in 1982 and are of modular construction, which have exceeded their useful life span. There are numerous problems with the units. Roof leaks may be allowing water to penetrate the structural steel tube members that support the towers. The sealant/weather-stripping at the ends of the unit's corrugated wall panels has deteriorated. Due to these two factors, rust and/or deterioration were present in varying degrees in the towers. It appears that the towers are not in immediate danger of failure, but due to this deterioration and the aforementioned problems the DOC is requesting funding to replace the guard towers. The replacement towers will be constructed of panelized concrete with metal roofs.

Section III-A, Page 33 REQ-04: Page 9 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	
l l				

ALBERT C. WAGNER YOUTH CORRECTIONAL FACILITY

KITCHEN FLOOR REPLACEMENT

LOCATION: KITCHEN

Dept Priority 23

Project ID: 26-143

Project Type Code: A06 Project Type Description: Preservation-Other

General:	\$4,011	\$4,011	\$0	\$0	\$0
Sub Total	\$4,011	\$4,011	60	0.2	90
Sub-Total:	\$ 4 ,011	Ψ4,011	ΨU	\$ U	\$ U

Operating Impact: Increase: \$0 Decrease: \$0

The kitchen floor at the Albert Wagner Youth Correctional Facility was declared unsafe by structural engineers and replaced in 1994. Since that time, new leaks have been discovered, creating a potential health hazard. This request will fund the replacement of the existing flooring and possibly the substructure in the areas of the leaks. The replacement of the floor will require the relocation of some kitchen equipment.

ADULT DIAGNOSTIC AND TREATMENT CENTER, AVENEL

PARAPET REPAIR/REPLACEMENT, STU ANNEX

LOCATION: STU ANNEX

Dept Priority 24 Project ID: 26-314

Project Type Code: A03 Project Type Description: Preservation-Critical Repairs

General:	\$307	\$307	\$0	\$0	\$0
Sub-Total:	\$307	\$307	\$0	\$0	\$0

Operating Impact: Increase: \$0 Decrease: \$0

The infrastructure and pre-cast concrete parapet walls have become compromised by water leaking into the substructure of the Special Treatment Unit Annex. Water has begun to enter into the mechanical room near the main electric panels, making this a serious safety issue for both staff and residents. The Department has contracted with a Structural Engineer to perform a structural condition survey and provide a report with summary of findings, recommendations and probable construction cost estimates for remediation of the problem.

BAYSIDE STATE PRISON

EXTENDING WASTEWATER TRT PLT OUTFLOW PIPE

LOCATION: WASTEWATER TREATMENT PLANT

Dept Priority 25 Project ID: 26-083

Project Type Code: C03 Project Type Description: Environmental-Wastewater Treatment

General:	\$9,739	\$5,115	\$4,624	\$0	\$0
Sub-Total:	\$9,739	\$5,115	\$4,624	\$0	\$0

Operating Impact: Increase: \$0 Decrease: \$0

This project calls for the extension of the outflow pipe from Riggins Ditch to the Delaware Bay and the dredging of Riggins Ditch. The capacity of the existing wastewater plant is now 550,000 gallons per day (gpd). The dredging and the extension of the outflow pipe may allow for an increased capacity of 1,000,000 gpd. This would enable the department to request that the Department of Environmental Protection modify our operating permit and increase the inmate population at the Medium and Minimum facilities, as well as the Southern State facility.

Section III-A, Page 34 REQ-04: Page 10 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

7 YR PROG F\	Y - 2011	FY- 2012	FY - 2013	FY 2014 - 2017

RECEPTION & ASSIGNMENT FACILITY

STORM DRAINS AND BUILDING ENVELOPE RENOVATIONS

LOCATION: FACILITY WIDE

Dept Priority 26

Project ID: 26-066

Project Type Code: A03 Project Type Description: Preservation-Critical Repairs

 General:
 \$10,000
 \$10,000
 \$0
 \$0

 Sub-Total:
 \$10,000
 \$10,000
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Install storm drains around building perimeter. Excavation of grounds with upgrades and repairs to masonry walls (exterior & amp; interior), windows, doors and walls of basement areas of facility. During the summer of 1996, heavy rains caused severe flooding of the basement area. Central Archives and Classification are located in this area. Water came extremely close to the main electrical switch gear. This could have caused a total loss of electrical power and the loss of inmate records. In April 2005, the department initiated the study/design phase of this project (C0805-00). The consultant's final report, which contains recommend solutions, was received in August 2006. This request is for the funding to carry out the recommendations.

This request also includes upgrades and repairs to walls, floors, ceilings and windows of non basement areas of the facility. These walls, floors and ceilings are deteriorating due to prior leaks and aging. Windows are not energy efficient and are leaking.

MOUNTAINVIEW YOUTH CORRECTIONAL FACILITY

ELECTRICAL SERVICE UPDATE

LOCATION: INMATE COTTAGES

Project ID: 26-067

Dept Priority 27

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$12,787
 \$1,279
 \$11,508
 \$0
 \$0

 Sub-Total:
 \$12,787
 \$1,279
 \$11,508
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Engineer and install a new electrical distribution system for the facility and update the electrical services for all housing units. Due to the poor condition of the electrical distribution system the facility has had several power outages during the last year. Due to the poor condition of the electrical services in the housing units many inmates use batteries. These batteries can be used as weapons by the inmates. The installation of the upgraded electrical service will eliminate the need for batteries and take away the threat of harm to both staff and inmates. This project is planned to be completed in 2 phases. The design for the entire project and the installation of the new facility wide distribution system will be included in the first Fiscal Year. The upgrading of the housing unit electrical services is planned for the second Fiscal Year.

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

REPLACE/REFURBISH FREIGHT ELEVATOR, FOOD SERVICE B

LOCATION: FOOD SERVICE BUILDING

Dept Priority 28
Project ID: 26-259

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$309
 \$309
 \$0
 \$0

 Sub-Total:
 \$309
 \$309
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Over the last 36 months, the costs for upkeep of the food service freight elevator have increased drastically. Based on the layout of the building and the location of the regular and refrigerated storage areas, this unit is in constant use. In addition to the cost of monthly maintenance, there are constant breakdowns and the need to replace and rebuild parts. This project would replace the outmoded lift system, upgrade the electrical components and refurbish or replace the existing cab and door system.

Section III-A, Page 35 REQ-04: Page 11 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

		AL COST R PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 201
--	--	-------------------	------------------------	-----------------------	------------------------	--------------------------------

SOUTHERN STATE CORRECTIONAL FACILITY

VIDEO SURVEILLANCE SYSTEM INSTALLATION

LOCATION:

Dept Priority 29

Project ID: 26-296

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$238
 \$238
 \$0
 \$0

 Sub-Total:
 \$238
 \$238
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

A video surveillance system would provide real time viewing and recording of the general compound areas of the Southern State facility. The system would enable facility staff to view and record and retrieve video data of inmate activity such as inmate gatherings, assaults on staff, fights, contraband exchange, escape attempts and misuse of equipment. Thereby increasing the safety of both staff and inmates. Also, video evidence is mandatory in the event of inmate alleged misconduct. Video documentation of the misconduct would assist in investigations and potentially protect the Department in the event of court proceedings. The Southern State system would include approximately 16 cameras in each Compound comprised of 2 camera types (fixed position and pan, zoom tilt with automatic adjustment) and sufficient recording equipment to support the cameras.

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

EXPAND VIDEO SURVEILLANCE COVERAGE

LOCATION: HOUSING UNITS; VOCATIONAL AREA

Dept Priority 30 Project ID: 26-322

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$250
 \$250
 \$0
 \$0

 Sub-Total:
 \$250
 \$250
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

This project calls for the addition of 32 new cameras to provide surveillance of housing units, vocational areas and other potential trouble spots. New flat screens monitors are to be installed in center. This new equipment must be integrated with the existing system for documentation and recording purposes.

NEW JERSEY STATE PRISON

KITCHEN FLOOR REPLACEMENT

LOCATION: KITCHEN

Dept Priority 31 Project ID: 26-140

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$3,885
 \$3,885
 \$0
 \$0

 Sub-Total:
 \$3,885
 \$3,885
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

A 1999 investigative study by a structural engineer revealed that no waterproofing was incorporated or placed in the existing floor area of the kitchen as required in the original construction documents, floor penetrations were not sufficiently sealed, floor tiles are cracked broken or missing in vital areas, the floor drains are high and the floor is not sloped properly. At that time, the consultant recommended a Phased Development Program, which included floor repair, relocation of kitchen equipment and equipment adjustments. By phasing the construction activities necessary to eliminate the problems it will be possible to maintain kitchen production and serving activities at 80% efficiency. This request is to fund this work.

Section III-A, Page 36 REQ-04: Page 12 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

MID-STATE CORRECTIONAL FACILITY

CENTER CONTROL RENOVATIONS

LOCATION: MAIN BUILDING

Dept Priority 32 Project ID: 26-117

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

\$1,375 \$1,375 \$0 \$0 \$0 General: Sub-Total: \$1,375 \$1,375 \$0 \$0 \$0

\$0 \$0 Operating Impact: Increase: Decrease:

Design and construction of the necessary renovations to modernize the facility's Center Control area. This project's SOW would entail, but not be limited to the following renovations: 1) Upgrade and/or replacement of existing security control system equipment; 2) Installation of security glass with pass-through windows as required; 3) Installation of necessary intercom and/or talk-through; 4) Revision of all communication equipment, as needed, to provide the most efficiency in this very limited space; 5) construction of a bathroom; and 6) the complete removal and replacement of the existing electronic door control system.

SOUTH WOODS STATE PRISON

VIDEO SURVEILLANCE SYSTEM REPLACEMENT

LOCATION:

Dept Priority 33

Project ID: 26-300

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

General: \$391 \$391 \$0 \$0 \$0 Sub-Total: \$391 \$391 \$0 \$0 \$0

\$0 Decrease: \$0 Operating Impact: Increase:

Replace the existing video surveillance system throughout the South Woods facility with a more manageable less labor intensive system utilizing pan-tilt cameras and touch screen video monitoring along with digital date recording capability. The new system would also integrate the visit hall camera system. The original video surveillance system is antiquated. There is no control of the cameras and video archiving is done by video tape. Also, the system constantly requires repair. This compromises the security and safety of both staff and inmates.

SOUTHERN STATE CORRECTIONAL FACILITY

HOUSING COMPOUND SECURITY ENHANCEMENTS

LOCATION:

Dept Priority 34 Project ID: 26-304

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

\$4,175 \$0 General: \$4,175 \$0 \$0 \$0 \$0 \$0 Sub-Total: \$4,175 \$4,175

Operating Impact: \$0 Decrease: \$0 Increase:

The Southern State Correctional Facility is comprised of 11 dormitory units each surrounded by a security fence with a gate to segregate the unit from the main compound and adjacent unit(s). This inner security fence is provided to separate each unit in the case of a life threatening event and/or security breach. Due to the system-wide increase in gang activity and the dormitory environment of the Southern State facility, facility staff believe there is an added potential for internal and external security breaches. The planned upgrades include, but are not limited to the replacement of the existing fence with a 16 ft. high chain link fence topped with several strands of razor wire and the installation of additional security lighting.

> REQ-04: Page 13 of 64 Section III-A, Page 37

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

CENTRAL OFFICE

RENOVATE THOMPSON COTTAGE

LOCATION: THOMPSON COTTAGE

Dept Priority 35 Project ID: 26-266

Project Type Code: A06 Project Type Description: Preservation-Other

\$1,916 \$1,916 \$0 \$0 General: \$0 Sub-Total: \$1,916 \$1,916 \$0 \$0 \$0

\$0 \$0 Operating Impact: Increase: Decrease:

Thompson Cottage is a vacant three- (3) story building located at the Department's Central Office Complex that is presently being used as short-term storage space. Due to the shortage of useable space for the Department's administrative staff, it has been determined that this unit be renovated for use as office space. This project addresses the complete renovation of this building. The Scope of Work includes, but is not limited to, the following items: removal of rotted flooring and installation of new sub-flooring and flooring; replacement of existing walls; new electrical services (main and secondary); a new HVAC system; and new plumbing services (domestic water and sewer).

NEW JERSEY STATE PRISON

HVAC REPAIRS/RENOVATION

LOCATION: NORTH & SOUTH COMPOUNDS

Project ID: 26-034

Dept Priority 36

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

General: \$1,251 \$1.251 \$0 \$0 \$0 Sub-Total: \$1,251 \$1,251 \$0 \$0 \$0

\$0 Decrease: \$0 Operating Impact: Increase:

This project is for the cleaning and sanitizing of the entire HVAC system including ductwork, mixing boxes and coils in order to improve the air quality in the North and South Compounds of the New Jersey State Prison. The North and South Compounds (occupied in 1982) were constructed with a state of the art HVAC system. However, no maintenance contract was provided with this installation and it is beyond the capabilities of the existing facility maintenance staff. Therefore, capital funding is now required to effect the cleaning of this system.

NORTHERN STATE PRISON

HVAC SYSTEM REPAIR. ACSU

LOCATION: ACSU

Dept Priority 37 Project ID: 26-271

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

\$1,355 General: \$1,355 \$0 \$0 \$0 Sub-Total: \$1,355 \$1,355 \$0 \$0 \$0

Operating Impact: Increase: \$0 Decrease: \$0

This project is for the engineering and installation of the work necessary to repair the HVAC system of the Nothern State Prison. Administrative Close Supervision Unit (ACSU). The ACSU is a maximum security facility which houses over 400 inmates. The unit, built in 1991, consists of two (2) three (3) story buildings totalling 42,000 square feet, which are connected to a one story visitor"s center. The problems with the system include, but are not limited to the pneumatic control system, dampers, thermostats and the compressors, heating and cooling coils and motors on the rooftop HVAC units. There are no operating windows in the ACSU facility, therefore it is imperative that the HVAC system function at all times.

> REQ-04: Page 14 of 64 Section III-A, Page 38

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	
TOTAL COST 7 YR PROG	

REQUESTED	REQUESTE
FY - 2011	FY- 2012

KEQU	JESTED	
FY	- 2013	

REQUESTED FY 2014 - 2017

BUREAU OF STATE USE INDUSTRIES

EXPANSION OF INMATE WORK SPACE

LOCATION: STATEWIDE

Dept Priority 38

Project ID: 26-001

Project Type Code: E03

Project Type Description: Construction-Renovations and Rehabilitation

General: \$14,782

\$0 \$13,373 \$1,409 \$0 \$0 \$13,373 \$1,409 \$0

Sub-Total: \$14,782

Operating Impact:

Increase:

\$0

Decrease: \$0

This multi-year funding request would provide additional space to augment existing industrial and program space and to also provide space to establish new manufacturing and service type programs. During the 1990's the increase in the Department's inmate population outpaced the number of available inmate work opportunities. This seriously constrains the Department of Corrections ability to provide practical and productive inmate work activities To alleviate the constraint, the Department recommends the following capital expansion program for inmate work opportunities.

EAST JERSEY STATE PRISON

ELECTRICAL UPGRADE, WING 3

LOCATION: MAIN COMPLEX

Dept Priority 39

Project ID: 26-092

Project Type Code: A01 Project Type Description: Preservation-Electrical

General: \$9

\$940	\$0	\$940	\$0	\$0
\$940	\$0	\$940	\$0	\$0

Sub-Total:

Operating Impact:

Increase: \$0

Decrease: \$0

Engineer and install new electrical distribution system including wiring, fixtures and panels. Double bunking has created problems due to the additional electric that is being used by the inmate population. Overloaded power lines at times cause circuit breakers to trip and put additional stress on the original wiring to the cells. Lighting on the tiers and in the cells is also in poor condition, most of the fixtures are original and need to be replaced with new energy efficient security lights.

SOUTH WOODS STATE PRISON

CHILLED WATER PIPING SYSTEM UPGRADE

LOCATION: MAINTENANCE/SHOP AREAS

Dept Priority 40 Project ID: 26-273

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$308
 \$0
 \$308
 \$0
 \$0

 Sub-Total:
 \$308
 \$0
 \$308
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

This project is for the installation of chilled water piping into the Maintenance Department shop areas. The electrical switch substation in the maintenance shop area becomes very hot and is at a critical limit. If the temperature becomes to high the system will fail. The shop areas are very uncomfortable for staff to perform daily routine work. There are no windows to open and the exhaust system is inadequate to keep the spaces tolerable for staff.

Section III-A, Page 39 REQ-04: Page 15 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	
			-	

NEW JERSEY STATE PRISON

WING 4 RENOVATIONS

LOCATION: WEST COMPOUND

Dept Priority 41

200/11

Project ID: 26-002

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$6,831
 \$0
 \$6,831
 \$0
 \$0

 Sub-Total:
 \$6,831
 \$0
 \$6,831
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Repair of water damaged walls and ceilings, replacement of sinks and commodes in the 83 cells with stainless steel combination units and replacement of the main water and sewer lines. In 1987, a section of the deteriorated ceiling fell and temporary repairs were made. The main sewer and water lines are in poor condition and need replacing. The sinks and showers in the bottom tier housing units drain into a french drain outside the main building. The plumbing work identified is similar to work recently completed in Wings 7 and 1 and requested for Wings 2, 3 and 5. Failure to fund this request will allow an already hazardous life safety condition to worsen.

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

GREEN HOUSE HEATING SYSTEM REPLACEMENT

LOCATION: GREEN HOUSE

Dept Priority 42

Project ID: 26-324

Project Type Code: A02 Project Type Description: Preservation-HVAC

 General:
 \$210
 \$0
 \$210
 \$0
 \$0

 Sub-Total:
 \$210
 \$0
 \$210
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Replacement of the entire heating system in the green house in the vocational area of the Garden State facility. The Scope of Work includes but is not limited to replacing heat exchangers and steam supply piping.

NORTHERN STATE PRISON

REPLACE YARD AND SALLY PORT GATES

LOCATION: HOUSING UNITS

Dept Priority 43

Project ID: 26-186

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$930
 \$0
 \$930
 \$0

 Sub-Total:
 \$930
 \$0
 \$930
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

To engineer and install new gates at the entrances to the Yard areas outside each Housing Unit and in outside sally ports. The work would include, but not be limited to the replacement of gates and gate operators as well as the relocation of the units. The gate operator that was originally installed is no longer manufactured. This makes locating replacement parts very difficult and in some cases facility staff must fabricate these parts. Also, the housing unit gates and operators were installed inside the yards. This not only makes servicing difficult, but also allows the inmates access to the operators and locks.

Section III-A, Page 40 REQ-04: Page 16 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	FY 2014 - 2017

DIVISION OF MANAGEMENT AND GENERAL SUPPORT

EXTERIOR BUILDING RENOVATIONS

LOCATION: VARIOUS BUILDINGS

Dept Priority 44

Project ID: 26-037

Project Type Code: A03 Project Type Description: Preservation-Critical Repairs

 General:
 \$1,641
 \$0
 \$1,641
 \$0
 \$0

 Sub-Total:
 \$1,641
 \$0
 \$1,641
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The buildings in the Central Office Complex are experiencing deterioration. Following the recommendations of the Structural Engineering firm which completed a Building Exterior Survey in March, 1999, this project addresses the exterior surface restoration, repointing, brick and stone sealing and general masonry repairs as well as repairing, painting or covering sofits, fascias and cornices as necessary on the buildings. Significant deterioration has occurred on the Administration, Edge, Stokes and Bates Buildings. Deterioration of a lesser degree can be found on other buildings. If left uncorrected, the deterioration will progress requiring more costly repairs and creating potentially unsafe conditions. The project is being completed in phases. Work has been completed on the Colpitts, Cubberly, Edge, Stokes and Bates Buildings.

RECEPTION & ASSIGNMENT FACILITY

UPGRADE PLUMBING SYSTEMS

LOCATION: FACILITY WIDE

Dept Priority 45

Project ID: 26-060

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$2,834
 \$0
 \$2,834
 \$0
 \$0

 Sub-Total:
 \$2,834
 \$0
 \$2,834
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Upgrade and repairs to hot and cold water distribution system throughout the institution as well as providing new plumbing fixtures, piping, fittings, etc... The distribution systems are very old and severely in need of repairs. Replacement parts for the existing fixtures are difficult to find.

MID-STATE CORRECTIONAL FACILITY

CARPENTER SHOP DUST COLLECTION SYSTEM

LOCATION: MAINTENANCE SHOP

Dept Priority 46 Project ID: 26-325

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$125
 \$0
 \$125
 \$0
 \$0

 Sub-Total:
 \$125
 \$0
 \$125
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The replacement of the existing dust collection system in the Carpentry Shop at the Mid-State facility. The existing system is inoperable and cannot be repaired. This is a health issue for inmates and staff utilizing this area. Saw dust becomes airborne and is inhaled

Section III-A, Page 41 REQ-04: Page 17 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

ADULT DIAGNOSTIC AND TREATMENT CENTER, AVENEL

ROADWAY BRIDGE REPAIR

LOCATION: PERIMETER ROAD

Dept Priority 47

Project ID: 26-316

Project Type Code: F02 Project Type Description: Infrastructure-Roads and Approaches

 General:
 \$115
 \$0
 \$115
 \$0
 \$0

 Sub-Total:
 \$115
 \$0
 \$115
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Repair of bridge that is part of facility"s perimeter roadway. The bridge was damaged by a delivery truck and is slowly deteriorating, which affects the condition of the roadway. If the bridge is lost the facility will have to re-route their perimeter patrol vehicles, thereby affecting facility security.

NORTHERN STATE PRISON

REPAIRS TO TOWER 3

LOCATION: TOWER 3

Dept Priority 48
Project ID: 26-272

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$240
 \$0
 \$240
 \$0
 \$0

 Sub-Total:
 \$240
 \$0
 \$240
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Tower 3 at the Northern facility is a five (5) sided, 48 foot high, freestanding, reinforced concrete structure constructed in 1985. In March 200,1 a structural engineer inspected the facility due to reported masonry distress. The consultant found that although the tower's main concrete structural frame is in overall good condition, the exterior block facade exhibits various degrees of structural distress. There is exterior open cracking and localized areas of spalled block. The consultant recommended the application of sealant over the cracks as a short term solution. The long term repair was to rebuild the facade with vertical control joints and shelf angle flashing. This project is requested to fund the long term solution.

MOUNTAINVIEW YOUTH CORRECTIONAL FACILITY

STEAM LINE/TRAPS REPLACEMENT

LOCATION: MAIN COMPLEX

Dept Priority 49 Project ID: 26-278

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$1,344
 \$0
 \$1,344
 \$0
 \$0

 Sub-Total:
 \$1,344
 \$0
 \$1,344
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Engineer and replace steam lines used for the heating and domestic hot water systems, including approximately 350 steam traps. Studies conducted on the facilities steam distribution and condensate return system have concluded that the older steam lines and traps are in deplorable condition and are operating at about 50% efficiency, which is very costly. Recently, the replacement of sections of the system yielded a significant improvement in efficiency. Replacement of the balance of the system, along with new steam traps (with flash tanks), would greatly increase efficiency and produce a significant cost reduction. As part of the project the facility's steam trap maintenance program would be upgraded with the installation of new equipment.

Section III-A, Page 42 REQ-04: Page 18 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

ADULT DIAGNOSTIC AND TREATMENT CENTER, AVENEL

SECURITY SURVEILLANCE UPDATE

LOCATION: ADMINISTRATION BUILDING

Dept Priority 50

Project ID: 26-269

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$800
 \$0
 \$800
 \$0

 Sub-Total:
 \$800
 \$0
 \$800
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The purpose of this project is to upgrade the central contol and monitoring system throughout the ADTC facility. The Scope of Work for the project shall include the repair and/or replacement of existing security surveillance cameras and monitors throughout the institution. The work shall include the replacement of the Central Control Monitoring Network and the center console at the Officers Station. Many of the existing cameeras and monitors are in need of repair, overhaul and/or replacement. The age of this equipment varies from brand new to over 15 years old.

ALBERT C. WAGNER YOUTH CORRECTIONAL FACILITY

CENTER CONTROL RENOVATIONS

LOCATION: ALBERT WAGNER YOUTH CORR FACIL

Dept Priority 51
Project ID: 26-185

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$1,109
 \$0
 \$1,109
 \$0
 \$0

 Sub-Total:
 \$1,109
 \$0
 \$1,109
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Design and construction of the necessary renovations to modernize the facility's Center Control Area. This project's SOW includes, but is not be limited to the upgrade and/or replacement of existing security control system equipment, the redesign of existing desks and cabinetry to provide the most efficient design for staff movement and functionality with the possible addition of cabinetry to provide needed storage and the revision of all communication equipment, as needed, to provide the most efficiency in this very limited space. Center Control is inadequate for monitoring and control of the main and satellite units (Ad Seg, I Wing, Work Release and New Lisbon Boot Camp). Design of this project was funded from the FY 2000 Capital Appropriation for Security Improvements. This request is for construction funding.

BAYSIDE STATE PRISON

REPLACE UNDERGROUND TELEPHONE CABLE

LOCATION: MEDIUM UNIT

Dept Priority 52 Project ID: 26-200

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$422
 \$0
 \$422
 \$0
 \$0

 Sub-Total:
 \$422
 \$0
 \$422
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Survey and replace the underground telephone cables for the Firing Range and the East and West Arcades in the Medium Unit with above ground cable. At the present time, there is inadequate telephone service to these areas due in part to the lack of adequate cable pairs and problems caused by deteriorated cables. Also, the emergency phone system, which is a primary security system, does not function properly due to the deteriorated cables.

Section III-A, Page 43 REQ-04: Page 19 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	
			-	

EAST JERSEY STATE PRISON

CEILING REPAIRS, ACSU

LOCATION: ACSU

Dept Priority 53

Project ID: 26-317

Project Type Code: A03 Project Type Description: Preservation-Critical Repairs

 General:
 \$423
 \$0
 \$423
 \$0
 \$0

 Sub-Total:
 \$423
 \$0
 \$423
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Correcting design flaw in the original design for the housing area ceilings in Wings A, C and D of the Administrative Close Supervision Unit. The Scope of Woprk will include, but not be limited to, the installation of additional steel bracing, re-anchoring the soffit system and repairing/replacing of sheetrock.

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

BACK-UP GENERATOR SYSTEM INSTALLATION

LOCATION: POWERHOUSE

Dept Priority 54
Project ID: 26-280

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$1,341
 \$0
 \$1,341
 \$0
 \$0

 Sub-Total:
 \$1,341
 \$0
 \$1,341
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The Department contracted with an Electrical Engineer to study the Edna Mahan facility's electrical distribution system. The consultant's report indicated that if there is a problem with the Co-Generation Plant and any attempts to temporarily tie into street power are unsuccessful, the existing backup generator will not provide the facility with sufficient power to maintain all systems. There is actually a good possibility it would fail. It is imperative that a facility of the size and type of the Edna Mahan facility have a functioning back-up generator system. This system would be in a self-contained trailer and would be strategically placed on grounds to take over in the event of total power loss.

SOUTH WOODS STATE PRISON

SECURITY ENHANCEMENTS RECREATION YARDS

LOCATION: HOUSING UNITS

Dept Priority 55 Project ID: 26-285

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$255
 \$0
 \$255
 \$0
 \$0

 Sub-Total:
 \$255
 \$0
 \$255
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

There are six (6) typical general housing units at the South Woods State Prison. Each unit has two (2) attached exterior recreation yards. The recreation yards are prototypical with some fencing variations. Given their intended use, an increased level of security containment is required. This is to be accomplished by upgrading the existing security fence at each of the twelve yards by modifactions to the existing fence and wall enclosures of each yard.

Section III-A, Page 44 REQ-04: Page 20 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

NEW JERSEY STATE PRISON

PLUMBING REPAIRS-WING 2

LOCATION: WEST COMPOUND

Dept Priority 56

Project ID: 26-052

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$2,230
 \$0
 \$2,230
 \$0
 \$0

 Sub-Total:
 \$2,230
 \$0
 \$2,230
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Removal and replacement of 270 toilets and sinks with stainless steel combination units. The existing fixtures are cast iron which are rusting away and have been cited by the Department of Health. In addition, a large concrete pad must be hand poured for mounting purposes which is neither time or cost efficient. Replacement of main water lines, due to rusting and deterioration, and piping changes are also required. A similar project has been completed in Wings 1. Failure to fund this request will allow an unhealthy condition to continue.

NORTHERN STATE PRISON

GYMNASIUM FLOOR REPLACEMENT

LOCATION: GYMNASIUM

Dept Priority 57

Project ID: 26-189

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$340
 \$0
 \$340
 \$0
 \$0

 Sub-Total:
 \$340
 \$0
 \$340
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Design and install a new gymnasium floor. The project would include an investigation of the floor sub-structure. The inmate gymnasium floor is disintegrating and in need of replacement. The numerous missing and broken pieces of tile present a safety hazard. The gym is used for inmate recreation as well as the contact visit program.

CENTRAL OFFICE

WINDOW/DOOR REPLACEMENT

LOCATION: VARIOUS BUILDINGS

Dept Priority 58 Project ID: 26-191

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$1,931
 \$0
 \$1,931
 \$0
 \$0

 Sub-Total:
 \$1,931
 \$0
 \$1,931
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The phased replacement of the exterior doors (with associated hardware) and windows in all the buildings of the Central Office Complex. Standards have been prepared for the replacements that meet the security and esthetic requirements of the department. Bid specifications have been prepared for the Cubberly and Colptts buildings.

Section III-A, Page 45 REQ-04: Page 21 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

MID-STATE CORRECTIONAL FACILITY

REPLACEMENT OF EXTERIOR DOORS

LOCATION: FACILITYWIDE

Dept Priority 59

Project ID: 26-326

Project Type Code: A03 Project Type Description: Preservation-Critical Repairs

 General:
 \$250
 \$0
 \$250
 \$0
 \$0

 Sub-Total:
 \$250
 \$0
 \$250
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Replacement of all exterior doors throughout the Mid-State facility with metal doors and the necessary security and fire safety hardware. These doors are used for security and fire escapes for inmates and staff. These doors are rotted and very hard to open creating significant safety and security concerns.

ADULT DIAGNOSTIC AND TREATMENT CENTER, AVENEL

CENTER CONTROL RELOCATION/RENOVATION

LOCATION: CENTER CONTROL

Dept Priority 60 Project ID: 26-270

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$1,201
 \$0
 \$1,201
 \$0
 \$0

 Sub-Total:
 \$1,201
 \$0
 \$1,201
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Design and construction of the necessary renovations to modernize the facility"s Center Control Area. The Center Control function at ADTC is divided into two distinct locations separated by the facility"s receiving area. This project"s SOW would include, but not be limited to the following renovations: 1) The installation of a masonry and security glass wall in the Receiving Area creaing a link between the two existing locations. 2) Revision of all existing security control system equipment and communication equipment, as needed, to provide the most efficiency in the combined spaces; 3) Redesign of existing desks and cabinetry to provide the most efficient design for staff movement and functionality with the possible addition of cabinetry to provide needed storage; and 4) Relocation of the existing armory. Center Control is inadequate for monitoring and control of the main and satellite units (5 Wing, The Special Treatment Unit-Kearny and the STU Annex.

RECEPTION & ASSIGNMENT FACILITY

HEATING/VENTILATION DISTRIBUTION SYSTEM

LOCATION: FACILITY WIDE

Dept Priority 61 Project ID: 26-059

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$2,562
 \$0
 \$2,562
 \$0
 \$0

 Sub-Total:
 \$2,562
 \$0
 \$2,562
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The steam piping system is in poor condition and is in need of immediate attention. Piping is deteriorated and leaking and is beyond simple repairs. The old system is a one pipe system. Radiators become clogged with debris which does not allow steam to pass through and causes the wings to have little or no heat. The piping repairs listed are necessary to ensure that the operation of the new system is as efficient as projected.

Section III-A, Page 46 REQ-04: Page 22 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	
			-	

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

EMERGENCY GENERATOR REPLACEMENT

LOCATION: MAIN COMPLEX

Dept Priority 62

Project ID: 26-277

Project Type Code: A01 Project Type Description: Preservation-Electrical

General:	\$2,401	\$0	\$2,401	\$0	\$0
Sub-Total:	\$2,401	\$0	\$2,401	\$0	\$0

Operating Impact: Increase: \$0 Decrease: \$0

This project is for the replacement of the three 750 KW diesel fired generators which provide back-up.emergency power for the Garden State facility. Two of these units were installed as part of the original construction in 1967. The Scope of Work includes, but is not limited to, the removal of the exiting generators and the installation of two (2) 2,000 KW diesel fired units, the required swithgear and the installation of all necessary ancillary equipment.

ALBERT C. WAGNER YOUTH CORRECTIONAL FACILITY

STAIRWELL REPAIR/REPLACEMENT

LOCATION:

Dept Priority 63

Project ID: 26-253

Project Type Code: A06 Project Type Description: Preservation-Other

General:	\$1,266	\$0	\$1,266	\$0	\$0
Sub Tatali	\$1.266	60	\$1.266	CO	¢0
Sub-Total:	\$1,200	\$0	\$1,200	\$ U	\$0

Operating Impact: Increase: \$0 Decrease: \$0

To provide the necessary repairs and/or replacements to the stairwells and doors in center corridor to ensure the safety and security of both inmates and staff. In June 2004 a section of he stairwell that supports D Wing collapsed. This unit was replaced and the remainder of the stairwells in the facility were reinforced.

BAYSIDE STATE PRISON

CLOSED CIRCUIT TV SYSTEM, MEDIUM UNIT

LOCATION: MEDIUM UNIT

Dept Priority 64
Project ID: 26-108

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

General:	\$1,114	\$0	\$1,114	\$0	\$0
Sub-Total:	\$1,114	\$0	\$1,114	\$0	\$0

Operating Impact: Increase: \$0 Decrease: \$0

Upgrade and expansion of the existing closed circuit TV system to include video taking capability. Currently, there are six cameras located in the dining hall, gym and auditorium with monitors located in Central Control. Funding is requested to purchase additional equipment which will be installed in Housing Units A -F, Chapel, Main Compound, East & Dest Arcades, Visit Room, Gym, Clothing Shop, Tag Shop, Bakery, Maintenance Shops and Trailer Complex in the Medium Unit. As well as Willow and Spruce Halls at Ancora and all Housing Units and Educational Shops at the Minimum Unit. Due to the increase in the inmate population over the last several years and the type of inmate now being classified to the facility, it is imperative that staff have the ability to monitor and record the activities of the inmate population. This system would act as a deterrent to the inmate population and also enhance the safety of the staff and inmates.

Section III-A, Page 47 REQ-04: Page 23 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED
FY - 2011	FY- 2012

REQUESTED FY - 2013

REQUESTED FY 2014 - 2017

EAST JERSEY STATE PRISON

SECURITY DOOR REPLACEMENT, ROTUNDA

LOCATION: ROTUNDA

Dept Priority 65

Project ID: 26-315

Project Type Code: A03 Project Type Description: Preservation-Critical Repairs

\$342 General:

\$0 \$342 \$0 \$0 \$0 \$342 \$0 \$0

Sub-Total: Operating Impact:

Increase:

\$342

\$0

Decrease: \$25,000

This project is for the complete removal and replacement of the existing electronic doors in the Rotunda area of the East Jersey facility. The existing doors are part of the sally port that controls the entrance to the main facility through the rotunda and the facility's center control. The existing doors are in an advanced state of deterioration and require constant maintenance in order to ensure that they operate properly and securely. This is a direct threat to the continuing security and safety of the prison and its population. The project scope will include new doors, electronic controls and motors.

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

UNDERGROUND STEAM LINE REPAIR/REPLACEMENT

LOCATION:

Dept Priority 66

Project ID: 26-281

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

General:

\$959	\$0	\$959	\$0	\$0
\$959	\$0	\$959	\$0	\$0

Sub-Total:

Operating Impact:

\$0 Increase:

Decrease: \$10

The Edna Mahan facility is constantly losing steam due to a variety of leaks within the underground steam distribution system. The Department would contract with a Mechanical Engineering firm to inspect the entire underground steam piping system to identify the problem areas and to provide recommendations to correct the problems. The second phase of the project would carry out the recommended repairs and or replacements.

SOUTH WOODS STATE PRISON

CATWALK INSTALLATION

LOCATION: FACILITY WIDE

Dept Priority 67 Project ID: 26-187

Project Type Code: Project Type Description: Preservation-Other A06

\$1,496 \$0 General: \$0 \$1,496 \$0 \$0 Sub-Total: \$1,496 \$0 \$1,496 \$0

Operating Impact: \$0 Decrease: \$0 Increase:

It was noted in a recent PEOSH inspection that the location of some of the air handling equipment throughout the facility creates a hazardous situation for maintenance staff. An engineering firm has been contracted to investigate the problem and provide recommendations to alleviate the hazard. The recommended solution is the installation of catwalks at each of the air-handling units.

> REQ-04: Page 24 of 64 Section III-A, Page 48

Department of Corrections

Agency Capital Budget Request

(000's)

	TOTAL COST 7 YR PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
ı					_

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

ROOF TOP ALARM SYSTEM

LOCATION:

Dept Priority 68

Project ID: 26-295

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$949
 \$0
 \$949
 \$0
 \$0

 Sub-Total:
 \$949
 \$0
 \$949
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The design and installation of a roof mounted security intrusion detection and alarm system throughout the facility. A recently completed institutional security audit of the Garden State facility revealed the need for a roof top alarm system due to the lack of a secure perimeter.

MID-STATE CORRECTIONAL FACILITY

CONSTRUCT PERMANENT MAILROOM

LOCATION: ADMINISTRATION BUILDING

Dept Priority 69 Project ID: 26-318

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$182
 \$0
 \$182
 \$0
 \$0

 Sub-Total:
 \$182
 \$0
 \$182
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

At the present time, the Mid-State facility utilizes a trailer unit that originally housed design staff on a facility construction project as it's mailroom. For safety and security reasons the unit was installed outside the secure perimter of the facility. The unit is old and deteriorating, which is not the proper environment for handling the facility's business and inmate mail. This project is for the design and installation of a new 1,000 sq. ft. building to replace the existing unit.

RECEPTION & ASSIGNMENT FACILITY

SECURITY SYSTEM UPGRADES & REPAIRS

LOCATION: FACILITY WIDE

Dept Priority 70 Project ID: 26-063

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$4,925
 \$0
 \$4,925
 \$0
 \$0

 Sub-Total:
 \$4,925
 \$0
 \$4,925
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Upgrade and repairs to locking devices and systems, surveillance and alarm systems. The locking devices are outdated and replacement parts are difficult to find. At the present time, the facility has an inadquate amount of the surveillance and alarm systems that are necessary for security purposes.

Section III-A, Page 49 REQ-04: Page 25 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

7 YR PROG FY - 2011 FY - 2012 FY - 2013 FY 2014 - 2017	TOTAL COST 7 YR PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
--	-------------------------	------------------------	-----------------------	------------------------	---------------------------------

ADULT DIAGNOSTIC AND TREATMENT CENTER, AVENEL

REPLACE STORAGE UNITS

LOCATION:

Dept Priority 71

Project ID: 26-210

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$432
 \$0
 \$432
 \$0
 \$0

 Sub-Total:
 \$432
 \$0
 \$432
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

At the present time, the Adult Diagnostic & Diagnostic &

MOUNTAINVIEW YOUTH CORRECTIONAL FACILITY

PLUMBING SYSTEM UPGRADES

LOCATION: FACILITY WIDE

Dept Priority 72 Project ID: 26-126

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$5,249
 \$0
 \$5,249
 \$0
 \$0

 Sub-Total:
 \$5,249
 \$0
 \$5,249
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Upgrades and repairs to hot and cold water distribution systems throughtout the institution as well as providing new plumbing fixtures (including stainless stell combination units), piping, fittings, etc.. The distribution systems are very old and severly in need of repairs. Replacement parts for existing fixtures are difficult to find.

SOUTHERN STATE CORRECTIONAL FACILITY

CENTRALIZED LAUNDRY

LOCATION:

Dept Priority 73

Project ID: 26-307

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$236
 \$0
 \$236
 \$0
 \$0

 Sub-Total:
 \$236
 \$0
 \$236
 \$0
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The Southern State facility currently has 1 laundry location each in Compounds A, B & Department of 2 washers and 2 dryers, which are commercial grade and operated by electric power. Each unit also has a detail of inmates working along with a custody staff person. These units service approximately 2,040 inmates. The existing equipment is not capable of handling the capacity generated by this number of inmates. The proposed laundry will be located outside the perimeter fence in front of Compound A on the access road between Compound A & Department of the existing machines and eliminating the need to transport these items to an outside facility. Existing laundries would be utilized to service inmate personal laundry.

Section III-A, Page 50 REQ-04: Page 26 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST
7 YR PROG

E03

REQUESTED	REQUESTED	REQUESTED
FY - 2011	FY- 2012	FY - 2013

REQUESTED FY 2014 - 2017

BAYSIDE STATE PRISON

REPLACEMENT OF INTERIOR GATES

LOCATION: MEDIUM COMPLEX

Dept Priority 74

Project ID: 26-214

Project Type Code:

Project Type Description: Construction-Renovations and Rehabilitation

\$836 \$0 \$836 \$0 \$0 General: \$836 Sub-Total: \$836 \$0 \$0 \$0

\$0 Decrease: \$0 Operating Impact: Increase:

Replacement of the existing Kitchen truck gate and Trailer TM1 - TM4 walk through gates with new gates, controls and motor assemblies. Locks shall be penal type.

EAST JERSEY STATE PRISON

UPGRADE ELECTRICAL DISTRIBUTION SYSTEM

LOCATION: MAIN COMPLEX

Dept Priority 75 Project ID: 26-212

Project Type Code: A01 Project Type Description: Preservation-Electrical

\$3,034 \$3,034 General: \$0 \$0 \$0 \$3,034 \$0 \$3,034 Sub-Total: \$0 \$0

\$0 \$0 Operating Impact: Increase: Decrease:

The objective of this project is to upgrade the 13.2KV system to include two main feeders, one new 2,000 KW emergency generator and the required primary switchgear. The necessary provisions for the installation of a second generator will be part of this project. The installation of the 2,000 KW generators will eliminate the need for all of the generators now on the site.

MOUNTAINVIEW YOUTH CORRECTIONAL FACILITY

REPLACE WINDOWS AND DOORS

LOCATION: MAIN COMPOUND Dept Priority 76

Project ID: 26-012

Project Type Code: Project Type Description: Preservation-Other A06

\$3,834 \$0 \$0 \$3,834 General: \$0 \$0 \$0 \$0 Sub-Total: \$3,834 \$3,834

Increase: Decrease: \$250 Operating Impact: \$0

To replace windows (1,397) as well as room and entrance doors (310) in all Cottages, the Industrial Building, the Assembly Building & the Administration Building. The windows are over 65 years old. The frames and sills are rotting resulting in loose units throughout the cottages, service buildings and industrial buildings. This condition creates a security problem as well as contributing to high heat loss in the units. Both the entrance doors and room doors are old, deteriorated and pose a security threat. Failure to fund this request will continue the unsafe and insecure conditions within the units.

> REQ-04: Page 27 of 64 Section III-A, Page 51

Department of Corrections

Agency Capital Budget Request

(000's)

7 YR PROG FY - 201			
7 1K FROG F1 - 201	1 FY-2	2012 FY - 201	FY 2014 - 2017

NEW JERSEY STATE PRISON

PLUMBING REPAIRS-WINGS 3 & 5 LOCATION: WEST COMPOUND

Dept Priority 77

Project ID: 26-048

Project Type Code: A06

Project Type Description: Preservation-Other

\$1,781 \$0 \$0 \$1,781 \$0 General: \$0 \$1,781 Sub-Total: \$1,781 \$0 \$0

\$0 \$0 Operating Impact: Increase: Decrease:

Replacement of water supply mains (3"), risers, commodes, sinks and main sewer lines in both units. The water supply mains need to be replaced due to age and low water pressure to the third tier housing units of Wing 3. The obsolete commodes and sinks should be replaced with stainless steel combination units. The main sewer line is cracked and split creating leakage and has ben cited by the Department of Health. The plumbing work identified is similar to work recently completed in Wing 1.

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

CENTRAL AIR, LEARNING CENTER

LOCATION: SCHOOL

Dept Priority 78

Project ID: 26-197

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

\$371 \$0 \$0 General: \$371 \$0 \$0 Sub-Total: \$371 \$0 \$371 \$0

Operating Impact: Increase: Decrease:

Provide necessary electrical improvements in service and equipment needed to air condition the Institutional Learning Center and Yard School areas. The project would also have to include the cost of a feasibility study and engineering specifications.

MID-STATE CORRECTIONAL FACILITY

SECOND FLOOR BATHROOM FACILITY

LOCATION: MAIN BUILDING

Dept Priority 79 Project ID: 26-327

Project Type Code: A06 Project Type Description: Preservation-Other

General: \$100 \$0 \$0 \$100 \$0 Sub-Total: \$100 \$0 \$0 \$100 \$0

Operating Impact: Increase: \$0 Decrease:

Construction of a new staff bathroom on the second floor of the Mid-State facility. There are no facilities for the staff to utilize, which has an impact on security in that staff must be relieved to utilize the facilities.

> REQ-04: Page 28 of 64 Section III-A, Page 52

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

ADULT DIAGNOSTIC AND TREATMENT CENTER, AVENEL

E02

VOCATIONAL TRAINING BUILDING

LOCATION: EXISTING SITE

Dept Priority 80

Project ID: 26-095

Project Type Code:

Project Type Description: Construction-New

 General:
 \$468
 \$0
 \$0
 \$468
 \$0

 Sub-Total:
 \$468
 \$0
 \$0
 \$468
 \$0

Operating Impact: Increase: \$0 Decrease:

Design and construction of a 1,200 sq. ft. prefabricated building to house various vocational education programs. The unit will be sited inside the secure perimeter of the facility and will include work shop and warehouse space. ADTC was opened in 1976 with a design capacity of 183 inmates. The present inmate population is 628. Although housing has been expanded to accommodate the population growth, there has been little done to provide additional vocational education space. If this is not funded, the lack of vocational educational programs will continue to seriously impact the institutions ability to provide worthwhile activities for inmates.

\$0

RECEPTION & ASSIGNMENT FACILITY

REPLACE TOWER 1

LOCATION: PERIMETER

Dept Priority 81

Project ID: 26-204

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$1,395
 \$0
 \$1,395
 \$0

 Sub-Total:
 \$1,395
 \$0
 \$1,395
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Design and construction a new perimeter guard tower adjacent to the existing Tower 1. Tower 1 has been in place since the opening of the facility over 75 years ago and due to age and deterioration has become unsafe. Based on the recommendations of a structural engineer, facility maintenance staff has undertaken repairs to the structure. However, this will only sustain the building for a couple of years. Tower 1 is an integral part of the perimeter security system of this facility.

NEW JERSEY STATE PRISON

REPLACE GYMNASIUM FLOOR

LOCATION:

Dept Priority 82 Project ID: 26-202

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$163
 \$0
 \$163
 \$0

 Sub-Total:
 \$163
 \$0
 \$163
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The existing floor is separating from the concrete base creating a health and safety hazard. Numerous minor repairs have failed to resolve the situation.

Section III-A, Page 53 REQ-04: Page 29 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

KITCHEN UPGRADES

LOCATION: MAIN BUILDING

Dept Priority 83

Project ID: 26-097

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$9,603
 \$0
 \$9,603
 \$0

 Sub-Total:
 \$9,603
 \$0
 \$9,603
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

This project would include an investigation of the Garden State food service operations. This investigation would provide various recommendations from which a program document would be prepared, followed by design documents and construction. This program would include, but not be limited to, replacement of the existing floor, the upgrade of necessary equipment and relocation, as needed, to improve the facility. This may entail recommended changes in transport carts that not only meet Health Department standards but which similarly meet the physical requirements of our facility including efficiency of food preparation, storage and serving both in the main dining halls and to remote feeding.

RECEPTION & ASSIGNMENT FACILITY

INMATE INTAKE/PROCESSING AREA RENOVATIONS

LOCATION: EAST WING

Dept Priority 84
Project ID: 26-061

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$3,780
 \$0
 \$3,780
 \$0

 Sub-Total:
 \$3,780
 \$0
 \$3,780
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Make necessary renovations to the inmate Intake and Processing area. Provide one controlled access and high visibility stairwell for code-mandated egress and security and one 5,000 pound elevator. This work will give better visibility and control of the area.

MID-STATE CORRECTIONAL FACILITY

NEW SEWAGE GRINDER

LOCATION: POWER HOUSE

Dept Priority 85
Project ID: 26-328

Project Type Code: C03 Project Type Description: Environmental-Wastewater Treatment

 General:
 \$64
 \$0
 \$0
 \$64
 \$0

 Sub-Total:
 \$64
 \$0
 \$0
 \$64
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

This item is needed to grind the debris flushed down the institutional sewer system which continuously creates a total sewage back-up. This problem causes raw sewage to flood the entire institution and creates a significant health and safety issue.

Section III-A, Page 54 REQ-04: Page 30 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

REQUESTED

FY 2014 - 2017

|--|

NEW JERSEY STATE PRISON

ELEVATOR DOOR CONVERSION

LOCATION: NORTH & SOUTH COMPOUND/COOKHOU

Dept Priority 86

Project ID: 26-203

Project Type Code: A06 Project Type Description: Preservation-Other

\$703 \$0 \$0 \$703 \$0 General: \$0 \$703 Sub-Total: \$703 \$0 \$0

\$0 \$0 Operating Impact: Increase: Decrease:

Due to the heavy use of the elevators in the North and South Compounds and Cookhouse for transportation of required food supplies, these elevators should be converted from strictly passenger-type to freight-type elevators. Currently, these passenger-type elevators are frequently out of service for repairs.

SOUTH WOODS STATE PRISON

AIR HANDLER REPAIRS

LOCATION:

Dept Priority 87 Project ID: 26-293

Project Type Description: Preservation-HVAC Project Type Code: A02

\$316 \$316 General: \$0 \$0 \$0 Sub-Total: \$316 \$0 \$0 \$316 \$0

Operating Impact: \$0 \$0 Increase: Decrease:

In May 2006, the DOC contracted with an Environmental Engineering firm to conduct a limited microbial and moisture assessment within designated areas of the South Woods facility. The inspection was initiated in response to a PEOSH program report that identified locations exhibiting visible fungal contaminants. The Consultant did identify evidence of condensation and water incursion and therefore recommended that the facility"s HVAC systems be evaluated by a Mechanical Engineer for interior environmental controls for humidity, ventilation and condensation. This project is requested to fund the recommendations made in the Mechanical Engineers evaluation report.

BAYSIDE STATE PRISON

REPLACE ELECRICAL DISTRIBUTION SYSTEM, ANCORA

LOCATION: ANCORA PSYCHIATRIC HOSPITAL

Dept Priority 88 Project ID: 26-078

Project Type Code: A01 Project Type Description: Preservation-Electrical

\$1,084 \$1,084 General: \$0 \$0 \$0 \$1,084 \$0 \$1.084 \$0 Sub-Total: \$0

Operating Impact: Increase: \$0 Decrease: \$20

The replacement of the exiting switchgear, conductors, circuit panels and recepticals at both Willow and Spruce Halls. The electrical systems in both units are over 40 years old and have experienced electrical outages due to obsolete parts, conductors that are undersized for current usage, wiring breakdown and circuit breakers that have failed.

> REQ-04: Page 31 of 64 Section III-A, Page 55

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

ADULT DIAGNOSTIC AND TREATMENT CENTER, AVENEL

ADDITION TO ADMINISTRATION BULDING

LOCATION: MAIN BUILDING

Dept Priority 89

Project ID: 26-100

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$1,564
 \$0
 \$0
 \$1,564
 \$0

 Sub-Total:
 \$1,564
 \$0
 \$0
 \$1,564
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Design and construct a 4,000 sq. ft. masonry addition to the existing Administration Building, including the necessary fixtures and furnishings. This area will house functions that must be moved to a location outside the secure perimeter (in accordance with departmental directives) or are presently located in substandard trailers. Functions that would be included are Special Investigation Division-Operations, Custody Operations/Scheduling and Commissary. As part of the project, a study will be performed to determine if relocation of existing offices will increase the operating efficiency of this area. Failure to fund this request will result in the continued use of substandard trailers, inefficiency in the administrative functions of the institution and the inability to meet departmental directives.

BAYSIDE STATE PRISON

REPLACE ELECTRICAL DISTR. SYSTEM, MINIMUM

LOCATION: MINIMUM UNIT

Dept Priority 90 Project ID: 26-079

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$1,852
 \$0
 \$1,852
 \$0

 Sub-Total:
 \$1,852
 \$0
 \$1,852
 \$0

Operating Impact: Increase: \$0 Decrease: \$25

Upgrade the existing high voltage switch panels, conductors and transformers to handle the existing load. The project includes new conduit and conductors, switchgear and all ancillary equipment for all buildings at the Minimum Unit. The current system has failed several times creating blackouts which result in disruptions to life safety systems.

MID-STATE CORRECTIONAL FACILITY

UPGRADE HVAC & PNEUMATIC CONTROL SYSTEMS

LOCATION: POWER HOUSE

Dept Priority 91 Project ID: 26-251

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$1,472
 \$0
 \$1,472
 \$0

 Sub-Total:
 \$1,472
 \$0
 \$1,472
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Engineer and install necessary upgrades to the facility's HVAC and pneumatic control systems. The Scope Of Work (SOW) for this project would include the installation of air handling equipment and duct work where necessary. Also included is the upgrade of the electrical distribution system. Parts of the building are without adequate air flow and ventilation, which creates an unhealthy situation during the summer months. Installation of this new HVAC system will alleviate this problem and allow for a more healthy environment for both staff and inmates. Also included inthe SOW, will be the replacement of the facility's pneumatic control system.

Section III-A, Page 56 REQ-04: Page 32 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	
	·		-	

BAYSIDE STATE PRISON

SECONDARY BRANCH ELECTRICAL UPGRADE

LOCATION: MEDIUM, MINIMUM & ANCORA UNITS

Dept Priority 92 Project ID: 26-074

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$5,173
 \$0
 \$0
 \$5,173
 \$0

 Sub-Total:
 \$5,173
 \$0
 \$0
 \$5,173
 \$0

Operating Impact: Increase: \$0 Decrease: \$25

Replace aluminum secondary distribution wiring with copper wiring. The primary distribution cable was replaced with copper wiring in 1997. This project would be a continuation of that work. The secondary wiring is aluminum and is constantly breaking down, disrupting various parts of the facility. Included in this work is the replacement of all electrical panels with new breakers with load shedding capability to reduce power usage. Also, included is the replacement of standard motors with high efficiency motors.

NEW JERSEY STATE PRISON

LIGHTING UPGRADES, RECREATION YADS

LOCATION: RECREATION YARDS

Dept Priority 93 Project ID: 26-130

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$559
 \$0
 \$559
 \$0

 Sub-Total:
 \$559
 \$0
 \$0
 \$559
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Evaluation and upgrade of the existing site lighting for the recreation yard. In 1994, the dirt surface of the recreation yard was completely covered with concrete. Then in 1999, the area was divided into four yards separated by chain link fencing and barb wire. This work has created dark areas within the yards which must be illuminiated.

ALBERT C. WAGNER YOUTH CORRECTIONAL FACILITY

WINDOW REPLACEMENT

LOCATION: MAIN INSTITUTION

Dept Priority 94
Project ID: 26-120

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$3,664
 \$0
 \$0
 \$3,664
 \$0

 Sub-Total:
 \$3,664
 \$0
 \$0
 \$3,664
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Replace all windows in the facility housing units with security/detention type windows. Due to their age and deteriorating condition, the window units in the main institution are in need of replacement. They are a source of continual maintenance, heat loss and costly repairs. With the increase in higher security inmates at the facility, security windows are a necessity.

Section III-A, Page 57 REQ-04: Page 33 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	
			-	

BAYSIDE STATE PRISON

REPLACEMENT OF PRIMARY FEEDERS, POWER HOUSE

LOCATION: POWER HOUSE

Dept Priority 95

Project ID: 26-216

Project Type Code: A01 Project Type Description: Preservation-Electrical

General:	\$465	\$0	\$0	\$465	\$0
Sub-Total:	\$465	\$0	\$0	\$465	\$0

Operating Impact: Increase: \$0 Decrease: \$0

The existing underground feedewrs that originate at the power house are over 30 years old. Also "A" feeder failed several years age. As a result of this failure, a temporary above ground feeder was installed. Over trhe past several years the facility has experienced power failures due to geese flying into the wires. This project is to replace both feeders using underground conduit through existing manholes. There should be no splices in the manholes.

RECEPTION & ASSIGNMENT FACILITY

INSTALL EGRESS AND VERTICAL CIRCULATION HUB

LOCATION: CENTRAL CORRIDOR

Dept Priority 96
Project ID: 26-062

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

General:	\$6,914	\$0	\$0	\$6,914	\$0
Sub-Total:	\$6,914	\$0	\$0	\$6,914	\$0

Operating Impact: Increase: \$0 Decrease: \$0

Provide two vertical circulation hubs each consisting of one controlled access and high visibility stairwell for code-mandated egress and security and one 5,000 pound elevator. This project is necessary to comply with ADA requirements and includes all associated demolition and renovation.

MID-STATE CORRECTIONAL FACILITY

REPLACE STORAGE UNITS

LOCATION:

Dept Priority 97

Project ID: 26-287

Project Type Code: E02 Project Type Description: Construction-New

General:	\$641	\$0	\$0	\$641	\$0
Sub-Total:	\$641	\$0	\$0	\$641	\$0

Operating Impact: Increase: \$0 Decrease: \$0

At the present time, the Mid-State facility utilizes storages sheds constructed by inmates at the Southern State Correctional Facility for records retention and general storage. These sheds are of various dimensions and are located throughout the site. This is not the proper environment for storing of Institutional records and materials. These sheds need to be replaced with a permanent structure. This project is for the design and installation of a new 3,400 sq. ft. storage building to replace the existing storage units.

Section III-A, Page 58 REQ-04: Page 34 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

|--|

EAST JERSEY STATE PRISON

ELECTRICAL UPGRADE, WING 2

LOCATION: WING 2

Dept Priority 98

Project ID: 26-090

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$2,123
 \$0
 \$0
 \$2,123
 \$0

 Sub-Total:
 \$2,123
 \$0
 \$2,123
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Engineer and install new electrical distribution system, including wiring and panels, to Wing 2 Down, Wing 2 Middle and Wing 2 Up. Double bunking, which took place 4 years ago, created problems due to the additional electric that is being used by the inmate population. Overloaded power lines are causing circuit breakers to trip and put additional stress on the existing wiring to the cells.

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

ELECTRICAL RENOVATIONS

LOCATION: FACILITY WIDE

Dept Priority 99 Project ID: 26-054

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$2,053
 \$0
 \$0
 \$2,053
 \$0

 Sub-Total:
 \$2,053
 \$0
 \$0
 \$2,053
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Replace the current obsolete standard wiring and panel boxes in various cottages and install electrical disconnects on fifteen poles. C Cottage, Conover, Silzer, Williamson, Ackerman & Department of the old fashioned cotton type jackets which are deteriorating due to age & Department of the oldest building on grounds still in use and utilize the old fashioned cotton type jackets which are deteriorating due to age & Department of the older type individual glass fuses are in use and should be changed to breakers. Some of the buildings have neutral leg fuses, which is a very hazardous condition. An overall evaluation of the electrical systems in these buildings would not meet electrical code standards. Also, electrical pole disconnects should be installed at each pole where the electrical wires enter the building (15 locations). The main reason for these disconnects are, in a case of fire or other emergency, the electricity can be shut off at the pole. This would facilitate response time as well as eliminating the hazard of attempting to enter a basement during an emergency.

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

FLOOR REPLACEMENT, DORM #1 & GYMNASIUM

LOCATION: MAIN BUILDING

Dept Priority 100 Project ID: 26-124

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$468
 \$0
 \$0
 \$468
 \$0

 Sub-Total:
 \$468
 \$0
 \$0
 \$468
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Design and replace the floor in Dorm #1 (approximately 15,000 sq. ft) and the Correction Gymnasium (approximately 25,000 sq. ft.). The SOW will include an investigation of the sub-flooring for possible deterioration. Water damage, due to roof leaks that have recently been repaired, and subsequent insect damage have deteriorated the condition of each floor. Dorm #1, which was originally a gymnasium, has added damage due to its conversion to a housing unit.

Section III-A, Page 59 REQ-04: Page 35 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST
7 YR PROG

REQUESTED	REQUESTE
FY - 2011	FY- 2012

REQUESTED FY - 2013

REQUESTED FY 2014 - 2017

\$0

\$0

MOUNTAINVIEW YOUTH CORRECTIONAL FACILITY

ROAD REPAIRS

LOCATION:

Dept Priority 101

Project ID: 26-255

Project Type Code: F02

Project Type Description: Infrastructure-Roads and Approaches

 General:
 \$376
 \$0
 \$376

 Sub-Total:
 \$376
 \$0
 \$376

Operating Impact: Increase: \$0 Decrease: \$0

To repair/install roads and parking lots. These repairs are necessary to maintain operations and have been scaled down to represent essential needs. Various entrance and perimeter roads and parking lots are in a serious state of disrepair. The sub-base in many areas has deteriorated and allowed the roadway to sink creating pot holes and checker-boarding of the blacktop. The facilities continue to patch pot holes as they appear, but a long range solution to this problem must be found. The maintenance of the DOC's road system is not just a convenience for the employees. It is also a security necessity due to the use of the road system for patrol of security perimeters and the access provided to the facilities for vendors, supplies, food service deliveries and various law enforcement personnel. Areas that require work at Mountainview are the Main Compound parking lot, the facility perimeter road and the farm driveways.

MID-STATE CORRECTIONAL FACILITY

WINDOW REPLACEMENT

LOCATION: MAIN BUILDING

Dept Priority 102

Project ID: 26-098

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$743
 \$0
 \$0
 \$743
 \$0

 Sub-Total:
 \$743
 \$0
 \$0
 \$743
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The replacement of all jalousie type windows at the facility. The facility has been experiencing continuous breakdowns and malfunctions mainly due to rusting and the wearing out of moveable parts. The existing windows are aluminum framed with double strength glass and are not energy efficient. A total of 247 replacement windows would allow the facility to save a great deal on fuel costs during the heating season.

NEW JERSEY STATE PRISON

WEST COMPOUND REPLACEMENT

LOCATION:

Dept Priority 103 Project ID: 26-206

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$343,565
 \$0
 \$0
 \$343,565
 \$0

 Sub-Total:
 \$343,565
 \$0
 \$0
 \$343,565
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The phased replacement of the West Compound of the maximum-security New Jersey State Prison (NJSP). A number of buildings in the West Compound were constructed more than 150 years ago making them is the Department's oldest facilities. Despite extreme efforts to provide short-term maintenance to this aged facility, the basic infrastructure is obsolete, outmoded and in a chronic state of disrepair. This includes the locking systems, roofing, plumbing, HVAC and power. This initiative provides the Department with a unique opportunity to assure optimal utilization of bedspacel and to maximize existing operational expenditures.

Section III-A, Page 60 REQ-04: Page 36 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST
7 YR PROG

REQUESTED	REQUESTEI
FY - 2011	FY- 2012

REQUESTED FY - 2013 **REQUESTED FY** 2014 - 2017

ALBERT C. WAGNER YOUTH CORRECTIONAL FACILITY

STOREROOM/CANTEEN DRY GOODS STORAGE

LOCATION: STOREROOM/CANTEEN

Dept Priority 104

Project ID: 26-244

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$1,083
 \$0
 \$1,083
 \$0

 Sub-Total:
 \$1,083
 \$0
 \$1,083
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

To design and construct a new canteen building of approximately 2,800 sq. ft. to be used as a canteen store. Presently, the canteen store is overcrowded and provides insufficient room to store merchandise and work effectively. As of October, 1998, the Department no longer allows inmates to receive food packages. Therefore, the Canteen has increased inventory to accommodate this change. This cannot be done successfully without expanded space.

SOUTH WOODS STATE PRISON

PARKING LOT LIGHTING AND PAVING

LOCATION:

Dept Priority 105

Project ID: 26-252

Project Type Code: F02 Project Type Description: Infrastructure-Roads and Approaches

 General:
 \$440
 \$0
 \$0
 \$440
 \$0

 Sub-Total:
 \$440
 \$0
 \$0
 \$440
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

This project is for the installation of a storm water drainage system, proper illumination and paving at the regional fueling station and the adjacent facility parking lot. Currently there is not enough parking for facility staff. The parking lot that has been installed across the street from the facility is unpaved and does not have any lighting. Staff is reluctant to park their vehicles in the lot due to the lack of lighting. The parking surface itself consists of gravel and becomes unsafe to use when it rains

BAYSIDE STATE PRISON

REPLACEMENT OF STEAM HOT WATER HEATERS

LOCATION: POWER HOUSE

Dept Priority 106 Project ID: 26-219

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$1,210
 \$0
 \$1,210
 \$0

 Sub-Total:
 \$1,210
 \$0
 \$1,210
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Engineer and install four (4) tank-less hot wateer heaters in the Power House to supply hot water to Barracks 1 - 6, Cottages 1 - 13, the Administration Building and the Education Building at the Minimum Unit. The SOW includes the design and construction of a concrete block addition to the Power House, above ground supply piping and the removal of all existing tanks.

Section III-A, Page 61 REQ-04: Page 37 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

RECEPTION & ASSIGNMENT FACILITY

ELECTRICAL REPAIRS AND UPGRADES

LOCATION: FACILITY WIDE

Dept Priority 107

Project ID: 26-064

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$6,611
 \$0
 \$0
 \$6,611
 \$0

 Sub-Total:
 \$6,611
 \$0
 \$6,611
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Upgrades and repairs to power distribution wiring and conduit. Power distribution wiring and conduit need to be updated to meet the current demands.

EAST JERSEY STATE PRISON

DINING ROOM FLOOR REPLACEMENT

LOCATION: INMATE DINING ROOM

Dept Priority 108 Project ID: 26-003

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$670
 \$0
 \$0
 \$670
 \$0

 Sub-Total:
 \$670
 \$0
 \$0
 \$670
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Replace the deteriorated tile floor in the inmate dining room with a non-skid terrazzo floor. The floor in the inmate dining room is deteriorating from age and has tiles which are either loose or missing. This is not only an unsanitary, but an unsafe situation for inmates and staff. As part of the project, a study will be conducted to insure the integrity of the sub-flooring. Areas of the dining room have been off limits at times due to damaged or missing floor tiles. Also, loose floor tiles can be used as a weapon against other inmates of facility staff.d

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

HOT WATER BOILER REPLACEMENTS

LOCATION: HOUSING UNITS

Dept Priority 109 Project ID: 26-329

Project Type Code: A02 Project Type Description: Preservation-HVAC

 General:
 \$180
 \$0
 \$180
 \$0

 Sub-Total:
 \$180
 \$0
 \$180
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

This project calls for the replacement of the hot water boilers for the Conover, Williamson, Ackerman and C Cottages. These are needed to maintain the hot water for inmate use.

Section III-A, Page 62 REQ-04: Page 38 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST
7 YR PROG

REQUESTED	REQUESTE
FY - 2011	FY- 2012

REQUESTED FY - 2013

REQUESTED FY 2014 - 2017

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

WATER DISTRIBUTION SYSTEM UPGRADE

LOCATION:

Dept Priority 110

Project ID: 26-303

Project Type Code: A06 Project Type Description: Preservation-Other

\$0

 General:
 \$2,530
 \$0
 \$0
 \$2,530
 \$0

 Sub-Total:
 \$2,530
 \$0
 \$0
 \$2,530
 \$0

Operating Impact:

Increase:

Decrease:

The upgrade of the domestic water distribution system of the Garden State facility. Due to the increase in population over the last 15 years the water distribution system is running at capacity. Also due to the age and condition of the existing system, ongoing maintenance is a problem. To improve the condition of the existing distribution system, an upgrade of the system, including but not limited to, new connections, valves, fire hydrants and relays and the cleaning and lining of all water mains must be completed.

\$0

SOUTHERN STATE CORRECTIONAL FACILITY

EMERGENCY GENERATOR CONTROL PANEL UPGRADE

LOCATION:

Dept Priority 111

Project ID: 26-299

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$583
 \$0
 \$0
 \$583
 \$0

 Sub-Total:
 \$583
 \$0
 \$0
 \$583
 \$0

Operating Impact: In

Increase: \$0

Decrease: \$0

There are two sets of generators supplying emergency power to the Southern State facility. Compound A is supplied by three 750 KW units and Compound B is supplied by four 750 KW units. Load demands for each compound vary from 1000 to 1500 KW. The control system was manufactured by ASCO in 1983. The facility has been experiencing operating problems with the generators. The problems have been traced, repeatedly, to the malfunctions of certain modules in the ASCO control panels. This project is for the design and installation of a new control system utilizing "State of the Art" equipment.

ALBERT C. WAGNER YOUTH CORRECTIONAL FACILITY

BATHROOM RENOVATIONS. A WING & E-1

LOCATION: A WING & E-1 WING

Dept Priority 112 Project ID: 26-248

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$1,321
 \$0
 \$0
 \$1,321
 \$0

 Sub-Total:
 \$1,321
 \$0
 \$0
 \$1,321
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

This project is for the complete renovation of the bathroom areas, including plumbing and sanitary systems, on all inmate housing areas of A Wing and in E-1. The fixtures, valves and piping of both the plumbing and the sanitary systems do not meet water conservation standards or ADA requirements. Although the main plumbing distribution line in the basement of the A Wing has been recently replaced with copper piping, most of the supply system to the bathroom areas is original.

Section III-A, Page 63 REQ-04: Page 39 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

REQUESTED

FY 2014 - 2017

TOTAL COST 7 YR PROG

REQUESTED	REQUESTED	REQUESTED
FY - 2011	FY- 2012	FY - 2013

BAYSIDE STATE PRISON

STEAM TRANSMISSION/CONDENSATE REPIPING

LOCATION:

Dept Priority 113

Project ID: 26-258

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$618
 \$0
 \$618
 \$0

 Sub-Total:
 \$618
 \$0
 \$618
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Engineer and build two underground sections of the steam supply and condensate piping under the existing access roadway to replace existing piping. The pipes will be supported by a galvanized steel bridge support. The existing underground piping has developed leaks and has required repairs, which are difficult to make given their location.

RECEPTION & ASSIGNMENT FACILITY

HEATING AND VENTILATION CONTROL SYSTEM

LOCATION: FACILITY WIDE

Dept Priority 114

Project ID: 26-065

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$12,294
 \$0
 \$12,294
 \$0

 Sub-Total:
 \$12,294
 \$0
 \$0
 \$12,294
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

New HVAC system and automatic temperature controls throughout the facility. The facility was built in stages over 50 years creating a number of different heating systems. It would be more economical and energy efficient to have one HVAC system throughout the facility.

EAST JERSEY STATE PRISON

CLOSED CIRCUIT SURVEILLANCE VIDEO SYSTEM

LOCATION: ACSU

Dept Priority 115

Project ID: 26-032

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$176
 \$0
 \$0
 \$176

 Sub-Total:
 \$176
 \$0
 \$0
 \$176

Operating Impact: Increase: \$0 Decrease: \$0

The 324 cells housing inmates, of which 36 are double bunked in the ACSU building, house the most dangerous prisoners incarcerated in the New Jersey correctional institutions. Physical altercations with inmates occur frequently. The capability to electronically observe and record any such situation is needed to preserve health and safety. Overall video surveillance provides an extremely valuable custody management resource in this maximum security setting.

Section III-A, Page 64 REQ-04: Page 40 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

PLUMBING REPLACEMENT, NORTH & SOUTH HALL

LOCATION: MAXIMUM SECURITY COMPOUND

Dept Priority 116
Project ID: 26-050

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$1,396
 \$0
 \$0
 \$1,396

 Sub-Total:
 \$1,396
 \$0
 \$0
 \$1,396

Operating Impact: Increase: \$0 Decrease: \$0

Replace all plumbing including both heat and domestic hot water distribution systems (with isolation valves), hot water pumps and epoxy combination sink/toilets within cell areas. These 25 year old maximum security buildings contain piping that has deteriorated from acidic water conditions and is equipped with pumps and valves for which parts are obsolete and no longer manufactured. Combo toilets/sinks within cell areas continue to be cited by the Department of Health during semi-annual inspections. Isolation valves are required in order to repair individual sinks without having to shut down the whole wing.

MOUNTAINVIEW YOUTH CORRECTIONAL FACILITY

COTTAGE EXTERIOR VINYL SIDING, CORNICES ETC.

LOCATION: COTTAGES

Dept Priority 117

Project ID: 26-309

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$262
 \$0
 \$0
 \$262

 Sub-Total:
 \$262
 \$0
 \$0
 \$262

Operating Impact: Increase: \$0 Decrease: \$0

All ten Units and the Industrial Building currently have a wooden exterior. This project would reface the buildings with vinyl siding. The exterior wood on these buildings is rotting and paint is peeling. It has been determined that by using vinyl siding, the buildings will be saved from further deterioration. Also, the vinyl will be low maintenance and limit the constant upkeep the buildings require.

ALBERT C. WAGNER YOUTH CORRECTIONAL FACILITY

TRANSFORMER REPLACEMENT

LOCATION: MAINTENANCE BUILDING

Dept Priority 118
Project ID: 26-257

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$322
 \$0
 \$0
 \$322

 Sub-Total:
 \$322
 \$0
 \$0
 \$0
 \$322

Operating Impact: Increase: \$0 Decrease: \$0

Replacement of transformers in the Maintenance Buildingloading dock area. These units are the old can type and because of their age and condition should be replaced with pad mounted units.

Section III-A, Page 65 REQ-04: Page 41 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	RE
7 YR PROG	F

REQUESTED	REQUESTED	REQUESTED
FY - 2011	FY- 2012	FY - 2013

REQUESTED FY 2014 - 2017

EAST JERSEY STATE PRISON

REPAIR OF BRICK WALLS, WINGS 1 & 4

LOCATION: WINGS 1 & 4

Dept Priority 119

Project ID: 26-010

Project Type Code: A03 Project Type Description: Preservation-Critical Repairs

General:	\$4,639	\$0	\$0	\$0	\$4,639
Sub-Total:	\$4,639	\$0	\$0	\$0	\$4,639

Operating Impact: Increase: \$0 Decrease: \$0

The brick walls of Wings 1 & Dear to be in an advanced state of deterioration. Sections of masonry have fallen from these structures. Large sections of the walls appear to be unsound. Although unsightly, the walls will not be repainted in order to prevent possible further damage due to moisture retention. Emergency repairs were made in 1999 to the front wall and window security bars of Wing 4 due to the threat from falling bricks and the failure of the security bars. A study must first be conducted to determine the extent of damage and course of action to repair and/or replace the brick walls as deemed necessary to maintain security.

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

WINDOW REPLACEMENT

LOCATION: FACILITY WIDE

Dept Priority 120

Project ID: 26-015

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

General:	\$1,466	\$0	\$0	\$0	\$1,466
Sub-Total:	\$1,466	\$0	\$0	\$0	\$1,466

Operating Impact: Increase: \$0 Decrease: \$81

To replace 526 windows with new vinyl units and associated repairs to sash and frames. Windows in all of the older structures at the facility, which are sash cord and weight type are rotting out, loose fitting and badly in need of repair. The replacement of these units would result in a savings in heating and maintenance costs. The following is a list of cottages that are in need of repair. Williamson Cottage (92), Conover Cottage (96), Silzer Cottage (96), Ackerman Cottage (161) & the Administration Building (81).

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

HOT WATER TANK REPLACEMENT

LOCATION: MAIN COMPLEX

Dept Priority 121 Project ID: 26-274

Project Type Code: A06 Project Type Description: Preservation-Other

General:	\$420	\$0	\$0	\$0	\$420
Sub-Total:	\$420	\$0	\$0	\$0	\$420

Operating Impact: Increase: \$0 Decrease: \$0

At the present time, the Garden State facility is supplied domestic hot water through four (4) existing hot water tanks. These tanks, which were part of the original construction of the facility are over 40 years old, inefficient, slow recovering and require a great deal of maintenance. The cement linings have crumbled and the tank design has made them obsolete. This project is for the engineering and installation of a new domestic hot water supply system utilizing an instantaneous feedback hot water system. The system requires only a minimum of floor space, provides water as it is needed (instantly), has a redundancy factor for complete system back-up an does not waste energy.

Section III-A, Page 66 REQ-04: Page 42 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

MOUNTAINVIEW YOUTH CORRECTIONAL FACILITY

NEW COMMUNICATION SYSTEM

LOCATION:

Dept Priority 122

Project ID: 26-310

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$1,235
 \$0
 \$0
 \$1,235

 Sub-Total:
 \$1,235
 \$0
 \$0
 \$1,235

Operating Impact: Increase: \$0 Decrease: \$0

To install an Intercom/All-Call system to all housing units and buildings throughout the facility, recreation and work areas. The system would be operated in Center Control allowing all points to be notified at once, interacting with housing units for return voice and paging. The Mountainview facility does not have the capability to reach all posts and areas at one time. Minimal response time by staff in an emergency is crucial in addressing emergent matters.

ADULT DIAGNOSTIC AND TREATMENT CENTER, AVENEL

PARKING LOT PAVING

LOCATION: PARKING LOT

Dept Priority 123 Project ID: 26-319

Project Type Code: F02 Project Type Description: Infrastructure-Roads and Approaches

 General:
 \$115
 \$0
 \$0
 \$115

 Sub-Total:
 \$115
 \$0
 \$0
 \$115

Operating Impact: Increase: \$0 Decrease: \$0

Provide base and asphalt for the facility parking areas. All work shall comply with NJDOT specifications. The parking space provided with the construction of the institution has become inadequate to meet the needs of our current staff as well as inmate"s visitors. It has become necessary to make improvements to existing parking areas.

ALBERT C. WAGNER YOUTH CORRECTIONAL FACILITY

UPGRADE ELECTRICAL SERVICE, FRONT HOUSE

LOCATION: FRONT HOUSE

Dept Priority 124

Project ID: 26-211

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$929
 \$0
 \$0
 \$929

 Sub-Total:
 \$929
 \$0
 \$0
 \$0
 \$929

Operating Impact: Increase: \$0 Decrease: \$0

The Front House, which houses the administrative offices for the facility, has been experiencing electrical outages. The main reason for these occurances is that the system is over 30 years old and, due to the requirenebts for computers and other modern electrical office equipment, has been expanded beyond its original capacity. This project is for engineering and installation of a new expanded electrical service.

Section III-A, Page 67 REQ-04: Page 43 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

|--|

BAYSIDE STATE PRISON

REPLACE PUBLIC ADDRESS SYSTEM

LOCATION: MEDIUM & MINIMUM UNITS

Dept Priority 125

Project ID: 26-080

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$1,036
 \$0
 \$0
 \$1,036

 Sub-Total:
 \$1,036
 \$0
 \$0
 \$1,036

Operating Impact: Increase: \$0 Decrease: \$0

Design and install new public address systems with new conduit, wiring, amplifiers and intercom for both the Medium and Minimum Units. Each branch system will be designed with fuses to prevent burnout of amplifiers in case of electrical shorts. The current public address systems at the Medium and Minimum units are over 30 years old and fail several times each year due to electrical short circuits in the wiring. This results in burn out and the repair/replacement of expensive amplifiers.

BAYSIDE STATE PRISON

WALL REPAIRS, ADMINISTRATION BLDG. MINIMUM UNIT

LOCATION: MINIMUM UNIT

Dept Priority 126

Project ID: 26-288

Project Type Code: A03 Project Type Description: Preservation-Critical Repairs

 General:
 \$104
 \$0
 \$0
 \$104

 Sub-Total:
 \$104
 \$0
 \$0
 \$104

Operating Impact: Increase: \$0 Decrease: \$0

The Administration Building at the Minimum (Farm) Unit is a three story structure (including basement) built circa 1920 - 1930. The exterior façade consists of painted eight inch block with punched windows. Above the first floor windows is a flat brick arch supported by a steel loose lintel. A report prepared by a structural engineer reported a continuous open horizontal crack above the first floor window head, blocks that have spalled and are outwardly displaced above window jambs, loose blocks along the north elevation and fine vertical cracks originating from window heads. Left unchecked this would eventually compromise buildeing structural integreity. Facility maintenance staff have implemented the short term repair recommendations of the consultant. This project is for the long term repair solution of removing the brick above the windows, repair/replace the steel lintel, install protective flashing and replace the brick.

EAST JERSEY STATE PRISON

BACK KITCHEN DEMOLITION

LOCATION: BACK KITCHEN

Dept Priority 127
Project ID: 26-036

Project Type Code: E01 Project Type Description: Construction-Demolition

 General:
 \$867
 \$0
 \$0
 \$867

 Sub-Total:
 \$867
 \$0
 \$0
 \$867

Operating Impact: Increase: \$0 Decrease: \$0

To demolish the old back kitchen. The old back kitchen is not in use and has been condemned and presents a safety hazard. The floor of this area is being supported by numerous "jacks" in order to prevent its collapse. The utility support systems for the building are in very poor condition and in some cases have fallen from their original installed location. The demolition of the back kitchen is a pre-condition for the construction of a new multi-purpose building. Even though this building is not in use as a kitchen, it must be utilized as a walkway for transporting garbage to the loading dock. The area has been checked by PEOSH Health and Safety Inspectors. Some of the violations the Maintenance Staff were able to correct but other corrections and repairs are needed to bring this building up to current requirements.

Section III-A, Page 68 REQ-04: Page 44 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	
7 YR PROG	

REQUESTED	REQUESTE
FY - 2011	FY- 2012

REQUESTED FY - 2013 **REQUESTED FY** 2014 - 2017

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

ACKERMAN BUILDING RENOVATION

LOCATION: ACKERMAN BUILDING

Dept Priority 128

Project ID: 26-024

General:

Project Type Code: A06 Project Type Description: Preservation-Other

\$1,406 \$0 \$0 \$1,406

Sub-Total: \$1,406 \$0 \$0 \$1,406

Operating Impact: Increase: \$0 Decrease: \$0

To renovate the entire building including the plumbing, heating and electrical utilities. The building, which contains program, housing and office space, is a very sound structure and should last for a long time given proper care and maintenance. The plumbing, heating and electrical utilities in the building are approximately 60 years old and need to be replaced as soon as possible. The health and safety of both employees and inmates is a major concern because of these deteriorating utilities.

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

CONSTRUCT PERMANENT MAILROOM

LOCATION: ADMINISTRATION BUILDING

Dept Priority 129
Project ID: 26-32

Project ID: 26-320

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$182
 \$0
 \$0
 \$182

 Sub-Total:
 \$182
 \$0
 \$0
 \$182

Operating Impact: Increase: \$0 Decrease: \$0

At the present time, the Garden State facility utilizes a trailer unit that originally housed design staff on a facility construction project as it's mailroom. For safety and security reasons the unit was installed outside the main facility. The unit is old and deteriorating, which is not the proper environment for handling the facility's business and inmate mail. This project is for the design and installation of a new 1,000 sq. ft. building to replace the existing unit.

MOUNTAINVIEW YOUTH CORRECTIONAL FACILITY

BUILDINGS FOR STOREROOM, PACKAGES & FRISK AREA

LOCATION: NEW BUILDING SITE

Dept Priority 130 Project ID: 26-025

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$2,780
 \$0
 \$0
 \$2,780

 Sub-Total:
 \$2,780
 \$0
 \$0
 \$2,780

Operating Impact: Increase: \$0 Decrease: \$0

Design and construct a masonry type one-story block building containing approx. 6,000 sq. ft. Institutional records may no longer be stored in the basement or the attic of the cottages due to water infiltration and other structural problems. This project will provide a secure and dry area for records to be stored.

Section III-A, Page 69 REQ-04: Page 45 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	
	·			

BAYSIDE STATE PRISON

KITCHEN UPGRADE (CONSTRUCTION)

LOCATION: MEDIUM UNIT

Dept Priority 131

26-221

E03

Project ID: Project Type Code:

Project Type Description: Construction-Renovations and Rehabilitation

\$2,416 \$0 \$0 \$0 \$2,416 General: Sub-Total: \$2,416 \$0 \$0 \$0 \$2,416

Operating Impact:

\$0 Increase:

\$0 Decrease:

The purpose of this request is to provide construction funding for the renovation of the existing kitchen to ensure that the unit can receive, store & amp; retermalize food. The SOW includes, but is not limited to, additional storage, rethermalization ovens, replacement of the existing floor and a new HVAC system. Design funding was provided in FY2001.

EAST JERSEY STATE PRISON

INTERIOR CELL WALL REPAIRS, WING 4

LOCATION: WING 4

Dept Priority 132 Project ID: 26-286

Project Type Code: A03 Project Type Description: Preservation-Critical Repairs

\$2,910 General: \$0 \$0 \$0 \$2,910 Sub-Total: \$2,910 \$0 \$0 \$0 \$2,910

Operating Impact:

\$0 Increase:

Decrease: \$0

This project is for the replacement of the rear walls of each cell unit in Wing 4. The Scope of Work would include, but not be limited to, the replacement of all plumbing and electrical fixtures and ancillary piping within the cell. 4 Wing contains 368 cells, which were constructed with modular metal sections connected by concrete flooring. Portions of the rear cell walls have become decayed to the point that some cells have been condemned. To allow this deterioration to go unchecked will result in the loss of additional maximum security bedspaces.

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

WINDOW REPLACEMENT

LOCATION: HOUSING UNITS

Dept Priority 133

Project ID: 26-121

Project Type Code: A06 Project Type Description: Preservation-Other

\$3,551 \$0 \$3,551 General: \$0 \$0 Sub-Total: \$3,551 \$0 \$0 \$0 \$3,551

\$0 Decrease: \$0 Operating Impact: Increase:

The replacement of all jalousie type windows (approximately 1,000) at the facility. The facility has been experiencing continuous breakdowns and malfunctions mainly due to rusting and the wearing out of moveable parts. The system is over 30 years old and replacement parts are unattainable.

> REQ-04: Page 46 of 64 Section III-A, Page 70

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED
FY - 2011	FY- 2012

REQUESTED FY - 2013 **REQUESTED FY** 2014 - 2017

MOUNTAINVIEW YOUTH CORRECTIONAL FACILITY

MULTI-PURPOSE/GYMNASIUM BUILDING

LOCATION: ADJACENT TO PRESENT GYM

Dept Priority 134

Project ID: 26-045

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$8,609
 \$0
 \$0
 \$8,609

 Sub-Total:
 \$8,609
 \$0
 \$0
 \$8,609

Operating Impact: Increase: \$0 Decrease: \$0

Design and construct a space for inmate indoor recreation which would serve the needs of the facility. Presently, the facility's gymnasium is used not only for recreation but also for educational programs. This creates limited space for both the Education Department and the inmate population during recreation. With the construction of this new building, more recreational activities may be provided for the inmates.

ALBERT C. WAGNER YOUTH CORRECTIONAL FACILITY

HVAC UPGRADE, VOCATIONAL AREAS

LOCATION: VOCATIONAL BUILDING

Dept Priority 135 Project ID: 26-247

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$616
 \$0
 \$0
 \$616

 Sub-Total:
 \$616
 \$0
 \$0
 \$0
 \$616

Operating Impact: Increase: \$0 Decrease: \$0

The Department has contracted with a Mechanical Engineering firm to investigate the HVAC systems for the Wood, Print and Barber Shops along with toilet, storage, hallway and tool room areas of the Vocational Building. The Department will initiate a construction project to upgrade these systems, based on the recommendations of the consultant.

BAYSIDE STATE PRISON

REPLACEMENT OF AIR HANDLING UNIT, TAG SHOP

LOCATION: INDUSTRIAL BUILDING

Dept Priority 136
Project ID: 26-136

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$417
 \$0
 \$0
 \$0
 \$417

 Sub-Total:
 \$417
 \$0
 \$0
 \$0
 \$417

Operating Impact: Increase: \$0 Decrease: \$0

Replace the air handling unit that supplies the Tag Shop, Industrial Complex. The pneumatic control, which regulates the unit, should be upgraded to provide energy savings to the complex. The unit is required to maintain air flow throught the buildings. The shaft in this unit has been repaired several times over the last thirty years. The steam coils that supply heat have deteriorated. It is becoming more difficult to locate parts to repair the unit.

Section III-A, Page 71 REQ-04: Page 47 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

REPLACEMENT OF GATE HOUSE & VISITORS CENTER

LOCATION: ENTRANCE GATE

Dept Priority 137

Project ID: 26-220

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$8,365
 \$0
 \$0
 \$8,365

 Sub-Total:
 \$8,365
 \$0
 \$0
 \$0
 \$8,365

Operating Impact: Increase: \$0 Decrease: \$0

The current gate house and visit center complex consists of an undersized building complemented by a modular unit. A new complex would provide sufficient space to properly service our visit program (which has increased proportionately with the facility's expanded population), consolidate our existing package room (currently housed in a separate trailer) and provide needed storage for county and release inmate property.

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

SALLYPORT LOCKING SYSTEM REPLACEMENT

LOCATION: RECEIVING GATE

Dept Priority 138

Project ID: 26-275

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$240
 \$0
 \$0
 \$240

 Sub-Total:
 \$240
 \$0
 \$0
 \$240

Operating Impact: Increase: \$0 Decrease: \$0

The existing Receiving Gate sallyport loading dock doors have exceeded their normal life expectancy. Numerous mechanical brakdowns and physical damage make them a constant maintenance problem. These doors operate seven (7) days a week and are damaged by the heavy equipment (forklifts, pallets, etc.) used on the dock. All supplies enter the institution through these doors. Therefore failure of these units would severly impact the operation of the institution. This project is for the replacement of the six (6) doors and the installation of a new electronic locking system.

MOUNTAINVIEW YOUTH CORRECTIONAL FACILITY

NEW CANTEEN BUILDING.

LOCATION: NEW BUILDING SITE

Dept Priority 139 Project ID: 26-033

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$1,084
 \$0
 \$0
 \$1,084

 Sub-Total:
 \$1,084
 \$0
 \$0
 \$1,084

Operating Impact: Increase: \$0 Decrease: \$0

To design and construct a new building approximately 2,800 sq.ft. to be used as a canteen store. Presently, the canteen store is overcrowded and provides insufficient room to store merchandise and work efffectively. As of October, 1998, the Department no longer allows inmates to receive food packages. Therefore, the Canteen has increased inventory to accommodate this change. This cannot be done successfully without expanded space.

Section III-A, Page 72 REQ-04: Page 48 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

NEW PUBLIC ADDRESS SYSTEM

LOCATION: FACILITY WIDE

Dept Priority 140

Project ID: 26-022

Project Type Code: A01 Project Type Description: Preservation-Electrical

General:	\$646	\$0	\$0	\$0	\$646
Sub-Total:	\$646	\$0	\$0	\$0	\$646

Operating Impact: Increase: \$0 Decrease: \$0

To install a PA system to all housing units and buildings throughout the facility, recreation and work areas. The system would be operated in Center Control allowing all points to be notified at once, interacting with housing units for return voice and paging. EMCFW does not now have the capability to reach all posts and areas at one time. Communication is by telephone and an all points alert for an emergency takes approx. 20 minutes, requiring several staff members. Center Control has only one override extension to interrupt a call. Mobile radio communication equipment is not available for all areas and would be cost prohibitive. All other facilities have an "all call" code system alert of some kind. Not having one at this facility with maximum security inmates equal in sentencing time with NJSP inmates is a serious security and safety breach. Minimal response time by staff in an emergency is crucial in addressing emergent matters.

BAYSIDE STATE PRISON

BOILER TRIM & FEED WATER SYSTEM

LOCATION: POWER HOUSE

Dept Priority 141 Project ID: 26-222

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

General:	\$650	\$0	\$0	\$0	\$650
Sub-Total:	\$650	\$0	\$0	\$0	\$650

Operating Impact: Increase: \$0 Decrease: \$0

Engineer and install a new feed water tank and control, new steam fed water pump, a centrifugal pump and soft start control to the boiler feed water system. In addition, provide oxygen boiler trim microprocessor systems and computerized Hawk Systems to all boilers. Finally, a blowdown heat recovery system, which will recover 90% of heat normally lost through blowdown, should be installed. The oxygen system will adjust fuel and oxygen mixture in the burners, which will reduce emission and fuel costs. The Hawk System provides operating data to the Operating Engineer on the various internal systems of the boilers. The existing boiler feed water system is over 30 years old and has failed several times, interrupting feed water to the boiler, which resulted in the loss of heat. The feed water control system also has parts that are obsolete.

Section III-A, Page 73 REQ-04: Page 49 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

NEW MAINTENANCE BUILDING

LOCATION: NEW BUILDING SITE

Dept Priority 142

Project ID: 26-030

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$837
 \$0
 \$0
 \$837

 Sub-Total:
 \$837
 \$0
 \$0
 \$0
 \$837

Operating Impact: Increase: \$0 Decrease: \$0

To design & Design &

CONTINUED IN EXPLANATION BLOCK.

GARDEN STATE RECEPTION AND YOUTH CORRECTIONAL FACI

STORM WATER OUTFALL REPAIR

LOCATION:

Dept Priority 143 Project ID: 26-330

Project Type Code: C03 Project Type Description: Environmental-Wastewater Treatment

 General:
 \$125
 \$0
 \$0
 \$125

 Sub-Total:
 \$125
 \$0
 \$0
 \$125

Operating Impact: Increase: \$0 Decrease: \$0

This project calls for the removal of debris from the outfall area surrounding the storm water collection system outfall. The area will then be built-up with large rock and/or rip rap rock formation to protect the area from additional debris collecting.

BAYSIDE STATE PRISON

REPLACEMENT OF FUEL TANKS

LOCATION: OIL STORAGE TANK AREA

Dept Priority 144
Project ID: 26-042

Project Type Code: C01 Project Type Description: Environmental-Hazardous Substances

 General:
 \$868
 \$0
 \$0
 \$868

 Sub-Total:
 \$868
 \$0
 \$0
 \$0
 \$868

Operating Impact: Increase: \$0 Decrease: \$0

Remove three single wall diesel heating tanks and piping. Install three 20,000 gallon above ground double walled tanks with monitoring controls. The existing tanks do not comply with current DEP or EPA regulations and are over 40 years old.

Section III-A, Page 74 REQ-04: Page 50 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED
FY - 2011	FY- 2012

REQUESTED FY - 2013

REQUESTED FY 2014 - 2017

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

GYM FLOOR REPLACEMENT

LOCATION: GYMNASIUM

\$0

Dept Priority 145

Project ID: 26-009

Project Type Code: A06 Project Type Description: Preservation-Other

General:

\$176 Sub-Total: \$176

\$0 \$0 \$0 \$0

\$176 \$0 \$0 \$176

\$884

\$884

Operating Impact:

Increase:

\$0 Decrease:

Remove the old and installation of a new floor in the gym. The gym roof leaked for a period of approximately five (5) years before the roof was replaced. This leaking completely destroyed the wooden gym floor. The floor boards are warped and very rough and even sanding does not help. The moisture has also gotten under the wooden floor boards and will not dissipate causing this warping to continually change. The condition of this floor constitutes a safety hazard. The only possible way to correct this is to replace the entire floor.

BAYSIDE STATE PRISON

HEATING SYSTEM CONVERSION, COTTAGES 1-13, MINIMUM

LOCATION: MINIMUM UNIT

Dept Priority 146

Project ID: 26-249

Project Type Code: F01

Project Type Description: Infrastructure-Energy Improvements

General:

General.	\$004
Sub-Total:	\$884

\$0	\$0	

\$0 Decrease: Operating Impact: Increase:

Engineering and installation of a steam heat system for cottages 1 - 13 at the Minimum Unit. The SOW for the project includes: 1) a tankless, central steam/hot water loop distribution system to the cottages; 2)the removal of gas heaters and hot water heaters from each cottage and 3) the installation of steam air handler units for each cottage.

\$0

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

FOOD SERVICE FACILITY UPGRADES

LOCATION: FOOD SERVICE BUILDING

\$0

Dept Priority 147

Project ID: 26-113

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

\$0

\$0

General:

Sub-Total: \$29,747

\$29,747

\$0 \$0

\$29,747 \$0 \$0 \$29,747

\$0

\$0

Operating Impact:

Increase:

\$0

Decrease: \$0

Modernization of the existing kitchen with an expansion into the inmate dining hall. Over the years as population has expanded, the food service area has been pressed to the limit with its ability to feed both the inmates and staff of three major State institutions. The entire food service building must be expanded to accommodate the current demands. Health and safety problems with the present structure are becoming critical.

> REQ-04: Page 51 of 64 Section III-A, Page 75

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

BAYSIDE STATE PRISON

EXPAND VISIT LOBBY, MEDIUM UNIT

LOCATION: MEDIUM UNIT

Dept Priority 148

Project ID: 26-301

Project Type Code: E02 Proje

Project Type Description: Construction-New

 General:
 \$189
 \$0
 \$0
 \$189

 Sub-Total:
 \$189
 \$0
 \$0
 \$189

Operating Impact: Increase: \$0 Decrease: \$0

Convert the room adjacent to the current visit lobby at the Medium Facility to additional visit space. This project would require architectural and engineering services to address all code related issues. The current visit room was designed to accommodate visits for 550 inmates. The present population at the Medium Facility exceeds 1,200. As the number of visitors has increased along with the population, it has become necessary to terminate visits early to accommodate all family members that arrive at the institution within the time frame established, to have their visit. When an inmate"s visit is terminated early it causes anxiety for both the inmate and his family. The addition of this room would allow all visits to continue until visiting hours are over.

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

WINDOW REPLACEMENT, COTTAGE C

LOCATION: COTTAGE C

Dept Priority 149

Project ID: 26-213

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$365
 \$0
 \$0
 \$365

 Sub-Total:
 \$365
 \$0
 \$0
 \$365

Operating Impact: Increase: \$0 Decrease: \$0

Cottage C has been designated as a housing unit for special needs inmates. The forty (40) cell windows and various common area glass needs to be replaced. These replacements will increase security, conserve energy and provide a more aesthetic and compassionate look, consistant with program goals.

ALBERT C. WAGNER YOUTH CORRECTIONAL FACILITY

HVAC UPGRADE. OFFICERS DINING ROOM

LOCATION: OFFICERS DINING ROOM

Dept Priority 150 Project ID: 26-246

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$440
 \$0
 \$0
 \$440

 Sub-Total:
 \$440
 \$0
 \$0
 \$0
 \$440

Operating Impact: Increase: \$0 Decrease: \$0

The Department has contracted with a Mechanical Engineering firm to investigate the HVAC systems for the staff dining area and adjacent offices in conjunction with the ventilation in the kitchen. The Department will initiate a construction project to upgrade these systems, based on the recommendations of the consultant.

Section III-A, Page 76 REQ-04: Page 52 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

7 YR PROG FY - 2011 FY - 2012 FY - 2013 FY 2014 - 2017	TOTAL COST 7 YR PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
--	-------------------------	------------------------	-----------------------	------------------------	---------------------------------

BAYSIDE STATE PRISON

DUCTWORK REPLACEMENT, HOUSING A-F

LOCATION: MEDIUM UNITS A-F

Dept Priority 151

Project ID: 26-089

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

\$1,681 \$0 \$0 \$0 \$1,681 General: Sub-Total: \$1,681 \$0 \$0 \$0 \$1,681

\$0 \$0 Operating Impact: Increase: Decrease:

Engineer and install new insulated ductwork, dampers, sump pumps and lighting fixtures in the basements of each unit. The system provides make-up air in the housing units. The existing ductwork has become inoperable due to severe rusting creating holes which allows head and make-up fresh air to escape into the basements.

EAST JERSEY STATE PRISON

DRILL HALL FLOOR REPLACEMENT

LOCATION: DRILL HALL

Dept Priority 152 Project ID: 26-013

Project Type Code: A06 Project Type Description: Preservation-Other

\$451 General: \$0 \$0 \$0 \$451 Sub-Total: \$451 \$0 \$0 \$0 \$451

\$0 Operating Impact: Increase: Decrease: \$0

Replace the flooring in Drill Hall which has been damaged due to roof leaks. The Drill Hall is the only indoor recreational area for the entire institution of approximately 1,700 inmates. The floor has holes and many not repairable, loose floor boards which create a severe safety hazard. This project would provide the inmates with a safe environment for recreation as well as prevent possible future litigation costs. Sections of the Drill Hall are not able to be used to their full extent due to the damaged floor, causing a decrease in inmate's use of the facility.

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

CENTER CONTROL BUILDING, RENOVATION/REPLACEMENT

LOCATION: CENTER CONTROL COTTAGE

Dept Priority 153 Project ID: 26-128

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

\$6,339 General: \$0 \$0 \$0 \$6,339 \$0 Sub-Total: \$6,339 \$0 \$0 \$6,339

Operating Impact: Increase: \$0 Decrease: \$0

To conduct a study to determine the feasibility of renovating the existing (Thompson Hall) or constructing a new center control building to include offices, line up room, locker rooms with toilet and shower facilities for male and female correction offficers and an upper level center control area with a 360 degree view. The present building is inadequate to handle all security functions as well as support additional staff. The control officer view window is below the grade of the maximum security area. Also, the present building infrastructure is unable to support a constantly increasing demand as well as the need for sophisticated security equipment. As a result of population expansion which required additional staff in Center Control, as well as various equipment modifications that have occurred or are scheduled to occur shortly (e.g., new emer. telephone equip. console, fire alarm controls, radio control system and All Call Intercom system), the institution is operating with an inefficient and uncoordinated center design.

> REQ-04: Page 53 of 64 Section III-A, Page 77

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

EAST JERSEY STATE PRISON

EXPAND FRONT HOUSE, EMPLOYEE DINING&RECORD STORAGE

LOCATION: FRONT HOUSE/STAFF DINING ROOM

Dept Priority 154

Project ID: 26-031

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$1,678
 \$0
 \$0
 \$1,678

 Sub-Total:
 \$1,678
 \$0
 \$0
 \$1,678

Operating Impact: Increase: \$0 Decrease: \$0

Design and construct an expansion to the front house, employee dining room and record retention storage. Due to the expansion of the prison population (both employee and inmate), existing employee office space, record retention storage and employee dining/break areas are inadequate. It is possible that employee office space is in violation of OSHA standards concerning minimum allocation of work area per employee. This overcrowding is compounded by the increased demand for space created by the wide scale use of computers and the very large volume of general record-keeping mandated by various regulations. Due to this overcrowding, some of the office areas have been supplemented by office trailers, but this is only a temporary stop-gap measure. The Classification Office is also undersized for the required number of employees and file storage area. Currently storage space is being utilized in other buildings within the compound which makes the search for information very time consuming and inefficient.

BAYSIDE STATE PRISON

NEW SEWAGE SYSTEM, TOWERS 7 & 8

LOCATION: MEDIUM UNIT

Dept Priority 155
Project ID: 26-224

Project Type Code: C

Project Type Code: C03 Project Type Description: Environmental-Wastewater Treatment

 General:
 \$465
 \$0
 \$0
 \$465

 Sub-Total:
 \$465
 \$0
 \$0
 \$465

Operating Impact: Increase: \$0 Decrease: \$0

Installation of a new sewerage system at Towers 7 and 8 that will tie into the existing facility sewage treatment system. An Environmental Engineer has designed a system, however funding has not been available to complete the project. At the present time, the towers have a septic system that must be emptied every week.

BAYSIDE STATE PRISON

FIRE TUBE STEAM BOILER

LOCATION: POWER HOUSE

Dept Priority 156 Project ID: 26-131

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$684
 \$0
 \$0
 \$684

 Sub-Total:
 \$684
 \$0
 \$0
 \$0
 \$684

Operating Impact: Increase: \$0 Decrease: \$0

Install one Clever-Brooks, or equal, boiler on the existing pad in the boiler house. Boiler rating must be 45,000 pounds per hour with a maximum steam pressure of 250 PSI, all critical Power House connections presently exist for installation of this boiler. A new boiler will result in significant savings and assist in meeting the present pollution standards.

Section III-A, Page 78 REQ-04: Page 54 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

	TOTAL COST 7 YR PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
--	-------------------------	------------------------	-----------------------	------------------------	---------------------------------

EAST JERSEY STATE PRISON

REPLACE WASTEWATER COLLECTION SYSTEM, WINGS 1 & 4

LOCATION: WINGS 1 & 4

Dept Priority 157

Project ID: 26-254

Project Type Code: C03 Project Type Description: Environmental-Wastewater Treatment

 General:
 \$1,129
 \$0
 \$0
 \$1,129

 Sub-Total:
 \$1,129
 \$0
 \$0
 \$1,129

Operating Impact: Increase: \$0 Decrease: \$0

This project is for replacement of the wastewater collection system in Wings 1 and 4 of the facility. The Scope of Work for the project includes the installation of a flow meter and sewage grinder on the connection of these systems to the main line of the facility.

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

HEAT REZONING

LOCATION: VARIOUS BUILDINGS

Dept Priority 158
Project ID: 26-053

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$784
 \$0
 \$0
 \$784

 Sub-Total:
 \$784
 \$0
 \$0
 \$0
 \$784

Operating Impact: Increase: \$0 Decrease: \$0

Create five separate heat zones in the Administration and four each in the Silzer, Conover and Williamson Buildings. This project would provide a more even distribution of heat and would realize a substantial energy savings after a payback period of four to five years.

BAYSIDE STATE PRISON

PNEUMATIC HEAT CONTROL REPLACEMENTS, ANCORA

LOCATION: WILLOW & SPRUCE HALLS

Dept Priority 159 Project ID: 26-082

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$465
 \$0
 \$0
 \$465

 Sub-Total:
 \$465
 \$0
 \$0
 \$465

Operating Impact: Increase: \$0 Decrease: \$10

Upgrade the existing heating system at the Willow and Spruce HallS with the installation of pneumatic controls. The existing systems are non-functional, which result in over heating the buildings. The new system will reduce fuel costs and provide climate control.

Section III-A, Page 79 REQ-04: Page 55 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

EAST JERSEY STATE PRISON

STORM WATER SYSTEM IMPROVEMENTS

LOCATION:

Dept Priority 160

Project ID: 26-306

Project Type Code: C03 Project Type Description: Environmental-Wastewater Treatment

 General:
 \$750
 \$0
 \$0
 \$750

 Sub-Total:
 \$750
 \$0
 \$0
 \$750

Operating Impact: Increase: \$0 Decrease: \$0

In July 2004 the DOC embarked on a statewide program to ensure that all facilities attained compliance with the NJDEP Municipal Separate Storm Sewer System regulations. Technical assistance was supplied by a Consultant contracted under the Department's Agency Consultant Program. As part of the Year 2 requirements for these regulations, the consultant has identified several areas of concern regarding stormwater and erosion concerns at the East Jersey facility. The existing swale that runs immediately north of the facility perimeter wall is in a continued state of deterioration. There is significant erosion exposing various stormwater pipe outfalls into a pond on facility grounds. Finally the existing culvert system, between the facility access road and the pond is deteriorating. This project is requesting funds to engineer and construct the various repairs to stabilize the aforementioned areas.

BAYSIDE STATE PRISON

HYDRONIC HEATING SYSTEM REPLACEMENT, EAST ARCADE

LOCATION: MEDIUM UNIT

Dept Priority 161

Project ID: 26-261

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$291
 \$0
 \$0
 \$291

 Sub-Total:
 \$291
 \$0
 \$0
 \$291

Operating Impact: Increase: \$0 Decrease: \$0

Replace the hydronic heat system in the East Arcade. The existing heat system piping was installed 30 years ago and supplies the heat to the entire East Arcade from the Classification Area mechanical room. The piping has been repaired several times, however it is still leaking, which causes a loss of heat to this area. Each time repairs are made the staff must relocate until the heat is restored. This creates a disruption in the operation of the facility.

EAST JERSEY STATE PRISON

HVAC UPGRADE, VISIT BUILDING

LOCATION: MAIN COMPLEX

Dept Priority 162 Project ID: 26-091

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$337
 \$0
 \$0
 \$337

 Sub-Total:
 \$337
 \$0
 \$0
 \$0
 \$337

Operating Impact: Increase: \$0 Decrease: \$0

Engineer and install an upgraded air handling system to better maintain control of the HVAC system in the Visit Building. Currently the building is being used for visits at all times and on hot, humid days the unit becomes very uncomfortable. With better airflow throughout the building a safer environment for health and security can be provided. The building could also be used for more programs and activities if the air quality were improved.

Section III-A, Page 80 REQ-04: Page 56 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

BAYSIDE STATE PRISON

REPLACEMENT OF STEAM HOT WATER HEATERS, ANCORA

LOCATION: WILLOW & SPRUCE HALLS

Dept Priority 163

Project ID: 26-086

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

General:	\$779	\$0	\$0	\$0	\$779
Sub-Total:	\$779	\$0	\$0	\$0	\$779

Operating Impact: Increase: \$0 Decrease: \$0

The replacement of the steam generated hot water heaters in Barracks 2 and 5, and the kitchen building at the Minimum unit, as well as the heaters in Spruce and Willow Halls at Ancora. Due to their size, the heaters must be housed in separate concrete buildings. The existing hot water heaters at Spruce and Willow Halls should be replaced with 2 self-contained units. The replacement of these units is necessary due to their age and condition. The barracks units were installed in 1950 and are used to supply hot water for personal hygiene. The kitchen unit was also installed in 1950. The existing units at the Spruce and Willow Halls have developed leaks. In the event of failure, mobile rental units will be required.

EAST JERSEY STATE PRISON

ACSU FENCE SHAKER SYSTEM REPLACEMENT

LOCATION: ACSU

Dept Priority 164

Project ID: 26-332

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

General:	\$450	\$275	\$0	\$0	\$175
Sub-Total:	\$450	\$275	\$0	\$0	\$175

Operating Impact: Increase: \$0 Decrease: \$0

The Scope of Work for this project calls for the replacement of the existing intrusion detection system on the Administrative Close Supervision Unit"s perimeter fence with a state of the art detection system. The manufacturer of the existing system no longer manufactures replacement components for the system.

BAYSIDE STATE PRISON

CONSTRUCT TRAINING FACILITY

LOCATION:

Dept Priority 165 Project ID: 26-226

Project Type Code: E02 Project Type Description: Construction-New

General:	\$650	\$0	\$0	\$0	\$650
Sub-Total:	\$650	\$0	\$0	\$0	\$650

Operating Impact: Increase: \$0 Decrease: \$0

Purchase and install a modular steel building approximately 28' X 70' to be used as classroom and office space. Existing 400 amp electrical power will be utilized. Water and sewage system tie-ins are required.

Section III-A, Page 81 REQ-04: Page 57 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

EAST JERSEY STATE PRISON

ACSU SHOWER DOOR & WINDOW REPLACEMENT

LOCATION: ACSU

Dept Priority 166

Project ID: 26-333

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$225
 \$0
 \$0
 \$225

 Sub-Total:
 \$225
 \$0
 \$0
 \$0
 \$225

Operating Impact: Increase: \$0 Decrease: \$0

The Scope of Work for this project calls for the replacemnet of the exterior windows and the doors to the inmate showers of the Administrative Close Supervision Unit (ACSU).

BAYSIDE STATE PRISON

CONVERT RESTROOMS TO COMPLY WITH ADA

LOCATION: FACILITY WIDE

Dept Priority 167 Project ID: 26-207

Project Type Code: B01 Project Type Description: Compliance-ADA

 General:
 \$1,673
 \$0
 \$0
 \$1,673

 Sub-Total:
 \$1,673
 \$0
 \$0
 \$1,673

Operating Impact: Increase: \$0 Decrease: \$0

Complete renovation of piping, walls and doors in all visit room and staff bathrooms throughout Bayside proper. The bathrooms at the Medium, Minimum and Ancora Units must be renovated to comply with ADA codes.

EDNA MAHAN CORRECTIONAL FACILITY FOR WOMEN

CENTRALIZED LAUNDRY SYSTEM

LOCATION:

Dept Priority 168

Project ID: 26-331

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$250
 \$0
 \$0
 \$250

 Sub-Total:
 \$250
 \$0
 \$0
 \$250

Operating Impact: Increase: \$0 Decrease: \$0

This project calls for the renovation of existing space to create a centralized laundry at the Edna Mahan facility.

Section III-A, Page 82 REQ-04: Page 58 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

REQUESTED

FY - 2013

TOTAL COST	l
TOTAL COST 7 YR PROG	

REQUESTED	REQUESTED
FY - 2011	FY- 2012

REQUESTED FY 2014 - 2017

EAST JERSEY STATE PRISON

REPLACE ADMINISTRATION BUILDING COMPOUND GATES

LOCATION: ADMINISTRATION BUILDING

Dept Priority 169

Project ID: 26-334

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$75
 \$0
 \$0
 \$75

 Sub-Total:
 \$75
 \$0
 \$0
 \$75

Operating Impact: Increase: \$0 Decrease: \$0

To engineer and install new gates at the entrances to the Administration Building Compound at the East Jersey facility. The work would include, but not be limited to the replacement of gates and gate operators as well as the relocation of the units.

BAYSIDE STATE PRISON

SECURITY TYPE BILCO DOORS-UNITS A-F

LOCATION: MEDIUM UNIT

Dept Priority 170 Project ID: 26-077

Project Type Code: E03 Project Type Description: Construction-Renovations and Rehabilitation

 General:
 \$605
 \$0
 \$0
 \$605

 Sub-Total:
 \$605
 \$0
 \$0
 \$605

Operating Impact: Increase: \$0 Decrease: \$0

The installation of concrete steps with security Bilco doors. Currently, the entrance to the basement of each housing unit is through a hatchway that is considered a confined space. Also, to perform any major maintenance work (for example removing piping) a wall must be removed to gain entrance.

EAST JERSEY STATE PRISON

REPAVING PARKING LOTS & ROADWAYS

LOCATION: PARKING LOTS & ROADWAYS

Dept Priority 171

Project ID: 26-335

Project Type Code: F02 Project Type Description: Infrastructure-Roads and Approaches

 General:
 \$175
 \$0
 \$0
 \$175

 Sub-Total:
 \$175
 \$0
 \$0
 \$175

Operating Impact: Increase: \$0 Decrease: \$0

To repair/install roads and parking lots. These repairs are necessary to maintain operations and have been scaled down to represent essential needs. Various entrance and perimeter roads and parking lots are in a serious state of disrepair. The facilities continue to patch pot holes as they appear, but a long range solution to this problem must be found. The maintenance of the DOC"s road system is not just a convenience for the employees. It is also a security necessity due to the use of the road system for patrol of security perimeters and the access provided to the facilities for vendors, supplies, food service deliveries and various law enforcement personnel.

Section III-A, Page 83 REQ-04: Page 59 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

BAYSIDE STATE PRISON

NEW MAINTENANCE BUILDING

LOCATION: MEDIUM UNIT

Dept Priority 172

Project ID: 26-035

Project Type Code: E02 Project Type Description: Construction-New

\$4,469 \$0 \$0 General: \$0 \$4,469 Sub-Total: \$4,469 \$0 \$0 \$0 \$4,469

\$0 \$20 Operating Impact: Increase: Decrease:

To construct a 25,000 sq. ft. maintenance facility outside of the security perimeter to accommodate all of the maintenance shops, offices, conference room and material storage. BSP now has two small maintenance facilities located a mile apart. This makes managerial control difficult and causes constant disruption of operations when even one person is not on duty. Also, total duplication of all machinery, tools, equipment and materials is necessary. Ordering of material and stock is duplicated with the resultant loss of man hours. Combining the two facilities will result in each shop having the opportunity to establish its priorities and send staff out each day on the critical items. The problem of having maintenance located inside the secure perimeter will be eliminated and security will be enhanced.

BAYSIDE STATE PRISON

NEW SEWAGE FORCE MAIN, TRAINING AREAS

LOCATION: TRAINING AREAS

Dept Priority 173 Project ID:

26-081

Project Type Code: C03 Project Type Description: Environmental-Wastewater Treatment

\$1,354 \$0 \$0 \$0 General: \$1,354 Sub-Total: \$1,354 \$0 \$0 \$0 \$1,354

\$0 Decrease: \$3 Operating Impact: Increase:

Engineer and installation of a sewage pump station with adequately sized force mains at the Training Trailer. The force mains will tie the area into the existing sewage collection system for the complex. The Training Trailer presently is served by a 200 gallon above ground sewage holding tank that must be pumped out weekly.

BAYSIDE STATE PRISON

COMPUTERIZED ENERGY MANAGEMENT SYSTEM

LOCATION: BAYSIDE & SOUTHERN STATE

Dept Priority 174 Project ID: 26-093

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

\$1,022 \$1,022 General: \$0 \$0 \$0 \$1,022 \$0 \$0 \$0 \$1,022 Sub-Total:

Operating Impact: \$0 Decrease: \$0 Increase:

Engineer and install an Energy Management System which will turn air-handler units on/off, reset schedule and control lighting system, etc... This will include a comprehensive Preventive Maintenance Program, in which a software designer will incorporate all of Bayside's equipment. The Energy Management System will print out work orders to service equipment per manufacturer's specification on a timely schedule. The system will also calculate savings of all systems. The existing control system is non-functional, which results in over heating of the buildings. The new system will reduce fuel costs and provide climate control.

> REQ-04: Page 60 of 64 Section III-A, Page 84

Department of Corrections

Agency Capital Budget Request

(000's)

REQUESTED FY 2014 - 2017

TOTAL COST		RE
7 YR PROG		

EQUESTED	REQUESTED	REQUESTED
FY - 2011	FY- 2012	FY - 2013

BAYSIDE STATE PRISON

NEW UTILITY SERVICE

LOCATION: DAIRY FARM

Dept Priority 175

Project ID: 26-134

Project Type Code: A01

Project Type Description: Preservation-Electrical

 General:
 \$1,036
 \$0
 \$0
 \$1,036

 Sub-Total:
 \$1,036
 \$0
 \$0
 \$1,036

Operating Impact: Increase: \$0 Decrease: \$0

Engineer and install a new utility service from Route 47 to the Dairy. A stand by emergency generator would be included.

BAYSIDE STATE PRISON

LAUNDRY WATER RECYCLE/TREATMENT SYSTEM

LOCATION: MEDIUM & MINIMUM UNITS

Dept Priority 176
Project ID: 26-087

Project Type Code: C03 Project Type Description: Environmental-Wastewater Treatment

 General:
 \$232
 \$0
 \$0
 \$232

 Sub-Total:
 \$232
 \$0
 \$0
 \$0
 \$232

Operating Impact: Increase: \$0 Decrease: \$20

Retrofit the Medium and Minimum Unit laundries with a process called Ultrafiltration Membrane Module. This system will recycle 80% of the water that is used in the laundry.

BAYSIDE STATE PRISON

SOLAR DOMESTIC HOT WATER SYSTEM

LOCATION: MEDIUM UNIT

Dept Priority 177
Project ID: 26-088

Project Type Code: F01 Project Type Description: Infrastructure-Energy Improvements

 General:
 \$593
 \$0
 \$0
 \$593

 Sub-Total:
 \$593
 \$0
 \$0
 \$593

Operating Impact: Increase: \$0 Decrease: \$30

Engineer and install solar panels on the Medium Unit roof to provide domestic hot water. Steam will be the secondary fuel source for the days when solar is not available.

Section III-A, Page 85 REQ-04: Page 61 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

BAYSIDE STATE PRISON

NEW STAFF DINING HALL, MINIMUM UNIT

LOCATION: MINIMUM UNIT

Dept Priority 178

Project ID: 26-084

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$750
 \$0
 \$0
 \$750

 Sub-Total:
 \$750
 \$0
 \$0
 \$750

Operating Impact: Increase: \$0 Decrease: \$0

Design and construct a 3,000 square foot addition to the Minimum Unit staff dining room. This expansion will include a new block structure, food service equipment and furniture to accommodate 50 staff. Since the dining hall was constructed, the Minimum Unit inmate population has doubled, which resulted in additional staff. The existing dining hall cannot accommodate the increased staffing.

BAYSIDE STATE PRISON

NEW ADMINISTRATIVE BLDG., MEDIUM UNIT

LOCATION: MEDIUM UNIT

Dept Priority 179
Project ID: 26-029

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$1,616
 \$0
 \$0
 \$1,616

 Sub-Total:
 \$1,616
 \$0
 \$0
 \$1,616

Operating Impact: Increase: \$0 Decrease: \$0

To construct a masonry type building of approximately 5,000 sq. ft. to be completely air conditioned with necessary fixtures and furnishings. In keeping with the DOC's policy to relocate the Classification Office, the SID Office and the institutional Pharmacy to a location outside the security area, it is proposed that an addition to the administration building be constructed which will house the office of the Administrator, the entire Business Office and possibly other administrative offices. Upon completion, the Classification, Internal Affairs and/or Pharmacy will then be relocated to the areas now occupied by the Administrator and Business Office. This request also includes the construction of arsenal space to address new security standards and increased storage requirements.

BAYSIDE STATE PRISON

CONSTRUCT MULTI-PURPOSE BLDG.. ANCORA UNIT

LOCATION: ANCORA UNIT

Dept Priority 180 Project ID: 26-020

Project Type Code: E02 Project Type Description: Construction-New

 General:
 \$2,046
 \$0
 \$0
 \$2,046

 Sub-Total:
 \$2,046
 \$0
 \$0
 \$0
 \$2,046

Operating Impact: Increase: \$0 Decrease: \$0

In May 1987, a second unit was opened at the Ancora site for the housing of inmates assigned to BSP. This expansion increased the total population at the Ancora Unit to 350 inmates. The visit program is currently held in the dayrooms of both Willow and Spruce Halls, directly adjacent to the housing units. This situation creates a security risk. In addition, the storage space for supplies and equipment, needed to maintain these units is insufficient. This request is for the construction of a pre-fabricated structure of approximately 25,000 sq. ft. to be used for the visit program and provide the Maintenance Department with a shop equipped with the supplies needed to effect repairs at the unit. Failure to fund this request will allow the security problems and inefficient maintenance operation to continue.

Section III-A, Page 86 REQ-04: Page 62 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

7 YR PROG FY - 2011 FY - 2012 FY - 2013 FY 2014 - 2017	TOTAL COST 7 YR PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
--	-------------------------	------------------------	-----------------------	------------------------	---------------------------------

BAYSIDE STATE PRISON

COMPOST SYSTEM - WASTEWATER

LOCATION: WASTEWATER TREATMENT PLANT

Dept Priority 181

Project ID: 26-044

Project Type Code: C03 Project Type Description: Environmental-Wastewater Treatment

 General:
 \$593
 \$0
 \$0
 \$593

 Sub-Total:
 \$593
 \$0
 \$0
 \$593

Operating Impact: Increase: \$0 Decrease: \$80

Install a containerized compost system that is portable and will meet all requirements of Bayside's NJDEP sludge application. Bayside sludge is approved by NJDEP for land application. With this system both sludge and food waste would be composted and applied to Bayside's fields. This system would also allow the facility to comply with the Executive Order to recycle foodwaste and sludge.

BAYSIDE STATE PRISON

REPLACE TOILETS & SINKS, MEDIUM UNIT (CONSTR.)

LOCATION: MEDIUM UNIT

Dept Priority 182 Project ID: 26-228

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$1,172
 \$0
 \$0
 \$1,172

 Sub-Total:
 \$1,172
 \$0
 \$0
 \$1,172

Operating Impact: Increase: \$0 Decrease: \$0

Replace damaged and temporarily repaired toilets and sinks in the 504 cells, the East and West Arcades, Kitchen, Trailers and Industrial Area. Over 40% of the toilets and sinks are in unrepairable condition and have reached an unsatisfactory health rating.

BAYSIDE STATE PRISON

ROADS AND APPROACHES

LOCATION:

Dept Priority 183

Project ID: 26-263

Project Type Code: F02 Project Type Description: Infrastructure-Roads and Approaches

 General:
 \$975
 \$0
 \$0
 \$975

 Sub-Total:
 \$975
 \$0
 \$0
 \$975

Operating Impact: Increase: \$0 Decrease: \$0

To repair/install roads and parking lots. These repairs are necessary to maintain operations and have been scaled down to represent essential needs. Various entrance and perimeter roads and parking lots are in a serious state of disrepair. The facilities continue to patch pot holes as they appear, but a long range solution to this problem must be found. The maintenance of the DOC's road system is not just a convenience for the employees. It is also a security necessity due to the use of the road system for patrol of security perimeters and the access provided to the facilities for vendors, supplies, food service deliveries and various law enforcement personnel. Areas that require work at BSP are: the steam line access road from Minimum Unit to Medium Unit entrance road; areas behind Housing Units A-F; the sawmill road; a new perimeter road at the Medium Unit; paving the dirt road connecting the Medium and Minimum Units repaving the Medium Unit entrance road from Route 47; repaving the Administrator's and Assistant Superintendent's residence driveways and repaving the Dairy and MinimumUnit roadways.

Section III-A, Page 87 REQ-04: Page 63 of 64

Department of Corrections

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

Totals For: Department of Corrections

General:	\$1,146,786	\$301,555	\$145,697	\$501,278	\$198,256	
Bond:	\$0	\$0	\$0	\$0	\$0	
Federal:	\$0	\$0	\$0	\$0	\$0	
Other:	\$0	\$0	\$0	\$0	\$0	
Sub-total:	\$1,146,786	\$301,555	\$145,697	\$501,278	\$198,256	

Section III-A, Page 88 REQ-04: Page 64 of 64

DEPARTMENT OF EDUCATION

EDUCATION

Overview

The primary mission of the Department of Education is to provide leadership within the public school system to ensure that all students receive a meaningful and effective education. The Department provides direction for improvements in all school districts through the Core Curriculum Content Standards and by fostering an education system that emphasizes success through flexibility, innovation, and collaboration.

The Department's primary objectives are to ensure a "thorough and efficient" education for all children between the ages of five and eighteen and to provide maintenance and support for the system of free public schools in New Jersey. The Department is responsible for ensuring accountability for public dollars by motivating schools to provide high-quality, cost-efficient programs, including a safe and drug-free learning environment. To assure accountability, the Department sets standards and assessments to determine student achievement levels and offers assistance in achieving the established goals and objectives.

In addition to overseeing the operation of all public schools, the Department is responsible for managing the Marie H. Katzenbach School for the Deaf and for administering the 10 Regional Day Schools for special needs students.

Educational Reform

The New Jersey Constitution guarantees that children, regardless of residency, will receive a "thorough and efficient" education. As a result of the New Jersey Supreme Court's *Abbott v. Burke* decision, the State was ordered to provide an equal educational opportunity for children from Abbott districts (special needs districts) comparable to the more affluent school districts, by insuring an equitable level of funding. Consequently, the State designed the Quality Education Act (QEA), and later developed the Comprehensive Educational Improvement and Financing Act (CEIFA) to address fiscal inequities between the urban poor and wealthy suburban districts. Finally, in 2008, the State designed the School Funding Reform Act (SFRA) to guarantee an equitable, transparent, and predictable funding methodology.

In addition to funding reform, the State designed the Core Curriculum Content Standards in 1996. These standards determine what students should know, after completing a thirteen-year public education program, in the areas of visual and performing arts, health and physical education, language arts, mathematics, science, social studies, and world languages. In the 2003-2004 school year, the standards were revised to include consumer, family, and life skills, and technology and career education to provide an awareness and exploration of occupations and professions.

School Construction and Renovation Program

The Court also found that a thorough and efficient education requires adequate facilities. In addition to curriculum standards, the Court directed the State to review the facility needs of schools in Abbott districts and to provide solutions on how to address such needs – independent of the district's willingness or ability to raise taxes or incur debt.

In compliance with *Abbott v. Burke*, the State developed facility needs in the 31 Abbott districts for instructional and administrative space in elementary, middle, and high schools. These facility standards provided the definition of "efficient" in the context of the "thorough and efficient" constitutional guarantee.

Once the magnitude of the need was established, the New Jersey Legislature passed the *Educational Facilities Construction and Financing Act*, providing a total of \$8.6 billion in State issued debt to be authorized for construction and renovation of schools in all districts, including \$2.6 billion in non-Abbott districts, \$100 million of which is reserved for county vocational schools. In 2008, an additional \$3.9 billion in funds was authorized: \$2.9 billion for Abbott districts and \$1 billion for regular operating districts. This funding, one of the largest and most comprehensive school construction programs in the nation, provides 100 percent of approved construction costs for Abbott schools and guarantees minimum State support of 40 percent of approved project costs in all other school districts.

Marie H. Katzenbach School for the Deaf

The Department of Education operates the Marie H. Katzenbach School for the Deaf. This school offers educational and vocational services, from birth through twelfth grade, to deaf and disabled deaf children. Residential services are provided for 43% of the school's 183 students on a five-day-a-week basis.

Regional Day Schools

The Regional Schools for the Handicapped were authorized by the *State Facilities for the Handicapped Bond Fund (Chapter 149, Laws of 1973)*. This act provided funds to construct state-owned schools for children with severe handicaps; these schools are managed by local school districts under contract with the Department of Education. Annually, approximately 870 students attend the regional schools. The schools' operating expenses are supported entirely from tuition charged to the sending districts, including facility improvements under \$50,000. However, capital improvements over \$50,000 are the responsibility of the State.

Department of Education FY 2011 Capital Budget Request By Project Category and Project Type: All Fund Sources

-----Department Request-----Number of

* Amounts Expressed in Thousands (000's)

	Number of			Department	:Request	
	FY2011 Projects	FY 2011	FY 2012	FY 2013	FY 2014 - 2017	Total
Preservation						
A01 Preservation-Electrical	0	\$0	\$0	\$350	\$350	\$700
A02 Preservation-HVAC	0	\$0	\$975	\$0	\$1,055	\$2,030
A03 Preservation-Critical Repairs	1	\$250	\$200	\$0	\$0	\$450
A04 Preservation-Roofs & Moisture Protection	0	\$0	\$0	\$0	\$715	\$715
A05 Preservation-Security Enhancements	1	\$200	\$186	\$275	\$0	\$661
A06 Preservation-Other	0	\$0	\$665	\$2,440	\$715	\$3,820
Sub Tota	als: 2	\$450	\$2,026	\$3,065	\$2,835	\$8,376
Compliance						
B01 Compliance-ADA	1	\$500	\$0	\$407	\$0	\$907
B02 Compliance-Fire Safety Over \$50,000	1	\$400	\$0	\$0	\$0	\$400
Sub Tot	als: 2	\$900	\$0	\$407	\$0	\$1,307
Environmental						
C02 Environmental-Asbestos	0	\$0	\$0	\$850	\$1,165	\$2,015
Sub Tota	als: 0	\$0	\$0	\$850	\$1,165	\$2,015
Infrastructure						
F04 Infrastructure-Other	0	\$0	\$0	\$0	\$175	\$175
Sub Tot	als: 0	\$0	\$0	\$0	\$175	\$175
Grand Tot	als: 4	\$1,350	\$2,026	\$4,322	\$4,175	\$11,873

By Department Priortiy 10/6/2009

Department of Education

Agency Capital Budget Request

(000's)

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED	REQUESTED	REQUESTED
FY - 2011	FY- 2012	FY - 2013	FY 2014 - 2017

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

SPRINKLER AND FIRE ALARM INSTALLATION

LOCATION: MERCER COUNTY

Dept Priority 1 Project ID:

34-082

Project Type Code: B02 Project Type Description: Compliance-Fire Safety Over \$50,000

General: \$400 \$400 \$0 \$0 \$0 \$400 \$400 \$0 \$0 \$0 Sub-Total:

\$0 Decrease: \$0 Operating Impact: Increase:

State Fire Inspector is requiring installation of sprinkler system in the windowless basement and the entry fover of the elementary school (building 1) - NJAC 5:70-4.7(h) & (build

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

HIGH SCHOOL AIR CONDITIONING

LOCATION: MERCER COUNTY

Dept Priority 2 Project ID: 34-083

Project Type Code: B01 Project Type Description: Compliance-ADA

\$500 \$500 \$0 \$0 General: \$0 Sub-Total: \$500 \$500 \$0 \$0 \$0

Operating Impact: \$0 Decrease: \$0 Increase:

Some students attending MKSD have medical conditions, which require their education programs to be provided air conditioned settings. The encessity for an air conditioned classroom is considered as the child study team develops the student"s individualized education (IEP). Failure to provide an education program under the conditions specified in a student's IEP can be a compliance or legal issue.

Approximately half of the school"s students attend classes in the vocational high school, which is more than 25 years old. The building is constructed with large glass pane windows tha do not open. The HVAC system cycles air through the building year round. The central air conditioning units have outlived their useful lifetime. they are now unreliable and need to be replaced. The units break down often or malfunction. When that happens, classroom temperatures can exceed 85 degrees forcing sutdents to be relocated elsewhere on campus.

Because of the age of the equipment, repairs are difficult and costly. Repairs also take time; sometimes it is necessary to relocate classes for several days while waiting for needed repairs. Because of the construction of the vocational high school, there is no alternative to replacing the air conditioning system. Without an HVAC, there is inadequate ventilation; it is not possible to use room air conditioners.

> REQ-04: Page 1 of 18 Section III-A, Page 94

Department of Education

Agency Capital Budget Request

(000's)

TOTAL COST
TOTAL COST 7 YR PROG

REQUESTED	REQUESTE
FY - 2011	FY- 2012

REQUESTED **REQUESTED** FY - 2013 FY 2014 - 2017

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

CAMPUS LIGHTING

LOCATION: MERCER COUNTY

Dept Priority 3

Project ID: 34-084

Project Type Description: Preservation-Security Enhancements Project Type Code: A05

General:	\$200	\$200	\$0	\$0	\$0
Sub-Total:	\$200	\$200	\$0	\$0	\$0

Operating Impact: Increase: \$0 Decrease: \$0

The school campus is home to students when school is in session. At night, the campus is dangerous because it is too dark to see in many locations. For deaf people, who rely more heaviliy upon their vision, this problem is exacerabated by their dependence upon vision to monitor their environment. Problems with outside lighting accounted for multiple fire code violations (NJAC5:70-4.11) cited 4/2008. Additional lighting is absolutely essential for the safety and security of students, their families, and staff. Improved lighting in the following areas is most critical: outside building #25; between buildings #1 & Dochen Center; high school ball field; between buildings #29 & amp; 30; around building #14; in the parking lot for building #24; behind building #18 (preschool); between the track and lower lake.

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

HIGH SCHOOL WINDOW REPLACEMENT

LOCATION: MERCER COUNTY

Dept Priority 4 Project ID: 34-086

Project Type Description: Preservation-Critical Repairs Project Type Code: A03

General:	\$250	\$250	\$0	\$0	\$0
Sub-Total:	\$250	\$250	\$0	\$0	\$0

Operating Impact: Increase: \$0 Decrease: \$0

This project is to replace damaged window panes in the vocational high school. The proejct was previously funded but never implemented; the funds reverted to the state. The project remains outstanding.

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

EXTERIOR CAMPUS LIGHTING UPGRADES

LOCATION: MERCER COUNTY

Dept Priority 8 Project ID:

34-080

Project Type Description: Preservation-Security Enhancements Project Type Code: A05

General:	\$186	\$0	\$186	\$0	\$0
Sub-Total:	\$186	\$0	\$186	0.2	\$0
Sub-Total.	φ100	ΨΟ	φ100	\$ 0	φυ

Operating Impact: \$0 Increase: Decrease: \$0

This project involves the installation of exterior lighting between buildings 24 and 30, the lower school and building 10, in the building 24 parking area. Lack of lighting in these areas present a serious safety concern for students and staff.

> REQ-04: Page 2 of 18 Section III-A, Page 95

Department of Education

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

DOMESTIC & SANITARY WATER PIPING & PLUMBING, BLDGS

LOCATION: MERCER COUNTY

Dept Priority 9

Project ID: 34-016

Project Type Code: A06 Project Type Description: Preservation-Other

General:	\$665	\$0	\$665	\$0	\$0
Sub-Total:	\$665	\$0	\$665	\$0	\$0

Operating Impact: Increase: \$0 Decrease: \$0

The Department of Education's Seven Year Plan has included three (3) Katzenbach School for the Deaf Projects in FY'03 involving the replacement of water and sewer lines. These projects are all included in this request. The majority of the sewer and water lines in this area of the campus, both between the buildings and internally, were installed between 1924 and 1929. Leaks and stoppages are a continuous reoccurring problem. The proposed solution is to replace both the water delivery and sanitary/waste removal pipes for all of the building in that quadrant of the Katzenbach campus, from the Clock Tower (Bldg. 7) back. This will include buildings 1, 8, 9, 10, 11, 12 and 13. Simultaneously the interior plumbing (supply and removal) in those individual structures will also be replaced. Currently, those structures have had their usefulness severely limited as leaking water pipes caused flooring problems and sanitary concerns.

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

STEAMLINE CONNECTIVE REPLACEMENT - VARIOUS BLDGS.

LOCATION: MERCER COUNTY

Dept Priority 10 Project ID: 34-079

Project Type Code: A03 Project Type Description: Preservation-Critical Repairs

General:	\$200	\$0	\$200	\$0	\$0
Sub-Total:	\$200	\$0	\$200	\$0	\$0

Operating Impact: Increase: \$0 Decrease: \$0

The steamline connections within Buildings 24, 25, 26, 27 & 28 must be replaced due to the fact that they are 70 years old. These buildings are residence halls and instructin buildings. If the current steamlines fail, it would require that the building be closed and would have a serious impact on school operations.

DIVISION OF ADMINISTRATION

AIR CONDITIONING & HEATING LOCATION: ESSEX COUNTY

Dept Priority 11 Project ID: 34-056

Project Type Code: A02 Project Type Description: Preservation-HVAC

General:	\$975	\$0	\$975	\$0	\$0
Sub-Total:	\$975	\$0	\$975	\$0	\$0

Operating Impact: Increase: \$0 Decrease: \$0

In FY'00 the sum of \$450k was appropriated to provide the school with modern air conditioning. During design and scope of work phases, there was extensive complications involving duct work, piping, ventilation and electrical. New electrical service and transformers alone cost \$182,000. While unable to complete the job, the interior core of the structure including gym/all purpose, cafeteria, lobby and hallways were air conditioned. The additional funds requested will allow the completion of air conditioning all offices and classrooms and student service areas and replacing the existing hot water perimeter radiator units with modern high efficiency units. The completion will result in a modern heating, air conditioning, electrical and control system.

Section III-A, Page 96 REQ-04: Page 3 of 18

Department of Education

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

DIVISION OF ADMINISTRATION

EXTERIOR DOOR REPLACEMENT

LOCATION: MIDDLESEX COUNTY

Dept Priority 12

Project ID: 34-058

Project Type Code: B01 Project Type Description: Compliance-ADA

 General:
 \$72
 \$0
 \$0
 \$72
 \$0

 Sub-Total:
 \$72
 \$0
 \$0
 \$72
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The purpose of this project is to replace fifteen exterior classroom doors, to replace several rear and side entry doors with fully automatic ADA compliant doors and, to convert existing fire exit windows in occupational/physical therapy room with ADA compliant emergency exit doors. Exterior classroom doors, now approximately 22 years old, have deteriorated/warped to the extent that there are significant air leaks around the doors resulting in costly heating/cooling losses and posing a potential health hazard to medically fragile students. Classroom, rear and side entry doors are not fully automated and post a significant safety risk in evacuating students with physical disabilities. The conversion of fire exit windows is also needed to provide additional safe egress for physically disabled students during emergency evacuation situations.

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

EMS TO LOOP TUNNEL - TEN BLDGS.
LOCATION: MERCER COUNTY

Dept Priority 13

Project ID: 34-019

Project Type Code: A06 Project Type Description: Preservation-Other

General:	\$160	\$0	\$0	\$160	\$0
Sub-Total:	\$160	\$0	\$0	\$160	\$0

Operating Impact: Increase: \$0 Decrease: \$35

In FY'94 the Katzenbach School installed a computer-based heat control system across 10 buildings. The system monitors temperature levels, establishes zones of temperature needs, and automatically controls setbacks and turndowns. Heating oil consumption has been reduced by over 1/3 on an annual basis in those buildings. This project builds up the subsequent installation of a fiber optic cable system that the Katzenbach School had installed to all the buildings in question, to extend the EMS system. The existence of the optical cable system allows us to include significantly more buildings to the system at no additional cost beyond the level originally planned. The system will be extended to the Cottage Loop (Bldg 8-13), the Nursery (Bldg 18); the Boiler Maintenance Shop (Bldg 22/23) and a dorminatory (Bldg 30). Based upon a comparison of square footage, using current EMS savings rates, we project energy cost savings of between \$35,000 to \$50,000 per year for these buildings being added to the system.

DIVISION OF ADMINISTRATION

LIGHTING REPLACEMENT

LOCATION: MIDDLESEX COUNTY

Dept Priority 14
Project ID: 34-021

Project Type Code: A06 Project Type Description: Preservation-Other

General:	\$65	\$0	\$0	\$65	\$0
Sub-Total:	\$65	\$0	\$0	\$65	\$0

Operating Impact: Increase: \$0 Decrease: \$10

The purpose of this project is to replace existing fluorescent lighting and fixtures with energy efficient lighting. Current lighting, in addition to not being energy efficient, is detrimental to the increasing number of autistic students served by the regional day school. The flickering direct lighting currently in use is a major distraction for the increasing autistic population as well as for the other children with disabilities served at the regional day school. Through project approval, we will replace lighting with high efficiency indirect lighting fixtures at or above the 50 lumins level.

Section III-A, Page 97 REQ-04: Page 4 of 18

Department of Education

Agency Capital Budget Request

(000's)

REQUESTED FY 2014 - 2017

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED	REQUESTED
FY - 2011	FY- 2012	FY - 2013

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

ASBESTOS TILE FLOOR REMOVAL - BUILDING 1

LOCATION: MERCER COUNTY

Dept Priority 15

Project ID: 34-071

Project Type Code: C02 Project Type Description: Environmental-Asbestos

 General:
 \$450
 \$0
 \$450
 \$0

 Sub-Total:
 \$450
 \$0
 \$450
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Remove asbestos floor tiles which are over 40 years old in Building 1. Worn, cracked, chipped tiles create a health and safety issue for staff and students.

DIVISION OF ADMINISTRATION

NURSE'S OFFICE & STUDENT BATHROOMS

LOCATION: MERCER COUNTY

Dept Priority 16 Project ID: 34-059

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$250
 \$0
 \$250
 \$0

 Sub-Total:
 \$250
 \$0
 \$250
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

This project will provide for the expansion of the existing nurse's room to provide space for an office and private examination room. Currently, the nurse shares space with therapists and case managers. The renovation will allow for the isolation and privacy of sick students. The project will also provide barrier free sinks and changing tables in each of four in-class bathrooms. This project is extremely important for meeting the health and safety needs of students with severe disabilities.

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

RESURFACE DAM

LOCATION: MERCER COUNTY

Dept Priority 17
Project ID: 34-028

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$125
 \$0
 \$0
 \$125
 \$0

 Sub-Total:
 \$125
 \$0
 \$0
 \$125
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Repair and resurface the dam at the end of the Katzenbach lake. The face of the dam is delaminating, thus weakening the structure.

Section III-A, Page 98 REQ-04: Page 5 of 18

Department of Education

Agency Capital Budget Request

(000's)

	TOTAL COST 7 YR PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
--	-------------------------	------------------------	-----------------------	------------------------	---------------------------------

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

WINDOW REPLACEMENT - BLDGS. 24, 25, 27, 28

LOCATION: MERCER SOUNTY

Dept Priority 18

Project ID: 34-029

Project Type Code: A06 Project Type Description: Preservation-Other

General:	\$385	\$0	\$0	\$385	\$0
Sub-Total:	\$385	\$0	\$0	\$385	\$0

Operating Impact: Increase: \$0 Decrease: \$2

Replace damaged, non-working and rusted windows in high use buildings. Windows that are rusted shut limit ventilation in non air conditioned buildings, thus affecting health.

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

UPGRADE STEAM PIPING AND RADIATORS

LOCATION: MERCER COUNTY

Dept Priority 19 Project ID: 34-031

Project Type Code: A06 Project Type Description: Preservation-Other

General:	\$600	\$0	\$0	\$600	\$0
,					
Sub-Total:	\$600	\$0	\$0	\$600	\$0

Operating Impact: Increase: \$0 Decrease: \$2

Replace steam lines and interior radiators in bldgs. 1, 29, 30, 8, 9, 10, 11. Current steam lines and radiators are old and worn and in need of frequent and costly repairs.

DIVISION OF ADMINISTRATION

ADL APARTMENT

Dept Priority 20 LOCATION: ESSEX COUTNY

Project ID: 34-032

Project Type Code: B01 Project Type Description: Compliance-ADA

General:	\$55	\$0	\$0	\$55	\$0
Sub-Total:	\$55	\$0	\$0	\$55	\$0

Operating Impact: Increase: \$0 Decrease: \$0

Renovation and creation of permanent ADL (Activities for Daily Living) apartment. This area is critically important for developing the independent living skills of students with severe disabilities.

Section III-A, Page 99 REQ-04: Page 6 of 18

Department of Education

Agency Capital Budget Request

(000's)

REQUESTED

FY - 2013

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED
FY - 2011	FY- 2012

REQUESTED FY 2014 - 2017

DIVISION OF ADMINISTRATION

REPAIR CATCH BASIN

LOCATION: ESSEX COUNTY

Dept Priority 21

Project ID: 34-030

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$75
 \$0
 \$0
 \$75
 \$0

 Sub-Total:
 \$75
 \$0
 \$0
 \$75
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Repair the existing catch basin at the front entrance of the building. The basin is cracked and has been repeatedly repaired. However, the current condition could pose a safety hazard to children and faculty.

DIVISION OF ADMINISTRATION

UPGRADE ELECTRICAL AND SECURITY SYSTEMS

LOCATION: HUDSON COUNTY

Dept Priority 22 Project ID: 34-051

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$350
 \$0
 \$350
 \$0

 Sub-Total:
 \$350
 \$0
 \$350
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

The current electrical system needs to be upgraded to prevent overload and to save usage for a system at maximum use. The project will prevent overloads and will ensure the safety of pupils and staff. In addition vandalism to the site and building have increased recently. This includes a hold-up on the property and a physical break-in. A security system is necessary.

DIVISION OF ADMINISTRATION

LIGHTING UPGRADE

LOCATION: ESSEX COUNTY

Project ID: 34-022

Dept Priority 23

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$80
 \$0
 \$0
 \$80
 \$0

 Sub-Total:
 \$80
 \$0
 \$0
 \$80
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Replace all lighting fixtures in classroom, halls and offices with modern electronic fixtures. Lighting levels are below educational adequacy standards, or 50 FC in an instructional classroom.

Section III-A, Page 100 REQ-04: Page 7 of 18

Department of Education

Agency Capital Budget Request

(000's)

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED
FY - 2011	FY- 2012

REQUESTED FY - 2013

REQUESTED FY 2014 - 2017

DIVISION OF ADMINISTRATION

REPLACE WINDOWS AND SKYLIGHTS

LOCATION: HUDSON CONTY

Dept Priority 24

Project ID: 34-023

Operating Impact:

Project Type Code: A06 Project Type Description: Preservation-Other

\$115 General:

\$0 \$0 \$115 \$0 \$0 \$0 \$115 \$0

Sub-Total: \$115

Increase: \$0

Decrease: \$0

Windows and skylights are showing age and leaks. Equipment is over 17 years old and shows usage and wear.

DIVISION OF ADMINISTRATION

RENOVATE NURSES OFFICE

LOCATION: ESSEX COUNTY

Dept Priority 25

Project ID: 34-025

Project Type Code: B01 Project Type Description: Compliance-ADA

General: \$50 Sub-Total: \$50

\$0	\$0	\$50	\$0
\$0	\$0	\$50	\$0

Operating Impact:

Increase:

Decrease: \$0

Refurbish nurse's office. Current location is in a makeshift space that does not allow for isolation of and privacy for sick students.

DIVISION OF ADMINISTRATION

STUDENT BATHROOMS

\$0

LOCATION: BERGEN COUNTY

Dept Priority 26 Project ID: 34-060

Project Type Code: Project Type Description: Compliance-ADA B01

General:

\$80

\$0 \$0

\$0

Sub-Total:

\$80

\$0

Operating Impact: Increase: \$0 Decrease: \$0

Creation of several classroom bathrooms including sinks, toilets and diaper changing tables; also refurbishing bathroom partitions in 4 existing bathrooms.

> REQ-04: Page 8 of 18 Section III-A, Page 101

\$80

\$80

\$0

\$0

Department of Education

Agency Capital Budget Request

(000's)

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED
FY - 2011	FY- 2012

REQUESTED REQUESTED FY 2014 - 2017

DIVISION OF ADMINISTRATION

ASBESTOS REMOVAL - BUILDING 1

LOCATION: MERCER COUNTY

Dept Priority 27
Project ID: 34-033

Project Type Code: C02 Project Type Description: Environmental-Asbestos

 General:
 \$400
 \$0
 \$0
 \$400
 \$0

 Sub-Total:
 \$400
 \$0
 \$0
 \$400
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Asbestos removal building 1 (project completion)

DIVISION OF ADMINISTRATION

POWER DOORS/UPGRADE FIRE EXIT DOOR

LOCATION: BERGEN COUNTY

Dept Priority 28
Project ID: 34-034

Project Type Code: B01 Project Type Description: Compliance-ADA

 General:
 \$150
 \$0
 \$150
 \$0

 Sub-Total:
 \$150
 \$0
 \$150
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Replace manual front doors with doors with power assist capacity; upgrade/modernize all exterior fire exits with power assist capacity. The school educates a population of students with severe disabilities.

DIVISION OF ADMINISTRATION

EMERGENCY LIGHTING SYSTEM

LOCATION: ESSEX COUNTY

Project ID: 34-035

Dept Priority 29

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$120
 \$0
 \$120
 \$0

 Sub-Total:
 \$120
 \$0
 \$120
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Install a back-up electrical generator system. Because of types and numbers of students, the building cannot be without power.

Section III-A, Page 102 REQ-04: Page 9 of 18

Department of Education

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED FY 2014 - 2017
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	

DIVISION OF ADMINISTRATION

REPLACEMENT OF CLASSROOM AND GYM DOORS

LOCATION: CAMDEN COUNTY

Dept Priority 30

Project ID: 34-036

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$85
 \$0
 \$85
 \$0

 Sub-Total:
 \$85
 \$0
 \$0
 \$85
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Replace exterior rear classroom doors and interior gym doors. The doors are old and frequently in need of repair. Conditions make opening and closing doors extremely difficult, especially in emergency situations.

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

SECURITY IMPROVEMENT

LOCATION: MERCER COUNTY

Dept Priority 31
Project ID: 34-039

Project Type Code: A05 Project Type Description: Preservation-Security Enhancements

 General:
 \$75
 \$0
 \$0
 \$75
 \$0

 Sub-Total:
 \$75
 \$0
 \$0
 \$75
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Install a new guard house, key card access system and surveillance cameras. The increased need to lease space at the school has resulted in a major increase in traffic on campus. Improved security is needed to prevent the occurrence of illegal activities.

DIVISION OF ADMINISTRATION

REPLACEMENT OF FLOOR COVERINGS

Dept Priority 32 LOCATION: HUDSON COUNTY

Project ID: 34-040

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$95
 \$0
 \$0
 \$95
 \$0

 Sub-Total:
 \$95
 \$0
 \$0
 \$95
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Tiles, carpeting and surfaces show high levels of deterioration and need replacement throughout the building. The building's 20 years of high use and traffic has worn the tile and carpets to their replacement point.

Section III-A, Page 103 REQ-04: Page 10 of 18

Department of Education

Agency Capital Budget Request

(000's)

	TOTAL COST 7 YR PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
--	-------------------------	------------------------	-----------------------	------------------------	---------------------------------

DIVISION OF ADMINISTRATION

FIRE & SECURITY ALARMS

LOCATION: MORRIS COUNTY

Dept Priority 33

Project ID: 34-061

Project Type Code: A05 Project Type Description: Preservation-Security Enhancements

 General:
 \$200
 \$0
 \$0
 \$0
 \$0

 Sub-Total:
 \$200
 \$0
 \$0
 \$200
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Both the fire and security alarms are over 20 years old and are prone to false alarms. The system is too old for upgrades and needs replacement.

DIVISION OF ADMINISTRATION

EMERGENCY LIGHTING

LOCATION: BERGEN COUNTY

Dept Priority 34 Project ID: 34-024

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$120
 \$0
 \$120
 \$0

 Sub-Total:
 \$120
 \$0
 \$120
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Replace existing system. The current system is outdated and prone to failure and high maintenance demands.

DIVISION OF ADMINISTRATION

WINDOW & DOOR REPLACEMENT

LOCATION: MORRIS COUNTY

Dept Priority 35

Project ID: 34-062

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$165
 \$0
 \$165
 \$0

 Sub-Total:
 \$165
 \$0
 \$165
 \$0

Operating Impact: Increase: \$0 Decrease: \$0

Replace wooden emergency doors with metal from all classrooms; provide power assist front door; install 2 additional emergency exit doors and window egress from library area.

Section III-A, Page 104 REQ-04: Page 11 of 18

Department of Education

Agency Capital Budget Request

(000's)

	TOTAL COST 7 YR PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
--	-------------------------	------------------------	-----------------------	------------------------	---------------------------------

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

ASBESTOS TILE FLOOR REMOVAL - BUILDING 2

LOCATION: MERCER COUNTY

Dept Priority 36

Project ID: 34-041

Project Type Code: C02 Project Type Description: Environmental-Asbestos

 General:
 \$250
 \$0
 \$0
 \$250

 Sub-Total:
 \$250
 \$0
 \$0
 \$250

Operating Impact: Increase: \$0 Decrease: \$0

Remove asbestos floor tiles which are over 40 years old. Worn, cracked, chipped tiles create a health and safety issue for staff and students.

DIVISION OF ADMINISTRATION

EXTERIOR WATERPROOFING AND RESTORATION

LOCATION: HUDSON COUNTY

Dept Priority 37
Project ID: 34-042

Project Type Code: A04 Project Type Description: Preservation-Roofs & Moisture Protection

 General:
 \$170
 \$0
 \$0
 \$170

 Sub-Total:
 \$170
 \$0
 \$0
 \$170

Operating Impact: Increase: \$0 Decrease: \$0

Exterior waterproofing and brick pointing on the entire building need to be redone. Age and weather deteriorate the surface.

DIVISION OF ADMINISTRATION

CITY SEWER HOOKUP

LOCATION: OCEAN COUNTY

Project ID: 34-063

Dept Priority 38

Project Type Code: F04 Project Type Description: Infrastructure-Other

 General:
 \$175
 \$0
 \$0
 \$175

 Sub-Total:
 \$175
 \$0
 \$0
 \$175

Operating Impact: Increase: \$0 Decrease: \$0

Hookup to city sewer will allow for elimination of septic field system with its quarterly pump outs and backups clogs. Current system dictates water use for showers and cleaning.

Section III-A, Page 105 REQ-04: Page 12 of 18

Department of Education

Agency Capital Budget Request

(000's)

REQUESTED

FY - 2013

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED
FY - 2011	FY- 2012

REQUESTED FY 2014 - 2017

DIVISION OF ADMINISTRATION

EXTERIOR WATERPROOFING AND RESTORATION

LOCATION: ESSEX COUNTY

Dept Priority 39

Project ID: 34-064

Project Type Code: A04 Project Type Description: Preservation-Roofs & Moisture Protection

 General:
 \$170
 \$0
 \$0
 \$170

 Sub-Total:
 \$170
 \$0
 \$0
 \$170

Operating Impact: Increase: \$0 Decrease: \$0

Exterior waterproofing and brick pointing on the entire building needs to be redone. Age and weather deteriorate the surface.

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

RECREATION EQUIPMENT LOWER SCHOOL AND NURSERY

LOCATION: MERCER COUNTY

Dept Priority 40 Project ID: 34-043

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$100
 \$0
 \$0
 \$100

 Sub-Total:
 \$100
 \$0
 \$0
 \$100

Operating Impact: Increase: \$0 Decrease: \$0

Replace current playground equipment. Current equipment is old, worn and obsolete and could create a safety hazard.

DIVISION OF ADMINISTRATION

RECREATION EQUIPMENT

LOCATION: HUDSON COUNTY

Dept Priority 41

Project ID: 34-044

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$60
 \$0
 \$0
 \$60
 \$60

 Sub-Total:
 \$60
 \$0
 \$0
 \$0
 \$60

Operating Impact: Increase: \$0 Decrease: \$0

Replace current playground equipment. Current equipment is old, worn and obsolete and could create a safety hazard.

Section III-A, Page 106 REQ-04: Page 13 of 18

Department of Education

Agency Capital Budget Request

(000's)

REQUESTED **FY** 2014 - 2017

	TOTAL COST	REQUESTED	REQUESTED	REQUESTE
	7 YR PROG	FY - 2011	FY- 2012	FY - 2013
ı		 		<u> </u>

DIVISION OF ADMINISTRATION

RECREATION EQUIPMENT

LOCATION: ATLANTIC COUNTY

Dept Priority 42

Project ID: 34-045

Project Type Code: Project Type Description: Preservation-Other A06

\$60 \$0 \$0 \$60 General: \$0 Sub-Total: \$60 \$0 \$0 \$0 \$60

Operating Impact: Increase: \$0 Decrease: \$0

Replace current recreational equipment. Current equipment is old, worn and obsolete and could create a safety hazard.

DIVISION OF ADMINISTRATION

RECREATION EQUIPMENT

LOCATION: CAMDEN COUNTY

Dept Priority 43 Project ID: 34-046

Project Type Code: Project Type Description: Preservation-Other A06

General: \$60 \$0 \$0 \$0 \$60 Sub-Total: \$60 \$0 \$0 \$0 \$60

Operating Impact: \$0 Increase: Decrease: \$0

Replace current playground equipment. Current equipment is old, worn and obsolete and could create a safety hazard.

DIVISION OF ADMINISTRATION

HVAC REPLACEMENT

LOCATION: SALEM COUNTY

Dept Priority 44 Project ID:

34-047

Project Type Code: Project Type Description: Preservation-HVAC A02

\$405 \$0 \$0 \$0 \$405 General: Sub-Total: \$405 \$0 \$0 \$0 \$405

Operating Impact: Increase: \$15 Decrease: \$0

Replace all HVAC heat pump units. Units are 17 years old and are critical to maintaining climate control.

REQ-04: Page 14 of 18 Section III-A, Page 107

Department of Education

Agency Capital Budget Request

(000's)

REQUESTED

FY - 2013

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED
FY - 2011	FY- 2012

REQUESTED FY 2014 - 2017

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

C02

ASBESTOR TILE FLOOR REMOVAL - BUILDING 25

LOCATION: MERCER COUNTY

Dept Priority 45

Project ID: 34-048

Project Type Code:

Project Type Description: Environmental-Asbestos

 General:
 \$250
 \$0
 \$0
 \$250

 Sub-Total:
 \$250
 \$0
 \$0
 \$250

Operating Impact: Increase: \$0 Decrease: \$0

Remove asbestos floor tiles which are over 40 years old. Worn, cracked, chipped tiles create health and safety issue for staff and students.

DIVISION OF ADMINISTRATION

ELECTRICAL SYSTEM UPGRADE

LOCATION: ESSEX COUNTY

Dept Priority 46

Project ID: 34-049

Project Type Code: A01 Project Type Description: Preservation-Electrical

 General:
 \$350
 \$0
 \$0
 \$350

 Sub-Total:
 \$350
 \$0
 \$0
 \$350

Operating Impact: Increase: \$0 Decrease: \$0

The current system needs to be upgraded and improved to meet modern demands for power. Electronic/computer program demands are growing constantly and taxing the current electrical distribution system.

DIVISION OF ADMINISTRATION

ORIGINAL WINDOW REPLACEMENT

LOCATION: SALEM COUNTY

Project ID: 34-050

Dept Priority 47

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$75
 \$0
 \$0
 \$75

 Sub-Total:
 \$75
 \$0
 \$0
 \$0
 \$75

Operating Impact: Increase: \$0 Decrease: \$0

Replace all original window units. Leaks and drafts continue to occur despite ongoing caulking and maintenance.

Section III-A, Page 108 REQ-04: Page 15 of 18

Department of Education

Agency Capital Budget Request

(000's)

TOTAL COST
7 YR PROG

REQUESTED	REQUESTED
FY - 2011	FY- 2012

REQUESTED FY - 2013

REQUESTED **FY** 2014 - 2017

DIVISION OF ADMINISTRATION

ROOF REPLACEMENT

LOCATION: HUDSON COUNTY

Dept Priority 48

Sub-Total:

Project ID: 34-066

Project Type Code: A04 Project Type Description: Preservation-Roofs & Moisture Protection

Decrease: \$0

\$375 General:

\$0 \$375 \$0 \$0 \$0 \$0 \$0 \$375

Operating Impact:

\$375 Increase:

Roof is 16+ years old and has begun to leak in various areas. Repairs will be ineffective at some point in the future.

DIVISION OF ADMINISTRATION

HVAC REPLACEMENT

\$0

LOCATION: ESSEX COUNTY

Dept Priority 49 Project ID:

34-067

Project Type Code: A02 Project Type Description: Preservation-HVAC

General: \$375 Sub-Total: \$375 \$0 \$0 \$0 \$375 \$0 \$0 \$0 \$375

Operating Impact:

Increase:

\$0

Decrease: \$0

Air conditioning units over 20 years old. Breakdowns and repeated repairs foreshadow need for replacement in next several years.

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

ASBESTOS TILE FLOOR REMOVAL - BUILDING 26

LOCATION: MERCER COUNTY

Dept Priority 50

Project ID: 34-052

Project Type Code: Project Type Description: Environmental-Asbestos C02

\$0

General:

\$400 \$0 \$0 \$0 \$400 \$400 \$0 \$0 \$0 \$400

Sub-Total:

Operating Impact:

Increase:

Decrease: \$0

Remove asbestos floor tiles which are over 40 years old. Worn, cracked, chipped tiles create health and safety issue for staff and students.

REQ-04: Page 16 of 18 Section III-A, Page 109

Department of Education

Agency Capital Budget Request

(000's)

	TOTAL COST 7 YR PROG	REQUESTED FY - 2011	REQUESTED FY- 2012	REQUESTED FY - 2013	REQUESTED FY 2014 - 2017
--	-------------------------	------------------------	-----------------------	------------------------	---------------------------------

DIVISION OF ADMINISTRATION

PLAYGROUNG EQUIPMENT

LOCATION: SALEM COUNTY

Dept Priority 51

Project ID: 34-053

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$100
 \$0
 \$0
 \$100

 Sub-Total:
 \$100
 \$0
 \$0
 \$100

Operating Impact: Increase: \$0 Decrease: \$0

Replace current playground equipment. The playground area is used by all studentss. Deterioration of 10 year old equipment creates a serious hazard to safety and well being of multiply disabled students.

DIVISION OF ADMINISTRATION

HVAC REPLACEMENT

LOCATION: SALEM COUNTY

Dept Priority 52 Project ID: 34-068

Project Type Code: A02 Project Type Description: Preservation-HVAC

 General:
 \$275
 \$0
 \$0
 \$275

 Sub-Total:
 \$275
 \$0
 \$0
 \$275

Operating Impact: Increase: \$0 Decrease: \$0

HVAC heat pump system is over 17 years old and requires constant maintenance and repairs. Replacement will be necessary in the near future in order to maintain a healthy indoor air quality.

DIVISION OF ADMINISTRATION

WINDOW REPLACEMENT

LOCATION: ESSEX COUNTY

Dept Priority 53 Project ID: 34-069

Project Type Code: A06 Project Type Description: Preservation-Other

 General:
 \$260
 \$0
 \$0
 \$260

 Sub-Total:
 \$260
 \$0
 \$0
 \$260

Operating Impact: Increase: \$0 Decrease: \$0

Windows throughout building stick, leak air and need constant maintenance. Many not operational on a regular basis.

Section III-A, Page 110 REQ-04: Page 17 of 18

Department of Education

Agency Capital Budget Request

(000's)

TOTAL COST	REQUESTED	REQUESTED	REQUESTED	REQUESTED
7 YR PROG	FY - 2011	FY- 2012	FY - 2013	FY 2014 - 2017

MARIE H. KATZENBACH SCHOOL FOR THE DEAF

ASBESTOS REMOVAL, BUILDING 24

LOCATION: MERCER COUNTY

Dept Priority 54

Project ID: 34-015

Project Type Code: C02 Project Type Description: Environmental-Asbestos

 General:
 \$265
 \$0
 \$0
 \$265

 Sub-Total:
 \$265
 \$0
 \$0
 \$265

Operating Impact: Increase: \$0 Decrease: \$0

Remove asbestos floor tiles which are over 40 years old. Worn, cracked, chipped tiles create health and safety issue for staff and students. Failure to remediate the problem will only increase the health and safety issues or continue until the structure is not usable.

Totals For:

Department of Education

General:	\$11,873	\$1,350	\$2,026	\$4,322	\$4,175	
Bond:	\$0	\$0	\$0	\$0	\$0	
Federal:	\$0	\$0	\$0	\$0	\$0	
Other:	\$0	\$0	\$0	\$0	\$0	
Sub-total:	\$11,873	\$1,350	\$2,026	\$4,322	\$4,175	

Section III-A, Page 111 REQ-04: Page 18 of 18