to Statement of Work: Physical Inspection Services HUD Mark-to-Market Program

FANNIE MAE PHYSICAL NEEDS ASSESSMENT GUIDANCE TO THE PROPERTY EVALUATOR

Used by Permission and Sublicense from Fannie Mae
Expected Useful Life Tables and Forms developed for Fannie Mae
by On-Site Insight of Needham, MA @1991 On-Site Insight, Inc.
Use, Reproduction, and Distribution of these Materials may be Made
Solely in Connection with the Implementation of the
Multifamily Assisted Housing Reform and Accountability Act of 1997

to Statement of Work: Physical Inspection Services HUD Mark-to-Market Program

Introduction

While many factors affect the soundness of a mortgage loan over time, one of the most significant is the physical condition of the property - past, present and future. A prudent lender must be concerned with the past maintenance and improvements because they may indicate owner and management practices as well as expenses to be incurred in the future. The lender must be concerned with the condition of the property at the time the loan is made, and over the term of the loan, because property condition may directly impact marketability to prospective tenants and the need for major expenditures may impact the economic soundness and value of the property. The lender must also be concerned with the condition of the property at the end of the loan term. If the property has deteriorated, the owner may not be able to secure sufficient financing to pay off the loan at maturity.

Most lenders have always given some attention to physical conditions and needs of properties in their underwriting. However, the amount of attention, the data secured, the quality and analysis of that data, and the impact of this information on underwriting has varied widely. Indeed, many properties and the loans that they secure are now in trouble because of inadequate consideration of physical needs in the underwriting coupled with inadequate attention to property maintenance which has diminished the marketability and overall value of the property.

The guidance and forms in this package, together with the guidance provided to our lenders in our Delegated Underwriting and Servicing (DUS) and Multifamily Guides, is based upon a desire to see a more standardized approach to assessing the physical needs of properties that will be securing our loans. These documents attempt to respond to stated desires on the part of our lenders for a "level playing field" among competing lenders who may otherwise have different notions of the level of data and analysis required to assess a property's physical condition. They also attempt to respond to the needs of property evaluators who, desiring to produce the quantity and quality of information deemed necessary, need specific guidance to avoid the appearance of glossing over problems or providing material which is too detailed or complex to be usable by the underwriters.

These documents are meant to provide useful guidance and tools to the evaluators. They cannot cover all situations and are not meant to be inflexible. They are designed to elicit the judgment of the evaluator (in a format which is useful to the underwriter), not to substitute for it. We welcome comments from evaluators in the field, as we did in developing this package, on improving either our forms or guidance so that this package can best serve the needs of both the evaluators and our lenders. If you have such comments, please contact April LeClair, Director of Multifamily Product Management, 3900 Wisconsin Avenue, N.W., Washington, DC 20016 (202-752-7439).

to Statement of Work: Physical Inspection Services HUD Mark-to-Market Program

Specific Guidance to the Property Evaluator

Purpose

The purpose of the Physical Needs Assessment is to identify and provide cost estimates for the following key items:

- Immediate Physical Needs repairs, replacements and significant maintenance items which should be done immediately
- Physical Needs Over the Term repairs, replacements and significant maintenance items which will be needed over the term of the mortgage and two years beyond.

As part of the process, instances of deferred maintenance are also identified.

The assessment is based on the evaluator's judgment of the actual condition of the improvements and the expected useful life of those improvements. It is understood that the conclusions presented are based upon the evaluator's professional judgment and that the actual performance of individual components may vary from a reasonably expected standard and will be affected by circumstances which occur after the date of the evaluation.

This package explains how to use the set of forms provided by Fannie Mae. It is important to recognize that the forms are intended to help the evaluator conduct a comprehensive and accurate assessment. They also present the results of that assessment in a relatively standard format which will be useful to the lender in making underwriting decisions. However, the forms should not constrain the evaluator from fully presenting his or her concerns and findings. The forms should be used and supplemented in ways which facilitate the preparation and presentation of information useful to the lender regarding the physical needs of the property.

The Systems and Conditions forms may be altered and/or computerized to serve the evaluators' needs so long as information is provided on the condition and Effective Remaining Life of all components and the Effective Remaining Life is compared to the standard Expected Useful Life (EUL). The Summary forms may also be extended or computerized so long as the basic format is maintained.

to Statement of Work: Physical Inspection Services HUD Mark-to-Market Program

Terms of Reference Form

The lender completes this form for the evaluator. It serves as a reference point for the assessment and provides the evaluator with basic information about the property and the term of the loan. Four additional topics are covered:

• Sampling Expectations - The lender's expectations about the number and/or percentage of dwelling units, buildings and specialized systems to evaluate may be stated. If there is no stated expectation, the evaluator should inspect sufficient units, buildings, and numbers of specialized systems to state with confidence the present and probable future condition of each system at the property. The evaluator should provide a separate statement indicating the sampling systems used to ensure a determination of conditions and costs with acceptable accuracy. If a Sampling Expectation is provided by the lender which is not adequate to achieve the requisite level of confidence, the evaluator should so advise the lender.

Considerations in determining an adequate sample size are age and number of buildings (especially if the property was developed in phases), total number of units, and variations in size, type and occupancy of units. Effective sampling is based on observing a sufficient number of each significant category. Using the above criteria, categories could include buildings by age of each building (e.g. inspect buildings in the 8 year old phase and in the 11 year old phase), buildings by type (e.g. rowhouse, L-shaped rowhouse, walkup, elevator) and/or buildings by construction materials (e.g. inspect the garden/flat roof/brick walls section and the garden/pitched roof/clapboard walls section). Dwelling units are separate categories from buildings. At a minimum, sampling is by unit size (0/1/2/3/4 bedrooms). There may be further categories if units are differently configured or equipped, or have different occupants (especially family or elderly). Generally, we would expect the percentage of units inspected to decrease as the total number of units increases. Systems which are not unit specific, such as boilers, compactors, elevators and roofs, will often have a 100% sample.

The overriding objective: SEE ENOUGH OF EACH UNIT TYPE AND SYSTEM TO BE ABLE TO STATE WITH CONFIDENCE THE PRESENT AND PROBABLE FUTURE CONDITION.

- Market Issues In certain instances, market conditions may necessitate action on certain systems. Examples are early appliance replacement or recarpeting, new entry paving, special plantings, and redecorated lobbies. If the owner or lender has identified such an action, the evaluator should include a cost estimation for such action and indicate what, if any, other costs would be eliminated by such action.
- Work In Progress In some instances, work may be underway (which can be
 observed) or under contract. When known by the lender, this will be noted. For

to Statement of Work: Physical Inspection Services HUD Mark-to-Market Program

purposes of the report, such work should be assumed to be complete, unless observed to be unacceptable in quality or scope.

Management-Reported Replacements - In some instances, the property ownership or
management will provide the lender with information about prior repairs or
replacements which have been completed in recent years. The lender may provide
this information to the evaluator to assist in the assessment of these components. The
evaluator should include enough units, buildings, or systems in the sample to
reasonably verify the reported repairs or replacements.

Systems and Conditions Forms

It is the responsibility of the evaluator to assess the condition of every system which is present at a property. All conditions, except as noted below, requiring action during the life of the loan must be addressed regardless of whether the action anticipated is a capital or operating expense.

To assist evaluators in reviewing all systems at a property, four Systems and Conditions Forms are provided. Each lists a group of systems typically related by trade and/or location. The four forms are Site, Architectural, Mechanical and Electrical, and Dwelling Units. While the forms have several columns in which information may be recorded, in many instances only the first three columns will be completed. If the condition of a system is acceptable, the Effective Remaining Life exceeds the term of the mortgage by two years, and no action is required, no other columns need to be completed.

The report is not expected to identify minor, inexpensive repairs or other maintenance items which are clearly part of the property owner's current operating pattern and budget so long as these items appear to be taken care of on a regular basis. Examples of such minor operating items are occasional window glazing replacement and/or caulking, modest plumbing repairs, and annual boiler servicing. However, the evaluator *should* comment on such items in the report if they do not appear to be routinely addressed or are in need of immediate repair.

The report is expected to address infrequently occurring "big ticket" maintenance items, such as exterior painting, all deferred maintenance of any kind, and repairs or replacements which normally involve significant expense or outside contracting. While the evaluator should note any environmental hazards seen in the course of the inspection, environment-related actions, such as removal of lead-based paint, will be addressed in a separate report prepared by an environmental consultant.

to Statement of Work: Physical Inspection Services HUD Mark-to-Market Program

Using the Systems and Conditions Forms

Purpose

The forms can be used both to record actual observations at a specific location and for an overall summary. For example, the Architectural form can be used for a specific building (or group or identical buildings) as well as for summarizing all information for buildings at a property. The same is true for the Dwelling Unit form. An unlabeled form is included which can be used as a second page for any of the Systems and Conditions Forms.

In some instances, the evaluator will note components which, while they may continue to be functional, may reduce marketability of the property. For example, single-door refrigerators or appliances in outmoded colors may have such an impact in some properties. The evaluator should note these items, discuss them with the lender, and provide separate estimates of the cost to replace such items if requested.

Items (EUL)

Each of the four forms has a number of frequently-occurring systems and components listed. This list represents only the most frequently observed and is not meant to be all inclusive. Every system present at the property must be observed and recorded. Any system not listed on the form may be included in the spaces labeled Other. Note that the assessment includes the systems and components in both residential and non-residential structures. Thus, garages, community buildings, management and maintenance offices, cabanas, pools, commercial space, and other non-residential buildings and areas are included.

The Expected Useful Life (EUL) figure which appears in parentheses after the Item is taken from the Expected Useful Life Table provided. This table provides standard useful lives of many components typically found in apartment complexes. Where the parentheses do not contain a number, it is because there are various types of similar components with differing economic lives. The evaluator should turn to the Expected Useful Life Table and select, and insert, the appropriate Expected Useful Life (EUL) number. If the Expected Useful Life (EUL) will, without question, far exceed the term of the mortgage plus two years, the Expected Useful Life (EUL) number need not be inserted.

Note: It is recognized that the Expected Useful Life Tables represents only one possible judgment of the expected life of the various components. If we receive substantial material to the effect that one or more of the estimates are inappropriate, we will make adjustments. Until such changes are made, the Tables provide a useful and consistent standard for all evaluators to use. They avoid debate on what the appropriate expected life is and permit focus on the evaluator's judgment of the effective remaining life of the actual component in place, as discussed below.

to Statement of Work: Physical Inspection Services HUD Mark-to-Market Program

Age

The evaluator should insert the actual Age of the component or may insert "OR" for original. If the actual age is unknown, an estimate is acceptable. If there is a range in Age (for example, components replaced over time), the evaluator may note the range (i.e., 5-7 years) or may use several lines for the same system, putting a different Age of that system on each line.

Condition

This space is provided to indicate the Condition of the component, generally excellent, good, fair, or poor, or a similar and *consistent* qualitative evaluation.

Effective Remaining Life

This space is provided for the evaluator to indicate the remaining life of the component as is. For standard components with standard maintenance, the Expected Useful Life Table provided by the Lender could be used to determine Effective Remaining Life by deducting the Age from Expected Useful Life (EUL). However, this should not be done automatically. A component with unusually good original quality or exceptional maintenance could have a longer life. On the other hand, if the component has been poorly maintained or was of below standard original quality, the useful life could be shorter that expected. The evaluator applies his or her professional judgment in making a determination of the Effective Remaining Life.

If the Effective Remaining Life is longer than the term of the loan plus two years, no deferred maintenance exists, and no action needs to be taken during the life of the loan, no other columns need to be filled out. The only exception may be Diff? (Difference), as discussed below. This should be noted when the evaluator's estimate of the Effective Remaining Life varies by more than two years from the standard estimate.

Diff? (Difference)

The Age of the component should be deducted from the Expected Useful Life (EUL) in parentheses and the answer compared to the Effective Remaining Life estimated by the evaluator. Where there is a difference of over two years, the evaluator should insert a footnote number in the DIFF? (Difference) column and supply, in an attached list of footnotes, a brief statement of why, in his or her judgment, the Effective Remaining Life of the component varies from the standard estimate. This approach provides consistency among evaluators while making best of the evaluators' professional judgment.

Action

to Statement of Work: Physical Inspection Services HUD Mark-to-Market Program

If any Action is required - immediately, over the life of the ban, or within two years thereafter - the Action should be recorded as repair, replace, or maintain. Repair is used when only a part of an item requires action, such as the hydraulics and/or controls of a compactor. Replace is used when the entire item is replaced. Maintain is used where special, non-routine maintenance is required, such as the sandblasting of a swimming pool. In cases where a repair or maintenance may be needed now, and replacement or further maintenance may be needed later, separate lines may be used to identify the separate actions and timing.

Now?

If the item involves a threat to the immediate health and safety of the residents, clearly affects curb appeal, will result in more serious problems if not corrected, or should otherwise be accomplished as part of an immediate repair, maintenance or replacement program, this space should be checked. Replacements which may be needed in year one, but do not require immediate attention, need not be checked.

DM (Deferred Maintenance)

The DM (Deferred Maintenance) space is marked in any instances where current management practice is clearly inadequate and the owner's attention should be called to the item, even if no major expenditure or significant labor may be required.

Quantity

For items requiring action, the evaluator should note the Quantity of the system, with the applicable unit of measure entered (each, unit, square feet, square yards, linear feet, lump sum, etc.).

Field Notes

This space, as well as attachments may be used to record the type of component (16cf, fros. free, Hotpoint), the problem (valves leaking) or other information (consider replacement for marketing purposes, replace 30% per year, work in progress, etc.) that the evaluator will need to complete the Evaluator's Summary.

Sample Form

The following example from the Dwelling Unit Systems and Conditions form illustrates how this form is properly used. The example presumes an 11 story building containing 1 and 2 bedroom units. There are 100 units. The age of the building is 9 years. The term of the proposed loan is 7 years.

to Statement of Work: Physical Inspection Services HUD Mark-to-Market Program

ITEM (EUL)	AG	COND	ERL	DIFF	ACTION	NOW	DM?	QUANTITY	NOTES
	E			?		?			,
Countertop/Sin	9	EX	10+	1	-	-	-	- ea.	Corian
k (10)				1					Stainless Steel
Refrigerator (15)	9	Good	6	-	REPL	-	- .	100ea	Hot point 16cf. ff 20%/yr @ YR 5
Disposal (5)	0-9	Good	0-5	-	REPL	-		100ea	
Bath Fixtures (20)	9	Good	11+		_	_		-	Dated Looking Repair - Now
Ceiling 04 stack ()	9	Hater Damag e			Repair	Yes	-	10ea	Plumbing Leak

Countertop/sinks are 9 years old. (The entry could also be "OR"). Condition is excellent, with an Effective Remaining Life of 10 years. This is significantly different from the anticipated Effective Remaining Life of 1 (an EUL of 10 years minus an Age of 9 years). Therefore, there is a footnote entry "1" in the Diff? (Difference) column. The footnote will indicate that this item is made of an exceptionally durable material (Corian), along with a top quality stainless steel sink. The evaluator's estimate of an Effective Remaining Life of 10 years + is beyond the term of +2. No capital need would be reported.

Refrigerators are also original, reported as 16 cf frost free Hotpoints. Replacement is expected around the Effective Remaining Life, noted as 20% annually and beginning in the 5th year of the loan when the refrigerators are 14 years old.

Disposals range from new to original (Age = 0-9). 20% per year replacements will be needed starting in year 1. The evaluator notes that disposals appear to be replaced as part of the project's normal operations.

Bath fixtures are original, and in good condition. No replacement is expected to be required during the term +2 years. The note indicates that they are "dated looking," which may prompt a market consideration for replacement.

Ceiling is a special entry. The "04" stack of units has experienced water damage to ceiling from major plumbing leak. This is noted for repair NOW. As this apparently occurs in all 10 units in this stack and therefore is likely to have more than a modest cost, this action would be reported on the Immediate Physical Needs summary form.

Evaluator's Summary Forms

to Statement of Work: Physical Inspection Services HUD Mark-to-Market Program

Two separate forms are used to summarize the evaluator's conclusions from the Systems and Conditions Forms. One summarizes Immediate Physical Needs and the other summarizes the Physical Needs Over The Term +2 years.

Evaluator's Summary: Immediate Physical Needs

All of the items for which Now? is checked are transferred to this form. This form provides for the listing of Items, Quantity, Unit Cost and Total Cost of each. The Item and Quantity are transferred directly from the Systems and Conditions Form.

Unit Cost - This is the cost per unit (sf, ea, lf, etc.) in current dollars to implement the required action. The source of the cost estimate should be listed in a separate attachment. The sources may include a third-party estimation service (e.g., R.S. Means: Repair and Remodeling Cost Data), actual bid or contract prices for the property, estimates from contractors or vendors, the evaluator's own cost files, or published supplier sources.

Total Cost - This is the result of multiplying the quantity times the unit cost. It is expressed in current year dollars.

DM (Deferred Maintenance) - If the item evidences deferred maintenance, this column is checked.

Comments - the comments column, or an attachment, should clearly provide information on the location and the nature of problem being addressed for each item. The information should be adequate for the owner to begin to implement the action.

Evaluator's Summary: Physical Needs Over the Term

Those items not listed on the Immediate Physical Needs form, but for which action is anticipated during the term of the loan plus two years, are listed on the form. The item and Quantity are transferred directly from the Systems and Conditions Form. The Unit Cost is calculated in the same manner as on the Immediate Physical Needs Form. An attachment should be provided which gives any necessary information on the location of action items and the problem being addressed for each item. The information should be adequate for the owner to begin to implement the action.

Cost by Year - the result of multiplying the quantity times the unit cost, in current dollars, is inserted in the column for the year in which the action is expected to take place. Generally, the Effective Remaining Life estimate provided by the evaluator on the Systems and Conditions will indicate the action year. For example, if the evaluator has indicated that the Effective Remaining Life of the parking lot paving is 4 years, the cost, in current dollars, is inserted in Year 4. If the items are likely to be done over a number of years, the costs, in current dollars should be spread over the appropriate period. For example, if the Effective Remaining Life of the Refrigerators is estimated to be 4 years

to Statement of Work: Physical Inspection Services HUD Mark-to-Market Program

or 3-5 years, one third of the cost of replacing the refrigerators may appear in each of Years 3, 4, and 5.

Total Uninflated - After inserting all of the appropriate action items, the evaluator should total the items for each year.

Total Inflated - The evaluator should multiply the Total Uninflated times the factor provided to produce the Total Inflated.

Total Inflated All Pages - On the last sheet, the evaluator should include the Total Inflated Dollars for that page and all prior pages.

Cumulative Total All Pages - On the last sheet, the evaluator should insert the Total Inflated Dollars of that year and all prior years.

Special Repair and Replacement Requirements

While performing a property inspection, the evaluator must be aware that certain building materials and construction practices may cause properties to experience (or to develop in a short time period) problems that can be corrected only with major repairs or replacements. The following identifies some specific construction related problems; however, the evaluator must be aware that other construction related problems may be found in any property and should be identified. If any of the following requirements are not met or if the evaluator determines that the following conditions (or others) are present, the evaluator must contact the lender immediately to discuss the timing as well as the cost of the repairs or replacements. The evaluator should ensure that any of these conditions are thoroughly addressed in the Physical Needs Assessment.

Minimum Electrical Capacity - Each apartment unit must have sufficient electrical capacity (amperage) to handle the number of electrical circuits and their use within an apartment. Therefore, the evaluator must determine, based on referencing the National Electric Code as well as local building codes, what is the minimum electrical service needed. In any event, that service must not be less than 60 amperes.

Electrical Circuit Overload Protection - All apartment unit circuits, as well as electrical circuits elsewhere in an apartment complex, must have circuit breakers as opposed to fuses as circuit overload protection.

Aluminum Wiring - In all cases, where aluminum wiring runs from the panel to the outlets of a unit, the evaluator's inspection should ascertain that the aluminum wiring connections (outlets, switches, appliances, etc.) are made to receptacles rated to accept aluminum wiring or that corrective repairs can be done immediately by the owner.

to Statement of Work: Physical Inspection Services HUD Mark-to-Market Program

Fire Retardant Treated Plywood - While performing the roof inspection, the evaluator should investigate whether there is any indication that fire-retardant treated plywood was used in the construction of the roof (primarily roof sheathing). This inspection should focus on sections of the roof that are subjected to the greatest amount of heat (e.g., areas that are not shaded or that are poorly ventilated) and, if possible, to inspect the attic for signs of deteriorating fire-retardant treated plywood or plywood that is stamped with a fire rating.

Our concern is that certain types of fire-retardant treated plywood rapidly deteriorate when exposed to excessive heat and humidity or may cause nails or other metal fasteners to corrode. Common signs of this condition include a darkening of the wood and the presence of a powder-like substance, warping of the roof and the curling of the shingles. Fire-retardant treated plywood is most likely to be in townhouse properties or other properties with pitched, shingled roofs that were constructed after 1981 and that are located in states east of the Mississippi River and some southwestern states.

Narrative Conclusion and Attachments

A complete narrative summary of the property and its components is not required. However, the evaluator should supply a concise summary of the conclusions reached concerning the overall condition of the property, its future prospects, and the quality of the current maintenance programs. Any items affecting the health and safety of residents should be clearly flagged.

The summary should include a discussion of the sampling approach used, discussed above, and any market issues which the evaluator believes it may be appropriate to address or which were noted by the lender.

The narrative, the forms use and the attachments (footnotes explaining Differences, information regarding sources of costs, and, if necessary, information needed to identify the location and type of problem addressed in the Evaluator's Summary: Physical Needs Over the Term) should be supplied.

to Statement of Work: Physical Inspection Services HUD Mark-to-Market Program

EXPECTED USEFUL LIFE TABLES

Forms and Expected Useful Life Tables developed for Fannie Mae by On-Site Insight of Needham, MA

E	EXPECTED USEFUL LIFE TABLE		
	Family Development	Elderly Development	
SITE SYSTEMS		,	Action
NOTE: 50+ "long-lived" systems: EUL based on	location and are made	314	"Action" equals replace unless
Basketball Courts			other wise noted
	15	25	
Built Improvements (playgrounds/site furniture) Catch Basin	20 .	20	
Cold Water Lines	40	40	·
	40	40	
Compactors	. 15	15	
DHW/Supply/Return	30	30	
Dumpsters	10	. 10	
Dumpster Enclosure	10	10	Fence Only
Earthwork	50+	50+	
Electrical Distribution Center	40	40	
Emergency Generator	1.5	15	
Fencing			ē
Chain Link	40	40 ·	
Wrought Iron	50+	50+	
Stockade/Basinweave	12	12	
Post and Rail	. 25	25	•
Gas Lines	40	40	
Heating Supply/Return	40	40	
Incinerators	50+	50+	
Irrigation System	30	30	•
Lift Station	50	50	
Mail Facilities	10	10	•
Landscaping	50+	50+	
Parking	301	. 304	
Asphalt	25	25	
Gravel	15	25	Resurface
Pedestrian Paving		15	Resurface
taran da antara da a	15	15	Resurface
Bimminors	15	15	
Concrete Poto inima Wells	30	30	•
Retaining Walls			•
Concrete	20	20	Fill Cracks/Repoint
Masonry	15	15	Fill Cracks/Repoint
Wood	15	15	Replace
Stone	15	15	Fill Cracks/Repoint
Roadways			e e
Asphalt (Sealing)	5	5	Seal ·
Asphalt	25	25	Resurface
Gravel	15	15	Resurface (grade and gravel)
Sanitary Treatment	40	40	(3 8
Site Electrical Main	40	40	
Site Gas Main	40	40	
Site Lighting	25	25	
Site Power Distribution	40	40	
Site Sanitary Lines	50+	50+	
Site Sewer Main	50+	50+	
Site Water Main	40	40	
Storm Drain Lines	50+	50+	
Swimming Pool - Deck	15		DC >= 1
Mechanical Equipment (filter/pump/etc.)	10	I.5	Resurface Deck
Fennis Courts	•	10	· ·
Fransformer	15	15	Resurface
	30	30	
Water Tower	50+	50+	

to Statement of Work:

Physical Inspection Services HUD Mark-to-Market Program

K'	XPECTED USEFUL LIFE		k-to-Market Program
	Family Development	Elderly Development	Action
BUILDING ARCHITECTURE			Action
NOTE: 50+ = "long-lived" systems: EUL based of	n location and use-specific	conditions	
Appurtenant Structures			
Porches	. 50	50	Paint at 5 years
Wood Decks	20	20	Paint at 5 years
Storage Sheds	30	30	Paint at 5 years
Greenhouses	50	50	*
Carports	40	40	
Garages	50+	50+	
Basement Stairs	50+	50+	
Building Mounted Exterior Lighting	. 6	10	
Building Mounted HID Lighting	6	20	
Bulkheads	30	30	
Canopies			
Wood/Metal	40	40	Replace
Concrete	20	20 .	Re-roof
Ceilings, Exterior or Open	5	5 ·	. Paint
Chimney	. 25	25	Point
Common Area Doors (fire/hall/closet/etc.)	50 +	50+	
Common Area Floors		·	
Ceramic/Quarry Tile/Terrazzo	50+	-50+	Replace
Wood (strip or parquet)	30	30	Replace Portion/Sand and Finish
Resilient Flooring (tile or sheet)	15	. 15	Replace
Carpet	7	7	Replace
Concrete	50+	50+	Replace
Common Area Railings	50+	50+	Кершее
Common Area Ceilings		20.	
Concrete/Drywall/Plaster	50+	50+	Replace (paint 5-8 years)
Acoustic Tile	20	20	Replace
Common Area Countertop & Sink	20	20	кершее
Common Area Dishwasher	15	15	•
Common Area Disposal	5 .	5	•
Common Area Walls	50 1	50÷	Replace (paint 5-8 years)
Exterior Common Doors			respines (parites o years)
Aluminum and Glass	30	30	Dooronly
Solid Core (wood or metal)	25 .	25	Door only
Amo	15	30	Door and mechanism
Exterior Stairs			Door Mad Michigan
Wood	30	30	Replace
Filled Metal Pan	20	20	Replace
Concrete	50+	50+	Replace
Exterior Unit Doors	25	25	227-1220
Exterior Walls			
Aluminum Siding	15	15	Prep and Paint
Brick or Block	40	40	Repoint
Brownstone/Stone Veneer	20	20	Waterproof and Caulk
Glass Block	15	15	Recaulk
Granite Block	40	40	Repoint
Metal/Glass Curtain Wall	10	10	Recaulk
Pre-cast Concrete Panel	15	15	Recaulk
Vinyl Siding	30	30	Replace
Wood shingle, Clapboard, Plywood, Stucco	5	5	Prep and Paint/Stain
Fire Escapes	40	40	Resecure
Foundations	50+	50+	roscomo

; 171≤	DECTED TICEETH TITE	TADIE	· · ·	
152	EXPECTED USEFUL LIFE TABLE			
	Family Development	Elderly Development		
YTotal as (Clusicality			Action	
Hatches/Skylights	30	20		
Access Hatch	30	30		
Smoke Hatch or Skylight Insulation/Wall	50+	50+		
· ·	50+	50+		
Interior Lighting	25	25		
Interior Railings	50+	50+	•	
Kitchen Cabinets	20	20		
Local HVAC Electrical Fan Coil	20	20	•	
Electrical Fan Con Blectric Heat/Electrical AC	20	20		
	15	15		
Gas Furnace With Split DX AC	20	20		
Heat Pump w/ Supplementary Electrical	15	15		
Heat Pump, Water Source Hydronic Fan Coil	20 30	20	\$	
	1	30		
Hydronic Heat/Electrical AC Mail Facilities	20 10	20 30		
	Į.			
Parapet Wall	50+	50+	a.t. as	
Penthouse Public Bathroom Accessories	25. 7	25	New Door and Pointing	
Public Bathroom Fixtures	15	7		
Radiation	15	15	,	
	£0	- 50	·	
Hydronic (baseboard or freestanding) Electric Baseboard	50 25	50		
Electric Panel		25	•	
	20	20		
Railings Roof	10	10	Paint	
Refrigerator, Common Area	15	15		
Residential Glass Doors	15	1.5		
Sliding	15	15		
Atrium/French	30	· 30		
Roof Covering		4.5	•	
Aluminum Shingles	40	40		
Asphalt Shingles	20	20		
Built-up (BUR)	20	20		
Membrane	20	20		
Metal (pre-formed)	40	40	•	
Slate, Tile, Clay, or Concrete Shingles	50+	50+		
Wood Shingles	20	20	NI C	
Roof Drainage Exterior (gutter and fascia)	25	25	New Gutters	
Roof drainage Interior (Drain Covers)	50+	50+	•	
Roof Structure	50+	50+		
Slab	50+	50+		
Service Doors Soffits	25	25		
Wood / Stucco / Concrete	<u>,</u>		70. ?	
	5 25 ·	5	Paint	
Aluminum or Vinyl		25	Replace	
Stair Structure	50+	50+		
Storm/Screen Doors	7	15	•	
Storm/Screen Windows	20	20		
Waterproofing Foundation	50+	50+		
Window Security	40	40	-	
Windows (Frames and Glazing)	30	30		
Wood Floor Frame .	50+	50+		

EX	PECTED USEFUL LIFE	TABLE	***
	Family Development	Elderly Development	-
NICHT THE CONTRACTOR	· · · · · · · · · · · · · · · · · · ·		Action
DWELLING UNITS		77	
NOTE: 50+ = "long-lived" systems: EUL based on l Bath Accessories			
Bath Fixtures (Sink, toilet, tub)	10	15	
Closet Doors	20	20	•
	10	20	
Countertop and Sink Dishwasher	10	. 20	
	10	15	
Disposal	. 5	8	
Electric Fixtures	20	20	•
Hallway Door	30	50	Door Only
Heat Detectors	20	20	·
Interior Door	30	50	Door Only
Interior Stairs	50+	50+	•
Kitchen Cabinets	20	25	"
Living Area Ceilings		}	
Concrete/Drywall/Plaster	50+	50+	Replace (Paint at 5-8 years)
Acoustic Tiles	20	20	
Living Area Floors	· .		•
Ceramic/Quarry Tile/Terrazzo	50+	50 +.	Replace
Wood (strip or parquet)	30	30	Replace Portion/Sand and Finish
Resilient Flooring (tile or sheet)	. 15	20	Replace
Carpet	7	10	Replace
Concrete	50+	50+	Replace
Living Area Walls	50+	50+	Replace (Paint at 5-8 years)
Local HVAC			replace (raine at 5-6 years)
Electric Fan Coil	20	. 20	
Electric Heat/Electric AC	15	15	•
Evaporative Condenser ("swamp cooler")	20	20	
Gas furnace With Split DX AC	20	20	
Heat Pump w/ Supplementary Electric	15	15	
Heat Pump, Water Source	20	20	
Hydronic Fan Coil	30	30	
Hydronic Heat/Electric AC	20	20	
Range	15	· · · · · · · · · · · · · · · · · · ·	
Rangehood	15	20	
Refrigerator	15	15	•
Smoke/Fire Detectors	10	15	
Unit Air Conditioning (Window)	15	10	•
Unit Electric Panel	1	15	
Unit Level Boiler	50+	50+	
	25	25	
Unit Buzzer/Intercom	20	30	
Unit Level DHW	. 10	10	
Unit Level Hot Air Furnace	25	25	-
Unit Radiation			
Hydronic or Steam (baseboard or freestanding)	50	50	A Company of the Comp
Electric Baseboard	25	25	
Unit Vent/Exhaust	15	15	
Unit Wiring	99	99	
Vanities	20	20	-
Window Covering	3-20	3-25	Material/User Specific

	XPECTED USEFUL LIFE	TABLE	
	Family Development	Elderly Development	
MECHANICAL/ELECTRICAL			Action
NOTE: 50+ = "long-lived" systems: EUL based o	a location and use specific.	aanditions	
Central Unit Exhaust, Roof Mounted	15	15	
Chilled Water Distribution	50+	50+	
Chilling Plant	15	25	
Compactor	L L	i I	•
Cooling Tower	15	. 15	
Electrical Switchgear	.25	25	
Electrical Wiring	50+	50+	
Elevator, Controller/Dispatcher	50+	50+	•
	15	20	
Elevator, Cab	15	20	Rebuild Interior
Elevator, Machinery	30	30	
Elevator, Shaftway Doors	20	30	Replace Gibs and Rollers
Elevator, Shaftways	1		·
Hoist Rails, Cables, Traveling Equipment	2.5	25	-
Hydraulic Piston and Leveling Equipment	25	25	Re-sleeve Piston
Emergency Call Alarm System, Station	15	15	
Emergency Generator	35 ·	35	
Emergency Lights	10	· 10	Battery operated
Evaporative Cooler	15	15	• •
Fire Pumps	20	20	Pump Motor
Fire Suppression	50+	50+	Piping
Gas Distribution	50+	50+	Piping
Heat Sensors	. 15	15	· - 48
Heating Risers and Distribution	50+	50+-	
Heating Water Controller	15	15	•
Hot and Cold Water Distribution	50	50	
HVAC		30	
Cooling Only	15	15	
Heat Only	15	15	•
Heating and Cooling	15	15	•
Master TV System	15		
Outdoor Temperature Sensor	10	15 10	
Sanitary Waste and Vent System	, ,	·	
Samuary waste and vent System Sewage Ejectors	50+	50+	
Sewage Ejectors Buzzer/Intercom Central Panel	50	50	
	15	15	
Smoke & Fire Detection System, Central Panel	15	15	
Sump Pump		_	
Residential	7	7	Replace
Commercial	15	15 .	Replace Motor
Water Softening and Filtration	15	15	
Water Tower	50÷	50+	
Boiler Room Equipment			
Blowdown and Water Treatment	1 25		
	25	25	
Boiler Room Pipe Insulation	With Boiler	With Boiler	
Boiler Room Piping	With Beiler	With Boiler	
Boiler Room Valves	15	15	Repack Valves
Boiler Temperature Controls	With boiler	With boiler	
Boilers	[.	
Oil-fired Sectional	22	22	
Gas or Dual-fuel-fired Sectional	-25	25	
Oil Gas or Dual-fuel-fired Package, Low MBH	30	30	

E.A.	PECTED USEFUL LIFE Family Development	Elderly Development	•
		,	Action
MECHANICAL/ELECTRICAL (continued)			
Oil Gas or Dual-fuel-fired Package, High MBH	40	10	
Gas-fired Atmospheric	25	40 25	•
Electric	20	20	
Bottled Gas Storage	20	20	
Building Heating Water Temperature Controls			
Residential	12	12	·
Commercial	15	15	
Combustion Air			
Duct with Fixed Louvers	50+	50+	Replace
Motorized Louver and Duct Make-up Air	25	25	Replace Motor
Compressors	25	25 15	Replace Fan/Preheater
Condensate and Feedwater	13	15	
Feedwater Only (Hydronic)	10	. 10	
Condensate and Feedwater (Steam)	With Boiler	With Boiler	
DHW Circulating Pumps DHW Generation	By Size	By Size	
Tank Only, Dedicated Fuel	10	10	
Exchanger in Storage Tank	15	15	
Exchanger in Boiler	15	15	•
External Tankless Instantaneous	15	15	
DHW Storage Tanks	10	10	
Small (up to 150 gallons)	12	12	Replace
Large (over 150 gallons)	7	7	Point Tank Lining
Domestic Cold Water Pumps	15	15	TOBIC TAIK LIMING
Fire Suppression	50+	50+	•
Flue Exhaust	With Boiler	With Boiler	
Free Standing Chimney	50+	50+	k.1
Fuel Oil Storage	25	25	•
Fuel Transfer System	25	25	
Heat Exchanger	35	35	
Heating Water Circulating Pumps	By size	By size	
Line Dryers	15	15	
Motorized Valves	12	12	•
Outdoor Temp Sensor	10	10	
Pneumatic Lines & Controls	30	30	
Purchased Steam Supply Station	50+	50+	
Solar Hot Water	20	20	Replace Collector
			Panels

Appendix I: Physical Condition Assessment Statement of Work

Qualifications:

Contractor must:

- 1. Be trained to evaluate building systems, health, and safety conditions, and physical and structural conditions, and to provide cost estimates for maintaining, rehabilitating, or improving deficiencies. Must also have environmental expertise, as inspection will include environmental issues as well. Must have any required licenses.
- 2. Have acceptably completed written evaluation reports for similar types of multifamily rental housing projects in similar physical condition and age in the subject market or in similar areas, preferably including two (2) or more buildings that were receiving Section 8 or some other type of housing assistance when the report was prepared.
- 3. Not be under suspension or debarment by HUD, or involved as a defendant in criminal or civil action with HUD.
- 4. Produce reports that are well regarded in the marketplace in terms of content, timeliness and responsiveness. The inspector should have this personal experience, not just the company.
- 5. Have the capacity to complete the project inspection and prepare the report in a time frame acceptable to the PAE.

Statement of Work

The Contractor shall:

- 1. Perform a Physical Condition Assessment (PCA) for each asset specified by the PAE and report the findings.
 - a. The report shall be prepared according to the Fannie Mae document: "Physical Needs Assessment Guidance To The Property Evaluator" (Attachment A), except as modified herein.
 - b. The report shall include color photographs and a detailed narrative describing the property's exterior and interior physical elements and condition, including architectural and structural components, and mechanical systems.
 - c. The Inspector will consult HUD Asset Management, Real Estate Assessment Center (REAC) and mortgagee (if available) files.

- d. The Contractor shall conduct site inspections of a minimum of 25% of all units. Units shall be randomly sampled while taking into consideration occupied and unoccupied units and the unit size mix, i.e. one bedrooms, two-bedrooms, etc. If a significant number of units are found to be in poor condition, the PAE may require that additional units be inspected.
- e. The report shall include:
 - (1) Critical items: Identify in detail, and report immediately to property management and the PAE, any repair item(s) that represents an immediate threat to health and safety;
 - (2) Repair/Rehab items (Short Term Physical Needs): Identify and estimate the cost of the repairs, replacements, and significant deferred and other maintenance items that will need to be addressed within 12 months of closing (do not include items that are not broken but may need replacement in the near future).
 - (3) Market Comparable Improvements. After discussion with the PAE and the PAE's appraiser, the inspector may include repairs or improvements that are necessary for marketability in the list of Repair/Rehab needs. The repairs/improvements identified should be those necessary for the project to retain its original market position as an affordable project in a decent, safe and sanitary condition (recognizing any evolution of standards appropriate for such a project). The project should be able to compete in the non-subsidized market on the basis of rents rather than amenities. Where a range of options exists, the least costly options for repair or rehabilitation should be chosen, when both capital and operating costs are taken into consideration.
 - (4) Long-term Physical Needs/Reserve items: Identify and provide an estimate of the major maintenance and replacement items that are required to maintain the project's physical integrity over the next twenty (20) years. (Note that the Fannie Mae Guidance to the Property Evaluator only requires an 18-year assessment maximum.)
 - (5) Environmental Concerns: The report shall provide a description of directly observed potential on-site environmental hazards and include a completed Environmental Restrictions Checklist (Form 4.4).
- f. The report shall identify any physical deficiencies as a result of:
 - (1) a visual survey;
 - (2) a review of any pertinent documentation; and
 - (3) interviews with the property owner, management staff, tenants, interested local community groups and government officials, to the extent possible.

- g. The report shall provide a cost-benefit analysis of any individual repair or improvement costing more than \$10,000 per work item that represents an upgrade to current elements or that could be considered to reduce the operating expenses. (For example, individual utility metering, extra insulation, thermopane windows, water savers on showers and toilets, automatic setback thermostats, and durable siding.) Compare the cost of the item with the long-term impact on rent and expenses, taking into account the remaining useful life of building systems, as needed. The Contractor should coordinate with the underwriter and appraiser on this analysis, as needed. (Note: This analysis does not apply to items proposed to address accessibility issues, discussed below.)
- h. The report shall explain how the project will meet the requirements for accessibility to persons with disabilities, to the extent applicable. (See Attachment B, Accessibility Law Compliance Chart, for specific guidance.) Paragraph 2-40 of HUD Handbook 4350.3 (change 24 issued 1-19-93) requires owners to develop a transition plan that identifies physical obstacles that limit accessibility and describes methods to make the project accessible. The contractor shall include items in the transition plan in the list of repairs.
- i. If requested by the PAE, the contractor shall take part in discussions with the owner, tenants, or other interested parties, including neighborhood associations, members of local government, and representatives from the public housing authority, including attendance at a meeting to solicit oral and written comments to be incorporated into the PCA. The contractor shall assist the PAE in evaluating and responding to tenant and local community comments concerning the physical condition of the project and recommended repairs.
- j. The contractor shall act as an independent third-party on behalf of the PAE to review the completeness and accuracy of any PCA submitted by the owner.
- k. The contractor shall provide the PAE with weekly status reports (upon request) during the preparation phase to track and monitor the progress.
- 2. The PCA report should also include the following subcomponents:
 - a. Acknowledgments (who prepared report, when report was prepared, who received report and when report was reviewed).
 - b. Appendices (color photographs, site plans, maps, etc.)
- 3. In addition to the above, the Contractor shall:
 - a. Recommend any additional professional reports needed, for example, to determine the presence or degree of structural defects, or to complete additional investigation into an environmental issue. (The PAE will be responsible for obtaining such reports.)

- b. If the services of a subcontractor were secured to perform the PCA, the Contractor shall review the inspection for quality, consistency and agreed upon format and conformance with Fannie Mae's and these requirements.
- c. If requested by the PAE, attend a formal kick-off meeting to clarify the requirements and scope of the work to be performed.

Deliverables

- 1. A draft report shall be submitted to the PAE for review prior to completion of the final report.
- 2. The final report shall be completed in the number of originals and copies requested by the PAE or its designee.