

# Return & Repair Form:

## Customer Information:

Company Name: New Jersey State Police B: \_\_\_\_\_ S: \_\_\_\_\_  
 Date Received: 1-22-09 Date Given to Service: \_\_\_\_\_  
 Carrier: ~~FedEx~~ UPS - DHL - USPS Method: GRD - NDA - 2DY - 3DY - Other

## Product Information:

Product: 7410 - 7110 - 6510 - 6810 Serial #: AR LM-0276  
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR -  
 Whole Instrument Top ½ Sim Ser #: \_\_\_\_\_  
 Other \_\_\_\_\_ Probe Ser # DD P -  
**ACCESSORIES:**  
 110 V A/C Adapter  Regulator  Mag Card Rdr# \_\_\_\_\_  
 Printer Paper  Printer Ribbon  Casio # \_\_\_\_\_  
 Mouthpieces  Carrying Case  Dry Gas  
 Other (Please Specify) \_\_\_\_\_ Warranty Exp. Date \_\_\_\_\_

## Repair Information:

Test #

Reason for Return: ? FC?

Part Number	Description	Qty	Total Cost
<u>6808455</u>	<u>FC</u>	<u>1</u>	
<u>MPCPL 71</u>	<u>CPL</u>	<u>1</u>	
<u>6809458</u>	<u>IR DETECTOR</u>	<u>1</u>	
<u>MPL LABOR</u>		<u>.5</u>	

### Repair Notes:

REPLACE FC - IR VOLTAGE WOULD NOT ADJUST TO SPECIFICATION -  
REPLACED IR DETECTOR  
CPL w/ QC OPS CHECKS

Service Technician: 

Date: 01/26/2009