

RETURN AND REPAIR FORM



Customer Information

B:

S:

Company Name: Mancalapan Twp NJ

Date Received: 8-2-11 Date given to service: 8-2-11

Carrier: FedEx UPS USPS Shipping Method: GRD 3DAY 2DAY
 NDA-PRI NDA-STD

Product: 6510 6810
 7110 8610
 7510 DT5000
 7410 Upper-half 9510
 7410 Whole

Serial Number: AR WK-0045
 Printer Serial#: AR
 Sim Serial#: DD
 Probe Serial#: DD

Warranty Expires: _____

Description: A B Plus Demo Screener Trade In

Accessories

110V A/C Adapter Regulator Printer Ribbon Printer Paper
 Mouthpieces 9510 Stylus 9510 Top Cover Carrying Case
 Dry Gas Other (please specify) _____

Repair Information:

Test#:

Part Number	Description	Qty	Total Cost
8315075	PCB board	1	w/c w
6808486	Plate	1	w/c w
6808455	Fuel Cell	1	w/c w
misc part	modem	1	w/c w
mp Cal 71	Cal	1	w/c w
mp labor	Labor	1.5	w/c w

Repair Notes: Unit would not call modem it would get a
line busy display. Install new board and modem,
also install a new Fuel Cell for preventive
maintenance old Fuel Cell # ARZE-0294.
New Fuel Cell # ARCA-0821
Cal w Qc; ops check

Service Technician: [Signature]

Date: 8-10-11