

# Return & Repair Form:

## Customer Information:

Company Name: Perth Amboy B: \_\_\_\_\_ S: \_\_\_\_\_  
 Date Received: 1-11-10 Date Given to Service: \_\_\_\_\_  
 Carrier: (FedEx) - UPS - DHL - USPS Method: (GRD) - NDA - 2DY - 3DY - Other

## Product Information:

Product: 7410-7110-6510-6810-7510  
 9510- Drug Tester 5000  
 Description: A - B - Plus - Screener - Demo  
 Serial #: AR UL - 0081  
 Printer Ser #: AR -  
 Whole Instrument Top 1/2  
 Sim Ser #: \_\_\_\_\_  
 Other \_\_\_\_\_  
 Probe Ser # DD P -  
**ACCESSORIES:**  
 110 V A/C Adapter  Regulator  Mag Card Rdr# \_\_\_\_\_  
 Printer Paper  Printer Ribbon  Casio # \_\_\_\_\_  
 Mouthpieces  Carrying Case  Dry Gas  
 Other (Please Specify) \_\_\_\_\_ Warranty Exp. Date \_\_\_\_\_

## Repair Information:

Reason for Return: FC Test # \_\_\_\_\_

Part Number	Description	Qty	Total Cost
<u>680 8455</u>	<u>FC</u>	<u>1</u>	<u>W/C WARR</u>
<u>680 9512</u>	<u>1 Barb Brass</u>	<u>1</u>	<u>W/C WARR</u>
<u>MP Cal 71</u>	<u>Cal</u>	<u>1</u>	<u>W/C WARR</u>
<u>MP Labor</u>	<u>Labor</u>	<u>.5</u>	<u>W/C WARR</u>

### Repair Notes:

Install new FC # APAJ-0055 and a new Barb Brass.

Cal w/QC 1 OPS Check

Service Technician: JL

Date: 2/12/2010