



RETURN AND REPAIR FORM

Customer Information

B:

S:

Company Name: Hopewell Twp. P.D., Titusville, NJDate Received: 05/27/15Date given to service: 05/27/15Carrier: FedEx UPS USPS Shipping Method: GRD 3DAY 2DAY
 NDA-PRI NDA-STDProduct: 6510 6810
 7110 8610
 7510 DT5000
 7410 Upper-half 9510
 7410 WholeSerial Number: AR UM-0048Printer Serial#: ARSim Serial#: DDProbe Serial#: DD

Warranty Expires: _____

Description: A B Plus Demo Screener Trade In

Accessories

 110V A/C Adapter Regulator Printer Ribbon Printer Paper
 Mouthpieces 9510 Stylus 9510 Top Cover Carrying Case
 Dry Gas Other (please specify) _____

Repair Information:

Test#:

Part Number	Description	Qty	Total Cost
4414161	Calibration	1	NC
4414166	Labor	5	NC
8315075	Alcotest 7110 Motherboard	1	NC

Repair Notes: Replaced defective Alcotest 7110 Motherboard.Motherboard was changed due to unit getting stuck in printing mode.

CAL W/QC AND OPS CHECK

Service Technician BCDate: 05/29/15