

Return & Repair Form:

Y0341534

Customer Information:

Company Name: New Assembly Shop LLC B: 3309 S: 53073
 Date Received: 1-22-09 Date Given to Service: _____
 Carrier: FedEx (UPS) DHL - USPS Method: GRD - NDA (2DY) 3DY - Other

Product Information:

Product: 7410 (7110) - 6510 - 6810 Serial #: AR WC - 0072
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR -
 Whole Instrument Top 1/2 Sim Ser #: _____
 Other _____ Probe Ser # DD _____ P -

ACCESSORIES:

- 110 V A/C Adapter
- Regulator
- Mag Card Rdr# _____
- Printer Paper
- Printer Ribbon
- Casio # _____
- Mouthpieces
- Carrying Case
- Dry Gas

Other (Please Specify) _____ Warranty Exp. Date _____

Repair Information:

Test #

Reason for Return: ? FC ? + ERROR 23.5

Part Number	Description	Qty	Total Cost
<u>6808455</u>	<u>FC</u>	<u>1</u>	
<u>MV CAL 71</u>	<u>CAL</u>	<u>1</u>	
<u>6809458</u>	<u>IR DETECTOR</u>	<u>1</u>	<u>N/C WARR</u>
710775			
<u>8315075</u>	<u>PCB</u>	<u>1</u>	
<u>MPLADOR</u>		<u>1.0</u>	

Repair Notes:

REPLACE FC / REPLACE IRD N/C / PROBLEM ON PCB - COMPONENT
BLOWS IR SOURCE - REPLACED SOURCE W/ NON-INVENTORY PART
REPLACED MOTHERBOARD (PCB)
CAL W/ QC & OPS CHECKS

Service Technician: AS / RL

Date: 03.25.09