

Return & Repair Form: 20001889

Customer Information:

Company Name: Top of Verona B: 61090 S: 61091  
 Date Received: 1-13-11 Date Given to Service: \_\_\_\_\_  
 Carrier: FedEx - UPS - DHL - USPS Method: GRD - NDA - 2DY - 3DY - Other

Product Information:

Product: 7410-7110-6510-6810-7510-9510- Drug Tester 5000 Serial #: AR WM0092  
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR  
 Whole Instrument Top 1/2 Sim Ser #: \_\_\_\_\_  
 Other \_\_\_\_\_ Probe Ser # DD P -  
**ACCESSORIES:**  
 110 V A/C Adapter  Regulator  Mag Card Rdr# \_\_\_\_\_  
 Printer Paper  Printer Ribbon  Casio # \_\_\_\_\_  
 Mouthpieces  Carrying Case  Dry Gas  
 Other (Please Specify) \_\_\_\_\_ Warranty Exp. Date Dec. 2013

Repair Information:

Reason for Return:		Test #		
Part Number	Description	Qty	Total Cost	
<u>6809514</u>	<u>BREATH HOSE</u>	<u>1</u>	<u>409<sup>00</sup></u>	
<u>MPCAL71</u>	<u>IMP CIR</u>	<u>1</u>	<u>120-</u>	
<u>AIPLABOR</u>		<u>.5</u>	<u>44-</u>	

Repair Notes:

BREATH HOSE HAS MARKINGS ON END THAT LOOKS LIKE  
PLIERS WERE USED - THE HEAT SHRINK TUBE (BLUE)  
AT END OF HOSE HEATER WIRE IS DAMAGED - REPLACE  
BREATH HOSE & CIR

New capture

573<sup>00</sup>  
+ 2 x  
RETURN  
S/IT/I

Service Technician: [Signature]

Date: 2/7/2011