

Return & Repair Form:

Customer Information:

Company Name: Tenally Boro B: _____ S: _____
 Date Received: 9/14/2010 Date Given to Service: _____
 Carrier: FedEx - UPS - DHL - USPS Method: GRD - NDA - 2DY 3DY - Other

Product Information:

Product: 7410-(110)6510-6810-7510 Serial #: AR XL - 0005
 9510- Drug Tester 5000
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR
 Whole Instrument Top 1/2 Sim Ser #: _____
 Other _____ Probe Ser # DD P

ACCESSORIES:

110 V A/C Adapter Regulator Mag Card Rdr# _____
 Printer Paper Printer Ribbon Casio # _____
 Mouthpieces Carrying Case Dry Gas
 Other (Please Specify) _____ Warranty Exp. Date _____

Repair Information:

Test #

| Reason for Return: | | | |
|--------------------|--------------|-----------|--------------|
| <u>FC</u> | | | |
| Part Number | Description | Qty | Total Cost |
| <u>Q808453</u> | <u>FC</u> | <u>1</u> | <u>N/C W</u> |
| <u>MP CAL 71</u> | <u>CAL</u> | <u>1</u> | <u>N/C W</u> |
| <u>MP Labor</u> | <u>Labor</u> | <u>.5</u> | <u>N/C W</u> |

Repair Notes:

Unit was inspected there were spots found on the mirrors, the spots were removed. The IRV was also checked and no problems found, the Curvette filter was inspected no problems found.
Cal w/OC / OMS check
FC ARYM-1534 Defect Nov, 2007. Will replace FC, with AR3E-0882

Service Technician: [Signature]

Date: 9/16/2010