

Return & Repair Form:

Customer Information:

Company Name: EMERSON BORO. PDB: _____ S: _____

Date Received: 8-31-2010 Date Given to Service: _____

Carrier: FedEx - UPS - DHL - USPS Method: GRD - NDA - 2DY - 6DY - Other

Product Information:

Product: 7410-1110-6510-6810-7510 Serial #: AR2L-0144

9510-Drug Tester 5000

Description: A - B - Plus - Screener - Demo Printer Ser #: AR -

Whole Instrument Top 1/2 Sim Ser #: _____

Other _____ Probe Ser # DD P -

ACCESSORIES:

110 V A/C Adapter Regulator Mag Card Rdr# _____

Printer Paper Printer Ribbon Casio # _____

Mouthpieces Carrying Case Dry Gas

Other (Please Specify) _____ Warranty Exp. Date _____

Repair Information:

Test #

Reason for Return:

IR Detector

Part Number	Description	Qty	Total Cost
<u>6809458</u>	<u>IR Detector</u>	<u>1</u>	<u>N/C w</u>
<u>MP Cal 71</u>	<u>Cal</u>	<u>1</u>	<u>N/C w</u>
<u>MP Labor</u>	<u>Labor</u>	<u>1.5</u>	<u>N/C w</u>

Repair Notes:

Inspected Fuel cell no problems, Dated 2008
Inspect Cuvette Found spots, tech cleaned Cuvette.
New Capable

Cal w/DC & ops check

Service Technician: AS

Date: 9-3-2010