## LEVELS OF SERVICE






## OPERATIONAL DEFICIENCIES

## EGEND

- NB I-295 LOS D IN A.M.
- NB I-295 LOS D IN A.M., LOS E IN P.M.
- SB 1-295 LOS E IN A.M. AND P.M.
- SB I-76 LOS E IN P.M.
   NB I-76 LOS E IN A.M.
- NB RT. 42 LOS D IN A.M.
   SB RT. 42 LOS D IN P.M.
- RAMP A LOS F IN A.M. AND P.M.
- RAMP B LOS E IN A.M.
- RAMP C LOS F IN A.M. AND P.M.
- RAMP E LOS E IN A.M. AND P.M.
- O RAMP F LOS E IN A.M.

& Analysis 1955-1977

WEAVING SECTION LOS F IN A.M. AND P.M.



New Jersey Department of Transportation

I-295/I-76/Rte. 42
INTERCHANGE RECONSTRUCTION