

PHOTO LOG: BA_Linden Site 1



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 1



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 1



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 2



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 2



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 2



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 3



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 3



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 3



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 4



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 4



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 4



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 5



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 5



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 5



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 6



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 6



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 6



Photo 5: Backyard of Property

PHOTO LOG: BA_Linden Site 7



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 7



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 7



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 8



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 8



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 8



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 9



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 9



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 9



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 10



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 10



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 10



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 11



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 11



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 11



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 12



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 12



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 12



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 13



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 13



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 13



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 14



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 14



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 14



Photo 5: Backyard of Property

PHOTO LOG: BA_Linden Site 15



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 15



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 15



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 16



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 16



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 16



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 16



Photo 7: Wetlands to the south

PHOTO LOG: BA_Linden Site 17



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 17



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 17



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 18



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 18



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 18



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 18



Photo 7: Wetlands to the south

PHOTO LOG: BA_Linden Site 19



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 19



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 19



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 20



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 20



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 20



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 20



Photo 7: Wetlands to the south

PHOTO LOG: BA_Linden Site 21



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 21



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 21



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 21



Photo 7: Wetlands to the south

PHOTO LOG: BA_Linden Site 22



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 22



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 22



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 22



Photo 7: Wetlands to the southeast

PHOTO LOG: BA_Linden Site 23



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 23



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 23



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 24



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 24



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 24



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 25



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 25



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 25



Photo 5: Backyard of Property

PHOTO LOG: BA_Linden Site 26



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 26



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 26



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 27



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 27



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 27



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 27



Photo 7: Wetlands to the south

PHOTO LOG: BA_Linden Site 28



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 28



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 28



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 29



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 29



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 29



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 29



Photo 7: Wetlands to the south

PHOTO LOG: BA_Linden Site 30



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 30



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 30



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 31



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 31



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 31



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 32



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 32



Photo 3: Left Side of Garage



Photo 4: Right Side of Garage

PHOTO LOG: BA_Linden Site 32



Photo 5: Backyard of Property



Photo 6: Wetlands to the south

PHOTO LOG: BA_Linden Site 32



Photo 7: Miscellaneous Trash

PHOTO LOG: BA_Linden Site 33



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 33



Photo 3: Street View

PHOTO LOG: BA_Linden Site 34



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 34



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 34



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 35



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 35



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 35



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 36



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 36



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 36



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 36



Photo 7: Wetlands



Photo 8: Wetlands

PHOTO LOG: BA_Linden Site 37



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 37



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 37



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 37



Photo 7: Wetlands to the east

PHOTO LOG: BA_Linden Site 38



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 38



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 38



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 38



Photo 7: Wetlands to the east

PHOTO LOG: BA_Linden Site 39



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 39



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 39



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 40



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 40



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 40



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 41



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 41



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 41



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 42



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 42



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 42



Photo 5: Street View



Photo 6: Backyard of Property

PHOTO LOG: BA_Linden Site 43



Photo 1: Front View



Photo 2: Rear View

PHOTO LOG: BA_Linden Site 43



Photo 3: Left Side of House



Photo 4: Right Side of House

PHOTO LOG: BA_Linden Site 43



Photo 5: Street View



Photo 6: Backyard of Property