

- Desktop review and site reconnaissance revealed an AST nearby. The tank appeared to be a fuel oil tank. It appeared to be approximately 275 gallons. The ASD for a tank of this size and nature is 161.52 feet (ASDPPU). The actual distance calculated by the desk top tool was **7.93** feet. See photograph NEP0067_EA_AST1.pdf. See location of the tank on map NEP0067_AST1Map.pdf. Upon measurement, the distance DID NOT meet the necessary Acceptable Separation Distance (ASD). **THIS PROJECT WILL NOT BE ELIGIBLE TO MOVE FORWARD UNLESS THE AST ISSUES MENTIONED ABOVE ARE MITIGATED.**
- Desktop review and site reconnaissance revealed an AST nearby. The tank appeared to be a propane tank. It appeared to be approximately 250 gallons. The ASD for a tank of this size and nature is 155.23 feet (ASDPPU). The actual distance calculated by the desk top tool was **14.79** feet. See photograph NEP0067_EA_AST2.pdf. See location of the tank on map NEP0067_AST2Map.pdf. Upon measurement, the distance DID NOT meet the necessary Acceptable Separation Distance (ASD). **THIS PROJECT WILL NOT BE ELIGIBLE TO MOVE FORWARD UNLESS THE AST ISSUES MENTIONED ABOVE ARE MITIGATED.**
- Desktop review and site reconnaissance revealed an AST nearby. The tank appeared to be a propane tank. It appeared to be approximately 250 gallons. The ASD for a tank of this size and nature is 155.23 feet (ASDPPU). The actual distance calculated by the desk top tool was **39.92** feet. See photograph NEP0067_EA_AST3.pdf. See location of the tank on map NEP0067_AST3Map.pdf. Upon measurement, the distance DID NOT meet the necessary Acceptable Separation Distance (ASD). **THIS PROJECT WILL NOT BE ELIGIBLE TO MOVE FORWARD UNLESS THE AST ISSUES MENTIONED ABOVE ARE MITIGATED.**
- Desktop review and site reconnaissance revealed an AST nearby. The tank appeared to be a propane tank. It appeared to be approximately 250 gallons. The ASD for a tank of this size and nature is 155.23 feet (ASDPPU). The actual distance calculated by the desk top tool was **69.85** feet. See photograph NEP0067_EA_AST4.pdf. See location of the tank on map NEP0067_AST4Map.pdf. Upon measurement, the distance DID NOT meet the necessary Acceptable Separation Distance (ASD). **THIS PROJECT WILL NOT BE ELIGIBLE TO MOVE FORWARD UNLESS THE AST ISSUES MENTIONED ABOVE ARE MITIGATED.**
- Desktop review and site reconnaissance revealed an AST nearby. The tank appeared to be a fuel oil tank. It appeared to be approximately 275 gallons. The ASD for a tank of this size and nature is 161.52 feet (ASDPPU). The actual distance calculated by the desk top tool was **302.87** feet. See photograph NEP0067_EA_AST5.pdf. See location of the tank on map NEP0067_AST5Map.pdf. Upon measurement, the distance exceeded the necessary Acceptable Separation Distance (ASD). No further action necessary.
- Desktop review and site reconnaissance revealed an AST nearby. The tank appeared to be a fuel oil tank. It appeared to be approximately 2,000 gallons situated within a 6' x 12' dike. The ASD for a tank of this size and nature is 51.51 feet (ASDPNPD). The actual distance calculated by the desk top tool was **1,139.81** feet. See photograph NEP0067_EA_AST6.pdf. See location of the tank on map NEP0067_AST6Map.pdf. Upon measurement, the distance exceeded the necessary Acceptable Separation Distance (ASD). No further action necessary.
- Desktop review and site reconnaissance revealed an AST nearby. The tank appeared to be a fuel oil tank. It appeared to be approximately 35,000 gallons situated within a 30' x 45' dike. The ASD

for a tank of this size and nature is 175.38 feet (ASDPNPD). The actual distance calculated by the desk top tool was **3,611.82** feet. See photograph NEP0067_EA_AST7.pdf. See location of the tank on Map NEP0067_AST7Map.pdf. Upon measurement, the distance exceeded the necessary Acceptable Separation Distance (ASD). No further action necessary.

- Desktop review and site reconnaissance revealed an AST nearby. The tank appeared to be a fuel oil tank. It appeared to be approximately 275 gallons. The ASD for a tank of this size and nature is 161.52 feet (ASDPPU). The actual distance calculated by the desk top tool was **5.51** feet. See photograph NEP0067_EA_AST8.pdf. See location of the tank on map NEP0067_AST8Map.pdf. Upon measurement, the distance DID NOT meet the necessary Acceptable Separation Distance (ASD). THIS PROJECT WILL NOT BE ELIGIBLE TO MOVE FORWARD UNLESS THE AST ISSUES MENTIONED ABOVE ARE MITIGATED.