Poche, Lauren

From: Atalaya Armstrong <Atalaya.Armstrong@dep.nj.gov>

Sent: Monday, December 22, 2014 1:06 PM

To: Clark, Courtney; DEP NJHPO

Cc: Poche, Lauren; Crowl, Heather; Lackowicz, Rob

Subject: Completed Submission 15-1159 NJDEP

Attachments: L2014-352.pdf

Ms. Clark:

The 126 Bright Street Apt 103 documentation has been reviewed, signed, and scanned.

Please find attached HPO-L2014-352

If you have any issues with the attachments or require additional information, please feel free to let us know.

Regards-A. Armstrong

Mail Code 501-04B Historic Preservation Office NJ DEP PO Box 420 Trenton, NJ 08625-0420 www.nj.gov/dep/hpo

From: Clark, Courtney [mailto:courtney.clark@urs.com]

Sent: Tuesday, December 16, 2014 2:57 PM

To: DEP NJHPO

Cc: Poche, Lauren; Crowl, Heather; Lackowicz, Rob

Subject: DEP Form 2, RRE0032126MF, 126 Bright St Apt 103, Jersey City

Good afternoon,

Attached for your review please find a Form – 2: Assessment of Effects RRE0032126MF, 126 Bright St Apt 103, Jersey City.

Please forward any questions you may have to me at courtney.clark@urs.com. We look forward to your response.

Thank you,

Courtney Clark Architectural Historian



Tel: 610.832.3500 Direct: 610.832.2792 courtney.clark@urs.com

Please note new address and phone number

This e-mail and any attachments contain URS Corporation confidential information that may be proprietary or privileged. If you receive this message in error or are not the intended recipient, you should not retain, distribute, disclose or use any of this information and you should destroy the e-mail and any attachments or copies.



New Jersey Department of Environmental Protection Hurricane Sandy

Community Development Block Grant Form – 2 : Assessment of Effects (Version 1.0)






Application ID #		RRE0032126MF											
Applicant Name:		ERIKA JACK											
Street Address:		126 Bright St Apt 103						The state of					
Municipality:		Jersey City (Jersey City)			Cou	County:		Hudson					
PAMS PIN:		0906_342_25.103_C0103			Acr	Acreage:		0.026					
Latitude:		40.71823474			Lon	gitude:	N. S.	-74.05070161					
Undertaking:	X	Rehabilitation:	In	iterior	Ext	erior	В	Both			Elev	vation	
		Reconstruction:	N	ithin Exist	ting F	ootprint,	plus	2 feet		Out	side E	xisting	Footprint
Property A	partn	ent 103 is one of sever	al units	in the buildin	g loca	ted at 126	Brigh	t Street, a	five-	story.	multip	le-family	apartment building
0	of construction to be between 1865 and 1895, based on the building's form, materials, and style, and on a review of historicaerials.com.												
	The building features a rectangular plan and occupies approximately the front 2/3 of its parcel. The flat-roof appears to be covered in a standing seam or rolled metal roofing material. The foods of the building features a paramet wall visible from the rear of the building												
		ling seam or rolled metal roofing material. The façade of the building features a parapet wall, visible from the rear of the building, contains an ornate, bracketed cornice line, which follows the symmetric, projecting, angular bays that reach from the ground level to											
		parapet. The main entry is centered on the second level of the building and is accessed by a stoop of four steps, presumably											
		posed of granite. A pair of heavy, ornate, cast iron railings flank each side of the steps and attach to the door surround, which											
		ures ornamented relief carvings. The main entry features a single leaf, four-paneled, wood door with an inset frosted glass window in											
		e upper half. A narrow, single-light transom, framed in wood, rests immediately above the door. The center bay of the three stories ove the front door each contains a rectangular, decorative brick pattern, which appears to resemble a checkerboard. Horizontal											
st	ringe	gers, most likely comprised of sections of granite, stretch between the bays and sides of the façade at each floor and at the window											
		of each of the angled											
		hung, vinyl-framed wi											
													on, however, each features
													r each of the windows on
													d, narrow, triangular air eatures narrow, wood-
		, one-over-one window											
		as well as a modern gal											
													t, from one floor to the
													I floor, from the left bay of
		fire escape. On the ground level, a central half-staircase descends into a dug-out, covered patio with retaining walls on three sides, by the fire escape system, above. Each floor of the rear elevation features two symmetrically placed modern, steel storm doors with											
ne	early .	full-length windows in:	set, behir	nd which exis	st the r	nain exteri	or doc	ors (obscu	ared f	rom v	iew). T	wo wind	wos sit between these
		n each level; the appea											
		e within the Van Vorst			t Exte	nsion, liste	d on t	the Nation	nal Re	gister	of His	toric Plac	ces on 3/5/1980 (1D
	1340)	and the State Register 8/2/1978											
T	he pro	project has low potential to affect archaeological sites because the project substantially conforms to the original footprint and affects previously disturbed soils as defined in the PA; therefore, it meets Tier I PA Allowance I as listed in Appendix B of the PA.											
			s as defir	ned in the PA	there	fore, it me	ets Ti	ier I PA A	Allowa	ance I	as liste	d in App	endix B of the PA.
Current Property		A THE RESERVE OF THE PARTY OF T		die Like									
National Historic I			m 7						es	X N			
National Register of Historic Places Listed?						C-UNIT		es	XN	lo	TO PERSON		
Within a National Register of Historic Places Historic District?						-24	⊠ Y	es	N	lo			
								$\boxtimes c$	ontri	butin	ıg 🗌	Non-C	Contributing
Does the property have a SHPO Opinion or COE?							Y	es	N	0	TEN		
Within a Known Archaeological Site?						178	Y	es 2	N	0			
Within an Area of	Within an Area of High Archaeological Sensitivity? Area of Previous Historic Occupation												
Property Located within HPO's Archaeological Site Sensitivity Grid													
Area Located on Well-Drained Soils located within 500 feet of													
waterways, wetland complexes, or relict glacial features.													
Dualimin and Day	· ort	Evaluation			, ator v	.a.j., wee	·	Joinpie	,		510	.oruz rea	
Preliminary Property Evaluation													
Architecture Review	Mike Verderosa, M	PS (UR	S Corporation	on)	Archaeology Reviewer Jeremy Lazelle, MA, RPA (URS Corporation				RPA (URS Corporation)				
Date Reviewed		12/15/2014					1794		100	112	F 17/5		THE RESERVE OF THE PERSON OF T



New Jersey Department of Environmental Protection Hurricane Sandy







Further Survey Necessary:		Archaeological Historic Architecture						
No Further Survey Necessary								
Recommend Eligible		Individual Contributing to: Van Vorst Park Historic District Extension						
		Criteria: [Check All That Apply]						
Reasonin	Park I vernac distric develo howev propos	residence falls within the historic area identified as the Van Vorst Park Historic District Extension, listed on the onal Register of Historic Places on 3/5/1980 (ID #1540) and the State Register 8/2/1978. As part of this application less for Hurricane Sandy disaster relief, URS assesses this residence to be a contributing resource to the Van Vorst Historic District Extension. The Van Vorst Park Historic District is an excellent collection of late Victorian acular rowhouses and is one of the best such representations in New Jersey. The urban streetscapes within the lict effectively portray Jersey City as it appeared in the late 19th and early 20th century during its meridian of dopment. The residence retains its integrity of location, setting, feeling, design, workmanship, and association, ever, it does not retain integrity of and materials because of the following alterations: the use of vinyl windows. The losed boundary for the property is the legal parcel. This property is not individually eligible for listing in the lonal Register of Historic Places.						
Recommend Ineligib		Lacks Integrity of Materials/Design						
		Not 48 Years of Age						
		Not Within / In View of a National Register of Historic Places Listed / Eligible Historic District						
		Not a Building (per FEMA Definition)						
		Other - Lacks Distinctive Characteristics That Make It Individually Eligible for Listing on NRHP						
Applicant ID #	RRE003							
Property Address:	operty Address: 126 Bright St Apt 103, Jersey City, NJ							
Assessment of Effects	No H	istoric Properties Adversely Affected						
	The proposed undertaking of rehabilitation will bave No Adverse Effect on the possible historic area identified as the Van Vorst Park Historic District Extension, listed on the National Register of Historic Places on 3/5/1980 (ID #1540) and the State Register 8/2/1978. As long as the attached scope of work is completed as described and will not include additional alterations to the building's exterior. The proposed work involves the removal and replacement of non-historic materials, or involves interior work not visible from the public-right-way, therefore the rehabilitation of this property will not alter the historic area's integrity of setting, feeling, and association. Adverse Effect							
National Historic Lands	mark Con	sultation Process [If Applicable]						
Undertaking Located Wit	thin NHL:	National Park Service						
Applying Allowances As	Defined in	Programmatic Agreement: National Park Service State Historic Preservation Office Tier I: Tier II:						
Adverse Effect: N	ational Par	rk Service State Historic Preservation Office Advisory Council on Historic Preservation						
Resolution of Adverse E	Effects [Abbreviated Consultation Process Memorandum of Agreement Programmatic Agreement						
Public Consultation								
Fe		cognized Tribes, Certified Local Governments, Historic Preservation Commissions, etc: equire consultation based on location and type of activity proposed.						
054 A V (m) = 10	Winds	HISTORIC PRESERVATION OFFICE USE ONLY						
I concur with this fir	nding,							
☐ I do not concur with	this findi	ng for the following reason(s):						
	Mike Verde	erosa, MPS (URS Corporation) Archaeology Reviewer Jeremy Lazelle, MA, RPA (URS Corporation)						



New Jersey Department of Environmental Protection Hurricane Sandy Community Development Block Grant Form – 2: Assessment of Effects (Version 1.0)



HPO USE ONLY
15-1159
62014-352

Daniel D. Saunders Deputy State Historic Preservation Officer	D.S.L	Date /19/14

Architecture Reviewer	Mike Verderosa, MPS (URS Corporation)	Archaeology Reviewer	Jeremy Lazelle, MA, RPA (URS Corporation)
Date Reviewed	12/15/2014	BENEVAL BUILDING	
			