## **FIELD INSPECTION REPORT**

Application ID: SBL619239

Applicant Name: Kelly Management Group

Project Name/Location: The Mad Hatter

10 East Ocean Avenue

Sea Bright, Monmouth County

Date of Field Inspection: March 10, 2015

Field Inspector: Beth Williams, Tetra Tech

## Field Notes Summary:

Ms. Beth Williams, Tetra Tech, visited the Mad Hatter establishment located at 10 East Ocean Avenue in Sea Bright, Monmouth County of March 10, 2015 to note general project site conditions and document such conditions with photographs. Ms. Williams observed only the exterior of the existing Mad Hatter structure from sidewalks and public thoroughfares that surround the project site. Ms. Williams did not access the interior of the existing structure during the field inspection. Ms. Williams also took note of properties which surround the project site. No recognized environmental conditions (RECs) were observed on the project site or surrounding properties. The existing Mad Hatter establishment was closed at the time of the March 10, 2015 field inspection.

Ms. Williams walked the project site and viewed surrounding properties from publicly accessible areas in an effort to identify large aboveground storage tanks (ASTs) within 1-mile of the project site. Ms. Williams conducted a windshield reconnaissance by vehicle in an effort to identify large ASTs within 1-mile. No large ASTs were identified during the field inspection. In addition, Google Earth aerial imagery within 1-mile of the project site was reviewed. No large ASTs were identified during the Google Earth aerial imagery review.

