80 LISTER AVENUE

NEWARK, N.J.

1/27/84

SUMMARY SHEET

80 LISTER AVENUE

NEWARK, N.J.

80 LISTER AVE NEWARK, NEW JERSEY

CANDI THE DUACE	#0f	Wipe		pp:	
SAMPLING PHASE	Data Points	Samples >10 ng	ND	<25	
On Site	9		0		
√Habitability	13		10		
Joseph Street and SCA Chemical Services	3		0		
Thomasset Colors, Inc.	2		2		
✓ Public Contact Areas - Phase I	68		58		
Transportation Routes - Phase I	169		50		
Passaic River Sediment	35		14		
Selected Grid - Phase I	152		72		
Passaic River Crabs and Fish	16		1	2	
✓ Hayes Park East TAT Vacuum Bags	4		2		
Public Contact Areas - Phase II	18		11		
Lockwood Street TAT Vacuuming Refuse	4		2		
Transportation Routes - Phase II	44		21		
37 Foundry Street	4		2		
Hayes Park After TAT Clean-up	4		3		
Transportation Routes Post Remedial Action	34		3		
Transportation Routes - Phase III	29		13		
Industrial Areas	10		4		
Selected Grid - Phase II	19		5		
/ Brady Iron and Metals	10		0		
Parkway Soil	34		10		
Ferry Street	18		12		
Brady Iron and Metals Perimeter	53	1	3	-	
Hildermann Property	18		2		
New Jersey Transit	15		13		
Brady Iron and Metals Remedial Grid and Wipe	50	12	n		
TOTAL (Not Including Tissue Analysis)	819		312		

80 LISTER AVE NEWARK, NEW JERSEY


<pre>ppt (parts per trillion)</pre>			ppb (parts per billion)			
<25	_>25 & <50	>50	<1	≥1 & 3	<u>></u> 3 & <5	>5
			0	0	0	9
			1	1	0	1
			0	3	0	0
			0	0	0	0
			4	(5)	4	0
			59	36	10	14
		•	15	۷	1	1
			66	11	2	1
2	3	10				
			2	9	0	0
			5	(1)	0	(1
			1	ŋ	0	0
			14	1	2	0
			2	ί,	0	0
			1	O	0	0
			17	10	2	2
			10	2	2	2
			5	1	0	0
			5	5	2	2
			0	1	0	9
			4	11	5	4
			3	3	0	0
			4	5	4	37
			11	7	0	3
			2	Ø	0	0
			3	3	2	30
			234	10 2	36	11:

ON SITE

80 LISTER AVENUE

NEWARK, N.J.

SUMMARY OF SAMPLES RESULTS 80 LISTER AVENUE ON SITE 5/27/83 SAMPLE RESULTS 80 LISTER AVENUE ON SITE 5/27/83



DIAMOND SHAMROCK

NEWARK, N.J.

SAMPLE LOCATION MAP

(NOT TO SCALE)

FIGURE 2-1

IN US

CORPORATION

A Halliburton Company

2-1

TABLE 1 SAMPLES WITH CONCENTRATIONS 1 PPB OR GREATER ON SITE 5/27/83

SAMPLE NUMBER	SAMPLE LOCATION	TCDD CONCENTRATION (ppb)		
		Initial	Repeat	
1	Adjacent to Bulkhead along Passaic River at north end of site	69		
2	South side of building #1	NĢ	100	
3	Adjacent to Bulkhead along Passaic River at north end of site	305	560 1,000 duplicate	
4	Under storage tank at NW corner of site	NG	>51,000	
5	Near railroad siding, western edge of site	427	530	
6	Adjacent to storm drain near tall stack, NE corner	NG	680	
7	Adjacent to railroad tracks, SW entrance	68		
8	Adjacent to railroad tracks, SE entrance	88	100	
9	Adjacent to railroad tracks, southern gate	60	·	

NOTES:

⁽a) 9 samples were collected.

⁽b) NG = Did not pass EPA Monitoring Management Branch QA/QC requirements.

TABLE 2 ALL SAMPLES INCLUDING QA/QC ON SITE 5/27/83

SAMPLE NUMBER	SAMPLE LOCATION	TCDD CONCENTRATION (ppb)		
		Initial	Repeat	
1	Adjacent to Bulkhead along Passaic River at north end of site	69		
2	South side of building #1	NG	100	
3	Adjacent to Bulkhead along Passic River at north end of site	30 <i>5</i>	560 1,000 duplicate	
4	Under storage tank at NW corner of site	NG	> 7 51,000	
5	Near railroad siding, western edge of site	427	530	
6	Adjacent to storm drain near tall stack, NE corner	NG	680	
7	Adjacent to railroad tracks, SW entrance	68		
8	Adjacent to railroad tracks SE entrance	88	100	
9	Adjacent to railroad tracks, southern gate	60		
10	Known Blank	ND		
10 N	Matrix Spike of Sample 10	1.1		

ND - Not Detected

NG = Did not pass EPA Monitoring Management Branch QA/QC requirements.