

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 12:120)



Date of Notification (1) 7/31/2019		Name of Building Owner/Operator (2) International Paper Company / Georgia Pacific LLC							
Agencies Notified	Type Notification	Street Address 6400 Poplar Avenue / 133 Peach Tree Street							
☒ EPA ☐ DEP ☒ DOL ☒ DOH ☐ DCA	☐ Initial ☒ Amended Amendment #1 _____ ☐ Emergency (including justification) ☐ Cancellation	City, State, Zip Code Memphis, TN 38197 / Atlanta, GA 30004							
		Name of Contact Dan Williams (Envirocon)	Telephone Number 314-600-8129						
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) Former Curtis Specialty Papers		Type of Facility (4) ☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e. private & commercial buildings, homes, etc.)							
Street Address Frenchtown Road		Square Feet 150,000	# of Floors Various						
City (5) Milford		Bldg. Age 70 +/-							
County (6) Hunterdon	County Code (7) (STATE USE ONLY) _____	Current Use (Prior if being demolished) Vacant (Abandoned)							
Name of Monitoring Firm Hired by Building Owner (8) Arcadis U.S., Inc.		ASCM No. _____	Name of Abatement Contractor (9) PRISM Response, LLC						
Street Address 1 Harvard Way, Unit 5		Street Address 102 Technology Lane							
City, State, Zip Code Hillsborough, NJ 0844		City, State, Zip Code Export, PA 15632							
Project Manager for Monitoring Firm Kevin Held		Telephone No. 908-526-1000	Telephone No. 7243253330						
Start Date (10) 4/8/2019		Scheduled Completion Date (11) 10/4/2019	License No. 01121						
Occupancy Status During Abatement (Check Only One) ☒ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Facility Hours ☐ Other - Describe: _____		Name of OSHA Monitor PRISM Response, LLC							
		Street Address 70 Hillside Drive, Suite 200							
		City, State, Zip Code Drums, PA 18222							
Scope of Work (Check All That Apply)									
☐ ≥3 sf or ≥3 lf ☒ ≥160 sf or ≥260 lf		☒ Renovation ☐ Demolition							
		☐ Full Containment with Negative Pressure ☐ Mini-Enclosure ☐ Glovebag Procedure ☐ Non-Exempted (*) and Non-Friable Procedure							
Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> In Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)		Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type				
	Yes	No			N/A	Removal	Repair	Encapsulate	Enclosure
SEE ATTACHED			X	SEE ATTACHED	ATTACHED	x			
Name of Registered Waste Hauler Waste Management		NJDEP Waste Hauler ID No. 17273	Cubic Yards of Waste 558	Name of Registered Landfill GROWS Landfill					
City, State Newark, NJ 07114		Disposal Date		City, State Morrisville, PA					
Completed by Jessica Wolfe		Title Admin. Support		Signature <i>Jessica Wolfe</i>		Date 7/31/2019			


Attachment A: Remaining Regulated Materials
Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal

Building	Material	Location	NESHAP Category	Quantity
MMA Basement				
46A	Grey window door caulk	West side of building, exterior door	Category II Non-Friable	1 door
48	Pipe fitting insulation debris	Along East wall, adjacent passageway between Buildings 6 and 48, behind large metal machines	Friable	2 sf
82	Caulk and glazing on 2-pane windows (2ft x 6 ft)	West side of building	Category II Non-Friable	17 windows
82	Caulk and glazing on tall single pane windows (9 ft x 2 ft)	West side of building	Category II Non-Friable	8 windows
82	Residue grey door caulk	West side of building, center opening where door used to be located	Category II Non-Friable	25 lf
MMA 1st Floor				
5	Transite debris associated with hoods	Around the holes left from the transite removal	Category II Non-Friable	3 sf
5	Caulk associated with fiberglass panels	Around doghouses, adjacent roof	Category II Non-Friable	260 lf of panels
6	Caulk associated with fiberglass panels	Around doghouses, adjacent roof	Category II Non-Friable	260 lf of panels
22	Electrical boxes	South side, along wall beneath staircase to roof	Category II Non-Friable	3 boxes
48	Pipe fitting insulation associated with fiberglass pipe insulation	Ceiling plenum, North side	Friable	Unknown
48	Pipe insulation	Ceiling plenum, North side	Friable	30 lf
51	Black pipe wrap	Exterior, North side	Category II Non-Friable	10 lf
56	Debris pile (roofing)	Exterior, West side, dirt pile and ground with roofing debris scattered	Category II Non-Friable	Building 56 exterior
70	Caulking on interior block windows	SE side and interior between Buildings 48 & 56	Category II Non-Friable	8 lf
73A (changing area)	Exterior breaching debris	East side exterior, on metal machine	Friable	40 sf
74	Caulk associated with door window	South wall	Category II Non-Friable	1 door
74	Pipe insulation	Interior SW corner, exterior SW corner	Friable	25 lf interior 15 lf exterior
80	Debris pile	Poly pile and debris	Category II Non-Friable	22 sf
82	2 pane windows (6 ft x 2 ft), exterior grey window caulk and glazing, interior window glazing	Along west wall	Category II Non-Friable	17 windows
128	3 pane metal door window	East and West sides	Category II Non-Friable	2 windows




Attachment A: Remaining Regulated Materials
Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal

Building	Material	Location	NESHAP Category	Quantity
128	4 x 2 pane metal window	East and North sides	Category II Non-Friable	2 windows
16	2 x 4 pane wood windows (window glazing)	MMA 2nd and 3rd Floor		
69	Caulk on door window	2nd floor, throughout	Category II Non-Friable	8 windows
		3rd floor, east side	Category II Non-Friable	1 door
		MMA Roof		
Main Mill	PI2-white mag pipe insulation	throughout (including roof)	Friable	25,800 SF
Main Mill	White mag pipe insulation debris (PI2)	throughout (including areas on roof)	Friable	17,850 SF
Main Mill	Defective pipe insulation (PI2)	throughout (including areas on roof)	Friable	1,300 LF
Main Mill	TP9-transite panel	throughout (including areas on roof)	Category II Non-Friable	46,300 SF
Main Mill	MF13-grey mudded fillings on fiberglass line	Area 80, area 46A & area 10 roof	Friable	185 EA
Main Mill	Built-up roofing	Area 69 roof	Category I Non-Friable	2,700 SF
Main Mill	Perimeter/Penetration flashing	Area 69 roof	Category I Non-Friable	250 SF
Main Mill	RF36-built-up roofing	Area 32-roof	Category I Non-Friable	8,745 SF
Main Mill	Built-up roofing debris (RF36)	Area 32	Category I Non-Friable	850 SF
Main Mill	T44-silver/black flashing tar layer	Area 32-roof	Category I Non-Friable	570 SF
Main Mill	RF37-built-up roofing	Area 1-roof	Category I Non-Friable	8,745 SF
Main Mill	T43- silver/black flashing tar	Area 1-roof	Category I Non-Friable	1,050 SF
Main Mill	RF39-built-up roofing	Area 02-roof	Category I Non-Friable	7,200 SF
Main Mill	T46- silver/black flashing tar	Area 02-roof	Category I Non-Friable	700 SF
Main Mill	RF40-built-up roofing	Area 44-roof	Category I Non-Friable	5,100 SF
Main Mill	T47- silver/black flashing tar	Area 44-roof	Category I Non-Friable	650 SF
Main Mill	RF41-built-up roofing	Area 19-roof	Category I Non-Friable	3,000 SF
Main Mill	T48-silver/black flashing tar	Area 19-roof	Category I Non-Friable	575 SF
Main Mill	RF42-built-up roofing	Area 51-roof	Category I Non-Friable	12,000 SF
Main Mill	T49- black flashing tar	Area 51-roof	Category I Non-Friable	800 SF




Attachment A. Remaining Regulated Materials
Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal

Building	Material	Location	NESHAP Category	Quantity
Main Mill	RF43- built-up roofing	Area 03-roof	Category I Non-Friable	14,150 SF
Main Mill	RF44- built-up roofing	Area 03-elevated roof	Category I Non-Friable	3,520 SF
Main Mill	C45-white caulk on ductwork	Area 03-roof	Category II Non-Friable	150 LF
Main Mill	C50-white window caulk	Area 03-roof	Category II Non-Friable	1080 LF
Main Mill	T50-silver/black flashing tar layer	Area 03-roof	Category I Non-Friable	2,150 SF
Main Mill	T51-silver/black flashing tar layer	Area 03-elevated roof	Category I Non-Friable	420 SF
Main Mill	RF49-built-up roofing	Area 03-elevated shack roof	Category I Non-Friable	185 SF
Main Mill	T52-black flashing tar	Area 47-roof	Category I Non-Friable	650 SF
Main Mill	Black flashing tar (T52) and roofing debris	Area 47	Category I Non-Friable	100 SF
Main Mill	RF47- built-up roofing	Area 17-roof	Category I Non-Friable	7,200 SF
Main Mill	Built-up roofing debris(RF47)	Area 17	Category I Non-Friable	150 SF
Main Mill	T53-silver/black flashing tar layer	Area 17-roof	Category I Non-Friable	840 SF
Main Mill	T54-black perimeter flashing tar	Area 58-roof	Category I Non-Friable	180 SF
Main Mill	RF50-built-up roofing	Area 04-roof	Category I Non-Friable	2,750 SF
Main Mill	T55-black/silver flashing tar	Area 04-roof	Category I Non-Friable	1,080 SF
Main Mill	RF56-black built-up roofing	Area 04-elevated roof	Category I Non-Friable	400 SF
Main Mill	RF51-built-up roofing	Area 21/22-roof	Category I Non-Friable	5,440 SF
Main Mill	RF52-silver built-up roofing	Area 21/22-elevated roof	Category I Non-Friable	400 SF
Main Mill	T56-silver/black flashing tar layer	Area 21/22-roof	Category I Non-Friable	450 SF
Main Mill	T57-silver tar coating	Area 21/22-roof	Category I Non-Friable	150 SF
Main Mill	RF53- built-up roofing	Area 22A-roof	Category I Non-Friable	1010 SF
Main Mill	RF54- built-up roofing	Area 70-roof	Category I Non-Friable	1,120 SF
Main Mill	RF58- built-up roofing	Area 70- shack roof	Category I Non-Friable	80 SF
Main Mill	T60-black flashing tar	Area 70-roof	Category I Non-Friable	5500 SF
Main Mill	T62-parapet flashing tar	Area 70-roof	Category I Non-Friable	235 LF




Attachment A: Remaining Regulated Materials
Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal

Building	Material	Location	NESHAP Category	Quantity
Main Mill	T68-black perimeter/penetration flashing tar	Area 56-roof	Category I Non-Friable	1,110 SF
Main Mill	RF68- silver/black built-up roofing	Area 59-roof	Category I Non-Friable	3,600 SF
Main Mill	T69-silver/black perimeter/penetration flashing tar	Area 59-roof	Category I Non-Friable	750 SF
Main Mill	C55-exterior white window caulk	Area 59-roof	Category II Non-Friable	140 LF
Main Mill	RF69-built-up roofing	Area 77-roof	Category I Non-Friable	3,600 SF
Main Mill	T70-black perimeter/penetration flashing tar	Area 77-roof	Category I Non-Friable	375 SF
Main Mill	RF70-built-up roofing	Area 15-roof	Category I Non-Friable	2,520 SF
Main Mill	T71-silver/black perimeter/penetration flashing tar	Area 15-roof	Category I Non-Friable	260 SF
Main Mill	T72-silver/black perimeter flashing tar	Area 63-roof	Category I Non-Friable	180 SF
Main Mill	RF72-built-up roofing	Area 07-roof	Category I Non-Friable	17,800 SF
Main Mill	Built-up roofing debris (RF72)	Area 07	Category I Non-Friable	25 SF
Main Mill	RF73-built-up roofing	Area 07 & 10-elevated roof	Category I Non-Friable	28,230 SF
Main Mill	RF94-silver built-up roofing	Area 07-roof	Category I Non-Friable	6,840 SF
Main Mill	T73-black perimeter/penetration flashing tar	Area 07 -roof	Category I Non-Friable	2,720 SF
Main Mill	T74- black perimeter flashing tar	Area 07 & 10-elevated roof	Category I Non-Friable	2,370 SF
Main Mill	T92-silver/black perimeter/penetration flashing tar	Area 07-roof	Category I Non-Friable	915 SF
Main Mill	C56-exterior white caulk on fiberglass panel base seams	Area 07-roof	Category II Non-Friable	300 LF
Main Mill	C57-red caulk between all seam joints (wall, roof, floor)	Area 07-roof-HVAC	Category II Non-Friable	720 LF
Main Mill	MINS1-light grey insulation in metal panels on walls and all sides	Area 07-roof	Friable	1,800 SF
Main Mill	RF74-built-up roofing	Area 80 & 81 roof	Category I Non-Friable	42,400 SF
Main Mill	T75-black perimeter/penetration flashing tar	Area 80 & 81-roof	Category I Non-Friable	4,200 SF
Main Mill	RF75- built-up roofing	Area 80A-roof	Category I Non-Friable	1,900 SF
Main Mill	T76- black perimeter/penetration flashing tar	Area 80A-roof	Category I Non-Friable	1,200 SF
Main Mill	RF78-built-up roofing	Area 45-roof	Category I Non-Friable	3,030 SF
Main Mill	RF79-white asphalt shingle	Area 45-roof	Category I Non-Friable	4,500 SF




Attachment A: Remaining Regulated Materials
Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal

Building	Material	Location	NESHAP Category	Quantity
Main Mill	C60-silver/red caulk on metal HVAC seams	Area 10 & 46 - roof	Category II Non-Friable	1,800 LF
Main Mill	RF102-built-up roofing	Area 10B - roof	Category I Non-Friable	2,250 SF
Main Mill	T98-black perimeter/penetration flashing tar	Area 10B - roof	Category I Non-Friable	300 SF
Main Mill	RF92-silver/black built-up roofing	Area 46 - roof	Category I Non-Friable	14,000 SF
Main Mill	RF96-black/silver asphalt roll-on	Area 46 - roof	Category I Non-Friable	330 SF
Main Mill	T90-silver/black flashing tar	Area 46 - roof	Category I Non-Friable	810 SF
Main Mill	WG80-interior white glaze on 12-pane metal window	Area 46 - roof	Category II Non-Friable	42 EA
Main Mill	T91-black perimeter/penetration flashing tar	Area 46A - roof	Category I Non-Friable	1,000 SF
Main Mill	WG81-light grey window caulk on elevator window roof	Area 46A - roof	Category II Non-Friable	4 EA
Main Mill	C61-white/tan caulk in parapet wall	Area 46A - roof	Category II Non-Friable	100 LF
Main Mill	RF97-built-up roofing	Area 8/13 - roof	Category I Non-Friable	2,660 SF
Main Mill	T93-black perimeter/penetration flashing tar	Area 8/13 - roof	Category I Non-Friable	370 SF
Main Mill	T94-black perimeter/penetration flashing tar	Area 82A - roof	Category I Non-Friable	180 SF
Main Mill	RF99-built-up roofing	Area 82B - roof	Category I Non-Friable	2,360 SF
Main Mill	T95-black perimeter/penetration flashing tar	Area 82B - roof	Category I Non-Friable	800 SF
Main Mill	T96-black perimeter/penetration flashing tar	Area 82C - roof	Category I Non-Friable	180 SF
Main Mill	RF101-built-up roofing	Area 62 - roof	Category I Non-Friable	2,900 SF
Main Mill	T97-black perimeter/penetration flashing tar	Area 62 - roof	Category I Non-Friable	255 SF
Main Mill	RF105-silver built-up roofing	Area 60A - roof	Category I Non-Friable	4,200 SF
Main Mill	T99-silver/black perimeter/penetration flashing tar	Area 60A - roof	Category I Non-Friable	500 SF
Main Mill	T100-black/perimeter/penetration flashing tar	Area 20, 41, 43 & 60 - roof	Category I Non-Friable	1,200 SF
Main Mill	T102- black perimeter/penetration flashing tar	Area 60 - roof	Category I Non-Friable	200 SF
Main Mill	RF108-built-up roofing	Area 60 - lower roof	Category I Non-Friable	1,800 SF
Main Mill	RF107-built-up roofing	Area 20 - roof	Category I Non-Friable	600 SF
Main Mill	T101-black perimeter flashing tar	Area 20 - roof	Category I Non-Friable	110 SF




Attachment A: Remaining Regulated Materials
Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal

Building	Material	Location	NESHAP Category	Quantity
Main Mill	RG8-tan rope gasket	Area 60- lower roof	Category I Non-Friable	250 LF
Brick House				
102	G6 - tan glue behind metal wall panels	Brick house- room 10	Category II Non-Friable	450 sf
102	P12 - loose aircell pipe insulation	Brick house- room 17	Friable	9 LF
102	9" x 9" white w/black streaks floor tile (FT2)	Brick house - room 14	Category I Non-Friable	75 sf
102	WC2 - exterior white window caulk	Brick house - 1st and 2nd floor exterior	Category II Non-Friable	30 windows
102	DC1 - exterior cream door caulk	Brick house - 1st floor exterior	Category II Non-Friable	4 doors
102	RF1 - silver tar coating over metal	Brick house - rear porch roof	Category I Non-Friable	380 sf
102	FL1 - black flashing tar	Brick house - front porch roof	Category I Non-Friable	60 sf
102	RF3 - grey asphalt roll-on (top layer)	Brick house - soffit roof	Category I Non-Friable	300 sf
102	FL2 - black flashing tar	Brick house - soffit roof	Category I Non-Friable	60 sf
102	TP1 - black transit panel in electric panel	Brick house - basement - electric panel	Category II Non-Friable	1 sf
102	T1 - tar coating over fiberglass duct to HVAC	Brick house exterior - B side	Category II Non-Friable	12 sf
102	C1 - cream caulk around conduit junction box	Brick house - exterior - B side	Category II Non-Friable	1 lf
102	P11 - mag pipe insulation	Brick house - basement (debris on floor below chase)	Friable	25 lf
102	9" x 9" tan confetti floor tile (FT1)	Brick house - rooms 1, 2, 3, 4, 5 and 7	Category I Non-Friable	1,000 sf
102	G5 - tan glue behind wall panel	Brick house - room 13	Category II Non-Friable	400 sf
Other MMA Outbuildings and WWTPA				
Outbuildings	Electrical boxes (w/ one or more of the following: EC1, EC2, EC3, EBB1, EP1, EP3, IB1, EPI2 and ABEB1)	Out Buildings - throughout (multiple types of boxes w/ predominantly Cutler & Hammer, GE & AB)	Category II Non-Friable	70 EA
Outbuildings	Pipe gaskets (PG1, PG4, PG5 & PG14)	Out Buildings-throughout	Category I Non-Friable	150 EA
107	PG1-pipe gasket	Well pump house 6	Category I Non-Friable	1 SF
107	BC1-dark grey caulk under metal wall frame	Well pump house 6	Category II Non-Friable	40 LF
110	T1-silver/black tar coating	Well pump house 2-roof	Category I Non-Friable	120 SF
111	RF1-built-up roofing	Oil tank building-roof	Category I Non-Friable	360 SF
111	PER1-black perimeter flashing	Oil tank building-roof	Category I Non-Friable	10 SF



Attachment A: Remaining Regulated Materials
Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal


Building	Material	Location	NESHAP Category	Quantity
111	PEN1-black penetration flashing	Oil tank building-roof	Category I Non-Friable	5 SF
111	PI1-white calsil type pipe insulation and associated mudded fittings	Oil tank building (underground pipes w/ PI1 run to the way to the Main Mill)	Friable	50 LF identifiable
111	Transite Pipe - underground	Runs from Building/Structure 111 to 60	Friable	50 LF identifiable
111	WG3-exterior white window glaze on 3-pane metal window	Oil tank building-exterior	Category II Non-Friable	4 windows
112	T4-black/ grey tar coating on roof fan	Large metal shed 2-roof	Category I Non-Friable	15 SF
Near 112	C7-red caulk between metal seams (between seam/seam)	HVAC1 & HVAC1	Category II Non-Friable	240 LF
Near 112	C8-white caulk between ductwork seams	HVAC1	Category II Non-Friable	60 LF
Near 112	C9-interior grey door caulk (on door)	HVAC1 & HVAC2	Category II Non-Friable	30 LF
Near 112	PS1-black pipe sealant coating	HVAC1 -exterior	Category II Non-Friable	5 SF
128	C10-interior white caulk on vent	Natural gas yard shed-exterior	Category II Non-Friable	5 LF
128	C11-exterior white door caulk	Natural gas yard shed-exterior	Category II Non-Friable	15 LF
128	C12-exterior white caulk along roof on edges	Natural gas yard shed-roof	Category II Non-Friable	10 SF
104	FT1-9"x9" black floor tile (in box)	Shed 1-room 1	Category I Non-Friable	1 box
104	DWG5-white window glaze on single pane door window	Shed 1 - A-side	Category II Non-Friable	1 door
104	T36-silver tar coating on metal roof	Shed 1-room 1	Category I Non-Friable	1,200 SF
104	PG6-cream pipe gasket	Shed 1 - room 1	Category I Non-Friable	1 gasket
118	Joint compound associated with SHR2	Sewer lift building - room 1	Category II Non-Friable	~500 SF
North of 111	WG4-white window glaze on 6-pane metal window	D-side of oil tank building - debris pile	Category II Non-Friable	1 window
67/88	WG14-exterior white window glaze on metal window		Category II Non-Friable	2 windows
121	R15-black asphalt roll-on	Waste pump house	Category I Non-Friable	640 SF
121	RF16-built-up roofing	Waste pump house	Category I Non-Friable	630 SF
66	TP5-transite panel	room 1 (room 4 walls)	Category II Non-Friable	125 SF
South of 66	TP5-transite panel	debris on road between Building 66 and clarifier	Category II Non-Friable	5 SF
East of 125	T14-seam tar on round concrete holding tank	Round concrete holding tank (between defoamer shed and clarifier tanks)	Category I Non-Friable	15 SF
83	T16-tar flashing on screws around perimeter	shed roof	Category I Non-Friable	3 SF



Inv #13182 PAID

OK 1740

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 5:16)




Date of Notification (1) 07 / 29 / 19		Name of Building Owner/Operator (2) Metro Real Estate Development Corp.		RECEIVED AUG - 1 2019 ASBESTOS CONTROL & LICENSING					
Agencies Notified ☒ EPA ☒ DOLWD ☒ DOH ☐ DCA (NJAC 5:23-8)		Type Notification ☐ Initial ☒ Amended Amendment #3 ☐ Emergency (including justification) ☐ Cancellation				Street Address 2 Broad Street, Suite 305 City, State, Zip Code Bloomfield, NJ 07003			
		Name of Contact Warren Sprake				Telephone Number 908-670-5711			
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) Commercial				Type of Facility (4) ☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e., private and commercial buildings, homes, etc.)					
Street Address 609-611 Bloomfield Avenue				Square Feet					
City (5) Bloomfield, NJ				# of Floors					
County (6) Essex				Bldg. Age					
County Code (7)(STATE USE ONLY)		Current Use (Prior if being demolished)							
Name of Monitoring Firm Hired by Building Owner (8) Mark Jovic Consulting LLC		ASCM No.		Name of Abatement Contractor (9) ALL PRO MANAGEMENT LLC					
Street Address 87 Main Street, Suite A		Street Address 27 Outwater Lane							
City, State, Zip Code Lincoln Park, NJ 07035		City, State, Zip Code Garfield, NJ 07026							
Project Manager for Monitoring Firm Mark Jovic		Telephone No. 973-650-0932		License No. 1188					
Start Date (10) 07 / 15 / 19		Scheduled Completion Date (11) 12 / 19 / 19		Name of OSHA Monitor ALL PRO MANAGEMENT LLC					
Occupancy Status During Abatement (Check only one) ☒ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Facility Hours - Describe Time of Abatement: ____AM-____PM/____PM-____AM				Street Address 27 Outwater Lane					
				City, State, Zip Code Garfield, NJ 07026					
Scope of Work (Check all that apply)									
☐ ≥3 sf or ≥3 lf ☒ ≥160 sf or ≥260 lf ☐ Renovation ☒ Demolition ☒ Full Containment with Negative Pressure ☐ Mini-Enclosure ☒ Glovebag Procedure ☒ Non-Exempted (*) and Non-Friable Procedure									
Location of Asbestos-Containing Material (ACM) TO BE ABATED IN Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)		Description of Asbestos Containing Material (ACM) (i.e., thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type				
	Yes	No			N/A	Removal	Repair	Encapsulate	Enclosure
Basement	☐	☐	☒	Pipe Insulation	50 LF	☒	☐	☐	☐
1st & 2nd Floor	☐	☐	☒	Plaster	8,000 SF	☒	☐	☐	☐
1st Floor	☐	☐	☒	Fluffy Material	800 SF	☒	☐	☐	☐
Exterior	☐	☐	☒	Window Caulking	25 LF	☒	☐	☐	☐
Name of Registered Waste Hauler Century Waste, LLC/Newark Carting		NJDEP Waste Hauler ID No. 32797 / 0283		Cubic Yards of Waste As Needed		Name of Registered Landfill			
City, State Elizabeth, NJ / Newark, NJ		Disposal Date TBD		City, State Morrisville, PA / Pen Argyl, PA					
Completed By (Print or Type) Allen Monchik		Title Project Manager		Signature Allen Monchik		Date 7/29/19			

RECEIVED
AUG - 1 2019
ASBESTOS CONTROL &
LICENSING
Abatement Type

Completed by: (Print or type) Allen Monchik	Title: Project Manager	Signature: <i>Allen Monchik</i>	Date: 7/29/19
--	------------------------	------------------------------------	------------------

Inv#13274
PAID
MD25824255028

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 12:120)



Date of Notification (1) 07/26/2019		Name of Building Owner/Operator (2) Ellen Sleeter							
Agencies Notified	Type Notification	Street Address [REDACTED]							
☒ EPA ☒ DEP ☒ DOL ☒ DOH ☐ DCA	☒ Initial ☐ Amended ☐ Amendment # _____ ☐ Emergency (including justification) ☐ Cancellation	City, State, Zip Code Maplewood, NJ 07040							
		Name of Contact Ellen Sleeter	Telephone Number						
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) House		Type of Facility (4) ☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e. private & commercial buildings, homes, etc.)							
Street Address [REDACTED]		Square Feet N/A	# of Floors N/A						
City (5) Maplewood		Bldg. Age N/A							
County (6) Essex	County Code (7) (STATE USE ONLY) _____	Current Use (Prior if being demolished) House							
Name of Monitoring Firm Hired by Building Owner (8) N/A		ASCM No.	Name of Abatement Contractor (9) D&S Abatement, Inc.						
Street Address		Street Address 11 Rosengren Avenue							
City, State, Zip Code		City, State, Zip Code Totowa, NJ 07512							
Project Manager for Monitoring Firm		Telephone No. 9733458685	License No. 01311						
Start Date (10) 08/06/2019	Scheduled Completion Date (11) 08/08/2019	Name of OSHA Monitor D&S Abatement, Inc.							
Occupancy Status During Abatement (Check Only One) ☐ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Facility Hours ☒ Other – Describe: Occupied		Street Address 11 Rosengren Avenue							
		City, State, Zip Code Totowa, NJ 07512							
Scope of Work (Check All That Apply)									
☐ ≥3 sf or ≥3 lf ☒ ≥160 sf or ≥260 lf		☒ Renovation ☐ Demolition							
		☒ Full Containment with Negative Pressure ☐ Mini-Enclosure ☐ Glovebag Procedure ☐ Non-Exempted (*) and Non-Friable Procedure							
Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> In Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
Attic		X		Vermiculite	650 SF	X			
Name of Registered Waste Hauler Atlantic Carting		NJDEP Waste Hauler ID No. 26085	Cubic Yards of Waste TBD	Name of Registered Landfill Grand Central					
City, State Wayne, NJ			Disposal Date TBD	City, State Pen Argyl, PA					
Completed by Oliver Hegedis		Title Project Manager	Signature [Signature]	Date 07/26/2019					

CK0026

Inv # 13231

PAID

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 12:120)

0026

Date of Notification (1) 7/27/19		Name of Building Owner/Operator (2) Nick Lombardi							
Agencies Notified	Type Notification	Street Address [REDACTED]							
☐ EPA ☐ DEP ☒ DOL	☒ Initial ☐ Amended Amendment # _____ ☒ Emergency (including justification) ☐ Cancellation	City, State, Zip Code Maplewood, NJ							
☐ DOH ☐ DCA		Name of Contact Nick							
Telephone Number [REDACTED]									
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) [REDACTED]		Type of Facility (4) ☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e. private & commercial buildings, homes, etc.)							
Street Address [REDACTED]									
City (5) Maplewood, NJ		Square Feet 1200	# of Floors 1						
County (6) Essex		Bldg. Age +50							
County Code (7) (STATE USE ONLY) _____		Current Use (Prior if being demolished) Residential							
Name of Monitoring Firm Hired by Building Owner (8)		ASCM No.	Name of Abatement Contractor (9) Dinago Corp.						
Street Address		Street Address 339-Lafayette Street							
City, State, Zip Code		City, State, Zip Code Newark, NJ 07105							
Project Manager for Monitoring Firm		Telephone No. 973-491-0877	License No. 01240						
Start Date (10) 7/30/19	Scheduled Completion Date (11) 7/31/19	Name of OSHA Monitor							
Occupancy Status During Abatement (Check Only One) ☒ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Facility Hours ☐ Other - Describe: _____		Street Address							
		City, State, Zip Code							
Scope of Work (Check All That Apply)									
☐ ≥ 3 sf or ≥ 3 lf ☐ ≥ 160 sf or ≥ 260 lf ☒ Renovation ☐ Demolition ☐ Full Containment with Negative Pressure ☒ Mini-Enclosure ☐ Glovebag Procedure ☐ Non-Exempted (*) and Non-Friable Procedure									
Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> In Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
Basement		X		Pipe insulation	100Lf.	X			
Name of Registered Waste Hauler Newark Carting Inc.		NJDEP Waste Hauler ID No. 04509	Cubic Yards of Waste	Name of Registered Landfill ISES BETHLEHEM LANDFILL					
City, State PO BOX 5670, NEWARK, NJ 07105			Disposal Date	City, State BETHLEHEM, PA.					
Completed by Carlos Gomes		Title President	Signature [Signature]	Date 7/27/19					


Inv #13275

Print Form

CK 7483

PAID

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 12:120)



Date of Notification (1) 7/29/19		Name of Building Owner/Operator (2) Joseph Idell Private Home							
Agencies Notified	Type Notification	Street Address [REDACTED]							
☒ EPA ☒ DEP ☒ DOL ☒ DOH ☐ DCA	☒ Initial ☐ Amended ☐ Amendment # ☐ Emergency (including justification) ☐ Cancellation	City, State, Zip Code Medford NJ 08055							
		Name of Contact Joe	Telephone Number						
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) Joseph Idell Private Home		Type of Facility (4)							
Street Address [REDACTED]		☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e. private & commercial buildings, homes, etc.)							
City (5) Medford NJ 08055		Square Feet 1000+	# of Floors 2						
County (6) Burlington		County Code (7) (STATE USE ONLY)	Bldg. Age 50+						
Name of Monitoring Firm Hired by Building Owner (8) N/A		Name of Abatement Contractor (9) Pernaco Inc							
Street Address		Street Address PO Box 329							
City, State, Zip Code		City, State, Zip Code West Berlin NJ 08091							
Project Manager for Monitoring Firm		Telephone No. 856-753-9800	License No. 00727						
Start Date (10) 8/9/19	Scheduled Completion Date (11) 8/13/19	Name of OSHA Monitor Same							
Occupancy Status During Abatement (Check Only One)		Street Address							
☒ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Facility Hours ☐ Other - Describe:		City, State, Zip Code							
Scope of Work (Check All That Apply)									
☐ ≥ 3 sf or ≥ 3 lf ☒ ≥ 160 sf or ≥ 260 lf		☒ Renovation ☐ Demolition							
		☐ Full Containment with Negative Pressure ☒ Mini-Enclosure ☐ Glovebag Procedure ☐ Non-Exempted (*) and Non-Friable Procedure							
Location of Asbestos-Containing Material (ACM) TO BE ABATED In Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
Crawl Space			x	Pipe Insulation	20 LF	x			
Name of Registered Waste Hauler United Roll Off		NJDEP Waste Hauler ID No. 22459	Cubic Yards of Waste 2	Name of Registered Landfill G.R.O.W.S.					
City, State Elm NJ		Disposal Date 8/13/19		City, State Morrisville PA 19067					
Completed by Anthony T Perna		Title President	Signature 			Date 7/29/19			

INV#13225
CK1012 PAID

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 12:120)

Date of Notification (1) 07/29/2019		Name of Building Owner/Operator (2) Manasquan Board of Education		DO NOT WRITE IN THESE SPACES CHECK NO. 1512 ASBESTOS CONTROL & LICENSING WASH. STATE DEPT. OF LABOR	
Agencies Notified	Type Notification	Street Address 169 Broad Street		City, State, Zip Code Manasquan, New Jersey 08738	
☐ EPA ☒ DEP ☒ DOL ☒ DOH ☐ DCA	☐ Initial ☐ Amended ☐ Amendment # ☒ Emergency (including justification) ☐ Cancellation	Name of Contact		Telephone Number	
FACILITY INFORMATION					
Name of Facility Where Abatement is Taking Place (3) Manasquan High School			Type of Facility (4)		
Street Address 167 Broad Street			☒ School (K-12) ☐ Subchapter 8 (Other than K-12) ☐ Other (i.e. private & commercial buildings, homes, etc.)		
City (5) Manasquan, New Jersey 08738			Square Feet 30,000	# of Floors 3	Bldg. Age 50+
County (6) Monmouth		County Code (7) (STATE USE ONLY)	Current Use (Prior if being demolished) High School		
Name of Monitoring Firm Hired by Building Owner (8) Environmental Connection, Inc		ASCM No. 00057	Name of Abatement Contractor (9) Lilich Corporation		
Street Address 120 North Warren Street		Street Address 245 Union Boulevard			
City, State, Zip Code Trenton, New Jersey 08608		City, State, Zip Code Totowa, New Jersey 07512			
Project Manager for Monitoring Firm Roland C. Jones		Telephone No. 609-392-4200	Telephone No. 973-225-8400	License No. 01104	
Start Date (10) 07/30/2019		Scheduled Completion Date (11) 08/09/2019		Name of OSHA Monitor Itis Environmental Laboratories, LLC	
Occupancy Status During Abatement (Check Only One)			Street Address 2333 Route 22 West		
☐ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Facility Hours ☒ Other - Describe: 8:00 AM			City, State, Zip Code Union, NJ 07083		
Scope of Work (Check All That Apply)					
☒ ≥ 3 sf or ≥ 3 lf ☐ ≥ 160 sf or ≥ 260 lf		☒ Renovation ☐ Demolition		☐ Full Containment with Negative Pressure ☐ Mini-Enclosure ☐ Glove Bag Procedure / Limited Containment & Tent ☒ Non-Exempted (*) and Non-Friable Procedure	
Location of Asbestos-Containing Material (ACM) TO BE ABATED In Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)
	Yes	No	N/A		
Rooms 120, 121		X		Pipe insulation (wrap & cut)	50 LF
Name of Registered Waste Hauler Lilich Corporation		NJDEP Waste Hauler ID No. 18724	Cubic Yards of Waste 1	Name of Registered Landfill Fairless Landfill	
City, State Totowa, New Jersey		Disposal Date 08/09/2019		City, State Morrisville, PA	
Completed by Adriana Olejarova		Title President		Signature 	Date 07/29/2019

Inv# 13263
CKILL PAID

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 12:120)

Date of Notification (1) 07/29/2019		Name of Building Owner/Operator (2) Dunellen Board of Education	
Agencies Notified	Type Notification	Street Address	DOL - 10 DAY Check No. 1611 ASBESTOS CONTROL & LICENSING
☒ EPA ☒ DEP ☒ DOL	☐ Initial ☐ Amended ☐ Amendment #	High and Leigh Streets	
☒ DOH ☐ DCA	☒ Emergency (including justification) ☐ Cancellation	City, State, Zip Code Dunellen, New Jersey 08812	
		Name of Contact Gene Mosely	Telephone Number 732-968-3325

FACILITY INFORMATION


Name of Facility Where Abatement is Taking Place (3) Dunellen High School		Type of Facility (4) ☒ School (K-12) ☐ Subchapter B (Other than K-12) ☐ Other (i.e. private & commercial buildings, homes, etc.)	
Street Address 411 1st Street		Square Feet 80,000	# of Floors 2
City (5) Dunellen, New Jersey 08812		Bldg. Age 50+	
County (6) Middlesex	County Code (7) (STATE USE ONLY)	Current Use (Prior if being demolished) High School	
Name of Monitoring Firm Hired by Building Owner (8) Environmental Connection, Inc.		ASCM No. 00057	Name of Abatement Contractor (9) Lilich Corporation
Street Address 120 North Warren Street		Street Address 808 McBride Ave	
City, State, Zip Code Trenton, New Jersey 08608		City, State, Zip Code Woodland Park, New Jersey	
Project Manager for Monitoring Firm Dominick Dercole		Telephone No. 609-392-4200	License No. 01104
Start Date (10) 07/29/2019	Scheduled Completion Date (11) 07/30/2019	Name of OSHA Monitor Iris Environmental Laboratories, LLC	
Occupancy Status During Abatement (Check Only One) ☒ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Facility Hours ☐ Other - Describe:		Street Address 2333 Route 22 West	
Scope of Work (Check All That Apply) ☒ ≥3 sf or ≥3 lf ☐ ≥160 sf or ≥280 lf ☒ Renovation ☐ Demolition ☐ Full Containment with Negative Pressure ☐ Mini-Enclosure ☐ Glove Bag Procedure / Limited Containment & Tent ☐ Non-Exempted (*) and Non-Frangible Procedure		City, State, Zip Code Union, NJ 07083	

Location of Asbestos-Containing Material (ACM) In Facility (13) TO BE ABATED	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
1st Floor hallway		X		Pipe Fitting Insulation (Wrap & Cut)	20 LF	X			

Name of Registered Waste Hauler Lilich Corporation	NJDEP Waste Hauler ID No. 18724	Cubic Yards of Waste 5	Name of Registered Landfill Fairless Landfill
City, State Woodland Park, New Jersey		Disposal Date 07/05/2019	City, State Morrisville, PA
Completed by Adriana Olejarova	Title President	Signature 	Date 07/29/2019

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 12:120)

Inv# 13278
MD24158774013 PAID




Date of Notification (1) 07/26/2019		Name of Building Owner/Operator (2) Diana Kinsella							
Agencies Notified	Type Notification	Street Address [REDACTED]							
☒ EPA ☒ DEP ☒ DOL ☒ DOH ☐ DCA	☒ Initial ☐ Amended ☐ Amendment # _____ ☐ Emergency (including justification) ☐ Cancellation	City, State, Zip Code Bloomfield, NJ 07003							
		Name of Contact Dana Kinsella	Telephone Number						
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) House		Type of Facility (4)							
Street Address [REDACTED]		☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e. private & commercial buildings, homes, etc.)							
City (5) Bloomfield		Square Feet N/A	# of Floors N/A						
County (6) Essex		County Code (7) (STATE USE ONLY) _____	Bldg. Age N/A						
Name of Monitoring Firm Hired by Building Owner (8) N/A		ASCM No.	Name of Abatement Contractor (9) D&S Abatement, Inc.						
Street Address		Street Address 11 Rosengren Avenue							
City, State, Zip Code		City, State, Zip Code Totowa, NJ 07512							
Project Manager for Monitoring Firm		Telephone No.	Telephone No. 9733458685						
			License No. 01311						
Start Date (10) 08/08/2019		Scheduled Completion Date (11) 08/09/2019							
Name of OSHA Monitor D&S Abatement, Inc.									
Occupancy Status During Abatement (Check Only One)		Street Address 11 Rosengren Avenue							
☐ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Facility Hours ☒ Other - Describe: <u>Occupied</u>		City, State, Zip Code Totowa, NJ 07512							
Scope of Work (Check All That Apply)									
☐ ≥3 sf or ≥3 lf ☒ ≥160 sf or ≥260 lf ☒ Renovation ☐ Demolition ☐ Full Containment with Negative Pressure ☐ Mini-Enclosure ☐ Glovebag Procedure ☒ Non-Exempted (*) and Non-Friable Procedure									
Location of Asbestos-Containing Material (ACM) TO BE ABATED In Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
Basement		X		VAT	530 SF	X			
Name of Registered Waste Hauler Atlantic Carting		NJDEP Waste Hauler ID No. 26085	Cubic Yards of Waste TBD	Name of Registered Landfill Grand Central					
City, State Wayne, NJ		Disposal Date TBD		City, State Pen Argyl, PA					
Completed by Oliver Hegedis		Title Project Manager		Signature [Signature]		Date 07/26/2019			


Inv# 13279
CK 1230 PAID

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 12:120)

CK 1230

Date of Notification (1) 07/30/2019		Name of Building Owner/Operator (2) Veronica Ng		RECEIVED AUG - 1 2019					
Agencies Notified		Type Notification				Street Address			
☐ EPA ☐ DEP ☒ DOL ☒ DOH ☐ DCA		☒ Initial ☐ Amended Amendment # _____ ☐ Emergency (including justification) ☐ Cancellation				City, State, Zip Code Hawthorne, NJ 07506 Name of Contact Veronica Telephone Number CONTROL & _____			
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) Private home				Type of Facility (4)					
Street Address				☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e. private & commercial buildings, homes, etc.)					
City (5) Hawthorne				Square Feet	# of Floors				
County (6) Passaic		County Code (7) (STATE USE ONLY)		Current Use (Prior if being demolished)					
Name of Monitoring Firm Hired by Building Owner (8)		ASCM No.		Name of Abatement Contractor (9)					
Street Address				Removal Safety LLC					
City, State, Zip Code				Street Address					
Project Manager for Monitoring Firm		Telephone No.		8 Crosby Ave					
Start Date (10) 08/08/2019		Scheduled Completion Date (11) 08/14/2019		City, State, Zip Code					
Occupancy Status During Abatement (Check Only One)				Paterson, NJ 07502					
☐ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Facility Hours ☒ Other - Describe: 8:00 am - 4:30 pm				Telephone No.					
				License No.					
				973-400-8711					
				01332					
				Name of OSHA Monitor					
				Same as (9)					
				Street Address					
				City, State, Zip Code					
Scope of Work (Check All That Apply)									
☒ ≥3 sf or ≥3 lf ☐ ≥160 sf or ≥260 lf		☒ Renovation ☐ Demolition		☐ Full Containment with Negative Pressure ☒ Mini-Enclosure ☐ Glovebag Procedure ☐ Non-Exempted (*) and Non-Friable Procedure					
Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> In Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
Basement			X	Pipe insulation	70 LF	X		X	
Name of Registered Waste Hauler		NJDEP Waste Hauler ID No.		Cubic Yards of Waste	Name of Registered Landfill				
Removal Safety LLC		0037007		2	Fairless				
City, State				Disposal Date	City, State				
Paterson, NJ				TBD	Morrisville, PA				
Completed by		Title		Signature		Date			
Lasko Veskov		President				07/30/2019			

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 5:16)



NO CK

Date of Notification (1) <u>7</u> / <u>18</u> / <u>19</u>		Name of Building Owner/Operator (2) Medford Leas / Job #1907-2463 Chk. #NA							
Agencies Notified ☐ EPA ☒ DOLWD ☒ DHSS ☐ DCA (NJAC 5:23-8)	Type Notification ☐ Initial ☒ Amended Amendment # <u>1</u> ☐ Emergency (including justification) ☐ Cancellation	Street Address One Medford Leas Way City, State, Zip Code Medford, NJ 08055 Name of Contact Steve Mirarchi Telephone Number 215-539-9124							
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) Medford Leas		Type of Facility (4) ☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e., private and commercial buildings, homes, etc.)							
Street Address 1 Medford Leas Road		Square Feet # of Floors Bldg. Age							
City (5) Medford		County Code (7)(STATE USE ONLY) Current Use (Prior if being demolished) Senior Housing/Residential Living							
County (6) Burlington		Name of Abatement Contractor (9) Asbestos and Mold Services, Corp.							
Name of Monitoring Firm Hired by Building Owner (8) Criterion Laboratories		ASCM No.							
Street Address 400 Street Road		Street Address PO Box 1239							
City, State, Zip Code Bensalem, PA 19020		City, State, Zip Code Delran, NJ 08075							
Project Manager for Monitoring Firm Mike Panepresso		Telephone No. 215-244-1300	License No. 00862						
Start Date (10) <u>7</u> / <u>29</u> / <u>19</u>	Scheduled Completion Date (11) <u>8</u> / <u>1</u> / <u>19</u>	Name of OSHA Monitor EMSL Analytical, Inc.							
Occupancy Status During Abatement (Check only one) ☒ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Facility Hours - Describe Time of Abatement: ____AM-____PM/____PM-____AM		Street Address 200 U.S. Route 130 North City, State, Zip Code Cinnaminson, NJ 08077							
Scope of Work (Check all that apply) ☒ ≥3 sf or ≥3 lf ☒ Renovation ☐ Full Containment with Negative Pressure ☐ ≥160 sf or ≥260 lf ☐ Demolition ☒ Glovebag Procedure ☐ Non-Exempted (*) and Non-Friable Procedure									
Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> IN Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e., thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
Throughout 3 work areas	☐	☐	☒	Elbows/Fittings with Insulation	45 each	☒	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
Name of Registered Waste Hauler Freehold Cartage, Inc.		NJDEP Waste Hauler ID No. 02265	Cubic Yards of Waste 5	Name of Registered Landfill GROWS Landfill					
City, State Freehold, NJ			Disposal Date 8/2/19	City, State Morrisville, PA 19067					
Completed By (Print or Type) Kimberly A. Trumbetti		Title Office Coordinator	Signature 			Date 7-26-19			

Inv# 13281

CK 5417

PAID

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 5:16)

RECEIVED

AUG 1 2019

/ Job #1907-2471 Chk. #5417

ASBESTOS CONTROL & LICENSING

Date of Notification (1) 7 / 30 / 19		Name of Building Owner/Operator (2) William A & Mary R Shurts		Street Address [REDACTED]	
Agencies Notified ☒ EPA ☒ DOLWD ☒ DHSS ☐ DCA (NJAC 5:23-8)		Type Notification ☒ Initial ☐ Amended Amendment # _____ ☐ Emergency (including justification) ☐ Cancellation		City, State, Zip Code Lambertville, NJ 08530	
Name of Contact William & Mary Shurts				Telephone Number [REDACTED]	
FACILITY INFORMATION					
Name of Facility Where Abatement is Taking Place (3) Residential Property				Type of Facility (4) ☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e., private and commercial buildings, homes, etc.)	
Street Address [REDACTED]				Square Feet +/- 2000 SF	
City (5) Lambertville				# of Floors 2	
County (6) Hunterdon				Bldg. Age 100	
County Code (7)(STATE USE ONLY)		Current Use (Prior if being demolished) Residential			
Name of Monitoring Firm Hired by Building Owner (8) Finog Environmental		ASCM No.		Name of Abatement Contractor (9) Asbestos and Mold Services, Corp.	
Street Address 617 Stokes Road Suite 4-318		Street Address 3859 Sylon Boulevard			
City, State, Zip Code Medford, NJ 08055		City, State, Zip Code Hainesport, NJ 08036			
Project Manager for Monitoring Firm Rebecca Rubnitz		Telephone No. 888-715-2211		License No. 00862	
Start Date (10) 8 / 8 / 19		Scheduled Completion Date (11) 8 / 9 / 19		Name of OSHA Monitor EMSL Analytical, Inc.	
Occupancy Status During Abatement (Check only one) ☒ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Facility Hours - Describe Time of Abatement: _____ AM- _____ PM/ _____ PM- _____ AM				Street Address 200 U.S. Route 130 North	
				City, State, Zip Code Cinnaminson, NJ 08077	
Scope of Work (Check all that apply)					
☐ ≥3 sf or ≥3 lf		☒ Renovation		☐ Full Containment with Negative Pressure	
☒ ≥160 sf or ≥260 lf		☐ Demolition		☐ Mini-Enclosure	
				☒ Glovebag Procedure (tenting)	
				☐ Non-Exempted (*) and Non-Friable Procedure	
Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> IN Facility (13)		Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)		Description of Asbestos Containing Material (ACM) (i.e., thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF) 50 LF
Basement		☐ Yes ☐ No ☒ N/A		☒ Removal ☐ Repair ☐ Encapsulate ☐ Enclosure	
Name of Registered Waste Hauler Waste Management		NJDEP Waste Hauler ID No. 17273		Cubic Yards of Waste 5	
City, State Lafayette, NJ		Disposal Date 8/9/19		Name of Registered Landfill Grand Central	
Completed By (Print or Type) Kaysi Gruner		Title Office Assistant		Signature [Signature]	
				Date 7/30/19	


State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 5:16)

NOCK

Date of Notification (1) 6 / 5 / 19		Name of Building Owner/Operator (2) Trustees of Newark Academy / Job #1904-2430 Chk. #NA							
Agencies Notified ☒ EPA ☒ DOLWD ☒ DHSS ☒ DCA (NJAC 5:23-8)	Type Notification ☐ Initial ☒ Amended Amendment # 4 ☐ Emergency (including justification) ☐ Cancellation	Street Address 91 South Orange Avenue City, State, Zip Code Livingston, NJ 07039							
		Name of Contact Brian Stephenson	Telephone Number 201-247-1617						
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) Newark Academy		Type of Facility (4) ☐ School (K-12) ☒ Subchapter 8 (Other than K-12) ☐ Other (i.e., private and commercial buildings, homes, etc.)							
Street Address 91 South Orange Avenue									
City (5) Livingston		Square Feet 250,000	# of Floors 2						
		Bldg. Age 1965							
County (6) Essex	County Code (7) (STATE USE ONLY)		Current Use (Prior if being demolished) School						
Name of Monitoring Firm Hired by Building Owner (8) Envirovision		ASCM No.	Name of Abatement Contractor (9) Asbestos and Mold Services, Corp.						
Street Address 20-21 Wagaraw Road, Bld. 35 E		Street Address 3859 Sylon Boulevard							
City, State, Zip Code Fair Lawn, NJ 07410		City, State, Zip Code Hainesport, NJ 08036							
Project Manager for Monitoring Firm Fred Larson		Telephone No. 973-633-9145	Telephone No. 609-702-0400						
		License No. 00862							
Start Date (10) 6 / 24 / 19	Scheduled Completion Date (11) 7 / 31 / 19		Name of OSHA Monitor EMSL Analytical, Inc.						
Occupancy Status During Abatement (Check only one) ☒ Facility Closed/Vacated During Entire Period of Abatement ☒ Abatement Performed Outside of Normal Facility Hours - Describe Time of Abatement: _____ AM- _____ PM/ _____ PM- _____ AM		Street Address 200 U.S. Route 130 North							
		City, State, Zip Code Cinnaminson, NJ 08077							
Scope of Work (Check all that apply)									
☐ ≥3 sf or ≥3 lf ☒ Renovation ☒ Full Containment with Negative Pressure ☒ ≥160 sf or ≥260 lf ☐ Demolition ☐ Mini-Enclosure ☐ ☐ ☐ Glovebag Procedure ☐ ☐ ☐ Non-Exempted (*) and Non-Friable Procedure									
Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> IN Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e., thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
Throughout	☐	☐	☒	Ceiling Plaster	4,400 SF	☒	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
Name of Registered Waste Hauler Waste Management		NJDEP Waste Hauler ID No. 17273	Cubic Yards of Waste 5	Name of Registered Landfill Grand Central					
City, State Lafayette, NJ		Disposal Date 7/31/19		City, State Penn Argyle, PA					
Completed By (Print or Type) Kim Trumbetti		Title Ops Coordinator		Signature <i>Kim Trumbetti</i>		Date 7/29/19			

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 12:120)

Check # 25935




Inv # 13342
OK 25935 PAID

Date of Notification (1) 7/31/2019		Name of Building Owner/Operator (2) Princeton YMCA							
Agencies Notified	Type Notification	Street Address 59 Paul Robeson Place							
☒ EPA ☐ DEP ☒ DOL ☒ DOH ☐ DCA	☒ Initial ☐ Amended ☐ Amendment # ☐ Emergency (including justification) ☐ Cancellation	City, State, Zip Code Princeton, NJ 08540							
		Name of Contact Paul Zeler							
FACILITY INFORMATION Name of Facility Where Abatement is Taking Place (3) YMCA Street Address 59 Paul Robeson Place City (5) Princeton, NJ 08540 County (6) Mercer Type of Facility (4) ☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e. private & commercial buildings, homes, etc.) Square Feet 15000 # of Floors 2 Bldg. Age 60 +/- County Code (7) (STATE USE ONLY) Current Use (Prior if being demolished)									
Name of Monitoring Firm Hired by Building Owner (8) MECS		Name of Abatement Contractor (9) Stevens Environmental Services, Inc.							
Street Address PO Box 341		Street Address PO Box 322							
City, State, Zip Code Chesterfield, NJ 08515		City, State, Zip Code Allentown, NJ 08501							
Project Manager for Monitoring Firm Bill Weisgarber		Telephone No. 609 298-4070	Telephone No. 609 259-9688						
Start Date (10) 8/9/2019		Scheduled Completion Date (11) 8/12/2019	License No. 00493						
Occupancy Status During Abatement (Check Only One)		Name of OSHA Monitor MECS							
☐ Facility Closed/Vacated During Entire Period of Abatement ☒ Abatement Performed Outside of Normal Facility Hours ☐ Other - Describe: 6 pm - 2 am		Street Address PO Box 341							
		City, State, Zip Code Chesterfield, NJ 08515							
Scope of Work (Check All That Apply)									
☒ ≥ 3 sf or ≥ 3 lf ☐ ≥ 160 sf or ≥ 260 lf ☒ Renovation ☐ Demolition ☐ Full Containment with Negative Pressure ☒ Mini-Enclosure ☐ Glovebag Procedure ☐ Non-Exempted (*) and Non-Friable Procedure									
Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> In Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
Basement Pool Mech Room	X			Thermal Pipe Insulation	60 lf	X			
Name of Registered Waste Hauler Stevens Environmental Services		NJDEP Waste Hauler ID No. 18292	Cubic Yards of Waste 2	Name of Registered Landfill Fairless Landfill					
City, State Allentown, NJ		Disposal Date 8/13/2019		City, State Morrisville, PA					
Completed by Mahlon E. Stevens		Title Project Manager		Signature			Date 7/31/2019		

Inv# 13343
OK 3103 PAID

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 5:16)



Date of Notification (1) 7 / 29 / 19		Name of Building Owner/Operator (2) The College of New Jersey	
Agencies Notified ☐ EPA ☒ DOLWD ☒ DHSS ☐ DCA (NJAC 5:23-8)	Type Notification ☒ Initial ☐ Amended Amendment # _____ ☐ Emergency (including justification) ☐ Cancellation	Street Address 2000 Pennington Road City, State, Zip Code Ewing, NJ 08628 Name of Contact Matt Bonomo	
		Telephone Number 609-847-1886	

FACILITY INFORMATION

Name of Facility Where Abatement is Taking Place (3) TCNJ-Green Hall		Type of Facility (4) ☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e., private and commercial buildings, homes, etc.)	
Street Address 2000 Pennington Road		Square Feet	
City (5) Ewing		# of Floors	
County (6) MERCER		Bldg. Age	
County Code (7)(STATE USE ONLY)		Current Use (Prior if being demolished)	
Name of Monitoring Firm Hired by Building Owner (8) USA Environmental Manangement Inc		ASCM No.	
Street Address 344 West State Street		Name of Abatement Contractor (9) BRISTOL ENVIRONMENTAL, INC.	
City, State, Zip Code Trenton, NJ 08618		Street Address 1123 BEAVER STREET	
Project Manager for Monitoring Firm William Weisgarber		City, State, Zip Code BRISTOL, PA 19007	
Telephone No. 609-656-8101		Telephone No. 215-788-6040	
License No. 00509			
Start Date (10) 8 / 8 / 19		Scheduled Completion Date (11) 8 / 9 / 19	
Name of OSHA Monitor BRISTOL ENVIRONMENTAL, INC.			
Occupancy Status During Abatement (Check only one) ☐ Facility Closed/Vacated During Entire Period of Abatement ☒ Abatement Performed Outside of Normal Facility Hours - Describe Time of Abatement: 7:00AM-3:30PM/____PM-____AM		Street Address 1123 BEAVER STREET	
		City, State, Zip Code BRISTOL, PA 19007	

Scope of Work (Check all that apply)

- ☒ ≥3 sf or ≥3 lf
☐ ≥160 sf or ≥260 lf
☒ Renovation
☐ Demolition
☐ Full Containment with Negative Pressure
☒ Mini-Enclosure
☒ Glovebag Procedure
☐ Non-Exempted (*) and Non-Friable Procedure


Location of Asbestos-Containing Material (ACM) TO BE ABATED IN Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e., thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
Basement Hallway	☐	☒	☐	Pipe insulation-Wrap & Cut	70 LF	☒	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐

Name of Registered Waste Hauler BRISTOL ENVIRONMENTAL, INC.		NJDEP Waste Hauler ID No. 18706		Cubic Yards of Waste	Name of Registered Landfill FAIRLESS LANDFILL	
City, State BRISTOL, PA 19007		Disposal Date		City, State FAIRLESS HILLS, PA		
Completed By (Print or Type) Brian Scafiro		Title Estimator		Signature Brian Scafiro / JSK		Date 7-29-19

ASB-41
MAY 11 B519100

* Do not use this form for asbestos licensure exempted activities.

"WRAP AND CUT" REMOVAL PROCEDURES FOR INSULATED PIPE



DESCRIPTION OF THE WORK

This Section describes the procedures to remove asbestos containing insulating materials utilizing "wrap and cut" methods.

PRODUCTS

- Amended Water
- Wettable/Adhesive Lagging Cloth
- Encapsulant (if specified in Section "Scope of Work")
- Disposal Bags
- Six mil polyethylene sheeting
- HEPA vacuum
- Duct Tape
- "Saw-zall"

DESCRIPTION OF THE WORK

All work shall be conducted in strict accordance with applicable federal, state and local regulations and shall be coordinated through the Owner's representative.

Bristol Environmental Inc. shall adequately wet all ACM with amended water and wrap all exposed thermal system insulation with two individual layers of 6-mil polyethylene sheeting. Each layer shall be sealed with high grade duct tape, and "candy-striped" around the pipe system to the best seal possible.

Upon the wetting, wrapping and sealing of thermal system insulation Bristol Environmental Inc. shall cut the pipe in existing spatial openings into sections no greater than ten (10) linear feet. These wetted, wrapped and sealed sections shall be properly labeled and disposed of as asbestos waste.

Where no spatial openings are present, Bristol Environmental Inc. shall perform glove bag abatement to remove approximately six (6) inches of ACM thermal system insulation to facilitate the cutting of the pipe as described.

Bristol Environmental Inc. shall remove all asbestos containing materials from the work site in double 6-mil polyethylene waste bags or impermeable packages. All asbestos materials shall be adequately wet with amended water using a fine low pressure sprayer or other wetting mechanism.

The surfactant used by Bristol Environmental Inc. shall be available at all times at the work site. Bristol Environmental Inc. shall assure that all asbestos waste materials are sufficiently saturated with amended water to prevent fiber emission and/or visible emissions.

All asbestos waste bags, pipe sections and other waste packages shall be labeled with the prescribed Federal OSHA warning signs and shall include site specific waste generator information.

Bristol Environmental Inc. shall provide a fully enclosed, watertight waste container complete with a locking device for storage of all contaminated waste removed from the site. The waste container shall have asbestos warning signs affixed to all sides and doors

Inv# 13344

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to N.J.A.C. 8:60 and 12:120)

PAID

Inv# 3614

RECEIVED	
AUG - 1 2019	
ASBESTOS CONTROL & LICENSING	
Telephone Number 609-298-3900	

Date of Notification (1) 7/29/19		Name of Building Owner / Operator (2) Northern Burlington County Regional School District	
Agencies Notified	Type Notification	Street Address 160 Mansfield Road East	City, State & Zip Code Columbus, NJ 08022
☐ EPA ☐ DEP ☒ DOL ☒ DOH ☐ DCA	☒ Initial ☐ Amended ☐ Emergency ☐ Cancellation	Name of Contact Richard Kaz	Telephone Number 609-298-3900

FACILITY INFORMATION

Name of Facility Where Abatement is Taking Place (3) Northern Burlington County Regional High School			Type of Facility (4) ☒ School (K-12) NON SUB-CHAPTER 8 ☐ Subchapter 8 (Other than K-12) ☐ Other (i.e. private & commercial buildings, homes, etc.)		
Street Address 160 Mansfield Road East			Square Feet 150,000	# of Floors 1	Bldg. Age 40+
City (5) Columbus	County (6) Burlington	County Code (7)	Current Use (Prior if being demolished) School		
Name of Monitoring Firm Hired by Building Owner (8) Briggs Associates			Name of Abatement Contractor (9) Bristol Environmental, Inc.		
Street Address 3 Crosswicks Street			Street Address 1123 Beaver Street		
City, State & Zip Code Bordentown, NJ 08505			City, State & Zip Code Bristol, PA 19007		
Project Manager for Monitoring Firm Mike Hoodak			Telephone Number 609-298-5520		License Number 00509
Scheduled Start Date (10) 8/12/19		Scheduled Completion Date (11) 8/14/19		Name of OSHA Monitor Bristol Environmental Inc.	
Occupancy Status During Abatement (Check only one) ☐ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Hours – 7am to 3pm Describe: ☒ Facility Occupied During Abatement 7:00AM – 3:30 PM			Street Address 1123 Beaver Street		
			City, State & Zip Code Bristol, PA 19007		


Scope of Work (Check all that apply)

- | | | |
|---|--|--|
| ☐ ≥ 3 sf or ≥ 3 lf | ☒ Renovation | ☐ Full Containment with Negative Pressure |
| ☒ ≥ 160 sf ≥ 260 lf | ☐ Demolition | ☐ Mini-Enclosure |
| | | ☐ Glove Bag Procedures |
| | | ☒ Non-Exempted and Non-Friable Procedure |

Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> in Facility (13)	Is Location Normally Used Solely by Maintenance or Custodial Staff? (12)			Description of Asbestos-Containing Material (ACM) (i.e., thermal systems insulation, surfacing, VAT or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
Exterior Overhang	☐	☒	☐	Transite	1,350 SF	☒	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐

Name of Registered Waste Hauler Service Transport Inc.	NJDEP Waste Hauler ID No. 20990	Cubic Yards of Waste 10 Cu Yd	Name of Registered Landfill Minerva Landfill
City, State Yardley, PA	Disposal Date 8/14/19	City, State Waynesburg, OH	
Completed By (Print or Type) Gino Pizzigoni	Title Project Manager	Signature <i>Gino Pizzigoni</i>	Date 7/29/19


State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 12:120)



Date of Notification (1) 7/31/2019		Name of Building Owner/Operator (2) International Paper Company / Georgia Pacific LLC							
Agencies Notified	Type Notification	Street Address 6400 Poplar Avenue / 133 Peach Tree Street							
☒ EPA ☐ DEP ☒ DOL	☐ Initial ☒ Amended Amendment #1 _____	City, State, Zip Code Memphis, TN 38197 / Atlanta, GA 30004							
☒ DOH ☐ DCA	☐ Emergency (including justification) ☐ Cancellation	Name of Contact Dan Williams (Envirocon)	Telephone Number 314-600-8129						
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) Former Curtis Specialty Papers		Type of Facility (4) ☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e. private & commercial buildings, homes, etc.)							
Street Address Frenchtown Road		Square Feet 150,000	# of Floors Various						
City (5) Milford		Bldg. Age 70 +/-							
County (6) Hunterdon	County Code (7) (STATE USE ONLY) _____	Current Use (Prior if being demolished) Vacant (Abandoned)							
Name of Monitoring Firm Hired by Building Owner (8) Arcadis U.S., Inc.		ASCM No. _____	Name of Abatement Contractor (9) PRISM Response, LLC						
Street Address 1 Harvard Way, Unit 5		Street Address 102 Technology Lane							
City, State, Zip Code Hillsborough, NJ 0844		City, State, Zip Code Export, PA 15632							
Project Manager for Monitoring Firm Kevin Held		Telephone No. 908-526-1000	License No. 01121						
Start Date (10) 4/8/2019	Scheduled Completion Date (11) 10/4/2019	Name of OSHA Monitor PRISM Response, LLC							
Occupancy Status During Abatement (Check Only One) ☒ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Facility Hours ☐ Other - Describe: _____		Street Address 70 Hillside Drive, Suite 200							
		City, State, Zip Code Drums, PA 18222							
Scope of Work (Check All That Apply)									
☐ ≥ 3 sf or ≥ 3 lf ☒ ≥ 160 sf or ≥ 260 lf		☐ Renovation ☒ Demolition							
		☐ Full Containment with Negative Pressure ☐ Mini-Enclosure ☐ Glovebag Procedure ☐ Non-Exempted (*) and Non-Friable Procedure							
Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> In Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
SEE ATTACHED			X	SEE ATTACHED	ATTACHED	x			
Name of Registered Waste Hauler Waste Management		NJDEP Waste Hauler ID No. 17273	Cubic Yards of Waste 558	Name of Registered Landfill GROWS Landfill					
City, State Newark, NJ 07114		Disposal Date		City, State Morrisville, PA					
Completed by Jessica Wolfe		Title Admin. Support		Signature <i>Jessica Wolfe</i>			Date 7/31/2019		

Attachment A: Remaining Regulated Materials
Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal

Building	Material	Location	NESHAP Category	Quantity
MMA Basement				
46A	Grey window door caulk	West side of building, exterior door	Category II Non-Friable	1 door
48	Pipe fitting insulation debris	Along East wall, adjacent passageway between Buildings 6 and 48, behind large metal machines	Friable	2 sf
82	Caulk and glazing on 2-pane windows (2ft x 6 ft)	West side of building	Category II Non-Friable	17 windows
82	Caulk and glazing on tall single pane windows (9 ft x 2 ft)	West side of building	Category II Non-Friable	8 windows
82	Residue grey door caulk	West side of building, center opening where door used to be located	Category II Non-Friable	25 lf
MMA 1st Floor				
5	Transite debris associated with hoods	Around the holes left from the transite removal	Category II Non-Friable	3 sf
5	Caulk associated with fiberglass panels	Around doghouses, adjacent roof	Category II Non-Friable	260 lf of panels
6	Caulk associated with fiberglass panels	Around doghouses, adjacent roof	Category II Non-Friable	260 lf of panels
22	Electrical boxes	South side, along wall beneath staircase to roof	Category II Non-Friable	3 boxes
48	Pipe fitting insulation associated with fiberglass pipe insulation	Ceiling plenum, North side	Friable	Unknown
48	Pipe insulation	Ceiling plenum, North side	Friable	30 lf
51	Black pipe wrap	Exterior, North side	Category II Non-Friable	10 lf
	Debris pile (roofing)	Exterior, West side, dirt pile and ground with roofing debris scattered		Building 56 exterior
56	Caulking on interior block windows	SE side and interior between Buildings 48 & 56	Category II Non-Friable	8 lf
70	Exterior breaching debris	East side exterior, on metal machine	Friable	40 sf
73A (changing area)	Caulk associated with door window	South wall	Category II Non-Friable	
74	Pipe insulation	Interior SW corner, exterior SW corner	Friable	
80	Debris pile	Poly pile and debris	Category II Non-Friable	
82	2 pane windows (6 ft x 2 ft), exterior grey window caulk and glazing, interior window glazing	Along west wall	Category II Non-Friable	
128	3 pane metal door window	East and West sides	Category II Non-Friable	



Attachment A: Remaining Regulated Materials
Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal

Building	Material	Location	NESHAP Category	Quantity
128	4 x 2 pane metal window	East and North sides	Category II Non-Friable	2 windows
16	2 x 4 pane wood windows (window glazing)	MMA 2nd and 3rd Floor		
69	Caulk on door window	2nd floor, throughout	Category II Non-Friable	8 windows
		3rd floor, east side	Category II Non-Friable	1 door
		MMA Roof		
Main Mill	PI2-white mag pipe insulation	throughout (including roof)	Friable	25,800 SF
Main Mill	White mag pipe insulation debris (PI2)	throughout (including areas on roof)	Friable	17,850 SF
Main Mill	Defective pipe insulation (PI2)	throughout (including areas on roof)	Friable	1,300 LF
Main Mill	TP9-transite panel	throughout (including areas on roof)	Category II Non-Friable	46,300 SF
Main Mill	MF13-grey mudded fillings on fiberglass line	Area 80, area 46A & area 10 roof	Friable	185 EA
Main Mill	Built-up roofing	Area 69 roof	Category I Non-Friable	2,700 SF
Main Mill	Perimeter/Penetration flashing	Area 69 roof	Category I Non-Friable	250 SF
Main Mill	RF36-built-up roofing	Area 32-roof	Category I Non-Friable	8,745 SF
Main Mill	Built-up roofing debris (RF36)	Area 32	Category I Non-Friable	850 SF
Main Mill	T44-silver/black flashing tar layer	Area 32-roof	Category I Non-Friable	570 SF
Main Mill	RF37-built-up roofing	Area 1-roof	Category I Non-Friable	8,745 SF
Main Mill	T43- silver/black flashing tar	Area 1-roof	Category I Non-Friable	1,050 SF
Main Mill	RF39-built-up roofing	Area 02-roof	Category I Non-Friable	7,200 SF
Main Mill	T46- silver/black flashing tar	Area 02-roof	Category I Non-Friable	700 SF
Main Mill	RF40-built-up roofing	Area 44-roof	Category I Non-Friable	5,100 SF
Main Mill	T47- silver/black flashing tar	Area 44-roof	Category I Non-Friable	650 SF
Main Mill	RF41-built-up roofing	Area 19-roof	Category I Non-Friable	3,000 SF
Main Mill	T48-silver/black flashing tar	Area 19-roof	Category I Non-Friable	575 SF
Main Mill	RF42-built-up roofing	Area 51-roof	Category I Non-Friable	12,000 SF
Main Mill	T49- black flashing tar	Area 51-roof	Category I Non-Friable	600 SF






Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal

Building	Material	Location	NESHAP Category	Quantity
Main Mill	RF43- built-up roofing	Area 03-roof	Category I Non-Friable	14,150 SF
Main Mill	RF44- built-up roofing	Area 03-elevated roof	Category I Non-Friable	3,520 SF
Main Mill	C45-white caulk on ductwork	Area 03-roof	Category II Non-Friable	150 LF
Main Mill	C50-white window caulk	Area 03-roof	Category II Non-Friable	1080 LF
Main Mill	T50-silver/black flashing tar layer	Area 03-roof	Category I Non-Friable	2,150 SF
Main Mill	T51-silver/black flashing tar layer	Area 03-elevated roof	Category I Non-Friable	420 SF
Main Mill	RF49-built-up roofing	Area 03-elevated shak roof	Category I Non-Friable	185 SF
Main Mill	T52-black flashing tar	Area 47-roof	Category I Non-Friable	650 SF
Main Mill	Black flashing tar (T52) and roofing debris	Area 47	Category I Non-Friable	100 SF
Main Mill	RF47- built-up roofing	Area 17-roof	Category I Non-Friable	7,200 SF
Main Mill	Built-up roofing debris(RF47)	Area 17	Category I Non-Friable	150 SF
Main Mill	T53-silver/black flashing tar layer	Area 17-roof	Category I Non-Friable	840 SF
Main Mill	T54-black perimeter flashing tar	Area 58-roof	Category I Non-Friable	180 SF
Main Mill	RF50-built-up roofing	Area 04-roof	Category I Non-Friable	2,750 SF
Main Mill	T55-black/silver flashing tar	Area 04-roof	Category I Non-Friable	1,060 SF
Main Mill	RF56-black built-up roofing	Area 04-elevated roof	Category I Non-Friable	400 SF
Main Mill	RF51-built-up roofing	Area 21/22-roof	Category I Non-Friable	5,440 SF
Main Mill	RF52-silver built-up roofing	Area 21/22-elevated roof	Category I Non-Friable	400 SF
Main Mill	T56-silver/black flashing tar layer	Area 21/22-roof	Category I Non-Friable	450 SF
Main Mill	T57-silver tar coating	Area 21/22-roof	Category I Non-Friable	150 SF
Main Mill	RF53- built-up roofing	Area 22A-roof	Category I Non-Friable	1010 SF
Main Mill	RF54- built-up roofing	Area 70-roof	Category I Non-Friable	1,120 SF
Main Mill	RF58- built-up roofing	Area 70- shak roof	Category I Non-Friable	180 SF
Main Mill	T60-black flashing tar	Area 70-roof	Category I Non-Friable	1500 SF
Main Mill	T62-parapet flashing tar	Area 70-roof	Category I Non-Friable	230 LF




Attachment A: Remaining Regulated Materials
Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal

Building	Material	Location	NESHAP Category	Quantity
Main Mill	T68-black perimeter/penetration flashing tar	Area 56-roof	Category I Non-Friable	1,110 SF
Main Mill	RF68- silver/black built-up roofing	Area 59-roof	Category I Non-Friable	3,600 SF
Main Mill	T69-silver/black perimeter/penetration flashing tar	Area 59-roof	Category I Non-Friable	750 SF
Main Mill	C55-exterior white window caulk	Area 59-roof	Category II Non-Friable	140 LF
Main Mill	RF69-built-up roofing	Area 77-roof	Category I Non-Friable	3,600 SF
Main Mill	T70-black perimeter/penetration flashing tar	Area 77-roof	Category I Non-Friable	375 SF
Main Mill	RF70-built-up roofing	Area 15-roof	Category I Non-Friable	2,520 SF
Main Mill	T71-silver/black perimeter/penetration flashing tar	Area 15-roof	Category I Non-Friable	260 SF
Main Mill	T72-silver/black perimeter flashing tar	Area 63-roof	Category I Non-Friable	180 SF
Main Mill	RF72-built-up roofing	Area 07-roof	Category I Non-Friable	17,800 SF
Main Mill	Built-up roofing debris (RF72)	Area 07	Category I Non-Friable	25 SF
Main Mill	RF73-built-up roofing	Area 07 & 10-elevated roof	Category I Non-Friable	28,230 SF
Main Mill	RF84-silver built-up roofing	Area 07-roof	Category I Non-Friable	6,840 SF
Main Mill	T73-black perimeter/penetration flashing tar	Area 07-roof	Category I Non-Friable	2,720 SF
Main Mill	T74- black perimeter flashing tar	Area 07 & 10-elevated roof	Category I Non-Friable	2,370 SF
Main Mill	T92-silver/black perimeter/penetration flashing tar	Area 07-roof	Category I Non-Friable	915 SF
Main Mill	C56-exterior white caulk on fiberglass panel base seams	Area 07-roof	Category II Non-Friable	300 LF
Main Mill	C57-red caulk between all seam joints (wall, roof, floor)	Area 07-roof-HVAC	Category II Non-Friable	720 LF
Main Mill	MINS1-light grey insulation in metal panels on walls and all sides	Area 07-roof	Friable	1,800 SF
Main Mill	RF74-built-up roofing	Area 80 & 81 roof	Category I Non-Friable	42,400 SF
Main Mill	T75-black perimeter/penetration flashing tar	Area 80 & 81-roof	Category I Non-Friable	4,200 SF
Main Mill	RF75- built-up roofing	Area 80A-roof	Category I Non-Friable	11,900 SF
Main Mill	T76- black perimeter/penetration flashing tar	Area 80A-roof	Category I Non-Friable	1,200 SF
Main Mill	RF78-built-up roofing	Area 45-roof	Category I Non-Friable	3,030 SF
Main Mill	RF79-white asphalt shingle	Area 45-roof	Category I Non-Friable	4,500 SF




Attachment A: Remaining Regulated Materials
Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal

Building	Material	Location	NESHAP Category	Quantity
Main Mill	C60-silver/red caulk on metal HVAC seams	Area 10 & 46 - roof	Category II Non-Friable	1,800 LF
Main Mill	RF102-built-up roofing	Area 10B - roof	Category I Non-Friable	2,250 SF
Main Mill	T98-black perimeter/penetration flashing tar	Area 10B - roof	Category I Non-Friable	300 SF
Main Mill	RF92-silver/black built-up roofing	Area 46 - roof	Category I Non-Friable	14,000 SF
Main Mill	RF96-black/silver asphalt roll-on	Area 46 - roof	Category I Non-Friable	330 SF
Main Mill	T90-silver/black flashing tar	Area 46 - roof	Category I Non-Friable	810 SF
Main Mill	WG80-interior white glaze on 12-pane metal window	Area 46 - roof	Category II Non-Friable	42 EA
Main Mill	T91-black perimeter/penetration flashing tar	Area 46A - roof	Category I Non-Friable	1,000 SF
Main Mill	WG81-light grey window caulk on elevator window roof	Area 46A - roof	Category II Non-Friable	4 EA
Main Mill	C61-white/tan caulk in parapet wall	Area 46A - roof (14" bead every 4')	Category II Non-Friable	100 LF
Main Mill	RF97-built-up roofing	Area 8/13 - roof	Category I Non-Friable	2,660 SF
Main Mill	T93-black perimeter/penetration flashing tar	Area 8/13 - roof	Category I Non-Friable	370 SF
Main Mill	T94-black perimeter/penetration flashing tar	Area 82A - roof	Category I Non-Friable	180 SF
Main Mill	RF99-built-up roofing	Area 82B - roof	Category I Non-Friable	2,360 SF
Main Mill	T95-black perimeter/penetration flashing tar	Area 82B - roof	Category I Non-Friable	800 SF
Main Mill	T96-black perimeter/penetration flashing tar	Area 82C - roof	Category I Non-Friable	180 SF
Main Mill	RF101-built-up roofing	Area 62 - roof	Category I Non-Friable	2,900 SF
Main Mill	T97-black perimeter/penetration flashing tar	Area 62 - roof	Category I Non-Friable	255 SF
Main Mill	RF105-silver built-up roofing	Area 60A - roof	Category I Non-Friable	4,200 SF
Main Mill	T99-silver/black perimeter/penetration flashing tar	Area 60A - roof	Category I Non-Friable	500 SF
Main Mill	T100-black/perimeter/penetration flashing tar	Area 20, 41, 43 & 60 - roof	Category I Non-Friable	1,200 SF
Main Mill	T102- black perimeter/penetration flashing tar	Area 60 - roof	Category I Non-Friable	200 SF
Main Mill	RF108-built-up roofing	Area 60 - lower roof	Category I Non-Friable	1,800 SF
Main Mill	RF107-built-up roofing	Area 20 - roof	Category I Non-Friable	600 SF
Main Mill	T101-black perimeter flashing tar	Area 20 - roof	Category I Non-Friable	110 SF



Attachment A: Remaining Regulated Materials
Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal

Building	Material	Location	NESHAP Category	Quantity
Main Mill	RG8-tan rope gasket	Area 60- lower roof	Category I Non-Friable	250 LF
102	G6 - tan glue behind metal wall panels	Brick House		
102	P12 - loose aircell pipe insulation	Brick house- room 10	Category II Non-Friable	450 sf
102	9" x 9" white w/black streaks floor tile (FT2)	Brick house- room 17	Friable	9 LF
102	WC2 - exterior white window caulk	Brick house - room 14	Category I Non-Friable	75 sf
102	DC1 - exterior cream door caulk	Brick house - 1st and 2nd floor exterior	Category II Non-Friable	30 windows
102	RF1 - silver tar coating over metal	Brick house - 1st floor exterior	Category II Non-Friable	4 doors
102	FL1 - black flashing tar	Brick house - rear porch roof	Category I Non-Friable	380 sf
102	RF3 - grey asphalt roll-on (top layer)	Brick house - front porch roof	Category I Non-Friable	60 sf
102	FL2 - black flashing tar	Brick house - soffit roof	Category I Non-Friable	300 sf
102	TP1 - black transite panel in electric panel	Brick house - soffit roof	Category I Non-Friable	60 sf
102	T1 - tar coating over fiberglass duct to HVAC	Brick house - basement - electric panel	Category II Non-Friable	1 sf
102	C1 - cream caulk around conduit junction box	Brick house exterior - B side	Category II Non-Friable	12 sf
102	P11 - mag pipe insulation	Brick house - exterior - B side	Category II Non-Friable	1 lf
102	9" x 9" tan confetti floor tile (FT1)	Brick house - basement (debris on floor below chase)	Friable	25 lf
102	G5 - tan glue behind wall panel	Brick house - rooms 1, 2, 3, 4, 5 and 7	Category I Non-Friable	1,000 sf
		Brick house - room 13	Category II Non-Friable	400 sf
Other MMA Outbuildings and WWTPA				
Outbuildings	Electrical boxes (w/ one or more of the following: EC1, EC2, EC3, EBB1, EPI1, EP3, IB1, EPI2 and ABEB1)	Out Buildings - throughout (multiple types of boxes w/ predominantly Cutler & Hammer, GE & AB)	Category II Non-Friable	70 EA
Outbuildings	Pipe gaskets (PG1, PG4, PG5 & PG14)	Out Buildings-throughout	Category I Non-Friable	150 EA
107	PG1-pipe gasket	Well pump house 6	Category I Non-Friable	1 SF
107	BC1-dark grey caulk under metal wall frame	Well pump house 6	Category II Non-Friable	40 LF
110	T1-silver/black tar coating	Well pump house 2-roof	Category I Non-Friable	120 SF
111	RF1-built-up roofing	Oil tank building-roof	Category I Non-Friable	360 SF
111	PER1-black perimeter flashing	Oil tank building-roof	Category I Non-Friable	10 SF



Attachment A: Remaining Regulated Materials
Table 1: Asbestos-Containing Materials Remaining in Site Buildings
Curtis Specialty Papers Site
Demolition Request for Proposal


Building	Material	Location	NESHAP Category	Quantity
111	PEN1-black penetration flashing	Oil tank building-roof	Category I Non-Friable	5 SF
111	PI1-white calsil type pipe insulation and associated mudded fittings	Oil tank building (underground pipes w/ PI1 run to the way to the Main Mill)	Friable	50 LF identifiable
111	Transite Pipe - underground	Runs from Building/Structure 111 to 60	Friable	50 LF identifiable
111	WG3-exterior white window glaze on 3-pane metal window	Oil tank building-exterior	Category II Non-Friable	4 windows
112	T4-black/ grey tar coating on roof fan	Large metal shed 2-roof	Category I Non-Friable	15 SF
Near 112	C7-red caulk between metal seams (between seam/seam)	HVAC1 & HVAC1	Category II Non-Friable	240 LF
Near 112	C8-white caulk between ductwork seams	HVAC1	Category II Non-Friable	60 LF
Near 112	C9-interior grey door caulk (on door)	HVAC1 & HVAC2	Category II Non-Friable	30 LF
Near 112	PS1-black pipe sealant coating	HVAC1 -exterior	Category II Non-Friable	5 SF
128	C10-interior white caulk on vent	Natural gas yard shed-exterior	Category II Non-Friable	5 LF
128	C11-exterior white door caulk	Natural gas yard shed-exterior	Category II Non-Friable	15 LF
128	C12-exterior white caulk along roof on edges	Natural gas yard shed-roof	Category II Non-Friable	10 SF
104	FT1-9"x9" black floor tile (in box)	Shed 1-room 1	Category I Non-Friable	1 box
104	DWG5-white window glaze on single pane door window	Shed 1 - A-side	Category II Non-Friable	1 door
104	T36-silver tar coating on metal roof	Shed 1-room 1	Category I Non-Friable	1,200 SF
104	PG6-cream pipe gasket	Shed 1 - room 1	Category I Non-Friable	1 gasket
118	Joint compound associated with SHR2	Sewer lift building - room 1	Category II Non-Friable	~500 SF
North of 111	WG4-white window glaze on 8-pane metal window	D-side of oil tank building - debris pile	Category II Non-Friable	1 window
67/68	WG14-exterior white window glaze on metal window		Category II Non-Friable	2 windows
121	R15-black asphalt roll-on	Waste pump house	Category I Non-Friable	640 SF
121	RF16-built-up roofing	Waste pump house	Category I Non-Friable	630 SF
66	TP5-transite panel	room 1 (room 4 walls)	Category II Non-Friable	125 SF
South of 66	TP5-transite panel	debris on road between Building 66 and clarifier	Category II Non-Friable	15 SF
East of 125	T14-seam tar on round concrete holding tank	Round concrete holding tank (between defoamer shed and clarifier tanks)	Category I Non-Friable	15 SF
83	T16-tar flashing on screws around perimeter	shed roof	Category I Non-Friable	3-SF

RECEIVED
AUG - 1 2019
ASBESTOS CONTROL

Inv # 13182
OK1740

PAID

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 5:16)



Date of Notification (1) 07 / 29 / 19		Name of Building Owner/Operator (2) Metro Real Estate Development Corp.							
Agencies Notified ☒ EPA ☒ DOLWD ☒ DOH ☐ DCA (NJAC 5:23-8)	Type Notification ☐ Initial ☒ Amended Amendment #3 ☐ Emergency (including justification) ☐ Cancellation	Street Address 2 Broad Street, Suite 305 City, State, Zip Code Bloomfield, NJ 07003 Name of Contact Warren Sprake Telephone Number 908-670-5711							
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) Commercial		Type of Facility (4) ☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e., private and commercial buildings, homes, etc.)							
Street Address 609-611 Bloomfield Avenue		Square Feet							
City (5) Bloomfield, NJ		# of Floors							
County (6) Essex		Bldg. Age							
County Code (7) (STATE USE ONLY)		Current Use (Prior if being demolished)							
Name of Monitoring Firm Hired by Building Owner (8) Mark Jovic Consulting LLC		ASCM No.							
Street Address 87 Main Street, Suite A		Name of Abatement Contractor (9) ALL PRO MANAGEMENT LLC							
City, State, Zip Code Lincoln Park, NJ 07035		Street Address 27 Outwater Lane							
Project Manager for Monitoring Firm Mark Jovic		City, State, Zip Code Garfield, NJ 07026							
Telephone No. 973-650-0932		Telephone No. 973-928-4888							
Start Date (10) 07 / 15 / 19		License No. 1188							
Scheduled Completion Date (11) 12 / 19 / 19		Name of OSHA Monitor ALL PRO MANAGEMENT LLC							
Occupancy Status During Abatement (Check only one) ☒ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Facility Hours - Describe Time of Abatement: ____ AM - ____ PM / ____ PM - ____ AM		Street Address 27 Outwater Lane							
Scope of Work (Check all that apply) ☐ ≥ 3 sf or ≥ 3 lf ☒ ≥ 160 sf or ≥ 260 lf ☐ Renovation ☒ Demolition ☒ Full Containment with Negative Pressure ☐ Mini-Enclosure ☒ Glovebag Procedure ☒ Non-Exempted (*) and Non-Friable Procedure		City, State, Zip Code Garfield, NJ 07026							
Location of Asbestos-Containing Material (ACM) TO BE ABATED IN Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)		Description of Asbestos Containing Material (ACM) (i.e., thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type				
	Yes	No			N/A	Removal	Repair	Encapsulate	Enclosure
Basement	☐	☐	☒	Pipe Insulation	50 LF	☒	☐	☐	☐
1st & 2nd Floor	☐	☐	☒	Plaster	8,000 SF	☒	☐	☐	☐
1st Floor	☐	☐	☒	Fluffy Material	800 SF	☒	☐	☐	☐
Exterior	☐	☐	☒	Window Caulking	25 LF	☒	☐	☐	☐
Name of Registered Waste Hauler Century Waste, LLC/Newark Carting		NJDEP Waste Hauler ID No. 32797 / 0283		Cubic Yards of Waste As Needed		Name of Registered Landfill			
City, State Elizabeth, NJ / Newark, NJ		Disposal Date TBD		City, State Morrisville, PA / Pen Argyl, PA					
Completed By (Print or Type) Allen Monchik		Title Project Manager		Signature Allen Monchik		Date 7/29/19			

RECEIVED
AUG - 1 2019
ASBESTOS CONTROL &
LICENSING
Abatement Type

Completed by: (Print or type) Allen Monchik	Title: Project Manager	Signature: <i>Allen Monchik</i>	Date: 7/29/19
--	------------------------	------------------------------------	------------------