

B & G proj. #: 2019-151

State of NJ
PAID Notification of Asbestos Abatement
 (Pursuant to NJAC 8:60-7 and 12:120-7)
 ***NON Subchapter 8 ***

Check # 9409

Date of Notification (1) 10/7/08/11/19/		Name of Building Owner/Operator (2) Sisters of Saint Dominic		<div style="border: 2px solid black; padding: 10px; margin: 0 auto; width: 150px;"> RECEIVED JUL 10 2019 ASBESTOS CONTROL & REMEDIATION </div>
Agencies Notified	Type Notification	Street Address 1 Ryerson Avenue		
<input type="checkbox"/> EPA	<input checked="" type="checkbox"/> Initial	City, State, Zip Code Caldwell, NJ 07006		
<input type="checkbox"/> DEP	<input type="checkbox"/> Amendment	Name of Contact Vincent DeCroce		
<input checked="" type="checkbox"/> DOL	<input type="checkbox"/> Cancellation	Telephone Number 973-747-6278		
<input checked="" type="checkbox"/> DOH				
<input type="checkbox"/> DCA				

FACILITY INFORMATION

Name of facility where abatement is taking place (3) Sisters of Saint Dominic (NON Sub 8)			Type of Facility (4) <input checked="" type="checkbox"/> School (K - 12) <input type="checkbox"/> Subchapter 8 (Other than K-12) <input type="checkbox"/> Other (Private/Commercial Bldgs./Homes, etc.)		
Street Address 1 Ryerson Avenue			Square Feet: 50,000 # of Floors: 2 Bldg. Age: 50+ Current Use (Prior if being demolished): educational		
City (5) Caldwell, NJ 07006	County (6) Essex	County Code (7) (State use only)			
Name of Monitoring Firm Hired by Bldg. Owner (8)		ASCM No.	Name of Abatement Contractor (9) B & G Restoration, Inc.		
Street Address			Street Address 105 Ryerson Road		
City, State, Zip Code			City, State, Zip Code Lincoln Park, NJ 07035		
Project Manager for Monitoring Firm		Phone Number	Telephone Number: (973)696-6869 License Number: 00378		
Scheduled Start Date (10) 07/18/2019		Sched. Completion Date (11) 07/19/2019	Name of OSHA Monitor B & G Restoration, Inc.		
Occupancy Status During Abatement (Check only one)			Street Address 105 Ryerson Road		
<input type="checkbox"/> Facility closed/vacated during entire period of abatement. <input type="checkbox"/> Abatement performed outside of normal facility hours- Describe: _____ <input checked="" type="checkbox"/> Other-Describe: occupied			City, State, Zip Code Lincoln Park, NJ 07035		

Scope of Work (check all that apply)

- | | | | |
|--|--|---|--|
| <input type="checkbox"/> Demolition | <input checked="" type="checkbox"/> Renovation | <input type="checkbox"/> Full Containment w/negative pressure | <input checked="" type="checkbox"/> Glovebag procedure |
| <input checked="" type="checkbox"/> >3 sf or >3 lf | <input type="checkbox"/> ≥160 sf or ≥260 lf | <input checked="" type="checkbox"/> Mini-enclosure | <input type="checkbox"/> Non-friable procedure |

Location of asbestos-containing material to be abated in facility (13)	Is location normally used solely by maintenance/custodial staff (12)			Description of asbestos-containing material (ACM)	Amount (Specify SF or LF)	R e m o v e	R e p a i r	E n c a p	E n c l
	Yes	No	N/A						
Boiler room			<input checked="" type="checkbox"/>	pipe insulation	9 lf	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Registered Waste Hauler B & G Restoration, Inc.	NJDEP Hauler ID# 19563	Cubic Yards of Waste 1/2	Name of Registered Landfill Grand Central Landfill
City, State Lincoln Park, NJ	Disposal Date 07/19/19	City, State Pen Argyle, PA	
Completed by (Print or Type) Gordana Luna	Title Secretary/Treasurer	Signature <i>Gordana Luna</i>	Date 07/08/2019

inv#12642

B & G proj. #: 2019-150

PAID

State of NJ
Notification of Asbestos Abatement
(Pursuant to NJAC 8:60-7 and 12:120-7)
*** Subchapter 8 ***

Check # 9405

Date of Notification (1) 07/10/19		Name of Building Owner/Operator (2) Newark Public Schools		<div>RECEIVED</div> <div>JUL 10 2019</div> <div>ASBESTOS CONTROL & LICENSING</div>
Agencies Notified	Type Notification	Street Address 2 Cedar Street		
<input type="checkbox"/> EPA	<input checked="" type="checkbox"/> Initial	City, State, Zip Code Newark, NJ 07106		
<input type="checkbox"/> DEP	<input type="checkbox"/> Amendment	Name of Contact Paulinus Egu		
<input checked="" type="checkbox"/> DOL	<input type="checkbox"/> Cancellation	Telephone Number 973-733-7355		
<input checked="" type="checkbox"/> DOH				
<input type="checkbox"/> DCA				

FACILITY INFORMATION

Name of facility where abatement is taking place (3) Early Childhood School West (Sub 8)			Type of Facility (4) <input checked="" type="checkbox"/> School (K - 12) <input type="checkbox"/> Subchapter 8 (Other than K-12) <input type="checkbox"/> Other (Private/Commercial Bldgs./Homes, etc.)		
Street Address 26 Speedway Avenue			Square Feet 50,000		
City (5) Newark, NJ 07106			# of Floors 2		
County (6) Essex			Bldg. Age 50+		
County Code (7) (State use only)			Current Use (Prior if being demolished) early childhood school		
Name of Monitoring Firm Hired by Bldg. Owner (8) TTI Environmental Inc.			Name of Abatement Contractor (9) B & G Restoration, Inc.		
Street Address 1253 North Church Street			Street Address 105 Ryerson Road		
City, State, Zip Code Moorestown, NJ 08057			City, State, Zip Code Lincoln Park, NJ 07035		
Project Manager for Monitoring Firm Jim Guillard			Telephone Number (973)696-6869		
Phone Number 609-304-3968			License Number 00378		
Scheduled Start Date (10) 07/19/2019			Name of OSHA Monitor B & G Restoration, Inc.		
Sched. Completion Date (11) 08/02/2019			Street Address 105 Ryerson Road		
Occupancy Status During Abatement (Check only one) <input type="checkbox"/> Facility closed/vacated during entire period of abatement. <input type="checkbox"/> Abatement performed outside of normal facility hours- Describe: <input checked="" type="checkbox"/> Other-Describe: occupied			City, State, Zip Code LincolnPark, NJ 07035		

Scope of Work (check all that apply)

- ☐ Demolition ☒ Renovation ☒ Full Containment w/negative pressure ☐ Glovebag procedure
☒ >3 sf or >3 lf ☐ ≥160 sf or ≥260 lf ☐ Mini-enclosure ☐ Non-friable procedure

Location of asbestos-containing material to be abated in facility (13)	Is location normally used solely by maintenance/custodial staff (12)			Description of asbestos-containing material (ACM)	Amount (Specify SF or LF)	R e m o v e	R e p a i r	E n c a p	E n c l
	Yes	No	N/A						
Boiler rm, mech rm, storage rm			<input checked="" type="checkbox"/>	fiberglass/pipe joint insulation	250 lf	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Storage room			<input checked="" type="checkbox"/>	transite electric panels	100 sf	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Registered Waste Hauler B & G Restoration, Inc.	NJDEP Hauler ID# 19563	Cubic Yards of Waste 5	Name of Registered Landfill Grand Central Landfill
City, State Lincoln Park, NJ	Disposal Date 07/19/19 - 08/02/19	City, State Pen Argyle, PA	
Completed by (Print or Type) Gordana Luna	Title Secretary/Treasurer	Signature Gordana Luna	Date 07/08/2019

Inv# 121043

B & G proj. #: 2019-121

PAID

State of NJ
Notification of Asbestos Abatement
(Pursuant to NJAC 8:60-7 and 12:120-7)

Check # 9404

Date of Notification (1) 07/10/19		Name of Building Owner/Operator (2) Debbie Martell		<div>RECEIVED</div> <div>JUL 10 2019</div> <div>ASBESTOS CONTROL & REMEDIATION</div>
Agencies Notified	Type Notification	Street Address [REDACTED]		
<input type="checkbox"/> EPA	<input checked="" type="checkbox"/> Initial	City, State, Zip Code Madison, NJ 07940		
<input type="checkbox"/> DEP	<input type="checkbox"/> Amendment	Name of Contact Debbie Martell		
<input checked="" type="checkbox"/> DOL	<input type="checkbox"/> Cancellation	Telephone Number		
<input checked="" type="checkbox"/> DOH				
<input type="checkbox"/> DCA				

FACILITY INFORMATION

Name of facility where abatement is taking place (3) Debbie Martell			Type of Facility (4) <input type="checkbox"/> School (K - 12) <input type="checkbox"/> Subchapter 8 (Other than K-12) <input checked="" type="checkbox"/> Other (Private/Commercial Bldgs./Homes, etc.)		
Street Address [REDACTED]			Square Feet # of Floors Bldg. Age		
City (5) Madison, NJ 07940	County (6) Essex	County Code (7) (State use only)	Current Use (Prior if being demolished) residential		
Name of Monitoring Firm Hired by Bldg. Owner (8) [REDACTED]		ASCM No.	Name of Abatement Contractor (9) B & G Restoration, Inc.		
Street Address [REDACTED]			Street Address 105 Ryerson Road		
City, State, Zip Code			City, State, Zip Code Lincoln Park, NJ 07035		
Project Manager for Monitoring Firm		Phone Number	Telephone Number (973)696-6869		
Scheduled Start Date (10) 07/18/2019		Sched. Completion Date (11) 07/19/2019	License Number 00378		
Occupancy Status During Abatement (Check only one) <input checked="" type="checkbox"/> Facility closed/vacated during entire period of abatement. <input type="checkbox"/> Abatement performed outside of normal facility hours- Describe: <input type="checkbox"/> Other-Describe:			Name of OSHA Monitor B & G Restoration, Inc.		
			Street Address 105 Ryerson Road		
			City, State, Zip Code Lincoln Park, NJ 07035		

Scope of Work (check all that apply)

- ☐ Demolition ☒ Renovation ☒ Full Containment w/negative pressure ☐ Glovebag procedure
☒ >3 sf or >3 lf ☐ ≥160 sf or ≥260 lf ☐ Mini-enclosure ☐ Non-friable procedure

Location of asbestos-containing material to be abated in facility (13)	Is location normally used solely by maintenance/custodial staff (12)			Description of asbestos-containing material (ACM)	Amount (Specify SF or LF)	R e m o v e	R e p a i r	E n c a p	E n c l
	Yes	No	N/A						
Garage			<input checked="" type="checkbox"/>	thick duct insulation	68 sf	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Registered Waste Hauler B & G Restoration, Inc.	NJDEP Hauler ID# 19563	Cubic Yards of Waste 2	Name of Registered Landfill Grand Central Landfill
City, State Lincoln Park, NJ	Disposal Date 07/19/2019	City, State Pen Argyl, PA	
Completed by (Print or Type) Gordana Luna	Title Secretary/Treasurer	Signature Gordana Luna	Date 07/08/2019

Inv# 12644