


OK  
2847

**State of New Jersey  
NOTIFICATION OF ASBESTOS ABATEMENT  
(Pursuant to NJAC 8:60 and 12:120)**



Date of Notification (1) 7-23-12		Name of Building Owner/Operator (2) Woodside Assoc.	
Agency Notified <input checked="" type="checkbox"/> EPA <input checked="" type="checkbox"/> DEP <input type="checkbox"/> DOL <input checked="" type="checkbox"/> DOH <input type="checkbox"/> DCA	Type Notification <input checked="" type="checkbox"/> Initial <input type="checkbox"/> Amended Amendment # <input type="checkbox"/> Emergency (including justification) <input type="checkbox"/> Cancellation	Street Address 19 Mt. Pleasant Drive	
		City, State, Zip Code Chester Heights, PA 19017	
		Name of Contact Doug	Telephone Number

**FACILITY INFORMATION**

Name of Facility Where Abatement is Taking Place (3) vacant single story structure		Type of Facility (4) <input type="checkbox"/> School (K-12) <input type="checkbox"/> Subchapter 8 (Other than K-12) <input checked="" type="checkbox"/> Other (i.e. private & commercial buildings, homes, etc.)	
Street Address N.J.S.H Route 31 and Country Road 579		Square Feet 3,000	# of Floors 2
City (5) West Amwell Township		Bldg. Age +/-50	
County (6) Hunterdon	County Code (7) (STATE USE ONLY)	Current Use (Prior if being demolished) vacant	
Name of Monitoring Firm Hired by Building Owner (8) Dynamic Earth		ASCM No.	Name of Abatement Contractor (9) Pepper Environmental Services, Inc.
Street Address 245 Main Street, Suite 204		Street Address 2251 Fraley Street	
City, State, Zip Code Chester, NJ 07930		City, State, Zip Code Philadelphia, PA 19137	
Project Manager for Monitoring Firm Pete Howell	Telephone No. 908-879-7095	Telephone No. 215-533-5155	License No. 00848
Start Date (10) 8/1/12	Scheduled Completion Date (11) 8/15/12	Name of OSHA Monitor Dynamic Earth	
Occupancy Status During Abatement (Check only one) <input checked="" type="checkbox"/> Facility Closed/Vacated During Entire Period of Abatement <input type="checkbox"/> Abatement Performed Outside of Normal Facility Hours <input type="checkbox"/> Other - Describe:		Street Address 245 Main Street, Suite 204	
		City, State, Zip Code Chester, NJ 07930	

Scope of Work (Check all that apply) \*abatement prior to demo\*

<input type="checkbox"/> $\geq 3$ sf or $\geq 3$ lf	<input type="checkbox"/> Renovation	<input type="checkbox"/> Full Containment with Negative Pressure
<input checked="" type="checkbox"/> $\geq 160$ sf or $\geq 260$ lf	<input type="checkbox"/> Demolition	<input type="checkbox"/> Mini-Enclosure
		<input type="checkbox"/> Glovebag Procedure
		<input checked="" type="checkbox"/> Non-Exempted (*) and Non-Friable Procedure

Location of Asbestos-Containing Material (ACM) TO BE ABATED IN Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e., thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type		
	Yes	No	N/A			Removal	Repair	Encapsulate
				*see attached*		X		

Name of Registered Waste Hauler Service Transport		NJDEP Waste Hauler ID No.	Cubic Yards of Waste	Name of Registered Landfill A & L Salvage	
City, State Morrisville, PA			Disposal Date	City, State Libson, OH	
Completed by Jennifer Niven	Title Dir. of Operations	Signature	Date 7-23-12		

West Amwell Twp.

DESCRIPTION OF MATERIAL	LOCATION OF MATERIAL	Amount	Code**	Code***
exterior window glazing	exterior	120	LF	REM
exterior building caulk	exterior	300	LF	REM
joint compound	throughout	2000	SF	REM
12x12 floor tile	finished garage/office	440	SF	REM
joint compound	throughout	4100	SF	REM
9x9 floor tile	shop	880	SF	REM
window glazing	shop windows	54	LF	REM
transite siding	roof	120	SF	REM

