


State of NJ  
 Notification of Asbestos Abatement  
 (Pursuant to NJAC 8:60-7 and 12:120-7)

B & G proj. #: 2019-136

OTW # 11020

**PAID**

Check # 9343



Date of Notification (1) 05/31/19		Name of Building Owner/Operator (2) NJ Department of Military & Veteran Affairs	
Agencies Notified <input checked="" type="checkbox"/> EPA <input type="checkbox"/> DEP <input checked="" type="checkbox"/> DOL <input checked="" type="checkbox"/> DOH <input type="checkbox"/> DCA		Type Notification <input checked="" type="checkbox"/> Initial <input type="checkbox"/> Amendment <input type="checkbox"/> Cancellation	
Street Address P.O. Box 340		City, State, Zip Code Trenton, NJ 08625	
Name of Contact Bill Leary/Carolyn Bill Leary Plumbing & Heating		Telephone Number 732-494-9200 Ext 205	

FACILITY INFORMATION

Name of facility where abatement is taking place (3) Teaneck Armory National Guard (NON-Sub 8)			Type of Facility (4) <input type="checkbox"/> School (K - 12) <input type="checkbox"/> Subchapter 8 (Other than K-12) <input checked="" type="checkbox"/> Other (Private/Commercial Bldgs./Homes, etc.)		
Street Address 1799 Teaneck Road			Square Feet		
City (5) Teaneck			County (6) Bergen		County Code (7) (State use only)
Current Use (Prior if being demolished) Armory National Guard			Bldg. Age		

Name of Monitoring Firm Hired by Bldg. Owner (8) Whitman Companies		ASCM No. 110	Name of Abatement Contractor (9) B & G Restoration, Inc.		
Street Address 7 Pleasant Hill Road		City, State, Zip Code Cranbury, NJ 08512	Street Address 105 Ryerson Road		
Project Manager for Monitoring Firm Kevin Lovely		Phone Number 732-644-5418	City, State, Zip Code Lincoln Park, NJ 07035		License Number 00378
Scheduled Start Date (10) 06/14/2019		Sched. Completion Date (11) 07/08/2019			
Occupancy Status During Abatement (Check only one) <input type="checkbox"/> Facility closed/vacated during entire period of abatement. <input type="checkbox"/> Abatement performed outside of normal facility hours- Describe: _____ <input checked="" type="checkbox"/> Other-Describe: _____					
Name of OSHA Monitor B & G Restoration, Inc.			Street Address 105 Ryerson Road		
City, State, Zip Code Lincoln Park, NJ 07035			City, State, Zip Code Lincoln Park, NJ 07035		

Scope of Work (check all that apply)

<input type="checkbox"/> Demolition	<input checked="" type="checkbox"/> Renovation	<input type="checkbox"/> Full Containment w/negative pressure	<input type="checkbox"/> Glovebag procedure
<input type="checkbox"/> >3 sf or >3 lf	<input checked="" type="checkbox"/> >160 sf or >260 lf	<input checked="" type="checkbox"/> Mini-enclosure	<input type="checkbox"/> Non-friable procedure

Location of asbestos-containing material to be abated in facility (13)	Is location normally used solely by maintenance/custodial staff (12)			Description of asbestos-containing material (ACM)	Amount (Specify SF or LF)	R e m o v e	R e p a i r	E n c a p	E n c l
	Yes	No	N/A						
basement, 1st Floor, attic			<input checked="" type="checkbox"/>	pipe insulation (wrap & cut)	5.000 lf	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>


Registered Waste Hauler B & G Restoration, Inc.		NJDEP Hauler ID# 19563	Cubic Yards of Waste 40	Name of Registered Landfill Grand Central Landfill	
City, State Lincoln Park, NJ		Disposal Date 06/13/2019		City, State Pen Argyl, PA	
Completed by (Print or Type) Gordana Luna		Title Secretary/Treasurer	Signature <i>Gordana Luna</i>		Date 05/31/2019



INV# 11019  
CK4635

PAID

State of New Jersey  
NOTIFICATION OF ASBESTOS ABATEMENT  
(Pursuant to NJAC 8:60 and 12:120)



Date of Notification (1) 06/04/2019		Name of Building Owner/Operator (2) McWilliams Forge Company	
Agencies Notified <input checked="" type="checkbox"/> EPA <input type="checkbox"/> DEP <input checked="" type="checkbox"/> DOL <input checked="" type="checkbox"/> DOH <input type="checkbox"/> DCA	Type Notification <input checked="" type="checkbox"/> Initial <input type="checkbox"/> Amended Amendment # _____ <input type="checkbox"/> Emergency (including justification) <input type="checkbox"/> Cancellation	Street Address 387 Franklin Ave.	
		City, State, Zip Code Rockaway, NJ 07866	
		Name of Contact William Hunnicutt	Telephone Number 973-627-0200

FACILITY INFORMATION

Name of Facility Where Abatement is Taking Place (3) McWilliams Forge Company Bldg.7		Type of Facility (4) <input type="checkbox"/> School (K-12) <input type="checkbox"/> Subchapter 8 (Other than K-12) <input checked="" type="checkbox"/> Other (i.e. private & commercial buildings, homes, etc.)		
Street Address 387 Franklin Ave.		Square Feet 10,000	# of Floors 1	Bldg. Age 50+
City (5) Rockaway	County (6) Morris	County Code (7) (STATE USE ONLY) _____	Current Use (Prior if being demolished) Warehouse	
Name of Monitoring Firm Hired by Building Owner (8) RK Occupational & Environmental, Inc.		ASCM No. 00090	Name of Abatement Contractor (9) Bako Construction & Restoration, Inc.	
Street Address 401 St. James Ave.		Street Address 265 A Route 46 Suite 3D		
City, State, Zip Code Phillipsburg, NJ 08865		City, State, Zip Code Totowa, NJ 07512		
Project Manager for Monitoring Firm Jon Gilbert		Telephone No. 908-434-6316	Telephone No. 973-256-7010	License No. 0666
Start Date (10) 06/17/2019	Scheduled Completion Date (11) 06/22/2019	Name of OSHA Monitor Bako Construction & Restoration, Inc.		

Occupancy Status During Abatement (Check Only One) <input checked="" type="checkbox"/> Facility Closed/Vacated During Entire Period of Abatement <input type="checkbox"/> Abatement Performed Outside of Normal Facility Hours <input type="checkbox"/> Other - Describe: _____	Street Address 265 A Route 46 Suite 3D
	City, State, Zip Code Totowa, NJ 07512

Scope of Work (Check All That Apply)

<input type="checkbox"/> ≥3 sf or ≥3 lf	<input checked="" type="checkbox"/> Renovation	<input type="checkbox"/> Full Containment with Negative Pressure
<input checked="" type="checkbox"/> ≥160 sf or ≥260 lf	<input type="checkbox"/> Demolition	<input type="checkbox"/> Mini-Enclosure
		<input checked="" type="checkbox"/> Glovebag Procedure
		<input checked="" type="checkbox"/> Non-Exempted (*) and Non-Friable Procedure

Location of Asbestos-Containing Material (ACM) TO BE ABATED In Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
Building 7 front wall		X		Transite wall panels	3,000 SF	X			

Name of Registered Waste Hauler Bako Const. & Rest. Inc/Newark Carting		NJDEP Waste Hauler ID No. 20889/4509	Cubic Yards of Waste 40	Name of Registered Landfill Fairless Hills/ Waste Management	
City, State Totowa, NJ/ Newark, NJ		Disposal Date TBD	City, State Morrisville, PA		
Completed by Damir Valjevac	Title Project Manager	Signature 		Date 06/04/2019	