

State of NJ  
Notification of Asbestos Abatement  
(Pursuant to NJAC 8:60-7 and 12:120-7)

B & G proj. #: 2011-235

Check # 4898

Date of Notification (1)  
11/18/11

Agencies Notified

EPA  
 DEP  
 DOL  
 DOH  
 DCA

Type Notification


Initial  
 Amendment  
 Cancellation

Name of Building Owner/Operator (2)  
Johanna & Anthony Giasullo

Street Address  
10 Franklin Place

City, State, Zip Code  
Maplewood, NJ 07040

Name of Contact  
Anthony Giasullo



FACILITY INFORMATION

Name of facility where abatement is taking place (3)  
Johanna & Anthony Giasullo

Street Address  
10 Franklin Place

City (5)  
Maplewood, NJ 07040

County (6)  
Essex

County Code (7)  
(State use only)

Type of Facility (4)

School (K - 12)  
 Subchapter 8 (Other than K-12)  
 Other (Private/Commercial Bldgs./Homes, etc.)

Square Feet    # of Floors    Bldg. Age

Current Use (Prior if being demolished)  
residential

Name of Monitoring Firm Hired by Bldg. Owner (8)  
n/a

Street Address

City, State, Zip Code

ASCM No.

Name of Abatement Contractor (9)  
B & G Restoration, Inc.

Street Address  
105 Ryerson Road

City, State, Zip Code  
Lincoln Park, NJ 07035

Telephone Number  
973-696-6869

License Number  
0378

Name of OSHA Monitor  
B & G Restoration, Inc.

Street Address  
105 Ryerson Road

City, State, Zip Code  
Lincoln Park, NJ 07035

Project Manager for Monitoring Firm

Phone Number

Scheduled Start Date (10)  
11/29/2011

Sched. Completion Date (11)  
11/30/2011

Occupancy Status During Abatement (Check only one)

Facility closed/vacated during entire period of abatement.  
 Abatement performed outside of normal facility hours- Describe:  
 Other-Describe:

Scope of Work (check all that apply)

Demolition     Renovation     Full Containment w/negative pressure     Glovebag procedure  
 >3 sf or >3 lf     ≥160 sf or ≥260 lf     Mini-enclosure     Non-friable procedure

Location of asbestos-containing material to be abated in facility (13)	Is location normally used solely by maintenance/custodial staff(12)			Description of asbestos-containing material (ACM)	Amount (Specify SF or LF)	R e m o v e	R e p a i r	E n c a p	E n c l
	Yes	No	N/A						
basement			X	pipe insulation	160 lf	X			

Registered Waste Hauler  
B & G Restoration, Inc.

NJDEP Hauler ID#  
19563

Cubic Yards of Waste  
2 yards

Name of Registered Landfill  
Tullytown Resource & Recovery Center

City, State  
Lincoln Park, NJ 07035

Disposal Date  
11/30/11 *GL*

City, State  
Tullytown, PA

Completed by (Print or Type)  
Gordana Luna

Title  
Treasurer

Signature  
*Gordana Luna*

Date  
11/18/2011