

APPENDIX C
PHOTOGRAPHIC LOG



Photo 1 – Greenbrook Regional Center



Photo 2 – Eastern Parking Lot



Photo 3 – Bridge to Dog Park Over Creek



Photo 4 – Vegetated Channel from East Parking Lot to Creek



Photo 5 – Creek and Culvert Under Greenbrook Road



Photo 6 – Transformer Cluster in Eastern Parking Lot Near Creek



Photo 7 – Greenbrook Regional Center East Side of Building



Photo 8 – Floor Drain Under Covered Area



Photo 9 – Western Parking Lot



Photo 10 – Wooded Area on Western Perimeter



Photo 11 – Drainage Culvert at Southwestern Corner of Western Parking Lot



Photo 12 – Electrical Power Station in Western Parking Lot



Photo 13 – 100-Gallon AST



Photo 14 – 6,000-Gallon Fuel Oil AST



Photo 15 – 330-Gallon Diesel AST



Photo 16 – AST Containment Area



Photo 17 – AST Containment Traffic Protection



Photo 18 – 1,500-Gallon “Brine” AST



Photo 19 – South Side of Building and Hazardous Materials Storage



Photo 20 – Inside of Hazardous Materials Storage Shed