

# Return & Repair Form:

## Customer Information:

Company Name: NTSP B: \_\_\_\_\_ S: \_\_\_\_\_  
 Date Received: 9-3-09 Date Given to Service: 9-3-09  
 Carrier: FedEx - UPS - DHL - USPS Method: GRD - NDA - 2DY - 3DY - Other

## Product Information:

Product: 7410 7110 - 6510 - 6810 Serial #: AR NL - 0047  
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR -  
 Whole Instrument Top 1/2 Sim Ser #: \_\_\_\_\_  
 Other \_\_\_\_\_ Probe Ser # DD P -  
**ACCESSORIES:**  
 110 V A/C Adapter  Regulator  Mag Card Rdr# \_\_\_\_\_  
 Printer Paper  Printer Ribbon  Casio # \_\_\_\_\_  
 Mouthpieces  Carrying Case  Dry Gas  
 Other (Please Specify) \_\_\_\_\_ Warranty Exp. Date \_\_\_\_\_

## Repair Information:

Test #

Reason for Return: NO POWER

Part Number	Description	Qty	Total Cost
<u>12029</u>	<u>POWER SUPPLY</u>	<u>1</u>	<u>N/C CUSTOMER</u>
<u>6808455</u>	<u>FC</u>	<u>1</u>	<u>N/C WARR</u>
<u>MP cal 71</u>	<u>cal</u>	<u>1</u>	<u>N/C WARR</u>
<u>6809500</u>	<u>CUVETTE</u>	<u>1</u>	<u>N/C WARR</u>
<u>MP labor</u>	<u>labor</u>	<u>.5</u>	<u>N/C WARR</u>

## Repair Notes:

FLOW SENSOR WIRES LOCATED UNDER SAMPLE UNIT BRACKET - REPAIRED  
NO POWER - DUE TO FAULTY POWER SUPPLY - REPLACED  
REPLACED IR FILTER - DUE TO ERROR 23 - CUVETTE LOOKS OK  
REPLACED FC  
Cal w/ QC, Ops Check

Service Technician: [Signature]

Date: 9-8-09