

Return & Repair Form:

Customer Information:

Company Name: NJSP Buena Vista B: _____ S: _____
 Date Received: 4/5/2011 Date Given to Service: 4/5/2011
 Carrier: FedEx - UPS - DHL - USPS Method: GRD - NDA - 2DY - 3DY - Other

Product Information:

Product: 7410-7110-6510-6810-7510 Serial #: AR W/C - 0011
 9510- Drug Tester 5000
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR -
 Whole Instrument Top 1/2 Sim Ser #: _____
 Other _____ Probe Ser # DD P -
ACCESSORIES:
 110 V A/C Adapter Regulator Mag Card Rdr# _____
 Printer Paper Printer Ribbon Casio # _____
 Mouthpieces Carrying Case Dry Gas
 Other (Please Specify) _____ Warranty Exp. Date _____

Repair Information:

Test

Reason for Return: _____

Part Number	Description	Qty	Total Cost
<u>6808455</u>	<u>FC</u>	<u>1</u>	<u>N/C W</u>
<u>12008</u>	<u>13umpers</u>	<u>6</u>	<u>N/C W</u>
<u>MP Misc</u>	<u>Case (8314685)</u>	<u>1</u>	<u>N/C W</u>
<u>MP Cal 71</u>	<u>Cal</u>	<u>1</u>	<u>N/C W</u>
<u>12094</u>	<u>SCREWS</u>	<u>2</u>	<u>N/C W</u>
<u>12095</u>	<u>NUTS</u>	<u>2</u>	<u>N/C W</u>
<u>12098</u>	<u>Washer</u>	<u>2</u>	<u>N/C W</u>
<u>MP labor</u>	<u>labor</u>	<u>.5</u>	<u>N/C W</u>

Repair Notes:

Unit arrived with case damage to the lower front section, there is also damage to FedEx Box same location as case, unit was also inspected by supervisor, which took pictures of damage.

Install new 7110 case, and FC # ARCA-0229

Cal w/DC & ops check

Service Technician: [Signature]

Date: 4/6/2011