

# RETURN AND REPAIR FORM



## Customer Information

B:

S:

Company Name: Old Tappan P.A. Old Tappan, N.J.

Date Received: 08/11/11 Date given to service: \_\_\_\_\_

Carrier:  FedEx  UPS  USPS Shipping Method:  GRD  3DAY  2DAY  
 NDA-PRI  NDA-STD

Product:  6510  6810  
 7110  8610  
 7510  DT5000  
 7410 Upper-half  9510  
 7410 Whole

Serial Number: AR XB-0087

Printer Serial#: AR

Sim Serial#: DD

Probe Serial#: DD

Warranty Expires: \_\_\_\_\_

Description:  A  B  Plus  Demo  Screener  Trade In

## Accessories

110V A/C Adapter  Regulator  Printer Ribbon  Printer Paper  
 Mouthpieces  9510 Stylus  9510 Top Cover  Carrying Case  
 Dry Gas  Other (please specify) \_\_\_\_\_

## Repair Information:

## Test#:

Part Number	Description	Qty	Total Cost
<u>mp cal 71</u>	<u>Calibrate</u>	<u>1</u>	<u>N/C/W</u>
<u>13336</u>	<u>Hose</u>	<u>8 IN</u>	<u>N/C/W</u>
<u>mp Labor</u>	<u>Labor</u>	<u>.5</u>	<u>Labor</u>

Repair Notes: Unit arrived with a error 43, after inspection, I found out that the hose that connects the pump and solenoid was pinched. Install new hose.

cal w/ DC ; ops check

Service Technician: [Signature]

Date: 8-11-11