

# Return & Repair Form

## Customer Information:

Company Name: Haledon P.D. B: \_\_\_\_\_ S: \_\_\_\_\_  
 Date Received: 9-16-08 Date Given to Service: \_\_\_\_\_  
 Carrier: FedEx - UPS - DHL - USPS Method: GRD - NDA - 2DY - 3DY - Other

## Product Information:

Product: 7410 - 7110 - 6510 - 6810 Serial #: AR XB - 0088  
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR -  
 Whole Instrument Top 1/2 Sim Ser #: \_\_\_\_\_  
 Other \_\_\_\_\_ Probe Ser # DD P -  
**ACCESSORIES:**  
 110 V A/C Adapter  Regulator  Mag Card Rdr# \_\_\_\_\_  
 Printer Paper  Printer Ribbon  Casio # \_\_\_\_\_  
 Mouthpieces  Carrying Case  Dry Gas  
 Other (Please Specify) \_\_\_\_\_ Warranty Exp. Date \_\_\_\_\_

## Repair Information:

Reason for Return: IR RESULTS + EC RESULTS? Test # \_\_\_\_\_

Part Number	Description	Qty	Total Cost
<u>6809458</u>	<u>DETECTOR</u>	<u>1</u>	<u>N/C WARR</u>
<u>MPCL71</u>	<u>CAL</u>	<u>1</u>	<u>N/C WARR</u>
<u>MPLABOR</u>		<u>.5</u>	<u>N/C WARR</u>

Repair Notes:  
FC WAS NEW (INSTALLED 3-26-08) (YM) BLOW OUT COUETTE /  
REPLACE IR DETECTOR PCB - IR FILTER LOOKS OK - IN PLACE  
AND CLEAN / CAL W/ QC 5 OPS CHECKS

Service Technician: [Signature] Date: 09-18-08