

RETURN AND REPAIR FORM



Customer Information

B: _____ S: _____

Company Name: Boro. of Haledon P.D., Haledon, NJ

Date Received: 04/28/15 Date given to service: 04/28/15

Carrier: FedEx UPS USPS Shipping Method: GRD 3DAY 2DAY
 NDA-PRI NDA-STD

Product: 6510 6810
 7110 8610
 7510 DT5000
 7410 Upper-half 9510
 7410 Whole

Serial Number: AR XB-0088
 Printer Serial#: AR
 Sim Serial#: DD
 Probe Serial#: DD

Warranty Expires: May 2013

Description: A B Plus Demo Screener Trade In

Accessories

110V A/C Adapter Regulator Printer Ribbon Printer Paper
 Mouthpieces 9510 Stylus 9510 Top Cover Carrying Case
 Dry Gas Other (please specify) _____

Repair Information:

Test#: _____

Part Number	Description	Qty	Total Cost
4414161	Calibration	1	
4414166	Labor	5	
6808455	Fuel Cell	1	
6808486	Spacer Plates	2	
8315075	Alcotest 7110 Motherboard	1	

Repair Notes: Replaced defective motherboard fuel cell, and spacer plates.

Motherboard was changed due to it giving the wrong solution reading.

Fuel Cell = ARFM-2058

CAL W/QC AND OPS CHECK

Service Technician BC

Date: 06/12/15